

15/5/2019

INS. CASE OWNER:

CC 3/EQ1801 5759, Kebh⁵²LKK:
IDAC:

Surveyor:

Klnneth

DOI:

ASSIGNMENT

28/8/18

Date / Time:

28/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 1256H

Name of Insured:

LAY SIEW HOON

Insured Tel No.:

HP:

25/8/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

GEO WEE LHEH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

0M181000095

Policy No.:

0MPPH18-000060

Make / Model:

Suzuki

Place of Accident:

P18 Tmg Lms.

OI GIA REPORT: ☒ YES / NOTP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SHF 615A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Transcab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/9/18
Ksher

SHF 615A - K

GMA 1256H - K

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: NO NEED

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

45 SS 4,050

(4 days) Reduction:

82 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 22.05.19

Confirm with: WMA YIN

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

WMA:

SS 4,333.50

DID REAR ENDED TP

Loss of Rental (LOR):

SS 595.42

(6 days) x 99.32

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

SS 7.44

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +100

Total:

SS 4,936.91

Global Sum SS:

FINAL PAYMENT

Date/Time: 22.05.19

Confirm with: WMA YIN

Email ☒ Call ☐

Payee 1:

SS 4,936.91

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
WMA/19bll
27/5/19
pu

EQ ✓

Kenneth



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI18015759/Keb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 29-08-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 1356H	Veh. Inspected	SHF 615A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/08/2018	Inspection Date	28/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI18015759/Keb3

Date: 29.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF615A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28.08.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	23,097.01
Revised Estimate Amount	: S\$	4,050.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A**AAD1808-216***Not Authorised
11 Sep 840506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 615A

VF1ABL15AUC278494

RENAULT

LATITUDE

25.8.2018

EQ**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>add 10.1</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 1,471.77 ✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56 X
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70
19	1 BOOT REAR	\$	<i>R</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
25	1 BOOT BADGE	\$	<i>nn</i> 225.36
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84

X

Trans-cab Auto Services Pte Ltd

AAD1808-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

30	1 BOOT INNER TRIM	\$	Sm	586.45	X
31	1 BOOT SWITCH	\$	Sm	168.13	X
32	1 BOOT LOCK	\$	Kn	202.67	X
33	1 BOOT LOCK CATCH	\$	Kn	74.40	X

	\$	16,046.87
10%	\$	1,604.69
	\$	14,442.19

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	Kn	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	Kn	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	Kn	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	Kn	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	Kn	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	Kn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	Kn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	Kn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	Kn	80.00	X
12	1 WINDSCREEN MOULDING	\$	Kn	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	Kn	100.00	X

TOTAL \$ 1,244.82

TOTAL PARTS \$ 15,687.01

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	440/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600/
To Rust-Proofing Of The Affected Areas.	\$	170.00	30/

Trans-cab Auto Services Pte Ltd

AAD1808-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X

TOTAL \$ 7,410.00**Over All Total \$ 23,097.01**

23046.99

(LUMP SUM)**Repair Days****10 DAYS**

4 days

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

Shu Pei (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 30 August 2018 10:07 AM
To: Shu Pei (LKKAuto)
Cc: Asher Sng (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SMA1356H (OI : EQI - TBA) AND SHF615A (TP : LKK REF - CC3/EQI18015759/Keb3) on 25.08.2018
Attachments: SMA1356H.PDF

Dear Shu Pei

Attached please find our insured's accident report for your attention.

Dear Asher

Please inform the surveyor to keep a look out for the front of SHF615A.
Check if there are any damages to the front of the vehicle as third party vehicle, SLR8168K alleged that SHF615A had contact with SJP2182S.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, August 30, 2018 9:11 AM
To: Joel Goh
Cc: Asher Sng (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SMA1356H (OI : EQI - TBA) AND SHF615A (TP : LKK REF - CC3/EQI18015759/Keb3) on 25.08.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHF 615A at M/s Trans-cab Auto Services Pte Ltd.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeit@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Wednesday, 22 May 2019 6:20 PM
To: Asher Sng (LKKAUTO); 'Ng Wai Yin'
Cc: claims@transcab.com.sg
Subject: RE: Your Ref: AAD1808-216, ACCIDENT INVOLVING SHF 615A AND SMA 1356H ON 25/08/2018
Attachments: image001.wmz

Without Prejudice

Dear Asher

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Wednesday, 22 May 2019 12:04 PM
To: jasminetan@transcab.com.sg; Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: claims@transcab.com.sg
Subject: Your Ref: AAD1808-216, ACCIDENT INVOLVING SHF 615A AND SMA 1356H ON 25/08/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Jasmine / Wai Yin,

We refer to the above matter.

ACCIDENT INVOLVING SHF 615A AND SMA 1356H ON 25/08/2018

Based on the previous bulk settlement should be as follows: -

1. Cost of Repair(w/GST)	\$ 4,333.50
2. Loss of Rental (6days x \$99.32)	\$ 595.92

3. LTA/GIA search fee	\$ 7.49
TOTAL	<u>\$ 4,936.91</u>

Kindly let us have the confirmation on the above settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ118015759/Keb3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 28-05-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 1356H	Veh. Inspected	SHF 615A
Policy No.	DMPPHQ18-000280	Coverage (\$)	0.00
Claim No.	DM18HO02255	Excess (\$)	0.00
Assign From		Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278494	Colour	METALLIC WHITE / RED
Odometer	284712	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	7 mm
L/H Front Tyre	215/60R16	GITI	7 mm
R/H Rear Tyre	215/60R16	GITI	7 mm
L/H Rear Tyre	215/60R16	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/08/2018	Inspection Date	28/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 615A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-

Report Ref No. CC3/EQI18015759/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
	LESS 10% DISCOUNT		-1,604.69	-412.66
			14,442.17	3,713.93
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,244.82	165.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00

Report Ref No. CC3/EQ18015759/Keb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND RELIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH. TO RUST-PROOFING OF THE AFFECTED AREAS.		3,000.00	600.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	30.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,410.00	1,190.00
GRAND TOTAL			23,096.99	5,068.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CC3/EQ18015759/Keb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.