



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8352H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER (CONSISTENT)	BUCKLED	801.80	801.80
1	FRT RH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	415.90	-
1	FRT RH BUMPER SIDE RETAINER (CONSISTENT)	DISTORTED	18.90	18.90
1	FRT RH FENDER WHEEL ARCH (CONSISTENT)	CUT	171.10	171.10
1	FRT RH RIM 16 (CONSISTENT)	DENTED	765.80	765.80
1	RH HEADLAMP (CONSISTENT)	* CHECK	1,715.10	-
	LESS 20% DISCOUNT		-777.72	-351.52
			3,110.88	1,406.08
	<u>LABOUR</u>			
	TO PANEL BEAT ON FRONT RH AFFECTED AREAS ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRT RH FENDER .		600.00	480.00
	TO PUTTY ,RESPRAY ON FRONT RH FENDER ,FRT BUMPER RIM AND AFFECTED AREAS.		750.00	500.00
	CHECK LIGHTING AND WIRING .		50.00	20.00
	CHECK AND ADJUST WHEEL ALIGNMENT.		120.00	80.00
			1,520.00	1,080.00
GRAND TOTAL			4,630.88	2,486.08
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,372.08 NETT)				2,486.08

Report Ref No. CC4/ASM18015761/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.