



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP

Vehicle No. : SLG2230K

Make & Model : HONDA SHUTTLE 1.5 HYBRID

Year of Manufacture : 2016

Chassis No. : GP71040385

Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 28/08/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 45.00

Labour (Appendix B) \$ 2,900.00

Total Repair Cost \$ 2,945.00

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

*Not Authorised
The money B'c pain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 29/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 045 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 29/8/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLG2230K Case Owner : Andrew
 Make & Model : HONDA SHUTTLE 1.5 HYI Year Manufacture : 2016
 Chassis No : GP71040385 Engine No : 0
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing <i>Sm</i>	1				\$ 45.00	X
2	Rear bumper <i>Bm</i>	1					✓
3	Rear bumper side retainer LH <i>Sm</i>	1					X
4	Rear bumper side retainer RH <i>Sm</i>	1					X
5	Rear bumper clips <i>Nm</i>	1					✓
6	Rear bumper reflector LH <i>Sm</i>	1					X
7	Rear bumper reflector RH <i>Sm</i>	1					X
8	Tailgate <i>Bm</i>	1					✓
9	Tailgate glass moulding upper <i>Nm</i>	1					
10	Tailgate glass moulding lower <i>Nm</i>	1					
11	Tailgate glass moulding LH <i>Nm</i>	1					
12	Tailgate glass moulding RH <i>Nm</i>	1					
13	Tailgate glass inner seal <i>Nm</i>	1					
14	Tailgate glass sealant <i>Nm</i>	1					
15	Tailgate weatherstrip	1					
16	Tailgate emblem logo H <i>Nm</i>	1					
17	Tailgate emblem SHUTTLE <i>Nm</i>	1					
18	Tailgate emblem HYBRID <i>Nm</i>	1					
19	Tailgate chrome moulding <i>Sm</i>	1					X
20	Tailgate chrome moulding clips <i>Nm</i>	4					X
21	Reverse sensor	1					?
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Note: If any of the quoted parts are recommended to be repaired, when an additional labour charge will be charged accordingly under supplementary.

