



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP

Vehicle No. : SLG2230K

Make & Model : HONDA SHUTTLE 1.5 HYBRID

Year of Manufacture : 2016

Chassis No. : GP71040385

Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 28/08/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 45.00

Labour (Appendix B) \$ 2,900.00

Total Repair Cost \$ 2,945.00

Contact No
Frnt Counter Operation
 6383 7466 - Patrick Tia
 6383 7730 - Brenda Ng
 6383 7890 - Rohani
braddell_cr@sparkcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 - Andrew Goh
 63838115 - William Wang

braddell_operation@sparkcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
Remarks By Surveyor		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	:\$ _____
(e) Signature of surveyor	:	_____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLG2230K Case Owner : Andrew

Make & Model : HONDA SHUTTLE 1.5 HYI Year Manufacture : 2016

Chassis No : GP71040385 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 45.00	
2	Rear bumper	1					
3	Rear bumper side retainer LH	1					
4	Rear bumper side retainer RH	1					
5	Rear bumper clips	1					
6	Rear bumper reflector LH	1					
7	Rear bumper reflector RH	1					
8	Tailgate	1					
9	Tailgate glass moulding upper	1					
10	Tailgate glass moulding lower	1					
11	Tailgate glass moulding LH	1					
12	Tailgate glass moulding RH	1					
13	Tailgate glass inner seal	1					
14	Tailgate glass sealant	1					
15	Tailgate weatherstrip	1					
16	Tailgate emblem logo H	1					
17	Tailgate emblem SHUTTLE	1					
18	Tailgate emblem HYBRID	1					
19	Tailgate chrome moulding	1					
20	Tailgate chrome moulding clips	4					
21	Reverse sensor	1					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

