

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1063G
 Ref. No : TAX/08/18/2087
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : NG TECK HOCK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 24/08/2018 08:40:00 PM
 Accident Reported Date / Time : 25/08/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097665
 Special Instruction to ARC, if any :
 DROVE IN / SLQ6334R
 Prepared Date : 25/08/2018 11:22:29 AM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan fah 97495749

WR'

27/4/18 @ 1640

Resurvey before paint
4 days

su@lkkauto.com

tan fah @ lkkauto.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603577127

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	1,476.00	0.00
Total Material Charges :	9,881.33	9,881.33
Other Charges :	1,170.00	0.00
TOTAL :	13,372.33	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	25/08/2018 01:23:28 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/08/2018 01:21:29 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 8/25/2018 1:28:54 PM

Section B - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00
Total Labour	845.00	0.00 400

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X
TO RESPRAY VIEW MIRROR	180.00	0.00 100
TO RESPRAY APRON PANEL LH	180.00	0.00 X
Total Spray Painting & Panel Beating	1,476.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80.
TO REMOVE AND REFIX UNDERCARRIAGE	350.00	0.00 150 ?
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 60.
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REMOVE AND REFIT TYRE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,170.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace <i>dl</i>	No
5211647050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace <i>ne</i>	No
8118547691			UNIT, HEADLAMP, LH	1	2,558.90	10.00	2,303.01	Replace	Replace ?	No
5380247100			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace <i>bt</i>	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace <i>ne</i>	No
5387647110			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace <i>dl</i>	No
5385247041			PAD, FR WHEEL LH	1	57.70	25.00	43.27	Replace	Replace ?	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace <i>x</i>	No
42611-47450			WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace <i>cut</i>	No
4852080492			ABSORBER SET, SHOCK, FRONT LH	1	398.10	25.00	298.57	Replace	Replace ?	No
4882047040			LINK ASSY, FRONT STABILIZER, RH & LH	1	196.70	25.00	147.52	Replace	Replace ?	No
4806947060			LOWER ARM SUB-ASSY, FRONT LH	1	631.60	25.00	473.70	Replace	Replace ?	No
4333019115			JOINT ASSY, LWR BALL, RH & LH	1	200.10	25.00	150.07	Replace	Replace ?	No
4355047020			HUB & BEARING ASSY, RH & LH	1	554.20	25.00	415.65	Replace	Replace ?	No
4321247040			KNUCKLE, STEERING, LH	1	555.20	25.00	416.40	Replace	Replace ?	No
5370247101			APRON SUB-ASSY, FRONT FENDER, LH	1	944.20	25.00	708.15	Replace	Replace <i>x</i>	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	25.00	432.00	Replace	Replace <i>x</i>	No
8794047440			MIRROR ASSY, OUTER REAR VIEW, LH	1	1,283.90	10.00	1,155.51	Replace	Replace ?	No
8796147440			MIRROR OUTER GLASS, LH	1	143.10	25.00	107.32	Replace	Replace ?	No
8174047010			LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	1	162.20	10.00	145.98	Replace	Replace <i>am</i>	No
8794547060A1			COVER, OUTER MIRROR, LH	1	89.50	25.00	67.12	Replace	Replace <i>mis</i>	No
8954347040			SENSOR, SPEED, FRONT LH	1	450.50	10.00	405.45	Replace	Replace ?	No
TOTAL MATERIALS								9,881.39	9,881.33	
TOTAL MATERIALS(Discounted)							9,881.33	9,881.33		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									