

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18015844/AHA3Q2

Date: 27/05/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SDK2485R

Insured Vehicle No :

SHD298S

Date of Loss: 26/08/2018

Nature of Claim:

TP

Claim No: C0474284

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDK2485R

Make & Model:

TOYOTA COROLLA, 1.5 (A)

Engine No:

1NZA161667

Reg. Date:

02/05/2001 (Man. Year: 2001)

Chassis No:

JTDBT23EX03043343

Colour:

Gold

Odometer:

312355 km

Engine Capacity:

1497 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/65 R14

Rear Tyre Size:

185/65 R14

Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,532.72	1,060.72	1,472.00	58.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,310.00	1,190.00	47.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,032.72	2,370.72	2,662.00	52.89
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	5,032.72	1,900.00	3,132.72	62.25
+ GST 7.00/7.00% (S\$)	352.29	133.00	219.29	62.25
Nett Amount (S\$)	5,385.01	2,033.00	3,352.01	62.25
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		2,333.00		
Liabe Amount (50.00%) (S\$)		1,166.50		
Global Sum Settlement (S\$)		1,100.00		

INSPECTION

Date of Assignment:

30/08/2018

Date Inspected:

14/12/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)

Blk 3023A Ubi Road 1, #01-61 & #01-58

Singapore 408717

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2020)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK2485R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Deformed	425.00 FL	*425.00 FL
2	1		*SET FRONT BUMPER CLIPS (CONSISTENT)	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER -RH (CONSISTENT)	Necessary	30.20 FL	*30.20 FL
4	1		*HEADLAMP -RH (CONSISTENT)	Cut	365.10 FL	*365.10 FL
5	1		*FRONT FENDER -RH (CONSISTENT)	Dented	484.00 FL	*484.00 FL
6	1		*FRONT FENDER INNER SHIELD -RH (CONSISTENT)	Not Necessary	135.70 FL	*- FL
7	1		*SET FRONT FENDER INNER SHIELD CLIPS-RH (CONSISTENT)	Not Necessary	80.00 FL	*- FL
8	1		*FRONT DOOR -RH (CONSISTENT)	Repair	1,024.10 FL	*- FL
9	1		*FRONT DOOR PROTECTOR -RH (CONSISTENT)	Not Necessary	130.20 FL	*- FL
10	1		*FRONT DOOR WEATHERSTRIPE-RH (CONSISTENT)	Not Necessary	166.00 FL	*- FL
11	1		*FRONT WHEEL RIM -RH (CONSISTENT)	Not Necessary	280.00 FS	*- FS
12	1		*FRONT WHEEL COVER -RH (CONSISTENT)	Cut	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,250.30	1,394.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	717.58	333.58

Total Parts (\$\$)	2,532.72	1,060.72
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT RH PORTION & RENEW ABOVE PARTS	New	1,000.00	600.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO TRANSFER DOOR FITTINGS	New	150.00	0.00
6	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	80.00
Gross Labour Cost (\$\$)			2,500.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >