

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3860D

DATE 27/8/2018

MAKE :

MODEL : HYUNDAI i40

AXA-45

TS

✓R

1710

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover ✓			\$ 562.30	
	Front Bumper Bracket Top (RH) ?			\$ 22.40	
	Front Bumper Bracket (RH) ?			\$ 24.60	
	Front Fender (RH) ✓			\$ 619.00	
	Front Fender Shield (RH) X			\$ 169.80	
	Front Fender Retainer X			\$ 9.20	
	Frt Wheel Alignment X			\$ 150.70	
	Sub Head Lamp (LH) ✓				
	Front wheel Cover (LH) ✓				
	Side Mirror (LH) X repg				
	SUB TOTAL			\$ 1,558.00	
	LESS 20%			\$ 311.60	
	DISCOUNTED TOTAL			\$ 1,246.40	
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge				
	Panel Beating			\$ 560.00 400	
	Spray Painting Charge			\$ 500.00 400	
	Tuff Kote			\$ 50.00 20	
	Frt Wheel Alignment			\$ 80.00 X	
	TOTAL LABOUR			\$ 1,190.00	
	ESTIMATE TOTAL			\$ 2,536.40	
	Kahinicks 29/8/18 1715h 2 hrs. 4/5 After Repair LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					