



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9134Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH (CONSISTENT)	SERVICEABLE	418.44	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,202.00	-
1	REAR BUMPER BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER (CONSISTENT)	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER (CONSISTENT)	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER (CONSISTENT)	TO REPAIR SEE LABOUR	623.76	-
1	REAR END PANEL INNER TRIM (CONSISTENT)	SERVICEABLE	263.84	-
1	REAR TAIL LAMP RH (CONSISTENT)	CRACKED	479.30	479.30
1	REAR TAIL LAMP INNER PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	359.00	-
	LESS 10% DISCOUNT		-546.13	-47.93
			4,915.15	431.37
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR FENDER INNER TRIM CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			30.00	-
<u>LABOUR</u>				
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR FENDER RH,REAR BUMPER,REAR BUMPER BEAM ,REAR END PANEL OUTER AND REAR TAIL LAMP INNER PANEL RH.		2,100.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		2,100.00	200.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			5,100.00	300.00
GRAND TOTAL			10,045.15	731.37

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			600.00
---	--	--	---------------

Report Ref No. CC3/ASM18015854/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.