

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18015859/R1GA3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SBS6370T

Insured Vehicle No :

SHC5123K

Date of Loss: 28/08/2018

Nature of Claim:

TP

Claim No: C0474294

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SBS6370T

Make & Model:

MERCEDES-BENZ CITARO O530, 6.4 L AT
TURBO ABS (A)

Engine No:

902926C0994207

Reg. Date:

01/03/2013 (Man. Year: 2012)

Chassis No:

WEB62808323124772

Colour:

Green

Odometer:

326158 km

Engine Capacity:

6374 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

275/70 R22.5

Rear Tyre Size:

275/70 R22.5 (D)

Front Left Side:

Michelin 8 mm

Rear Left Side:

Michelin 8/8 mm

Front Right Side:

Michelin 8 mm

Rear Right Side:

Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,964.06	1,964.06	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	3,300.00	1,050.00	24.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,314.06	5,264.06	1,050.00	16.63
+ GST 7.00/7.00% (S\$)	441.98	368.48	73.50	16.63
Nett Amount (S\$)	6,756.04	5,632.54	1,123.50	16.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 31/08/2018 Inspected At:

Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Apr 2020)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6370T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Cracked	701.56 F	*701.56 F
2	1		*BUMPER FRONT O/S (CONSISTENT)	Cracked	784.55 F	*784.55 F
3	1		*HEADLAMP RH (CONSISTENT)	Broken	369.20 F	*369.20 F
4	1		*BLINKER LAMP O/S (CONSISTENT)	Broken	54.80 F	*54.80 F
5	1		*LOCK FOR O/S BUMPER (CONSISTENT)	Bent	41.60 F	*41.60 F
6	1		*FASTENER (FRONT O/S BUMPER) (CONSISTENT)	Necessary	12.35 F	*12.35 F

F=Franchise part.

Total Parts (S\$) **1,964.06** **1,964.06**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	New	4,350.00	3,300.00
Gross Labour Cost (\$\$)			4,350.00	3,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >