



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### General Details

Involving	TPVD BMW 535I 3.0L AT D/AB 2WD 4DR GAS/D SR HUD (SLS230K)
Date of Loss	28 August 2018
Time of Loss	11.10
Loss Description	SFW1141C (INSD) COLLISION WITH SLS230K (TP)
Comment	

### Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$56,000.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	45



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Vehicle &amp; Driver Details

Vehicle Registration# SLS230K

Purchase Date dd/mm/yyyy 

Registration State SINGAPORE

Registration Date \* 08/06/2010 

Mileage 145570

Age of Vehicle 8

## CATEGORY

## POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2005

2010

Make

TOYOTA

B.M.W.

Model

VIOS 1.5

535I 3.0L AT D/AE

## Driver Details

## CATEGORY

## FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

GOH JUN DE

Date of Birth



23 December 1990

dd/mm/y 

Age

27

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value="▼"/>
Type of Paint		<input type="text"/>
Chassis No	MR053HY4204137744	<input type="text" value="WBAFR72010C26"/>
Engine No	1NZX285389	<input type="text" value="07517378N55B3C"/>
Engine Capacity		<input type="text" value="2979"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="56000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="▼"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date		<input type="text" value="dd/mm/y"/> 
License Expiration Date		<input type="text" value="dd/mm/y"/> 
Address	BLK 4 UPPER ALJUNIED LANE, #04-24, 360004, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	GOH JUN DE	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

03/09/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

275/35ZR19

Rear Tyre Size

275/35ZR19

Front left side

MICHELIN5mm

Rear left side

MICHELIN5mm

Front right side

MICHELIN5mm

Rear right side

MICHELIN5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18015862/Gz4d3e2		
8 SHENTON WAY #24-01		Date: 24-09-2018		
AXA TOWERS SINGAPORE 068811				
ATTN: CYNTHIA LOH		Code: ASM		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SFW 1141C	Veh. Inspected	SLS 230K	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00TQQ	Excess (\$)	0.00	
Assign From	CYNTHIA LOH	Assign Date	30/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 535I	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAFR72010C264569	Colour	RED	
Odometer	145570 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/35Z R19	MICHELIN	5 mm	
L/H Front Tyre	275/35Z R19	MICHELIN	5 mm	
R/H Rear Tyre	275/35Z R19	MICHELIN	5 mm	
L/H Rear Tyre	275/35Z R19	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
<b>5. General Information</b>				
Accident Date	28/08/2018	Inspect Date / Time	03/09/2018 ( 11:00 AM )	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/ASM18015862/Gz4d3e2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.