

22/03/2003

ASS. REC. BY:

REF:

CS8/IPC17015460/Bqbr-1

Special Instruction:

SURVIVOR:

Richard

ASSIGNMENT (Office)

From (Person):

Bic Woo

of

RPC

Date/Time: 30/8/2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8GL3126E

Insured: 8GD 8882 P

at Workshop m/s N-51

Tel: 68420051

of 2 Kaki Bukit Ave #01-18

Policy No:

Claim No: 17/17/17/VPOS/020040

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8/8/2017

(Client's Record)

11/8/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

8/8

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	8GL3126E - X
	8GD 8882P - X
	Submit PRS report
07/9/18	submit LS 65650, 6 days (red & 13050, 70%)

RECEIVED 03 SEP 2018

Jmmta

31/8/2018.

urgent
not yet sign
By email first
no bill

Richard

REF:

LR

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGL 3126E

at Workshop mis:

N-51

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11/8/2017

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

PRE

Veh No:

SGL 3126E

Yr Regn:

01/08/2006

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW M5

C.C.

4999

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading:

148076

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBSNB92030CU18111

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ normal / Jammed / Leaked / Burnt or

Brake: ☒ normal / Jammed / Leaked / Burnt or

Modi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

255/35R20

MIC

R:

295/30R20

PIR

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/08 09:00

D.O.I.

11/8 10:40

Survey held at

N51

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

HS 5200/2

Repair days 7

TALIM

31/8/18

Date/Time File Pass to:

typist

Date/Time File Return to:



Preli. Report



Final Report

Days Of Repair: 7-6

Resurvey No. of Trip: -

Survey Fee

Transportation

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) \$ - RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$

7P

5650

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 30 August 2018 3:39 PM
To: Catherine Chong (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/17/17/VP05/020040 Accident involving SGD 8882P & SGL 3126E along Bukit Timah Rd towards Newton Circus on 8/8/2017
Attachments: 20040 TPD SURVEY.pdf

*Celine this
are tomorrow
morning
I will come
open ref.*

Dear Catherine

Attached is the TP survey report.

Please let us have your surveyor's review/report.

Thanks,
Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 10 August, 2017 10:07 AM
To: ERIC WOO JUN KIAT; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/17/17/VP05/020040 Accident involving SGD 8882P & SGL 3126E along Bukit Timah Rd towards Newton Circus on 8/8/2017

Dear Eric,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]
Sent: Tuesday, 8 August, 2017 4:39 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Our Ref: 17/17/17/VP05/020040 Accident involving SGD 8882P & SGL 3126E along Bukit Timah Rd towards Newton Circus on 8/8/2017

Dear Catherine,

Kindly refer to our attachment.

Please proceed to appoint Adrian Ling to conduct a survey of the vehicle SGL 3126E on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

PAR Automotive Consultancy

Regn No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

- Report No: 0424-18-N51

23 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Sim Lian Huat
132 Lorong L Telok Kurau #03-03
Singapore 425569

VEHICLE INFORMATION:

Vehicle Reg No.:	SGL3126E	Odometer:	148076km
Make & Model:	BMW M5	Colour:	Black
Chassis number:	WBSNB92030CU18111	Date of accident:	08/08/2017
Year of Regn.:	01/08/2006	Date inspected:	11/08/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	14/08/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Michelin	6mm/Michelin	255/35ZR20
Rear:	6mm/Pirelli	6mm/Pirelli	295/30ZR30

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Regn. No. 52086974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0424-18-N51

23 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Sim Lian Huat
132 Lorong L Telok Kurau #03-03
Singapore 425569

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SGL3126E	<i>Odometer:</i>	148076km
<i>Make & Model:</i>	BMW M5	<i>Colour:</i>	Black
<i>Chassis number:</i>	WBSNB92030CU18111	<i>Date of accident:</i>	08/08/2017
<i>Year of Regn.:</i>	01/08/2006	<i>Date inspected:</i>	11/08/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	14/08/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
REAR BOOTLID	1	buckled	2,231.45	2,231.45	R X
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	69.50	69.50	NECV
REAR BOOTLID 'M5' EMBLEM	1	necessary	79.95	79.95	NEV
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	1	deformed	93.25	93.25	SVCX
REAR BOOTLID MECHANISM LOCK	1	bent	99.05	99.05	BT✓
REAR BOOTLID OUTER GARNISH	1	fractured	458.50	458.50	SVCX
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	24.40	24.40	NNX
REAR BOOTLID WEATHERSTRIP	1	deformed	210.75	210.75	CUT✓
REAR BUMPER	1	squashed	1,953.50	1,953.50	CUT✓
REAR BUMPER INNER FRAME GARNISH	1	deformed	58.95	58.95	CUT✓
REAR BUMPER LOWER COVER	1	fractured	151.20	151.20	BR✓
REAR BUMPER REINFORCEMENT	1	bent	529.25	529.25	BT✓
REAR BUMPER REINFORCEMENT BRACKET L/R	2	bent	285.00	285.00	BT✓
REAR BUMPER REVERSE SENSOR	2	shorted	1,409.00	1,409.00	704.50
REAR BUMPER REVERSE SENSOR 'O' RING	4	necessary	20.00	20.00	NECV
REAR BUMPER REVERSE SENSOR HOLDER BRACKET	4	necessary	72.00	36	72.00 NECV
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	snapped	183.90	183.90	CUT✓/NN
REAR BUMPER SIDE BRACKET L/R	2	necessary	211.00	211.00	NECV
REAR END PANEL	1	buckled	800.95	800.95	R X
REAR END PANEL INNER TOP GARNISH	1	fractured	108.25	108.25	CUT
REAR LH EXHAUST RUBBER MOUNTING	1	distorted	33.65	33.65	NNX
REAR LH EXHAUST SILENCER CHROME TAIL PIPE	2	distorted	600.00	600.00	SVCX
REAR RH EXHAUST RUBBER MOUNTING	2	distorted	67.30	67.30	NNX
REAR RH EXHAUST SILENCER CHROME TAIL PIPE	2	distorted	600.00	600.00	SVCX
REAR TAILLAMP BACK RUBBER SEAL L/R	2	necessary	54.20	54.20	NECV
REAR TAILLAMP L/R	2	fractured	708.20	708.20	CRA✓
Subtotal before discount			S\$ 11,113.20	S\$ 11,113.20	
Percentage discount 0% and 5%			S\$ 0.00	S\$ 555.66	
Sub-total 1			S\$ 11,113.20	S\$ 10,557.54	

4344.83

REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS - SET

1 necessary 60.00 60.00 NN X

REAR BUMPER CLIPS - SET

1 necessary 50.00 50.00 NECV

REAR END PANEL INNER TOP GARNISH CLIPS - SET

1 necessary 30.00 30.00 NECV

REAR EXHAUST SILENCER REPAIR KIT L/R

2 necessary 300.00 300.00 NECV NN

REAR FENDER INNER SHIELD CLIPS L/R - SET

2 necessary 60.00 40.00 NECV

REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET

2 necessary 100.00 60.00 NECV

REAR LH EXHAUST SILENCER BOX

1 bent 3,500.00 3,500.00 SVC X

REAR NUMBER PLATE

1 reuse 25.00 0.00

REAR NUMBER PLATE HOLDER

1 reuse 50.00 0.00

REAR RH EXHAUST SILENCER BOX

1 bent 3,500.00 3,500.00 SVC X

Subtotal before discount S\$ 7,675.00 S\$ 7,540.00 480.00

Sub-total 2 S\$ 7,675.00 S\$ 7,540.00 480.00

Parts-total S\$ 18,788.20 S\$ 18,097.54 4824.80

LABOUR

To reset system after repair works

800.00 200 ✓ 600.00 NN X

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

100.00 50.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

150.00 60.00 NN X

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,800.00 1,320.00 600.00

To apply paint protection system to enhance shine, durability of paint work.

400.00 400.00 100.00

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

200.00 150.00 80.00

To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.

1,500.00 1,250.00 800.00

To apply anti-rust chemical on repaired and replaced panel.

120.00 60.00

Labour Total S\$ 5,070.00 S\$ 3,890.00

Parts & Labour Total S\$ 23,858.20 S\$ 21,987.54

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 18,700.00
and the recommended number of working days for the repairs is within 8 day(s).

B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

45
Repair days 6



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17015460/Bqbs2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 11-09-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 8882P	Veh. Inspected	SGL 3126E
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020040	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	30/08/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. M5	c.c	4999
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WBSNB92030CU18111	Colour	GREEN
Odometer	148076	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35R20	MICHELIN	6 mm
L/H Front Tyre	255/35R20	MICHELIN	6 mm
R/H Rear Tyre	255/35R20	PIRELLI	6 mm
L/H Rear Tyre	255/35R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/08/2017	Inspection Date	11/08/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 3126E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	2,231.45	-
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	69.50	69.50
1	REAR BOOTLID 'M5' EMBLEM	NECESSARY	79.95	79.95
1	REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	SERVICEABLE	93.25	-
1	REAR BOOTLID MECHANISM LOCK	BENT	99.05	99.05
1	REAR BOOTLID OUTER GARNISH	SERVICEABLE	458.50	-
2	REAR BOOTLID RUBBER GUIDE STOPPER L/R	NOT NECESSARY	24.40	-
1	REAR BOOTLID WEATHERSTRIP	CUT	210.75	210.75
1	REAR BUMPER	CUT	1,953.50	1,953.50
1	REAR BUMPER INNER FRAME GARNISH	CUT	58.95	58.95
1	REAR BUMPER LOWER COVER	BROKEN	151.20	151.20
1	REAR BUMPER REINFORCEMENT	BENT	529.25	529.25
2	REAR BUMPER REINFORCEMENT BRACKET L/R	BENT	285.00	285.00
4	REAR BUMPER REVERSE SENSOR	SHORTED 2PCS ONLY	1,409.00	704.50
4	REAR BUMPER REVERSE SENSOR 'O' RING	NECESSARY	20.00	20.00
4	REAR BUMPER REVERSE SENSOR HOLDER BRACKET	NECESSARY 2PCS ONLY	72.00	36.00
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	183.90	-
2	REAR BUMPER SIDE BRACKET L/R	NECESSARY	211.00	211.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	800.95	-
1	REAR END PANEL INNER TOP GARNISH	CUT	108.25	108.25
1	REAR LH EXHAUST RUBBER MOUNTING	NOT NECESSARY	33.65	-
2	REAR LH EXHAUST SILENCER CHROME TAIL PIPE	SERVICEABLE	600.00	-
2	REAR RH EXHAUST RUBBER MOUNTING	NOT NECESSARY	67.30	-
2	REAR RH EXHAUST SILENCER CHROME TAIL PIPE	SERVICEABLE	600.00	-
2	REAR TAILLAMP BACK RUBBER SEAL L/R	NECESSARY	54.20	54.20
2	REAR TAILLAMP L/R	CRACKED	708.20	708.20
	LESS 5% DISCOUNT		-	-263.97
			11,113.20	5,015.33
SPECIAL NETT ITEMS				
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS3/LPC17015460/Bqbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
2	REAR EXHAUST SILENCER REPAIR KIT L/R (SN)	NOT NECESSARY	300.00	-
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NECESSARY	60.00	40.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NECESSARY	100.00	60.00
1	REAR LH EXHAUST SILENCER BOX (SN)	SERVICEABLE	3,500.00	-
1	REAR NUMBER PLATE (SN)	REUSE	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)	REUSE	50.00	-
1	REAR RH EXHAUST SILENCER BOX (SN)	SERVICEABLE	3,500.00	-
			7,675.00	180.00
	LABOUR			
	TO RESET SYSTEM AFTER REPAIR WORKS.		800.00	200.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	50.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	NOT NECESSARY	150.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,800.00	600.00
	TO APPLY PAINT PROTECTION SYSTEM TO ENHANCE SHINE, DURABILITY OF PAINT WORK.		400.00	100.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		200.00	80.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID AND REAR END PANEL.		1,500.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			-	-
			-	-
			-	-
			5,070.00	1,890.00
	GRAND TOTAL		23,858.20	7,085.33

Report Ref No. CS3/LPC17015460/Bqbs2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,650.00
---	--	--	-----------------

Report Ref No. CS3/LPC17015460/Bqbs2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.