

22/03/2002

ASS. REC. BY:

REF:

CS3 / AIG / 8015888 / G24d3h

Special Instruction:

✓

Surveyor

Minion

GA

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

30/8/18 @ 10:53am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S/L 8738X

Insured:

GBD 4295U

at Workshop m/s

Sq Recovery

Tel:

9240 6288

of

25 Keeki Blk Rd 4 #03-24

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/08/2018

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time:

1:44pm @ 30/8/18

Person Contacted:

Ah Jun

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

S/L 8738X - X

GBD 4295U - X

31/8/18

Dismissed.

(08/11/13) wef
ASS. REC. BY: *Xml.*

REF: *AlG*

B 3324E x

ASSIGNMENT

(2018)

From: _____ Date: *30/8/18*
Estimated Cost: _____
OP: TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SJL 8738X*
at Workshop m/s: *SG Recovery*
of: *25 kaki Bkt Rd 4 #03-24*
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *SJL 8738X* Yr Regn: *15 Dec 2008*
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: *Mercedes* c.c. *1598*
Colour: *Black* A/C: Insured / Std / NI / NA
Sp. Reading: *115761* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *IM6BK106280440998*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<i>Q</i>	
N/S	O/S

Bal. or Market Value: *\$11K*
IDAC Accident Rport: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *45* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS *up*
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: *205/55 R16*
R: *11*
BS: DUNLOP EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. _____ D.O.I. *30-08-18*
Survey held at: *W/S* *4:30 pm*
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>\$2000 - \$2000</i>
<i>3/9/18</i>	<i>submit DAR Report</i>

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) _____
Date/Time, File Return to?
2) _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<i>180</i>
Transportation:	
Others:	<i>20</i>
TOTAL	<i>200</i>

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 30/8/2018 10:53:33 AM

Attachments:  2nd PRS SG. AIG.PDF  PRI - GBD4295U.TIF

Hi LKK,

Kindly assist to survey, vehicle is in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref : GBD 4295U
Our Ref : **SJL 8738X/SG/jp/ps**
Date : 29 August 2018

FAX: 6538 3708
DID: 3152 0985
Email: accident@kscgp.com

AIG Asia Pacific Insurance Pte Ltd.

BY EMAIL ONLY

Dear Sirs,

DATE OF ACCIDENT: 25 AUGUST 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 29 August 2018.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor
1	Ho Joo Loong, Danny
2	Lee Kok Weng
3	Seah Kwang Boon

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : SG Recovery
25 Kaki Bukit Road 4
#03-24 Synergy@KB
Singapore 417800

Contact Person/Hp/Tel : Ah Lun 9240 6288

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,

PS

Your Ref : GBD 4295U
Our Ref : SJL 8738X/SG/jp/ps
Date : 29 August 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as
follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015888/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBD 4295U	Veh. Inspected	SJL 8738X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Engine No.	HIDDEN	Accident Date	25/08/2018	Inspection Date	30/08/2018
Survey held at	-				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

(03)Stuffed (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Tom
 (14)Unconfirmed (15)Not Working

MOTOR CAR (Frt)

(1)Replace (✓) (2)Repair (X) (3)Check (?)
 (4)Not Consistent (NC)

Front Portion

Vehicle No: **SJL 8738X**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRA	✓	
1002	991887	Frt Number Plate Base	RA	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	KCR	R X	
1005	992341	Frt Bumper Clips	38.00	NEC	✓
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DS	✓	2
1008	991433	Frt Bumper Reinforcement	DD	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	115.50	CAT	✓
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	DD	✓	
1022	991328	Frt Grille Emblem	35.00	NEC	✓
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	CRA	✓	
1026	992025	Frt Support Panel Top Garnish Cover	BR	✓	
1027	992416	Horn	92.00		
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	800.00	DD	✓
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator	BT	✓	
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Labour			
		1. Paintwork			400.00
		2. Labour			400.00

No of Items:

Accessories:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Aug 2018 Edit Reg		30 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Chua Bak Lan @ Chua Sak Lan , ID: S0575322H								
Main Claimant:	-								
Vehicle Reg. No.:	SJL8738X	Date of Loss:	25/08/2018 00:00 - :59 [116 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7454054920SG	Policy/Cover Note No.:	2100487686						
Vehicle Reg. No. (Insured):	GBD4295U	Policy No. (Claimant):							
		Excess:							
Repairer:	Sg Recovery (HQ) 25 Kaki Bukit Road 4, #03-24, Synergy @ KB, 417800 Kaki Bukit - Tel: 92406288								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/09/2018]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (04/09/2018): Request To Upload TP GIA Report AIG_SG (04/09/2018): No OI GIA Report (GBD4295U VS SJL8738X) 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL8738X (7454054920SG)**
[GBD4295U]
TP

Aug 25 2018 12:00AM
[Chua Bak Lan @ Chua Sak Lan]
Sg Recovery

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="checkbox"/>
Photos/Images						3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
2	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
3	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
4	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
5	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
6	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
7	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
8	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
9	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
10	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
11	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
12	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
13	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
14	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
15	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
16	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
17	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
18	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
19	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
20	31/08/18 12:35	General View		 Load JPG	<input checked="" type="checkbox"/>	
21	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
22	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
23	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
24	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
25	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
26	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
27	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
28	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
29	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
30	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
31	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
32	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	
33	03/09/18 09:04	Dismantled Parts		 Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST

Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015888/GZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100487686
Claimant Vehicle No : SJL8738X	Insured Vehicle No :	GBD4295U
Date of Loss: 25/08/2018	Nature of Claim:	TP
		Claim No: 7454054920SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL8738X	Engine No:	HIDDEN
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BK106280440998
Reg. Date:	15/12/2008 (Man. Year: 2008)	Odometer:	115761 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/08/2018	
Date Inspected:	30/08/2018	Inspected At:
		Sg Recovery (HQ) 25 Kaki Bukit Road 4, #03-24, Synergy @ KB Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT BUMPER	Repair	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Cut	0.00 F	*- F
8	1		*FRT GRILLE	Dented	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
11	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*BONNET	Dented	0.00 F	*- F
14	1		*BONNET LOCK	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >