

2/05/2008

ASS. REC. BY:

REF: CS/FCI/8015894/Kqd3 n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Keren Tan

of FCI

Date/Time: 1:33pm 30/8/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 4986Z

Insured: SHC 3476D

at Workshop m/s Lim Jun Motor

Tel: 84845418

of 176 Sin Ming drive #03-09

Policy No:

Claim No: D18006460 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/08/18

(Client's Record)

3/9/18 after 10:30am

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 10:05am 30/8/18

Person Contacted: Richard

Vehicle - IN / (OUT)

Date/Time	Action/Instruction ( → ) Estimate
	SKS 4986Z - NA / MSG / 6013499 / r3 DOA: 20/7/16
05/9/18 @ 4:58pm	SHC 3476D - CE3 / EQI / 6008226 / H / hg 342 DOA: 30/4/16 revised to Keren Tan by email.
13/9	L1 Pn 8 275d Confirm (red B 994.74, 76%)

Synovate

REF: FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SKS 4986Z  
 at Workshop m/s Lim Pan Motor  
 of 176 S/m #03-09.  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$16k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 06 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: SKS 4986Z Yr Regn: 06 09  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toy Axi A1 C.C. 1598  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 199551 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MR0538EE106146499  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/45R17  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 25/8/18 D.O.I. 3/9/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 O/S FR & N/S body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/9	File pass to Catherine
RECEIVED 14 SEP 2018	

Date/Time, File Pass to?  : Preli. Report  
 1) 14/9  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: 6  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech. Invs (\$ )  
 Weekend (\$ )

Survey Fee: 130  
 Transportation: 50  
 S+RS: \$  
 Photos: 17  
 Others: \_\_\_\_\_  
 TOTAL: 197

Report Format: TP  
 Lump Sum / LB: (\$ 7750 )



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015894/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3976D	Veh. Inspected	SKS 4986Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18006460MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	31/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/08/2018	Inspection Date	03/09/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006460MFSH

Date: 05 September 2018

Our Ref: CS/FCI18015894/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKS 4986Z.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/09/2018 at the premises of M/s LIM TAN MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,021.35</u> .
Revised Estimate Amount	: S\$ <u>2,750.55</u> .
"Check" Items Amount	: S\$ <u>160.80</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

**Description of Damage:**

The vehicle sustained damages at the o/s front portion & n/s body.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

*4.33pm*

**MOTOR SURVEY ASSIGNMENT**

Date	29-08-2018	<i>to Oson Richard ANI</i>	Our Ref No. D18006460MFSH
Accident Date	25-08-2018		Claim Type. Third Party
Insured Vehicle	SHC3976D		Third Party Vehicle. SKS4986Z
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE		
Contact Person.	RICHARD ANG		
Contact No.	64520893/ 84845418		Fax No. 64589127
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA		Fax No. 68416315
Contact Number.	NA		

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 5 September 2018 1:58 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006460MFSH/1  
**Attachments:** CSFC118015894Kqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SKS 4986Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 30 August 2018 10:06 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18006460MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 29 August 2018 4:32 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [KARENTAN@MSFIRSTCAPITAL.COM.SG](mailto:KARENTAN@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18006460MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

9874I

### Vehicle Details

Vehicle No.:

SKS4986Z

Vehicle to be Exported:

No

Intended De-registration Date:

27 Aug 2018

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA ALTIS 1.6 AUTO

Primary Colour:

White

Manufacturing Year:

2009

Engine No.:

3ZZ4893845

Chassis No.:

MRO53ZEE106146499

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$17,500.00

Original Registration Date:

05 Jun 2009

First Registration Date:

05 Jun 2009

Transfer Count:

3

Actual ARF Paid:

\$17,500.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

04 Jun 2019

PARF Rebate Amount:

\$8,750.00

### Intended COE Rebate Details

COE Expiry Date:

04 Jun 2019

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$8,489.00

COE Rebate Amount:

\$655.00

**Total Rebate Amount:**

**\$9,405.00**

The information contained herein is correct as at 27 Aug 2018

OK

*Not Notified  
 U/S by @ ?  
 Putty After Paint  
 6 days*



**ESTIMATE TO REPAIR**

VEHICLE NO. : SKS 4986 Z  
 MAKE : TOYOTA  
 MODEL : COROLLA ALTIS 1.6 AUTO  
 YEAR : 2009  
 CHASSIS NO : MR053ZEE106146499

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 29-Aug-18  
 DATE OF ACCIDENT : 25-Aug-18  
 THIRD PARTY REF : SHC 3976 D / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			<i>Bu</i> \$	563.80
1 pc	O/S Front Bumper Retainer			<i>DIS</i> \$	85.50
1 pc	O/S Headlamp			<i>objcm</i> \$	568.40
1 pc	O/S Front Fender			<i>Bu</i> \$	689.70
1 pc	O/S Front Fender Under-Shield			<i>su</i> \$	214.40
				\$	2,121.80
	Less 25%			\$	530.45
				\$	1,591.35
	To putty and spray painting.			\$	950.00
	To check front wiring and focus headlamp.			\$	30.00
	Labour Charges.			\$	450.00
					900
					201
					400
TG-RA/-	<b>TOTAL</b>				<b>\$ 3,021.35</b>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Lim Tan Motor Pte Ltd  
 Blk 178 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel: 85-64520893 Fax: 65-64589127 Website: www.LTM.sg  
 Co Reg No 199307277D GST Reg No M2-0019098 0

*3741.24*

**SUPPLEMENTARY TO REPAIR**

VEHICLE NO. : SKS 4986 Z  
 MAKE : TOYOTA  
 MODEL : COROLLA ALTIS 1.6 AUTO  
 YEAR : 2009  
 CHASSIS NO : MR053ZEE106146499

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 5-Sep-18  
 DATE OF ACCIDENT : 25-Aug-18  
 THIRD PARTY REF : SHC 3976 D / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	N/S Front Door Side Mirror Less 25%			<i>CMA</i>	\$ 959.85 ✓ \$ 239.96 \$ 719.89
	Parts \$1907.40 Supp \$957.85 <u>\$2867.25</u> Less 25% \$716.81 <u>\$2150.44</u> Labour \$1320.00 <u>\$3470.44</u> Less 20% \$694.09 <u>\$2776.35</u> 4/5 \$ 2750.00 ✓ 06 days ✓ <i>2/9/18</i>				
TG-RA/-	<b>TOTAL</b>				<b>\$ 719.89</b>

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015894/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3976D	Veh. Inspected	SKS 4986Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18006460MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	30/08/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053ZEE106146499	Colour	WHITE
Odometer	199551	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/08/2018	Inspection Date	03/09/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4986Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	BUCKLED	563.80	563.80
1	O/S FRONT BUMPER RETAINER	DISTORTED	85.50	85.50
1	O/S HEADLAMP	MTG CRACKED	568.40	568.40
1	O/S FRONT FENDER	BUCKLED	689.70	689.70
1	O/S FRONT FENDER UNDER-SHIELD	SERVICEABLE	214.40	-
1	N/S FRONT DOOR SIDE MIRROR (ADDITIONAL)	CRACKED	959.85	959.85
	LESS 25% DISCOUNT		-770.41	-716.81
			<b>2,311.24</b>	<b>2,150.44</b>
<b>LABOUR</b>				
	TO PUTTY AND SPRAY PAINTING.		950.00	900.00
	TO CHECK FRONT WIRING AND FOCUS HEADLAMP.		30.00	20.00
	LABOUR CHARGES.		450.00	400.00
			<b>1,430.00</b>	<b>1,320.00</b>
<b>GRAND TOTAL</b>			<b>3,741.24</b>	<b>3,470.44</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,750.00</b>

Report Ref No. CS/FC118015894/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.