

ASS. REC. BY:

REF: CS/MSG18015956/Krd3¹²

Special Instruction:

Surveyor:
menimen

Kenneth
Muhd Ashik

ASSIGNMENT (Office)

of MSG

Date/Time 31/8/18 @ 9.42am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 2664E

Insured:

XE 7999L

at Workshop m/s

Cheng He Motor

Tel:

6481 2001

of

10 Amk Ind. Park 2A #01-04

Policy No:

28611259 MEC

Claim No:

568900

Sum Insured:

Excess:

Make of Veh:

D.O.A

29/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10.38am @ 31/8/18

Person Contacted:

Daryllyn

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 2664E - NA/INC/50/5/42/d2

DOA: 5/9/15

XE 7999L - X

6755 6142

Revert 1A thm menimen

85452.86 Confirm June (Red: 82028.40, 271.)

(08/11/12) wel
ASS REC BY:

REF: MS19

ASSIGNMENT

Front:

Date: 31/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKU 2664E

at Workshop m/s

Cheng Hoe

of 10 Amic Ind. park 2A # 01-04

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

hp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKU 2664E

Yr Regn:

07, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hundai

Elantra C.C

1591

Colour:

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

65717

T/Radio: Insured / Std / NI / NA

Eng/No:

KM14DH 41CMFU 441514

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

P

mm

D.O.A.

29/8/18

D.O.I.

31/8/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R & L/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/9 File pass to Catherine

RECEIVED 20 NOV 2018

16/11/2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I. (\$

5452.86

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
10

160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 07 Nov 2018

Preliminary Advice

Insured Vehicle No	: XE7999L	Accident Date	: 29/08/2018
TP Vehicle No	: SKU2664E	Assignment Date	: 31/08/2018
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 5.00
Date of Inspection	: 31/08/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	7,481.26
Revised Amount	:S\$	5,372.22
Check Items (Estimated)	:S\$	1,708.40
Total	:S\$	7,080.62

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2018		31 Aug 2018 09:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HONG FA LOGISTICS & ENGINEERING, Co. Reg. No.: 200616695M		
Main Claimant:	NGO SEE HIAN, ID: S1169585Z		
Vehicle Reg. No.:	SKU2664E	Date of Loss:	29/08/2018 23:00 - :59 [37 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568900	Policy/Cover Note No.:	28611259MKC Coverage: 09/09/2017 - 08/09/2018
Vehicle Reg. No. (Insured):	XE7999L	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/09/2018]		
Adj Asg. Remarks:	on WP, OI non reporting. Liability not clear, TP agree with SJE- Assign LKK Auto Consultants Pte Ltd, contact: Dorlyn Li - 6481 2001		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9585Z
Vehicle Details	
Vehicle No.:	SKU2664E
Vehicle to be Exported:	No
Intended De-registration Date:	30 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	G4FGFU181721
Chassis No.:	KMHDH41CMFU441514
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$14,640.00
Original Registration Date:	15 Jul 2015
First Registration Date:	15 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$14,640.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2025
PARF Rebate Amount:	\$10,980.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$40,332.00
Total Rebate Amount:	\$51,312.00

The information contained herein is correct as at 30 Aug 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES1891001/AMK

Date: 31 Aug 2018

Policy No: 5072723664-03

Veh Reg No: SKU2664E

Make/Model: HYUNDAI ELANTRA
 1.6A

WS Ref: TP/MSIG/AMK

Chassis No: KMHDH41CMFU441514

Claim Type: Third Party

Engine No: G4FGFU181721

Accident Date: 29/08/2018

Reg. Date:

TP Veh Reg No: XE7999L

Estimate Repair Cost to Vehicle No :SKU2664E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	474.40	1 PC	474.40	✓
2 FRONT BUMPER RH SIDE RETAINER	21.60	1 PC	21.60	✓
3 FRONT BUMPER INNER SIDE BRACKET	12.00	2 PC	24.00	✓
4 FRONT BUMPER CLIP	2.00	5 PC	10.00	✓
5 FRONT RH FENDER	456.10	1 PC	456.10	✓
6 FRT RH FENDER INNER SHIELD	88.80	1 PC	88.80	✓
7 FRONT RH FENDER INNER SHIELD CLIP	2.00	6 PC	12.00	✓
8 FRONT RH FENDER PROTECTOR	18.00	1 PC	18.00	✓
9 HEADLAMP RH	1,756.40	1 PC	1,756.40	✓
10 FRONT RH DOOR	1,820.80	1 PC	1,820.80	✓
11 FRONT RH DOOR BOTTOM HINGE	39.00	1 PC	39.00	✓
12 FRONT RH DOOR CHECKER	39.80	1 PC	39.80	✓
13 FRONT RH DOOR FRAME STICKER	38.00	1 SET	38.00	✓
14 FRONT RH SHOCK ABSORBER	290.30	1 PC	290.30	✓
15 FRONT RH KNUCKLE ARM	363.68	1 PC	363.68	✓
16 FRONT RH WHEEL BEARING	135.90	1 PC	135.90	✓
17 FRONT RH LOWER ARM	296.80	1 PC	296.80	✓
18 FRONT RH RIM 16"	891.00	1 PC	891.00	✓
			6,776.58	
		Less 20%	1,355.32	5,421.26
Special Net				
19 FRONT RH TYRE	180.00	1 PC	180.00	180.00
			180.00	180.00
Labour				
20 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP,FRT RH FENDER,FRT RH DOOR & ATTACHMENTS,KNOCKING & REPAIR FRT RH DOOR PILLAR & REALIGN THE SAME	750.00	1 LA	750.00	550
21 PUTTY & RESPRAY FRT BUMPER,FRT RH FENDER,FRT RH DOOR,FRT RH SIDE MIRROR,FRT RH DOOR PILLAR & ALL AFFECTED AREAS	700.00	1 LA	700.00	650
22 REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
23 REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	120.00	1 LA	120.00	✓
24 REMOVE & REFIX FRT RH TYRE,RIM,BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	20
25 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	60

2 wheel dynamometer
 check report is
 needed for
 carriage replacement

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 29/08/2018
TP Veh Reg No: XE7999L

Estimate No: ES1891001/AMK
Date: 31 Aug 2018
Policy No: 5072723664-03
Veh Reg No: **SKU2664E**
Make/Model: HYUNDAI ELANTRA
1.6A
Chassis No: KMHDH41CMFU441514
Engine No: G4FGFU181721
Reg. Date:

Estimate Repair Cost to Vehicle No :SKU2664E

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
26 RUSTPROOFING	90.00	1 LA	90.00	601
27 TOWING	50.00	1 LA	50.00	✓
			1,880.00	1,880.00
			Total	SS 7,481.26
			Add GST @ 7%	523.69
			Total Amount Payable	SS 8,004.95

VEHICLE LYING AT:
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



WHEEL ALIGNMENT SYSTEM

Customer:	CHENG HOE	Reg. N.:	SKU 2664 E
Description:	HYUNDAI ELANTRA	Repair order no.	
Reference Diameter:	15"	Mileage:	km
Working Notes:			
Date:	31/08/2018	Time:	16.38.49
Operator:			

FRONT AXLE

Total toe
Half-toe
Max Dif.
Camber
Max Dif.
Caster
Max Dif.
King-pin angle
Max Dif.
Included angle
Steering angle diff. at 20°
Max Int. Steering Angle
Max Ext. Steering Angle
Set Back

Tyre
Pressure measured
Tread depth (mm)

Data		Databank	
LH	RH	- Tolerance	+ Tolerance
00°00'	00°00'	-00°14'	+00°14'
00°00'	00°00'	-00°07'	+00°07'
00°00'	00°00'	-00°30'	+00°30'
+02°21'	+02°21'	-00°30'	+00°30'
+12°30'	+12°30'	-00°30'	+00°30'

Previous Values

LH	RH
+00°50'	+00°50'
-00°10'	+01°00'
-00°18'	-01°24'
+04°28'	+04°30'
+10°38'	+13°55'
+10°20'	+12°31'

Final Values

LH	RH
+00°50'	+00°50'
-00°10'	+01°00'
-00°18'	-01°23'
+04°28'	+04°31'
+10°38'	+13°55'
+10°20'	+12°31'
	+00°14'
	+00°14'
LH	RH

REAR AXLE

Total toe
Half-toe
Max Dif.
Camber
Max Dif.
Set Back
Thrust angle
Track difference

Tyre
Pressure measured
Tread depth (mm)

Data		- Tolerance		+ Tolerance	
LH	RH				

LH	RH
+00°25'	+00°09'
+00°15'	+00°09'
-01°20'	-01°17'
-00°15'	-00°15'
+00°03'	+00°03'
+00°07'	+00°07'

LH	RH
+00°23'	+00°08'
+00°15'	+00°08'
-01°20'	-01°17'
-00°15'	-00°15'
+00°03'	+00°03'
+00°07'	+00°07'
LH	RH



WHEEL ALIGNMENT SYSTEM

Customer: CHENG HOE
 Description: HYUNDAI ELANTRA
 Reference Diameter: 15"
 Working Notes: *
 Date: 06/09/2018
 Operator:

Reg. N.: SKU 2664 E
 Repair order no.
 Mileage: km

Time: 09.37.09

FRONT AXLE

Total toe
 Half-toe
 Max Dif.
 Camber
 Max Dif.
 Caster
 Max Dif.
 King-pin angle
 Max Dif.
 Included angle
 Steering angle diff. at 20°
 Max Int. Steering Angle
 Max Ext. Steering Angle
 Set Back

Tyre
 Pressure measured
 Tread depth (mm)

Data		Databank	
LH	RH	- Tolerance	+ Tolerance
00°00'	00°00'	-00°14'	+00°14'
00°00'	00°00'	-00°07'	+00°07'
00°00'	00°00'	-00°30'	+00°30'
+02°21'	+02°21'	-00°30'	+00°30'
+12°30'	+12°30'	-00°30'	+00°30'

Previous Values

LH	RH
+00°57'	+00°57'
+00°20'	+00°37'
-00°19'	-00°35'
+04°45'	+04°59'
+10°19'	+10°56'
+10°01'	+10°21'

Final Values

LH	RH
+00°05'	+00°08'
-00°32'	-00°30'
+04°55'	+05°15'
+10°19'	+10°56'
+09°47'	+10°26'

+00°05' -00°02'
 LH RH

REAR AXLE

Total toe
 Half-toe
 Max Dif.
 Camber
 Max Dif.
 Set Back
 Thrust angle
 Track difference

Tyre
 Pressure measured
 Tread depth (mm)

Data		- Tolerance		+ Tolerance	
LH	RH				

LH	RH
+00°27'	+00°23'
+00°15'	+00°12'
-01°25'	-01°16'
-00°13'	-00°10'
+00°01'	-00°03'
+00°05'	+00°05'

LH	RH
+00°08'	+00°14'
-01°28'	-01°23'
-00°10'	-00°03'
+00°05'	+00°05'
LH	RH

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18015956/KRD3N2

Date: 26/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28611259MKC
Claimant Vehicle No :	SKU2664E	Insured Vehicle No :	XE7999L
Date of Loss:	29/08/2018	Nature of Claim:	TP
		Claim No:	568900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2664E	Engine No:	G4FGFU181721
Make & Model:	HYUNDAI ELANTRA, 1.6 D/AB 2WD 4DR (A)	Chassis No:	KMHDH41CMFU441514
Reg. Date:	15/07/2015 (Man. Year: 2015)	Odometer:	65717 km
Colour:	Metallic Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,601.26	3,882.86	1,718.40	30.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,570.00	310.00	16.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,481.26	5,452.86	2,028.40	27.11
+ GST 7.00/7.00% (S\$)	523.69	381.70	141.99	27.11
Nett Amount (S\$)	8,004.95	5,834.56	2,170.39	27.11

INSPECTION

Date of Assignment: 31/08/2018

Date Inspected: 31/08/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
10 ANG MO KIO IND PARK 2A, #01-04
ANG MO KIO AUTOPOINT
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts:	143	HYUNDAI ELANTRA 1.6 D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU2664E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	21.60 FL	*21.60 FL
3	2		*FRONT BUMPER INNER SIDE BRACKET	Necessary	24.00 FL	*24.00 FL
4	5		*FRONT BUMPER CLIP	Necessary	10.00 FL	*10.00 FL
5	1		*FRONT RH FENDER	Bent	456.10 FL	*456.10 FL
6	1		*FRT RH FENDER INNER SHIELD	Cracked	88.80 FL	*88.80 FL
7	6		*FRONT RH FENDER INNER SHIELD CLIP	Necessary	12.00 FL	*12.00 FL
8	1		*FRONT RH FENDER PROTECTOR	Cut	18.00 FL	*18.00 FL
9	1		*HEADLAMP RH	Serviceable	1,756.40 FL	*- FL
10	1		*FRONT RH DOOR	Bent	1,820.80 FL	*1,820.80 FL
11	1		*FRONT RH DOOR BOTTOM HINGE	Repair	39.00 FL	*- FL
12	1		*FRONT RH DOOR CHECKER	Repair	39.80 FL	*- FL
13	1		*SET FRONT RH DOOR FRAME STICKER	Necessary	38.00 FL	*38.00 FL
14	1		*FRONT RH SHOCK ABSORBER	Serviceable	290.30 FL	*- FL
15	1		*FRONT RH KNUCKLE ARM	Bent	363.68 FL	*363.68 FL
16	1		*FRONT RH WHEEL BEARING	Necessary	135.90 FL	*135.90 FL
17	1		*FRONT RH LOWER ARM	Distorted	296.80 FL	*296.80 FL
18	1		*FRONT RH RIM 16	Dented	891.00 FL	*891.00 FL
19	1		*FRONT RH TYRE (90%)	Punctured	180.00 FS	*162.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,956.58	4,813.08
- List Item Discount on L Items 20.00/20.00% (S\$)	1,355.32	930.22
Total Parts (S\$)	5,601.26	3,882.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER GRILLE,HEADLAMP,FRT RH FENDER,FRT RH DOOR & ATTACHMENTS,KNOCKING & REPAIR FRT RH DOOR PILLAR & REALIGN THE SAME	New	750.00	550.00
2	PUTTY & RESPRAY FRT BUMPER,FRT RH FENDER,FRT RH DOOR,FRT RH SIDE MIRROR,FRT RH DOOR PILLAR & ALL AFFECTED AREAS	New	700.00	650.00
3	REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	New	60.00	60.00
4	REMOVE & REFIX FRT RH UNDERCARRIAGE & REALIGN THE SAME	New	120.00	120.00
5	REMOVE & REFIX FRT RH TYRE,RIM BALANCE & REALIGN THE SAME	New	50.00	20.00
6	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
7	RUSTPROOFING	New	90.00	60.00
8	TOWING	New	50.00	50.00
Gross Labour Cost (\$\$)			1,880.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >