

23/03/2002

ASS. REC. BY:

REF:

CS3/AG18015960/G240302

Special Instruction:

Surveyor
menmen

Gao Chang

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AG

Date/Time:

31/8/18 @ 3.58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 38832

Insured:

SLM 3431

at Workshop m/s

Paul Hoo Batteries

Tel:

9623 5068

of

81k1 Kaki Blt Ave 6 # 01-109

Policy No:

2100505434

Claim No:

283681842086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

26/8/18

CA / REV / REP. / REV 24 HRS

(cup)

31/9/18 @ Morning

H.O.D. Endorsement:

Date/Time:

4:35pm @ 31/8/18

Person Contacted:

paul

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

GBE 38832 - NA / EQ1 1700 / S81 / h4

D.O.A: 24/11/17

SLM 3431 J - X

3/9/18

Dismissed

5/9/18

After repair

Signature

PRS
KMR

REF:

AIG

C8651N /

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 3883Z

at Workshop m/s Paul Hoe.

of 1 Kaki Bukit Ave 6 #01-109.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2.0 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GBE 3883Z

Yr Regn:

01 Jun 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Every

C.C

658

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

1859

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

DA17V820955

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

145/80R12

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

03-09-18

Survey held at

w/s

11:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/9

~~\$3400~~ ~~\$4400~~ ~~\$2500~~ ~~\$3500~~
Submit DAR report.

Repair days 4

Tarim Lin

RECEIVED 19 SEP 2018

18/9/18

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

180

Transportation:

) S + RS, SI

) Photos

20

) Others

Report Format: DAR.

Lump Sum / I.B.I: (\$

TOTAL

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015960/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLM 3431J	Veh. Inspected	GBE 3883Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/08/2018	Inspection Date	03/09/2018
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 31/8/2018 3:58:10 PM
Attachments:  PRI - SLM3431J - 29.08.18.tif

Hi LKK,

Kindly assist to survey, vehicle is in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC
Advocates & Solicitors **Commissioner For Oaths** **Notary Public**
UEN NO : 201523418E
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
 MANHATTAN HOUSE
 SINGAPORE 169876
 TEL : (65) 6532 2458
 FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tcmg.com.sg
 Our Ref : TCMG/GBE 3883 Z/0818/PHB

Your Ref : SLM 3431 J

29 August 2018

M/s AIG Asia Pacific Insurance Pto Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120

BY FAX NO. 6835-7416 ONLY

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for M/s SG Intergrated Engineering Pte Ltd, the owner and/or driver of motor vehicle no. GBE 3883 Z, which was involved in an accident along TPE exit into Pasir Drive 8 on 26th August 2018 at 15:45 hours.

We hereby give you NOTICE that we are claiming against your insured motor vehicle no. SLM 3431 J for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Paul Hoe Batteries & Motor Service, (1 Kaki Bukit Avenue 6 #01-109 - Paul Hoe @ 9623 5068).

If we do not hear from you within the next two (2) working days, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,


LING LEONG HUI (MR)

cc. M/s Paul Hoe Batteries & Motor Services
 (Yref : GBE 3883 Z)

BY FAX NO. 6747 6918 ONLY

DIRECTOR : LING LEONG HUI

CONSULTANTS : TOMMY CHOO TUCK SOON
 POOTS LAURENCE JAMES

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8651N
Vehicle Details	
Vehicle No.:	GBE3883Z
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2018
Vehicle Make:	SUZUKI
Vehicle Model:	EVERY JOIN TURBO 660 AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	R06A2137542
Chassis No.:	DA17V820955
Maximum Power Output:	-
Open Market Value:	\$16,441.00
Original Registration Date:	01 Jun 2018
First Registration Date:	01 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$823.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$27,595.00
COE Rebate Amount:	\$26,875.00
Total Rebate Amount:	\$26,875.00

The information contained herein is correct as at 04 Sep 2018

OK

Vehicle No: GBE 3883E

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer RH	CR	✓	
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD	✓	
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	DD	✓	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant	NEC	✓	
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

[illegible]

6

Assessor:

TGC:im *[Signature]*
18/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2018 Edit Reg		31 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN SOON TECK (CHEN SHUNDE) , ID: S7734163C								
Main Claimant:	-								
Vehicle Reg. No.:	GBE3883Z	Date of Loss:	26/08/2018 00:00 - :59 [2 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2836818420SG	Policy/Cover Note No.:	2100505434 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLM3431J	Policy No. (Claimant):							
		Excess:							
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/09/2018]								
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (03/09/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE3883Z (2836818420SG)

[SLM3431J]

TP

-

Aug 26 2018 12:00AM

[TAN SOON TECK (CHEN SHUNDE)]

Paul Hoe Batteries & Motor Services

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page ☐ ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	03/09/18 13:58	Accident Statement From: SC - Reg. No: SLM3431J, Claimant: TAN SOON TECK	1	Load HTM Thumbnail Print
Photos/Images			3 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	04/09/18 09:10	General View	1	Load JPG ☒
2	04/09/18 09:10	General View	1	Load JPG ☒
3	04/09/18 09:10	General View	1	Load JPG ☒
4	04/09/18 09:10	General View	1	Load JPG ☒
5	04/09/18 09:10	General View	1	Load JPG ☒
6	04/09/18 09:10	General View	1	Load JPG ☒
7	04/09/18 09:10	General View	1	Load JPG ☒
8	04/09/18 09:10	General View	1	Load JPG ☒
9	04/09/18 09:10	General View	1	Load JPG ☒
10	04/09/18 09:10	General View	1	Load JPG ☒
11	04/09/18 09:10	General View	1	Load JPG ☒
12	04/09/18 09:10	General View	1	Load JPG ☒
13	04/09/18 09:10	Odometer Reading	1	Load JPG ☒
14	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
15	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
16	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
17	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
18	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
19	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
20	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
21	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
22	04/09/18 09:11	Dismantled Parts	1	Load JPG ☒
23	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
24	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
25	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
26	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
27	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
28	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
29	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
30	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
31	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
32	19/09/18 12:42	Photo After Spray	1	Load JPG ☒
33	19/09/18 12:42	Photo After Spray	1	Load JPG ☒

Assessment Reports				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
34	19/09/18 12:42	Photo After Spray		 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015960/GZ4D3E2

Date: 20/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505434
Claimant Vehicle GBE3883Z **Insured Vehicle No :** SLM3431J
No :
 Date of Loss: 26/08/2018 Nature of Claim: TP Claim No: 2836818420SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE3883Z**
 Make & Model: SUZUKI EVERY, 658cc GA (A) Engine No: R06A2137542
 Reg. Date: 01/06/2018 (Man. Year: 2017) Chassis No: DA17V820955
 Colour: White Odometer: 1859 km
 Engine Capacity: 658 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 145/80 R17 Rear Tyre Size: 145/80 R17
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/08/2018
 Date Inspected: 03/09/2018 Inspected At: Paul Hoe Batteries & Motor Services (HQ)
 1 KAKI BUKIT AVE 6 #01-109
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER SIDE RETAINER RH	Cracked	0.00 F	*- F
3	1		*REAR END PANEL	Dented	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >