

CERTIFICATE OF INSURANCE

0.000000

(The below excerpt is subject to GIST)

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00

WINDSCREEN EXCESS
(Our policies with effect from 1st November 2020)

SLD2118T

Tee Kong Kee @Tay Kong Kee

9 Jun 2017

8 Jun 2018

SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured.

b) Any other person who is driving on the insured's order or with his permission

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$53,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Use only for social, domestic and pleasure purposes and for the insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MERCEDES-BENZ AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Loop Service Center - 188 Pandan Loop (Tel: 6777 8388)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ethos - 30 Bukit Batok Cres(Tel:66547777)

4. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: /

LOSS OF USE 15 Days Replacement Car only for repairs at C&C - Refer to policy wordings for details

* NAMED DRIVER NA

HIRE PURCHASE COMPANY MERCEDES-BENZ FINANCIAL SERVICES (S) LTD
/EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 31 May 2017

AIG Asia Pacific Insurance Pte. Ltd.

504380-258
CYCLE & CARRIAGE - RUTHZH
239 ALEXANDRA ROAD
SINGAPORE 159930

AUTHORISED REPRESENTATIVE

Sketch Plan #6

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	22 Sep 1981
Class 2A	Motorcycles between 201 cc and 400 cc	22 Sep 1981
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	22 Sep 1981

NP 428A



FOR G&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S2513188F**

Name: **TEE KONG KEE**

Birth Date: **13 Mar 1949**

Issue Date: **30 Jul 2003**

00970066TG



POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20171029/2024

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 4

Report No. T/20171029/2024

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/10/2017 10:05		Vide Report No.:		Station Diary No.: 29
Informant's Particulars				
Name of Informant: TEE KONG KEE		Address: 94 WESTWOOD AVENUE SINGAPORE 648416		
ID Type / ID No.: FIN NO / S2513188F		Contact No.: Home/Office: Mobile: 90232118		
Nationality: MALAYSIAN		Email: -		
Sex: Male	Age: 68	Date of Birth: 13/03/1949	Type of Informant: Driver	
Race: Chinese		Language: -	Institution / School Name: -	
Occupation: PRINCIPAL CONSULTANT		Driving Licence Information: Class: 2B.3 Date of Expiry: -		

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/09/2017 16:05	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 TEBAN GARDENS CRESCENT PENJURU ROAD T-Junction of the two above mentioned roads near AYE				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved					
GU3426S	Van	-	-	-	Seriously Damaged 0
SLD2118T	Car	MERCEDES BENZ	E200 SEDAN EDITION E (R18 LED SR)	Grey	Seriously Damaged 0

Details of Vehicle Insurance	
Vehicle No. / Insurance Company:	Effective / Expiry Date:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20171029/2024

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 4
Report No. T/20171029/2024

CONTINUATION OF REPORT

SLD2118T	AIG ASIA PACIFIC INSURANCE PTE LTD.	2100468691	09/05/2017	08/06/2018
----------	-------------------------------------	------------	------------	------------

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	Koh Yeow Yong, Roy	ID No.	S9346881C
Related Vehicle	GU3426S (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	TEE KONG KEE	ID No.	S2513188F
Related Vehicle	SLD2118T (Car)	Contact No.	90232118
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/09/2017 at about 1610hrs, I was driving out of Teban Gardens Crescent onto Penjuru Road in my Mercedes (SLD2118T) when a van (GU3426S) driving on Penjuru Road that had just exited the AYE collided into my car from the right side. The road speed limit is 50kph and there is no way that that van was driving at that speed. I was stationary at the stop line at the Teban Gardens Crescent road when the collision occurred. My vehicle had passed the stop line as I was checking for traffic. When I saw the Van I thought it would avoid me but it did not slow down and collided with me.

I have both front and rear camera footage that are with my Cycle and Carriage Service Adviser Mr. Vincent Seah Yong Kuan (HP:83320082, DID:67714401). My car is still in the workshop and is scheduled to be returned to me on the 6th November 2017. I am making this report due to a Police letter dated on 21 October asking me to lodge an NP168 Traffic Accident Report.

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Traffic Police
Singapore Police Force
10, Ubi Avenue 3
Singapore 408865
Tel : 6547 0000
Fax : 6547 6259

Date : 21 Oct 2017

Your Ref :
Our Ref : TP/P/56679/2017

TEE KONG KEE
94 WESTWOOD AVENUE
SINGAPORE 648416

281-000188



Dear Sir / Madam,

CASE OF TRAFFIC ACCIDENT ALONG TEBAN GARDENS CRESCENT ON 27 SEP 2017 @ 4.05 PM

Please be informed that Traffic Police is investigating into the above matter and will update you the status in due course.

2 IF you have not lodged a Police Report of a Traffic Accident (NP168) in respect of the said accident which is now required for police investigation, please do so as soon as possible at the nearest police station, Neighbourhood Police Centre (NPC), Neighbourhood Police Post (NPP) or online via Singapore Police Force Electronic Police Centre (<http://www.police.gov.sg/epc>).

3 Please note that the information given by you in the Police Report of a Traffic Accident (NP168) will be carefully considered. You may not be called upon for an interview if the information in the Police Report is sufficient for our investigation. However, if you have any further information or other evidence (such as CCTV footages) which you have not stated in your report and which you think will assist in the investigation, you are advised to contact the Investigation Officer within 2 weeks of this letter to arrange for an appointment.

4 You may contact the Investigation Officer YEO KIA HUAT at his / her office number: 65476325 or the supervisor CHEN SIEW LEE at 65476182 if you have any further queries.

5 Thank you.

Yours faithfully,

PUTEH BTE SHARIFF (DSP)
CHIEF INVESTIGATION OFFICER
INVESTIGATION BRANCH
TRAFFIC POLICE

This is computer generated and does not require a signature.

A FORCE FOR THE NATION



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
VEN: 5863500205 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MCC 41712P435 Vehicle Registration No: SLD 21187
Name (as shown in NRIC): Tee Hong Kee @ Tay Hong Kee NRIC/FIN/Passport No.: S 25131847
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: _____ Singapore()
Contact (Tel): _____ Mobile No.: _____
Email Address: _____
Date of Accident: 27/09/17 Time of Accident: 16:10
Place of Accident: T-Junction of Penjuru Rd & Tabon Garden Crescent
Insurance Company: AIS

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Attach 2 video clip

Policyholder / Driver's Signature
Date: 03/10/17

Reporting Centre Personnel's Signature
Name: Vincent
NRIC/FIN No.: _____



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
8 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S045500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCL417128435 Vehicle Registration No: SLD 2118T
Name (as shown in NRIC) : Teo Kong Kee @ Teo Kong Kee NRIC/FIN/Passport No : S25131887
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : _____ Singapore()

Contact (Tel) : _____ Mobile No. : _____

Email Address : _____

Date of Accident : 27/09/17 Time of Accident : 16:00pm

Place of Accident : T- Junction of Penjuru Rd & Teban Garden Crescent

Insurance Company: AIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Attach Police Report

Policyholder / Driver's Signature
Date: 30/10/17

Reporting Centre Personnel's Signature
Name: Chen
NRIC/FIN No.:
Date: 30/10/17

PAR Automotive Consultancy

Regn. No. 52980974L

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel 645 31173, Fax 645 36131

Report No: 0326-18-TCA

25 June 2018

ACCIDENT VEHICLE SURVEY REPORT

System Technic Engineering Pte Ltd
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	GU3426S	Odometer:	430582km
Make & Model:	Toyota Hiace	Colour:	Silver
Chassis number:	LH1721003298	Date of accident:	27/09/2017
Year of Regn.:	01/03/2001	Date inspected:	29/09/2017
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	20/10/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	4mm/Bridgestone	4mm/Bridgestone	185R14
Rear:	4mm/Bridgestone	4mm/Bridgestone	185R14

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON BLOWER MOTOR	1	shorted	972.85	972.85 DD ✓
AIRCON BLOWER MOTOR CASING	1	fractured	561.60	561.60 BR ✓
AIRCON COOLING UNIT	1	fractured	1,218.50	1,218.50 NCX no pic NN
FRONT BUMPER	1	bent	511.70	511.70 BR ✓
FRONT BUMPER LH AIR DUCT	1	warped	172.25	172.25 DD ✓
FRONT BUMPER LH FOGLAMP COVER	1	warped	181.90	181.90 DD ✓
FRONT BUMPER MOULDING	1	deformed	172.10	172.10 BT ✓
FRONT BUMPER REINFORCEMENT	1	bent	41.90	41.90 BT ✓
FRONT BUMPER SIDE HOLDER CLIPS L/R	4	necessary	26.00	26.00 NEC ✓
FRONT BUMPER SIDE HOLDER L/R	2	necessary	264.50	264.50 NEC ✓
FRONT BUMPER UPPER BRACKET	1	bent	348.80	348.80 BT ✓
FRONT FLOOR PANEL	1	buckled	972.10	972.10 DIS ✓ BUC
FRONT GLOVE BOX	1	reuse	561.60	0.00
FRONT GRILLE	1	fractured	381.72	381.72 MIS ✓
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	61.10	61.10 NEC ✓
FRONT HEADLAMP GARNISH L/R	2	fractured	203.40	203.40 CR ✓
FRONT INSTRUMENT LH SPEAKER	1	reuse	531.35	0.00
FRONT INSTRUMENT LH SPEAKER COVER	1	crushed	182.10	182.10 CR ✓
FRONT INSTRUMENT PANEL	1	distorted	972.10	972.10 DIS ✓
FRONT INSTRUMENT PANEL REINFORCEMENT	1	bent	581.25	581.25 BT ✓ XRD
FRONT LH CENTRE PILLAR	1	bent	681.10	681.10 BT ✓ XRD
FRONT LH DOOR	1	buckled	1,218.10	1,218.10 DD ✓
FRONT LH DOOR ARCH PANEL	1	buckled	631.30	631.30 DD ✓
FRONT LH DOOR ARCH PANEL GARNISH	1	deformed	372.10	372.10 DIS ✓
FRONT LH DOOR BODY WEATHERSTRIP	1	deformed	276.60	276.60 CUT ✓
FRONT LH DOOR CENTRE LOCK MOTOR	1	shorted	581.90	581.90 SVCX
FRONT LH DOOR CHECKER	1	bent	172.25	172.25 BT ✓
FRONT LH DOOR GLASS	1	shattered	581.10	581.10 BR ✓
FRONT LH DOOR GLASS BRACKET	2	bent	282.90	282.90 BT ✓
FRONT LH DOOR GLASS CHANNEL	1	bent	151.90	151.90 BT ✓
FRONT LH DOOR GLASS CHANNEL BRACKET	1	bent	141.25	141.25 BT ✓
FRONT LH DOOR GLASS REGULATOR	1	bent	374.10	374.10 BT ✓
FRONT LH DOOR GLASS REGULATOR MOTOR	1	shorted	581.90	581.90 SVCX
FRONT LH DOOR HINGES	2	bent	264.50	264.50 BT ✓
FRONT LH DOOR INNER HANDLE	1	distorted	141.45	141.50 SVCX
FRONT LH DOOR INNER HANDLE COVER	1	distorted	155.50	155.50 BT ✓
FRONT LH DOOR INNER MOULDING	1	deformed	171.10	171.10 DIS ✓
FRONT LH DOOR INNER PILLAR	1	bent	631.35	631.35 BT ✓
FRONT LH DOOR INNER TRIM BOARD	1	deformed	781.10	781.10 DIS ✓
FRONT LH DOOR LOWER WEATHERSTRIP	1	deformed	287.75	287.75 CUT ✓
FRONT LH DOOR MECHANISM LOCK	1	bent	372.45	372.45 BT ✓
FRONT LH DOOR OUTER HANDLE	1	distorted	178.10	178.10 SVCX

PAR Automotive Consultancy

Annex A Page 2
Report No: 0326-18-TCA-GI/3426S

FRONT LH DOOR OUTER MOULDING	1	necessary	182.25	182.25	NECV
FRONT LH DOOR OUTER PILLAR	1	bent	631.35	590.00 631.35	BT ✓
FRONT LH DOOR QUARTER GARNISH	1	warped	372.10	372.10	BT ✓
FRONT LH DOOR RUBBER GUIDE STOPPER	2	deformed	87.80	87.80	CUT ✓
FRONT LH DOOR STEP PANEL	1	buckled	631.10	400.00 631.10	BT ✓
FRONT LH DOOR STEP PANEL TOP GARNISH	1	deformed	277.10	277.10	DIS ✓
FRONT LH DOOR WEATHERSTRIP	1	deformed	231.35	231.35	CUT ✓
FRONT LH DOOR WIRE HARNESS	1	reuse	181.90	0.00	
FRONT LH HEADLAMP	1	broken	372.25	372.25	BR ✓
FRONT LH HEADLAMP BRACKET	1	buckled	177.85	177.85	BT ✓
FRONT LH KNUCKLE ARM	1	distorted	581.90	581.90	SVC X
FRONT LH KNUCKLE ARM BEARING	1	dislodged	172.10	172.10	DL ✓
FRONT LH LINKAGE	1	bent	374.45	374.45	} SVC X
FRONT LH LOWER ARM	1	bent	387.90	387.90	
FRONT LH LOWER BALL JOINT	1	dislodged	172.10	172.10	DL X NA
FRONT LH MIRROR BRACKET	1	reuse	281.70	0.00	
FRONT LH SHOCK ABSORBER	1	bent	274.40	274.40	SVC X
FRONT LH SIDE LAMP	1	broken	182.10	182.10	BR ✓
FRONT LH STAY ARM	1	bent	372.45	372.45	SVC X
FRONT LH STEERING TIE ROD	1	reuse	172.85	0.00	
FRONT LH STEERING TIE ROD END	1	reuse	178.10	0.00	
FRONT LH UPPER ARM	1	bent	971.10	971.10	SVC X
FRONT LH UPPER ARM ROD	1	reuse	374.45	0.00	
FRONT LH WHEEL HUB	1	dislodge	581.90	581.90	SVC X
FRONT PANEL	1	buckled	971.40	850.00 971.40	DD ✓
FRONT WASHER TANK	1	reuse	172.10	0.00	
FRONT WASHER TANK MOTOR PUMP	1	reuse	277.10	0.00	
FRONT WINDSCREEN GLASS	1	cracked	972.10	850.00 972.10	CR ✓
FRONT WINDSCREEN WEATHERSTRIP	1	necessary	172.50	172.50	NECV
FRONT WIPER LINKAGE	1	bent	374.40	374.40	SVC X
FRONT WIPER MOTOR	1	shorted	561.60	561.60	SVC X
HEATER BLOWER UNIT	1	fractured	1,218.50	600.00 1,218.50	7X RPT
LH SLIDING DOOR	1	repair	1,712.40	0.00	
LH SLIDING DOOR SWITCH	1	reuse	374.85	0.00	
RADIATOR SPARE TANK	1	deformed	381.90	381.90	DD ✓

Subtotal before discount S\$ 33,360.02 S\$ 28,541.67

Percentage discount 25% and 25%

S\$ 8,340.01 S\$ 7,135.42

Sub-total 1 S\$ 25,020.02 S\$ 21,406.25

FRONT BUMPER CLIPS - SET	1	necessary	50.00	30.00	NECV
FRONT FLOOR PANEL INSULATOR MAT	1	necessary	600.00	500.00	GUT V
FRONT GRILLE CLIPS - SET	1	necessary	50.00	20	30.00 NECV
FRONT HEADLAMP GARNISH CLIPS L/R - SET	2	necessary	60.00	25	40.00 NECV
FRONT LH 14" WHEEL RIM	1	distorted	200.00	200.00	R X
FRONT LH 185/14 TYRE	1	abraded	280.00	280.00	STX NH
FRONT LH DOOR 'COMPANY DETAIL' STICKER	1	necessary	80.00	30	80.00 NEC
FRONT LH DOOR ARCH PANEL GARNISH CLIPS - SET	1	necessary	30.00	20	30.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	50.00	25	50.00
FRONT LH DOOR QUARTER GARNISH CLIPS - SET	1	necessary	30.00	10	20.00
FRONT LH DOOR SPEAKER	1	crushed	180.00	120	180.00 GUT V
FRONT LH DOOR STEP PANEL TOP GARNISH CLIPS - SET	1	necessary	30.00	20	30.00
FRONT WINDSCREEN E.R.P BRACKET	1	necessary	50.00	25	50.00
FRONT WINDSCREEN E.R.P BRACKET STICKER	1	necessary	15.00	15.00	X NH
FRONT WINDSCREEN SOLAR FILM	1	necessary	800.00	800.00	NH X
REAR LH FENDER ADVERTISEMENT & ART WORK	1	necessary	200.00	150	200.00 NECV
Subtotal before discount			SS 2,705.00	SS 2,635.00	
Sub-total 2			SS 2,705.00	SS 2,635.00	
Parts-total			SS 27,725.02	SS 24,041.25	

LABOUR

To remove, replaced aircon evaporator unit, aircon blower motor and etc to vacuum system and top up gas.	250.00	120.00	200.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	120.00	60.00	30
To remove, change windscreen. (Front)	120.00	80.00	100.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	500.00	200.00	400.00
To remove, reinstall brake parts, brake line, brake pump and bleeding brake system.	180.00	100.00	NH X
To road test driving, check and resetting wheel alignments system.	180.00	60.00	150.00
To remove, reinstall, change steering column shaft, coupling, indicator handle, brake, clutch pedal and etc.	120.00	80.00	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00	80.00	120.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	100.00	80.00	60
To remove, change dashboard fascia and transfer where necessary.	350.00	150.00	250.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,200.00	600.00	1,600.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,900.00	1600.00	3,300.00
To mount vehicle on to Car 'O' Liner.	400.00	400.00	NH X 200 / Δ
To apply anti-rust chemical on repaired and replaced panel.	150.00	60.00	150.00
Labour Total		SS 8,720.00	SS 7,010.00
Parts & Labour Total		SS 36,445.02	SS 31,051.25

Repair days 16 days

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 26,400.00
and the recommended number of working days for the repairs is within 23 day(s).



B J Loi (Eng., MIML, AIR1E)

Automotive Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 3426S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIRCON BLOWER MOTOR	DENTED	972.85	972.85
1	AIRCON BLOWER MOTOR CASING	BROKEN	561.60	561.60
1	AIRCON COOLING UNIT (NOT NECESSARY)	NOT CONSISTENT WITH THE IMPACT	1,218.50	-
1	FRONT BUMPER	BROKEN	511.70	511.70
1	FRONT BUMPER LH AIR DUCT	DENTED	172.25	172.25
1	FRONT BUMPER LH FOGLAMP COVER	DENTED	181.90	70.00
1	FRONT BUMPER MOULDING	BENT	172.10	172.10
1	FRONT BUMPER REINFORCEMENT	BENT	41.90	41.90
4	FRONT BUMPER SIDE HOLDER CLIPS L/R	NECESSARY	26.00	26.00
2	FRONT BUMPER SIDE HOLDER L/R	NECESSARY	264.50	264.50
2	FRONT BUMPER UPPER BRACKET	BENT 1PC ONLY	348.80	174.40
1	FRONT FLOOR PANEL	BUCKLED	972.10	972.10
1	FRONT GLOVE BOX	REUSE	561.60	-
1	FRONT GRILLE	MISSING	381.72	381.72
1	FRONT GRILLE 'LOGO' EMBLEM	NECESSARY	61.10	61.10
2	FRONT HEADLAMP GARNISH L/R	CRACKED	203.40	203.40
1	FRONT INSTRUMENT LH SPEAKER	REUSE	531.35	-
1	FRONT INSTRUMENT LH SPEAKER COVER	CRACKED	182.10	182.10
1	FRONT INSTRUMENT PANEL	DISTORTED	972.10	972.10
1	FRONT INSTRUMENT PANEL REINFORCEMENT	TO REPAIR SEE LABOUR	581.25	-
1	FRONT LH CENTRE PILLAR	TO REPAIR SEE LABOUR	681.10	-
1	FRONT LH DOOR	DENTED	1,218.10	950.00
1	FRONT LH DOOR ARCH PANEL	DENTED	631.30	631.30
1	FRONT LH DOOR ARCH PANEL GARNISH	DISTORTED	372.10	372.10
1	FRONT LH DOOR BODY WEATHERSTRIP	CUT	276.60	276.60
1	FRONT LH DOOR CENTRE LOCK MOTOR	SERVICEABLE	581.90	-
1	FRONT LH DOOR CHECKER	BENT	172.25	172.25
1	FRONT LH DOOR GLASS	BROKEN	581.10	581.10
2	FRONT LH DOOR GLASS BRACKET	BENT	282.90	282.90

Report Ref No. CS1/AIG18016000/Bqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH DOOR GLASS CHANNEL	BENT	151.90	151.90
1	FRONT LH DOOR GLASS CHANNEL BRACKET	BENT	141.25	141.25
1	FRONT LH DOOR GLASS REGULATOR	BENT	374.10	374.10
1	FRONT LH DOOR GLASS REGULATOR MOTOR	SERVICEABLE	581.90	-
2	FRONT LH DOOR HINGES	BENT	264.50	264.50
1	FRONT LH DOOR INNER HANDLE	SERVICEABLE	141.45	-
1	FRONT LH DOOR INNER HANDLE COVER	BENT	155.50	155.50
1	FRONT LH DOOR INNER MOULDING	DISTORTED	171.10	171.10
1	FRONT LH DOOR INNER PILLAR	BENT	631.35	631.35
1	FRONT LH DOOR INNER TRIM BOARD	DISTORTED	781.10	455.60
1	FRONT LH DOOR LOWER WEATHERSTRIP	CUT	287.75	287.75
1	FRONT LH DOOR MECHANISM LOCK	BENT	372.45	372.45
1	FRONT LH DOOR OUTER HANDLE	SERVICEABLE	178.10	-
1	FRONT LH DOOR OUTER MOULDING	NECESSARY	182.25	182.25
1	FRONT LH DOOR OUTER PILLAR	BENT	631.35	590.00
1	FRONT LH DOOR QUARTER GARNISH	BENT	372.10	372.10
2	FRONT LH DOOR RUBBER GUIDE STOPPER	CUT	87.80	87.80
1	FRONT LH DOOR STEP PANEL	BENT	631.10	400.00
1	FRONT LH DOOR STEP PANEL TOP GARNISH	DISTORTED	277.10	277.10
1	FRONT LH DOOR WEATHERSTRIP	CUT	231.35	231.35
1	FRONT LH DOOR WIRE HARNESS	REUSE	181.90	-
1	FRONT LH HEADLAMP	BROKEN	372.25	372.25
1	FRONT LH HEADLAMP BRACKET	BENT	177.85	177.85
1	FRONT LH KNUCKLE	SERVICEABLE	581.90	-
1	FRONT LH KNUCKLE ARM BEARING	DISLODGE	172.10	172.10
1	FRONT LH LINKAGE	SERVICEABLE	374.45	-
1	FRONT LH LOWER ARM	SERVICEABLE	387.90	-
1	FRONT LH LOWER BALL JOINT	NOT NECESSARY	172.10	-
1	FRONT LH MIRROR BRACKET	REUSE	281.70	-
1	FRONT LH SHOCK ABSORBER	SERVICEABLE	274.40	-
1	FRONT LH SIDE LAMP	BROKEN	182.10	182.10
1	FRONT LH STAY ARM	SERVICEABLE	372.45	-
1	FRONT LH STEERING TIE ROD	REUSE	172.85	-

Report Ref No. CS1/AIG18016000/Bqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH STEERING TIE ROD END	REUSE	178.10	-
1	FRONT LH UPPER ARM	SERVICEABLE	971.10	-
1	FRONT LH UPPER ARM ROD	REUSE	374.45	-
1	FRONT LH WHEEL HUB	SERVICEABLE	581.90	-
1	FRONT PANEL	DENTED	971.40	850.00
1	FRONT WASHER TANK	REUSE	172.10	-
1	FRONT WASHER TANK MOTOR PUMP	REUSE	277.10	-
1	FRONT WINDSCREEN GLASS	CRACKED	972.10	850.00
1	FRONT WINDSCREEN WEATHERSTRIP	NECESSARY	172.50	172.50
1	FRONT WIPER LINKAGE	SERVICEABLE	374.40	-
1	FRONT WIPER MOTOR	SERVICEABLE	561.60	-
1	HEATER BLOWER UNIT	REPEATED	1,218.50	-
1	LH SLIDING DOOR	TO REPAIR SEE LABOUR	1,712.40	-
1	LH SLIDING DOOR SWITCH	REUSE	374.85	-
1	RADIATOR SPARE TANK	DENTED	381.90	381.90
	LESS 25% DISCOUNT		-8,340.00	-4,327.72
			25,020.02	12,983.15
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT FLOOR PANEL INSULATOR MAT (SN)	CUT	600.00	500.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	20.00
1	SET FRONT HEADLAMP GARNISH CLIPS L/R (SN)	NECESSARY	60.00	25.00
1	FRONT LH 14" WHEEL RIM (SN)	TO REPAIR SEE LABOUR	200.00	-
1	FRONT LH 185/14 TYRE (SN)	NOT NECESSARY	280.00	-
1	FRONT LH DOOR 'COMPANY DETAIL' STICKER (SN)	NECESSARY	80.00	30.00
1	SET FRONT LH DOOR ARCH PANEL GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT LH DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	25.00
1	SET FRONT LH DOOR QUARTER GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
1	FRONT LH DOOR SPEAKER (SN)	CUT	180.00	120.00
1	SET FRONT LH DOOR STEP PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	FRONT WINDSCREEN E.R.P BRACKET (SN)	NECESSARY	50.00	25.00

Report Ref No. CS1/AIG18016000/Bqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN E.R.P BRACKET STICKER (SN)	NOT NECESSARY	15.00	-
1	FRONT WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	800.00	-
1	REAR LH FENDER ADVERTISEMENT & ART WORK (SN)	NECESSARY	200.00	150.00
			2,705.00	975.00
	LABOUR			
	TO REMOVE, REPLACED AIRCON EVAPORATOR UNIT, AIRCON BLOWER MOTOR AND ETC TO VACUUM SYSTEM AND TOP UP GAS.		250.00	120.00
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)		120.00	30.00
	TO REMOVE, CHANGE WINDSCREEN. (FRONT)		120.00	80.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		500.00	200.00
	TO REMOVE, REINSTALL BRAKE PARTS, BRAKE LINE, BRAKE PUMP AND BLEEDING BRAKE SYSTEM.	NOT NECESSARY	180.00	-
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		180.00	60.00
	TO REMOVE, REINSTALL, CHANGE STEERING COLUMN SHAFT, COUPLING, INDICATOR HANDLE, BRAKE, CLUTCH PEDAL AND ETC.		120.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		150.00	80.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		100.00	60.00
	TO REMOVE, CHANGE DASHBOARD FASCIA AND TRANSFER WHERE NECESSARY.		350.00	150.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,200.00	900.00

Report Ref No. CS1/AIG18016000/Bqbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT INSTRUMENT PANEL REINFORCEMENT, FRONT LH CENTRE PILLAR, LH SLIDING DOOR AND FRONT LH 14" WHEEL RIM.		3,900.00	1,600.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.		400.00	200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	60.00
			8,720.00	3,620.00
GRAND TOTAL			36,445.02	17,578.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,050.00

Report Ref No. CS1/AIG18016000/Bqbs2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)**BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.