

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 5795027453SG-003

Date: 13th September 2018

Our Ref: CS1/AIG18016000/Bqbs2

## M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16 Chartis Building Singapore 079120 (The Motor Claims Department)

Attn: Angie Gan

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

**GU 3426S** 

INSURED VEHICLE: SLD 2118T ACCIDENT DATE: 27/09/2017

We thank you for your instruction on 30/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GU 3426S from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles GU 3426S and SLD 2118T.
- c) Colour damaged vehicle photographs of GU 3426S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: GU 3426S

Make & Model

: Tovota Hiace

Year of Registration

: 2001

Chassis Number

: LH1721003298

Engine Capacity

: 2986 cc

- We recommend that the repairs of the entire damage require about <u>16 (Sixteen)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.