

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG18016006/KSBE2**Date:** 21/09/2018REFERENCE

Insured/Claimant:	FABIAN CHEW PENG BOON	Policy No:	2100484074-01
Date of Loss:	30/08/2018	Nature of Claim:	OD
		Claim No:	6743099403SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFQ183U		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20Y416617
Reg. Date:	29/09/2016 (Man. Year: 2016)	Chassis No:	JF1SJ5KC5GG077744
Colour:	Metallic Grey	Odometer:	30333 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,287.91	2,997.94	2,289.97	43.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,425.00	1,925.00	57.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,637.91	4,422.94	4,214.97	48.80
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	8,237.91	4,022.94	4,214.97	51.17
+ GST 7.00/7.00% (\$\$)	576.65	281.61	295.04	51.16
Nett Amount (\$\$)	8,814.56	4,304.55	4,510.01	51.17

INSPECTION

Date of Assignment:	03/09/2018
Date Inspected:	03/09/2018 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
2	1		*FRAME SD FF CP RH	Repair	540.00 FL	*- FL
3	1		*RAD PNL COMPL RPR	Repair	360.00 FL	*- FL
4	1		*FRT FENDER RH	Buckled	270.00 FL	*270.00 FL
5	1		*EXT FENDER F CP RH	Serviceable	25.20 FL	*- FL
6	1		*HOOD F CPL	Bent	882.00 FL	*882.00 FL
7	1		*STAY ASSY F HOOD	Repair	93.60 FL	*- FL
8	1		*COVER FENDER UPR RH	Serviceable	18.00 FL	*- FL
9	1		*HINGE COMPL F HD RH	Distorted	43.20 FL	*43.20 FL
10	1		*HINGE COMPL F HD LH	Repair	43.20 FL	*- FL
11	1		*BUMPER FACE F STD	Bent	502.60 FL	*502.60 FL
12	1		*BRKT CORNER F RH	Cracked	36.00 FL	*36.00 FL
13	1		*BRKT SD F RH	Serviceable	12.60 FL	*- FL
14	1		*MOLDING BMPR F	Serviceable	43.20 FL	*- FL
15	1		*BUMPER FACE F NA	Repeated	594.00 FL	*- FL
16	1		*BACK BEAM CPL F	Repair	288.00 FL	*- FL
17	1		*ENERGY ABSOR F	Serviceable	126.00 FL	*- FL
18	1		*COVER HOOK F STD	Serviceable	4.30 FL	*- FL
19	1		*FOG LAMP ASSY F LHS	Serviceable	272.00 FL	*- FL
20	1		*BRKT F FOG ASSY RH	Serviceable	19.80 FL	*- FL
21	1		*NOZZLE H L WASHERRH	Serviceable	80.00 FL	*- FL
22	1		*NOZZLE COVER ASSYRH	Missing	54.00 FL	*54.00 FL
23	1		*GRILLE ASSY F UPR	Serviceable	140.40 FL	*- FL
24	1		*GRILLE ASSY F CT	Serviceable	180.00 FL	*- FL
25	1		*GRILLE ASSY F LWRHG	Serviceable	316.80 FL	*- FL
26	1		*MUD GUARD ASSY F RH	Distorted	86.40 FL	*86.40 FL
27	1		*LAMP ASSY HEAD EOF RHS	MTG Cracked	2,380.00 FL	*2,380.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					7,511.30	4,274.20
- List Item Discount on L Items 30.00/30.00% (\$\$)					2,223.39	1,276.26
Total Parts (\$\$)					5,287.91	2,997.94

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRONT BUMPER, FRT RHS FENDER, FRT HOOD AND PANEL	New	1,500.00	625.00
2	RESPRAY FRONT BUMPER, FRT RHS FENDER, FRT HOOD AND PANEL	New	1,200.00	800.00
3	FAULT DIAGNOSTIC CHECK AND RESET SYSTEM	New	235.00	0.00
4	TO CONDUCT FRONT ANTI-RUST COATING	New	290.00	0.00
5	REMOVE & REFIX FRONT HEADLAMP WASHER AND PIPING	New	125.00	0.00
Gross Labour Cost (\$\$)			3,350.00	1,425.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >