

ASS. REC. BY:

REF: CB/EC1180160114/Ksb n2 Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person): Yee Pei Li of ECL Date/Time: 03/09/01 10:13am

Estimated Cost: Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1655 Insured: YP 3515G

at Workshop m/s TRHS Pub Tel:

of No. 2 AMK St 63

Policy No: Claim No: YP3515G/SL

Sum Insured: Excess:

Make of Veh: D.O.A. 28/08/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SHD 1655 - X
	YP 3515G - X
04/09/01	@ 15:45 pm revised RA to Pei Li via email.
	1/1 Lm @ 4800l

ASS. REC. BY:

REF: ERZ /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140165S

Yr Regn:

09, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c.

1991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

890423

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL11A69RJB8 10446P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/8/18

D.O.I.

3/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9

File pass to Catherine

04/10/19

Confirmed H/S \$4,800/- @ 1 days with Kenneth (\$16,917.43 Red - 78%)

RECEIVED 07 JAN 2019

Date/Time, File Pass to?

1) 07/01/19

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Factors

Others

TOTAL

350

Report Format :

Lump Sum / I.B.I. (\$

4,800/- H/S



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YP3515G/SL

Date: 04 September 2018

Our Ref: CS/EGI18016014/Ksb

The Motor Claims Department
Ergo Insurance Pte Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 165S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/09/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 21,717.43</u> .
Revised Estimate Amount	: <u>S\$ 5,972.51</u> .
"Check" Items Amount	: <u>S\$ 449.95</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 4 January 2019 4:32 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'SUR'
Subject: FW: TCS REF: AAD1808-248--Accident involving SHD 165S & YP 3515G on 28.08.18
Attachments: ESTIMATE MARKED.pdf

WITHOUT PREJUDICE

Dear Shirley

We confirmed the COR amount \$4,800.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 4 January, 2019 11:14 AM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: TCS REF: AAD1808-248--Accident involving SHD 165S & YP 3515G on 28.08.18

Dear Wai Yin,

Please confirm final fig \$4,800.00 (lump sum) @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 4 September 2018 3:49 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: ASSIGNMENTS@LKKAUTO.COM; 'SUR'; 'Catherine Chong (LKK Auto)'
Subject: RE: YP3515G / TP : SHD165S/LKK / DOA : 28/08/2018
Attachments: SHD 165S - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SHD 165S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 3 September 2018 12:03 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: ASSIGNMENTS@LKKAUTO.COM; 'SUR' <sur@lkkauto.com>
Subject: RE: YP3515G / TP : SHD165S/LKK / DOA : 28/08/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Monday, 3 September, 2018 10:13 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : YP3515G / TP : SHD165S/LKK / DOA : 28/08/2018

Dear Catherine/Nivitha,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 165S	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	GHIEN YEE LOONG @ 6287 6666	YP3515G/SL	STEVE LIM	DOA: 28/08/2018 WP

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 3 September, 2018 10:13 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : YP3515G / TP : SHD165S/LKK / DOA : 28/08/2018
Attachments: YP3515G - SAS.pdf; SHD165S - SAS.pdf; SHD165S - PRS FORM.pdf; RE: Arrange for survey - SHD165S (140 KB)

Dear Catherine/Nivitha,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHD 165S	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	GHIEN YEE LOONG @ 6287 6666	YP3515G/SL	STEVE LIM	DOA: 28/08/2018 WP

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD1655
Vehicle to be Exported:	Yes
Intended De-registration Date:	29 Aug 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1456990K
Chassis No.:	KL1LA69RJBB104469
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,578.00
Original Registration Date:	07 Sep 2012
First Registration Date:	07 Sep 2012
Transfer Count:	0
Actual ARF Paid:	\$14,578.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Sep 2020
PARF Rebate Amount:	\$10,204.00

Intended COE Rebate Details

COE Expiry Date:	06 Sep 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,531.00
COE Rebate Amount:	\$13,024.00
Total Rebate Amount:	\$23,228.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Aug 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 165S**AAD1802-248***Not Authored**L/Sy D*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 165S

KL1LA69RJBB104469

CHEVROLET

EPICA 2.0

28.8.2018

ERGO**PART****LIST**

1	1	Rear Bumper
2	1	Rear Bumper Beam
3	1	Rear Bumper Centre Absorber
4	1	Rear Bumper Side Retainer RH
5	1	Rear Bumper Side Retainer LH
6	1	Rear Bumper Reflectors RH
7	1	Rear Bumper Reflectors LH
8	1	Rear Bumper Tow Hook Cover
9	1	Rear End Panel Outer
10	1	Rear End Panel Inner Trim
11	1	Rear Luggage Floor Panel
12	1	Rear Luggage Floor Panel Insulator
13	1	Rear Luggage Floor Panel Trim Board
14	1	Bootlid
15	1	Bootlid inner trim board
16	1	Bootlid Weatherstrip
17	1	Bootlid Lock - Top
18	1	Bootlid 'CHEVROLET' Badge
19	1	Bootlid Logo
20	1	Bootlid 'EPICA LT' Badge
21	1	Bootlid Reflector Centre
22	1	Bootlid Reflector RH
23	1	Bootlid Reflector LH
24	1	Rear Tail Lamp RH
25	1	Rear Tail Lamp LH
26	1	Rear Exhaust Box (Muffler A-EXH,RR)
27	1	Rear Fender RH
28	1	Rear Fender Inner Trim RH
29	1	Rear Fender LH

\$	<i>Bu</i>	1,202.00	✓
\$	<i>R</i>	239.94	X
\$	<i>Sn</i>	260.00	X
\$	<i>Sn</i>	68.76	X
\$	<i>Sn</i>	68.76	X
\$	<i>Sn</i>	119.74	X
\$	<i>Sn</i>	119.74	X
\$	<i>Sn</i>	93.00	X
\$	<i>Bu</i>	623.76	✓
\$	<i>Dis</i>	263.84	✓
\$	<i>R</i>	973.00	X
\$	<i>Sn</i>	63.50	X
\$	<i>Sn</i>	378.00	X
\$	<i>Bu</i>	973.00	✓
\$	<i>Sn</i>	400.00	X
\$	<i>Dis/Ref</i>	344.28	<i>508.00</i>
\$	<i>R</i>	466.56	X
\$	<i>Ru</i>	120.62	✓
\$	<i>Ru</i>	138.84	✓
\$	<i>Ru</i>	119.84	✓
\$	<i>Cm</i>	217.97	✓
\$	<i>Cm</i>	128.40	✓
\$	<i>Cm</i>	128.40	✓
\$	<i>Sn</i>	479.30	X
\$	<i>Cm</i>	479.30	✓
\$	<i>R</i>	1,110.00	X
\$	<i>R</i>	1,145.00	X
\$	<i>Sn</i>	418.44	X
\$	<i>R</i>	1,145.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 165S

30	1	Rear Fender Inner Trim LH	\$	<i>Sh</i>	418.44	<i>X</i>
----	---	---------------------------	----	-----------	--------	----------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	<i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sh</i>	300.00	<i>X</i>
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i>	30.00	
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	
6	1	Rear Exhaust Mounting	\$	<i>Sh</i>	300.00	
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1	Spare Tyre	\$	<i>Sh</i>	180.00	
10	1	Spare Wheel Rim	\$	<i>Sh</i>	126.74	
11	1	REAR BOOT ADVERTISEMENT STICKER	\$	<i>nn</i>	300.00	
12	1	REAR BUMPER ADVERTISEMENT STICKER	\$	<i>nn</i>	200.00	
13	1	LEFT REAR FENDER ADVERTISEMENT STICKER	\$	<i>nn</i>	300.00	
14	1	RIGHT REAR FENDER ADVERTISEMENT STICKER	\$	<i>nn</i>	300.00	

TOTAL	\$	2,330.74
--------------	-----------	-----------------

TOTAL PARTS	\$	13,767.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>700</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>20</i>
----	--------	-----------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>60</i>
----	--------	-----------

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	<i>800</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>60</i>
----	--------	-----------

Trans-cab Auto Services Pte Ltd

AAD1808-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 165S

To transfer of end panel fittings and conduct water seepage test.

\$ ~ 170.00 X

To transfer of boot fittings and conduct water seepage test.

\$ 170.00 601

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 1001

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

\$ 7,950.00

TOTAL \$ 21,717.43

Repair Days (LUMP SUM)

10 DAYS
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18016014/Ksbn2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 08-01-2019



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3515G	Veh. Inspected	SHD 165S
Policy No.		Coverage (\$)	0.00
Claim No.	YP3515G/SL	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	03/09/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB104469	Colour	WHITE / RED
Odometer	890423	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	9 mm
L/H Front Tyre	195/65 R15	GITI	9 mm
R/H Rear Tyre	195/65 R15	GITI	9 mm
L/H Rear Tyre	195/65 R15	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/08/2018	Inspection Date	03/09/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 165S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,202.00	1,202.00
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER	BUCKLED	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	CRACKED	217.97	217.97
1	BOOTLID REFLECTOR RH	CRACKED	128.40	128.40
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP LH	CRACKED	479.30	479.30
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-

Report Ref No. CS/EGI18016014/Ksbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,236.31	-439.60
			11,126.84	3,956.37
1	BOOTLID WEATHERSTRIP (50%)(SN)	DISTORTED / DENTED	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14
	SPECIAL NETT ITEMS			
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	300.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
1	REAR BOOT ADVERTISEMENT STICKER (SN)	NOT NECESSARY	300.00	-
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	200.00	-
1	LEFT REAR FENDER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	300.00	-
1	RIGHT REAR FENDER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	300.00	-
			2,330.74	44.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM,REAR LUGGAGE FLOOR PANEL,BOOTLID LOCK-TOP,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH.		3,500.00	700.00

Report Ref No. CS/EGI18016014/Ksbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	800.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,950.00	1,800.00
	GRAND TOTAL		21,717.43	5,972.51
RECOMMENDED COST OF LUMP SUM REPAIR (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/EGI18016014/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.