

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18016029/GDA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100210032-08

Claimant

Vehicle No : GBA5870T

Insured Vehicle No : SJX1864Y

Date of Loss: 30/08/2018

Nature of Claim: TP

Claim No: 4888807240SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBA5870T

Make & Model: SUZUKI EVERY, 658cc PA 660 (A)

Engine No: K6A7120999

Reg. Date: 30/08/2007 (Man. Year: 2007)

Chassis No: DA64V201537

Colour: White

Odometer: 112221 km

Engine Capacity: 658 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 155 R12

Rear Tyre Size: 155 R12

Front Left Side: Radial 6 mm

Rear Left Side: Radial 6 mm

Front Right Side: Radial 6 mm

Rear Right Side: Radial 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,214.17	1,706.46	6,507.71	79.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,790.00	1,990.00	52.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,994.17	3,496.46	8,497.71	70.85
Approved Total (Overridden) (\$\$)		2,800.00		
Nett Amount (\$\$)	11,994.17	2,800.00	9,194.17	76.66
+ Car Rental (8.0 x S\$100.00/day) (\$\$)		800.00		
Nett Liability (\$\$)		3,600.00		

INSPECTION

Date of Assignment: 03/09/2018

Date Inspected: 03/09/2018 Inspected At:

Unimotor Company (HQ)
1, Kaki Bukit Avenue 6,
Autobay@Kaki Bukit, #01-94
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE WINDSCREEN MOULDING	Not Necessary	90.70 FL	*- FL
2	1		*REAR TAILGATE PANEL	Buckled	1,348.90 FL	*868.95 FL
3	2		*REAR TAILGATE HINGES	Not Necessary	192.40 FL	*- FL
4	2		*REAR TAILGATE ABSORBER UNIT	Not Necessary	571.60 FL	*- FL
5	1		*REAR TAILGATE LOCK ASSY	Not Necessary	215.30 FL	*- FL
6	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	43.50 FL	*- FL
7	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	293.40 FL	*- FL
8	1		*REAR TAILGATE SUZUKI LOGO	Necessary	63.30 FL	*55.00 FL
9	1		*REAR BUMPER ASSY	Deformed	998.40 FL	*540.05 FL
10	2		*REAR BUMPER SIDE RETAINER	Deformed (1 PCS ONLY)	124.60 FL	*20.00 FL
11	2		*REAR BUMPER BRACKET	Not Necessary	117.60 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Not Necessary	354.90 FL	*- FL
13	1		*REAR BUMPER R/H SIDE REFLECTOR	Cracked	189.60 FL	*90.00 FL
14	1		*REAR FLOOR OUTER PANEL	Buckled	315.00 FL	*260.05 FL
15	1		*REAR FLOOR INNER PANEL	Not Necessary	424.00 FL	*- FL
16	1		*REAR R/H CORNER PANEL	Not Necessary	298.50 FL	*- FL
17	1		*REAR R/H FENDER ASSY	Repair	1,356.30 FL	*- FL
18	1		*REAR R/H FENDER INNER TRIM PANEL	Not Necessary	987.60 FL	*- FL
19	1		*REAR R/H FENDER INNER TRIM BOARD	Not Necessary	175.00 FL	*- FL
20	1		*REAR R/H FENDER INNER SHIELD	Deformed	81.70 FL	*67.00 FL
21	1		*REAR R/H AIR DUCT	Cracked	174.20 FL	*24.20 FL
22	1		*REAR FLOOR PANEL	Repair	823.70 FL	*- FL
23	1		*REAR 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
24	1		*REAR 4 PAX STICKER	Necessary	15.00 FS	*15.00 FS
25	1		*REAR REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
26	1		*REAR WINDSCREEN DAM RUBBER	Necessary	60.00 FS	*40.00 FS
27	1		*REAR R/H FENDER GLASS DAM RUBBER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,600.20	1,995.25
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,386.03	288.79
Total Parts (\$\$)	8,214.17	1,706.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO COMPLETE WHEEL ALIGNMENT	New	120.00	0.00
2	TO SPRAY UNDERCOATING IN REPAIR	New	180.00	60.00
3	TO DISM/REFIX REAR WINDSCREEN R/H FENDER GLASS	New	280.00	100.00
4	TO DISM/REWIRE DAMAGED PORTION	New	200.00	30.00
5	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,800.00	800.00
6	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,780.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >