

ASB RES ID: CS3/AIG18009889/Atb-1  
 From Person: Adrian Saliba  
 Estimated Cost: AIG  
 Date/Time: 03 09 2018  
 Bill to: AIG  
 OD (TP) WS/TP RES / OD RES / EVA / INV / MYTCS  
 To Inspect Vehicle: SBC 81817  
 at Workshop: Alpha Car Services  
 of Kalei Bulait Ave 6 # 01-54 Blk C  
 Policy No: 0423501611SG-003  
 Sum Insured: 0423501611SG-003  
 Make of Veh: SJ 728M  
 (Client's Record): 6509 8258  
 D.O.A: 30/5/2018  
 CA / REV / REP. / REV 24 HRS (up)  
 Date/Time: 12pm @ 31/5/18 Person Contacted: ceiling  
 H.O.D. Endorsement: Vehicle IN OUT

Date/Time	Action/Instructon (X) Estimate
	<u>SBC 81817 - X</u>
	<u>SJ 728M - X</u>
<u>1/6/18</u>	<u>disassembled</u>
<u>4/6/18</u>	<u>After repair</u>

lump sum \$ 3500/- (Red: 3700, 51%)  
 5 days

251A- Pile pass to typist.

RECEIVED 26 SEP 2018.

ASS. REC. BY: Adrian King

REF: \_\_\_\_\_

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05/8/18 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SBC8181TYr Regn: 2017, MarshType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camryc.c 2494Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053AK5004D11839Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 31/05/18Survey held at AlphaDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG TRS.1/6/18 Submit DAR Report

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)Survey Fee: 180

Transportation: \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

Photos \_\_\_\_\_

☐ : Tech. Invs (\$ \_\_\_\_\_)Others 20☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

200

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

## Catherine Chong (LKK Auto)

---

**From:** Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>  
**Sent:** Monday, 3 September, 2018 2:37 PM  
**To:** 'SUR'; Catherine Chong (LKK Auto)  
**Subject:** ref: 0423501611SG-003  
**Attachments:** 0423501611SG part 1.pdf

Dear Sirs,

Kindly assist to do paper RI in view that LKK had previously conducted paper RI.

Enclosed is the part 1 of the survey report

thank you,

PLEASE NOTE THAT CONTENTS OF THIS EMAIL SHOULD NOT BE CONSTRUED AS ANY ADMISSION OF LIABILITY ON THE PART OF OUR INSURED AND/OR INSURERS. WE HEREBY MAINTAIN FULL RESERVATION OF RIGHTS AND ALL DEFENCES AVAILABLE TO US

Saliha Syed Yusoff  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

[saliha.syed-yusoff@aig.com](mailto:saliha.syed-yusoff@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other

defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



account number  
14885

Notes: <sup>1</sup> Includes the 1997-1998 and 2000-2001 seasons. <sup>2</sup> See Chapter 10. <sup>3</sup> See *Verstehen: The Party Rules* and *Compassion and Truth* (1997) and *Verstehen: The Party Rules* (1997) (Chicago). <sup>4</sup> See *Verstehen: The Party Rules* (1997) (Chicago).

## Page 10 of 19

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 2605B

### Vehicle Details

Vehicle No.: SBC8181T  
Vehicle to be Exported: Yes  
Intended De-registration Date: 15 Aug 2018  
Vehicle Make: TOYOTA  
Vehicle Model: CAMRY 2.5 AUTO  
Primary Colour: Blue  
Manufacturing Year: 2016  
Engine No.: 2ARU354802  
Chassis No.: MR053AK5004011839  
Maximum Power Output: 133.0 kW (178 bhp)  
Open Market Value: \$29,570.00  
Original Registration Date: 13 Mar 2017  
First Registration Date: 13 Mar 2017  
Transfer Count: 0  
Actual ARF Paid: \$33,398.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 12 Mar 2027  
PARF Rebate Amount: \$25,048.00

### Intended COE Rebate Details

COE Expiry Date: 12 Mar 2027  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$50,621.00  
COE Rebate Amount: \$40,496.00  
Total Rebate Amount: \$65,544.00

The information contained herein is correct as at 15 Aug 2018

OK

**Radiology Report**

<b>Patient Name:</b>	RACHEL WANG MANMAN		
<b>Patient MRN:</b>	S8472605B	<b>Location:</b>	Emergency
<b>Gender:</b>	Female	<b>Exam Date:</b>	30-May-2018 18:20
<b>Date of Birth:</b>	01/09/1984	<b>Exam ID:</b>	9438743
<b>Ordering Doctor:</b>	NG KIM BOON (04470I)		
<b>Procedure:</b>	XR, CERVICAL SPINE, AP & LATERAL		

**Main report text:**

Exam(S) Ordered : XR, CERVICAL SPINE, AP &amp; LATERAL

Exam No : 9438743

Completed Date : 30-MAY-2018 06:21 PM

Ordering Physician : NG KIM BOON

**REPORT STATUS :**

\*\*\*APPROVED\*\*\*

**XR, CERVICAL SPINE, AP & LATERAL**

Loss of normal cervical lordosis with no significant spondylolisthesis.

The vertebral heights and disk spaces are relatively preserved.

Mild osteophyte lipping may represent early spondylosis.

The prevertebral soft tissue is not significantly thickened.

No acute fracture is detected.

**#R2i#**

Report Entered By : DR (Reg) Teng Sheng Yeow Victor on 30-MAY-2018 07:32 PM

Report Co read By : DR (Reg) Teng Sheng Yeow Victor on 30-MAY-2018 07:32 PM

Report Approved By : DR (Reg) Teng Sheng Yeow Victor on 30-MAY-2018 07:32 PM

**Dictated by:** (Reg) Teng Sheng Yeow Victor at 30-May-2018 19:32**Approved by:** (Reg) Teng Sheng Yeow Victor at 30-May-2018 19:32

Verified by: NG KIM BOON (04470I) on 30-May-2018 19:49

11 July, 2018

Your reference: AJ.tk.6002.2018.AC – PD+PI

Crossborders LLC  
Advocates & Solicitors  
133 New Bridge Road #23-03/04/05  
Chinatown Point  
Singapore 059413

Dear Sir/Mdm,

**RE: MS RACHEL WANG MANMAN, S8472605B**

Ms Rachel Wang Manman was seen at the EMD, NUH on the 30 May 2018.

She alleged that she was a back seat passenger of a car, involved in a road traffic accident, hit by another car from behind. She complained of neck pain after the accident.



On examination, she was well. There was reduction of range of movement of the neck. No neurological deficits.

X-ray was done which showed loss of lordosis, no bony deformity

Diagnosis: Neck Strain.

She was given analgesics and 3 days of medical leave upon discharge.

Warmest regards,

  
Dr Ng Kim Boon  
MCR: M044701  
EMD, NUH  
A/Prof Malcolm Mahadevan  
MBBS (Singapore), FRCp (Edin),  
FRCSEd (A&E), FAMS  
Head & Senior Consultant  
Emergency Medicine Department  
National University Hospital





PHOTOCOPY

Your Ref : AJ.tk.6002.2018.AC-PD+PI  
 Our Ref : OMR 2018-12545-0  
 Date : 9 Jul 2018

CROSSBORDERS LLC  
 133 NEW BRIDGE ROAD  
 #23-03/04/05  
 CHINATOWN POINT  
 SINGAPORE 059413

ATTENTION: -

**RE: MEDICAL REPORT FOR RACHEL WANG MANMAN (NRIC NO: S8472605B)**

We refer to your request dated 28 Jun 2018 for a medical report. The medical report will be forwarded in due course.

For patients who are collecting the report personally, please bring along your NRIC. If patient is authorising someone to collect on his/her behalf, please provide a photocopy of patient's NRIC and an authorisation letter. Please note that Ministry of Manpower Workmen Compensation Report will be forwarded directly to the Ministry.

Thank you.

Medical Records Office  
 Kent Ridge Wing, Level 1

## OFFICIAL RECEIPT

Receipt No. : MRS-265561

Date : 9 Jul 2018

GST REG NO.: M2-0069889-4

**ORIGINAL**

SERVICE DESCRIPTION	AMOUNT (\$)
ORDINARY MEDICAL REPORT	80.25
<b>RACHEL WANG MANMAN S8472605B</b>	
Your Ref : AJ.tk.6002.2018.AC-PD+PI Our Ref : OMR 2018-12545-0 Payment : CHEQUE MB 003888	

7% GST is included in the amount charged.

Note: Administrative charges of 1/3 of the cost of medical report will be imposed if a cancellation request is made while the medical report is being processed.

For enquiries, please contact Norelela Binte Abdullah

Tel No: 6772-6163/6772-6163 (Kent Ridge Wing, Level 1, Singapore 119074)  
 Tel: (65) 6779 5555, Fax: (65) 6779 5678, www.nuh.com.sg, Company Registration No: 198500843R

A member of the NUHS

**TAX INVOICE**

PHOTOCOPY

TO:

MDM. RACHEL WANG MANMAN  
BLK 24 #14-02  
BUKIT BATOK STREET 52  
GUILIN VIEW  
SINGAPORE - 659246

MRN/NRIC : S8472605B  
CASE NO : 1518618794C-00001  
VISIT DATE : 30.05.2018 16:41  
LOCATION : NCA&E  
INVOICE DATE : 30.05.2018  
TYPE OF SUPPLY : CASH/CREDIT  
GST REG NO : M2-0069889-4

PATIENT NAME : RACHEL WANG MANMAN  
LOCATION : EMERGENCY

PLEASE PAY UPON RECEIPT OF THIS INVOICE

**SERVICE****AMOUNT**

A&E Facility/Service Fee 230.00  
XR, CERVICAL SPINE, AP & LATERAL 55.00

Diclofenac Sod 75mg SR Tab 1.68

Total Charges 286.68  
Government Subsidy 170.00-

Total Amount Payable 116.68

**ADJUSTMENT:**

ROUND DOWN FOR AMOUNT PAYABLE BY PATIENT 0.03-

**PAYMENT:**

RACHEL WANG MANMAN 116.65

**TOTAL DUE AFTER PAYMENT** 0.00

**DUE FROM:**

RACHEL WANG MANMAN 0.00

**FOR INFORMATION**

Total amount payable after GST is \$124.85.

Total GST for this bill at 7% is \$8.17 which is absorbed by the Government.

The amount payable by patient has been rounded down to the nearest 5 cents.

**National University Hospital (Singapore) Pte Ltd**

5 Lower Kent Ridge Road, Singapore 119074

TEL: (65) 6779 5555

Business Registration No.198500843R



**MEDICAL CERTIFICATE**

**ORIGINAL**

**NUH18140642**

**NAME: RACHEL WANG MANMAN**

**NRIC: S8472605B**

Type of Medical Leave granted : **OUTPATIENT SICK LEAVE**

The above named is unfit for duty for a period of **3** day(s) from **30-May-2018** to **01-Jun-2018** inclusive

The certificate is not valid for absence from court attendance.

The above named attended for Examination/Treatment from **30-May-2018 16:41** to **30-May-2018 19:50**

30-May-2018

Date

A member of the NUHS

NG KIM BOON (044701)

Issued by

A&E

Location

  
Signature

# MOTORCAR (Rear)

## Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT	✓	
1142	994085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	993341	Rear Bumper Clips	NEC	✓	
1147	993976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	993970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993319	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No: SBC 8181T

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sucker			

## Claim Documents

\*SBC8181T (0423501611SG)  
[SJJ728M]






































TP






















RACHEL WANG MANMAN

May 30 2018 9:00AM

[TAN SIEW HOW]

Alpha Car Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <span>View in Browser</span>	
Photos/Images														3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print	
1	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
2	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
3	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
4	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
5	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
6	01/06/18 15:37	General View													<input checked="" type="checkbox"/>	
7	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
8	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
9	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
10	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
11	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
12	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
13	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
14	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
15	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
16	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
17	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
18	01/06/18 15:38	General View													<input checked="" type="checkbox"/>	
19	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
20	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
21	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
22	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
23	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
24	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
25	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
26	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
27	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
28	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
29	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
30	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
31	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
32	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
33	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
34	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
35	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
36	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	
37	01/06/18 15:38	Dismantled Parts													<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/06/18 08:34	OI GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009889/AZ4D3E2  
Date: 08/06/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479019  
Claimant Vehicle No: SBC8181T Insured Vehicle No: SJJ728M  
Date of Loss: 30/05/2018 Nature of Claim: TP Claim No: 0423501611SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBC8181T  
Make & Model: TOYOTA CAMRY, 2.4 (A) Engine No: 2ARU354802  
Reg. Date: 13/03/2017 (Man. Year: 2016) Chassis No: MR053AK5004011839  
Colour: Blue Odometer: 0 km  
Engine Capacity: 2494 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 30/05/2018  
Date Inspected: 31/05/2018 Inspected At: Alpha Car Services Pte Ltd (HQ)  
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit  
Autobay  
Singapore 417883  
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*REAR BUMPER	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*BOOTLID	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

# L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Rachel Wang Manman  
C/o: Alpha Car Services Pte Ltd  
No.1 Kaki Bukit Ave 6 #01-59  
Kaki Bukit AutoBay, Singapore 417883

Date : 18 June 2018  
Our ref : ACS/05/1808/TP

Accident Date : 30 May 2018  
Inspection Date : 30 May 2018  
Repairer Name : Alpha Car Services Pte Ltd  
No.1 Kaki Bukit Ave 6 #01-59  
Kaki Bukit AutoBay, Singapore 417883

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : SBC 8181 T  
Make / Model : Toyota Camry  
Chassis No : MR053AK5004011839  
Engine No : 2ARU354802

Year / Capacity : 2017 / 2494 cc  
Colour : Grey  
Mileage : 23288

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Dunlop	215/55 R17	5 mm	Sport
Front Offside	: Dunlop	215/55 R17	5 mm	Sport
Rear Nearside	: Dunlop	215/55 R17	5 mm	Sport
Rear Offside	: Dunlop	215/55 R17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 76 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 7,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

# **SCL APPRAISER PTE LTD**

Vehicle Registration No: SBC 8181 T

Our Ref No: ACS/05/1808/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear boot lid <i>Reps</i>	Damage	\$ 996.80	\$ 996.80 <i>x</i>
2	Rear boot hinges <i>3 new</i>	Intact	\$ 242.60	<i>x</i>
2	Rear boot lamps	Intact	\$ 521.60	<i>x</i>
1	Rear boot lock <i>new</i>	Damage	\$ 349.30	\$ 349.30 <i>x</i>
1	Rear boot logo	Necessary	\$ 47.50	\$ 47.50 <i>✓</i>
1	Rear boot rubber <i>new</i>	Necessary	\$ 250.60	\$ 250.60 <i>x</i>
1	Rear boot "CAMRY" emblem	Necessary	\$ 89.80	\$ 89.80 <i>✓</i>
1	Rear boot "2.5" emblem	Necessary	\$ 80.00	\$ 80.00 <i>✓</i>
2	Rear taillamps	Damage	\$ 948.60	\$ 948.60 <i>✓</i>
1	Rear end panel	Damage	\$ 855.80	\$ 855.80 <i>692</i>
1	Rear end panel inner garnish <i>new</i>	Damage	\$ 434.30	\$ <u>434.30</u> <i>342.60</i>
1	Rear keyless sensor <i>new</i>	Damage	\$ 288.80	\$ 288.80 <i>x</i>
1	Rear bumper	Damage	\$ 899.50	\$ <u>899.50</u> <i>665.20</i>
2	Rear bumper brackets <i>new</i>	Damage	\$ 182.90	\$ 182.90 <i>x</i>
1	Rear bumper reinforcement	Damage	\$ 488.80	\$ 488.80 <i>379.20</i>
2	Rear bumper side retainers	Necessary	\$ 120.00	\$ 120.00 <i>✓</i>
4	Rear bumper PDC sensors <i>2 pieces damaged</i>	Damage	\$ 1,415.80	\$ 1,415.80 <i>550</i>
1	Rear bumper sensor wire harness set <i>new</i>	Damage	\$ 355.80	\$ 355.80 <i>x</i>
1	Rear floor panel	Intact	\$ 937.30	
1	Rear floor board <i>new</i>	Damage	\$ 980.50	\$ 980.50 <i>x</i>
			<b>\$ 10,486.30</b>	<b>\$ 8,784.80</b>
<i>Less 25%</i>			<b>\$ 2,621.58</b>	<b>\$ 2,196.20</b>
<b>Total Cost - List Items</b>			<b>\$ 7,864.73</b>	<b>\$ 6,588.60</b>

*3867.40*  
*2500.55*

## SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00 <i>30</i>
<b>Total Cost - Special Nett items</b>			<b>\$ 50.00</b>	<b>\$ 50.00</b>

*30*

**Total cost of parts**

**\$ 7,914.73    \$ 6,638.60**

# **SCL APPRAISER PTE LTD**

Vehicle Registration No: SBC 8181 T

Our Ref No: ACS/05/1808/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 7,914.73</b>	<b>\$ 6,638.60</b>

## **LABOUR**

- |   |  |             |                            |
|---|--|-------------|----------------------------|
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring   | \$ 80.00    | \$ <del>50.00</del> 30     |
| 2 | To remove and refit inner garnishes, inner trim to assist repair.  | \$ 150.00   | \$ <del>120.00</del> 60    |
| 3 | To remove and refit rear reverse sensor.   | \$ 150.00   | \$ <del>120.00</del> 60    |
| 4 | To transfer boot lid mechanism and wiring assembly to assist repair.   | \$ 80.00    | \$ 60.00 X                 |
| 5 | To apply undercoating on repaired and replaced panel.  | \$ 150.00   | \$ <del>90.00</del> 50     |
| 6 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,400.00 | \$ <del>1,000.00</del> 600 |
| 7 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.  | \$ 1,200.00 | \$ <del>880.00</del> 600   |

**GRAND TOTAL**

**\$ 11,124.73    \$ 8,958.60**

# C L APPRAISER PTE LTD

Vehicle Registration No: SBC 8181 T

Our Ref No: ACS/05/1808/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,200.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

## Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD

  
\_\_\_\_\_  
Cheong K. H  
Automotive Appraiser

total 4330.55.  
2/5: 3450 3500  
06 days.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009889/Atbs2-1

78 SHENTON WAY #08-16

CHARTIS BUILDING

SINGAPORE 079120

ATTN: SALIHA

Date : 26-09-2018



Code : AIG

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJJ 728M	Veh. Inspected	SBC 8181T
Policy No.	2100479019	Coverage (\$)	0.00
Claim No.	0423501611SG	Excess (\$)	0.00
Assign From	SALIHA	Assign Date	03/09/2018

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA CAMRY	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053AK5004011839	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/55R17	DUNLOP	6 mm
L/H Front Tyre	215/55R17	DUNLOP	6 mm
R/H Rear Tyre	215/55R17	DUNLOP	6 mm
L/H Rear Tyre	215/55R17	DUNLOP	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	30/05/2018	Inspection Date	31/05/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBC 8181T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	996.80	-
2	REAR BOOT HINGES	NOT NECESSARY	242.60	-
2	REAR BOOT LAMPS	NOT NECESSARY	521.60	-
1	REAR BOOT LOCK	NOT NECESSARY	349.30	-
1	REAR BOOT LOGO	NECESSARY	47.50	47.50
1	REAR BOOT RUBBER	NOT NECESSARY	250.60	-
1	REAR BOOT "CAMRY" EMBLEM	NECESSARY	89.80	89.80
1	REAR BOOT "2.5" EMBLEM	NECESSARY	80.00	80.00
2	REAR TAILLAMPS	DAMAGED	948.60	948.60
1	REAR END PANEL	DAMAGED	855.80	692.00
1	REAR END PANEL INNER GARNISH	DAMAGED	434.30	342.60
1	REAR KEYLESS SENSOR	NOT NECESSARY	288.80	-
1	REAR BUMPER	DAMAGED	899.50	665.20
2	REAR BUMPER BRACKETS	NOT NECESSARY	182.90	-
1	REAR BUMPER REINFORCEMENT	DAMAGED	488.80	379.20
2	REAR BUMPER SIDE RETAINERS	NECESSARY	120.00	120.00
4	REAR BUMPER PDC SENSORS	DAMAGED 2PCS ONLY	1,415.80	550.00
1	SET REAR BUMPER SENSOR WIRE HARNESS	NOT NECESSARY	355.80	-
1	REAR FLOOR PANEL	INTACT	937.30	-
1	REAR FLOOR BOARD	NOT NECESSARY	980.50	-
	LESS 25% DISCOUNT		-2,621.57	-978.73
			7,864.73	2,936.17
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
			50.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM		150.00	60.00

Report Ref No. CS3/AIG18009889/Atbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR REVERSE SENSOR.	NOT NECESSARY	150.00	60.00
	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.		80.00	-
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		150.00	50.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		1,400.00	600.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	600.00
			3,210.00	1,400.00
	<b>GRAND TOTAL</b>		<b>11,124.73</b>	<b>4,366.17</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,500.00</b>

Report Ref No. CS3/AIG18009889/Atbs2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.