

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

AAD1808-267

*Not Authorized
 L1 Sum @ 2050h*

SHC 5085L

Vehicle No.:	SHC 5085L
Chassis No.:	VF1ABL15AUC276024
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	29.8.2018
Third Party Insurer :	AIG

PART	LIST
1 DOOR PANEL REAR LH	\$ <i>N</i> 2,844.66 X
1 FENDER PANEL REAR LH	\$ <i>N</i> 3,299.13 X
1 FENDER PANEL INNER TRIM REAR	\$ <i>Sn</i> 671.45 X
1 WHEELARCH REAR LH	\$ <i>N</i> 543.47 X
1 ROCKER PANEL INNER GARNISH LH	\$ <i>Sn</i> 466.51 X
1 ROCKER PANEL INNER LH	\$ <i>N</i> 1,024.79 X
1 ROCKER PANEL CENTER LH	\$ <i>N</i> 990.25 X
1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
1 BUMPER LOWER REAR	\$ <i>Sn</i> 768.84 X
1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47 X
1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97 X
1 BUMEP R RETAINER RH REAR	\$ <i>Sn Ret</i> 44.99 X
1 BUMPER REFLECTOR RH	\$ <i>Sn</i> 43.61 X
1 BUMEP R BRACKET SIDE LH REAR	\$ <i>nit R</i> 135.97 X X
1 BUMEP R RETAINER LH REAR	\$ <i>Sn Ret</i> 44.99 ✓ X
1 BUMPER REFLECTOR LH	\$ <i>Sn</i> 43.61 X
1 BUMPER BEAM REAR	\$ <i>R</i> 777.52 X
1 BUMPER BEAM BRACKET LH REAR	\$ <i>N</i> 225.95 X
1 BUMPER BEAM BRACKET RH REAR	\$ <i>N</i> 225.95 X
	<hr/>
	\$ 13,509.60
	10% \$ 1,350.96
	<hr/> \$ 12,158.64 <hr/>

Special Nett

1 REAR DOOR STICKER '6555 3333'	\$ <i>Nu</i> 80.00 X
1 DOOR CHECK BOLT	\$ <i>Sn</i> 22.69 X
1 DOOR GUIDE SCREW	\$ <i>Sn</i> 10.85 X

Trans-cab Auto Services Pte Ltd

AAD1808-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5085L

1	DOOR CHECK BOLT	\$	Sh	22.69	X
1	DOOR CHECK NUT	\$	Sh	3.75	X
1SET	DOOR LOCK SCREW L70Y	\$	Sh	6.12	<
1SET	DOOR CATCH SCREW L70Y	\$	Sh	10.06	<
1	PARKING AID	\$	Sh	700.00	X
1SET	BUMPER BRACKET CTR CLIP	\$	na	66.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	33.00	—
1SET	BUMEPR RETAINER RH CLIP RR	\$	na	10.00	} X
1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	20.00	
1SET	BUMEPR RETAINER CLIP LH RR	\$	na	10.00	
1	BUMPER LOWER REAR RIVET	\$	na	20.00	
1SET	BUMPER LOWER REAR CLIP	\$	na	22.00	
1	FENDER WHEELARCH REAR RH CLIP	\$	na	66.00	
1	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
1	FENDER INNER TRIM CLIP LH	\$	na	35.00	
1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
2	TAILLAMP CLIP RH	\$	na	28.00	
1	TAILLAMP CLIP LH	\$	na	5.00	
1	REAR WINDSCREEN SELANT	\$	na	5.00	
1	WINDSCREEN MOULDING	\$	na	80.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	LEFT REAR TYRE RIM	\$	na	385.00	✓
1	LEFT REAR TYRE	\$	Sh	330.00	X

	\$	2,079.63
TOTAL		
	\$	14,240.23
TOTAL PARTS		

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	440

Trans-cab Auto Services Pte Ltd

AAD1808-267

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5085L

To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>801</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
Towing Fees.	\$	<i>na</i> 120.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>na</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL	\$	14,890.00
--------------	-----------	------------------

Over All Total	\$	28,177.27
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**10 DAYS***2 day*

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
