

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Withheld
Lily & ? 1/10/18.*

5 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **03.09.2018**

Accident Date : 28.08.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Subaru Exiga" Reg. No. SJY7938Z Claiming Against Your Insured Reg. No. SLX5183D			
1pc	Bonnet		<i>RM</i> 810.00 ✓
1pc	Bonnet Chrome Moulding		<i>CM</i> 276.00 ✓
1pc	Bonnet Rubber Seal		<i>SM</i> 39.30 X
2pcs	Bonnet Side Seals	23.90	<i>SM</i> 47.80 X
1pc	Bonnet Lock		<i>RM</i> 74.50 ✓
1pc	Grille		<i>CM</i> 484.50 ✓
1pc	Grille Emblem		<i>RM</i> 63.90 ✓
1pc	Grille Chrome Surround		<i>CM</i> 367.00 ✓
2pcs	Headlamps Assy	1,090.00	<i>RM</i> 2,180.00 ✓
1pc	Front Bumper		<i>RM</i> 846.00 ✓
10pcs	Front Bumper Clips	3.80	<i>RM</i> 38.00 ✓
1pc	Front Bumper Bracket RH		<i>RM</i> 35.00 ✓
1pc	Front Bumper Reinforcement		317.00 ✓
1pc	Front Bumper Reinforcement Top Retainer RH		<i>RM</i> 113.00 ✓
1pc	Front Bumper Sponge		<i>CM</i> 83.00 ✓
1pc	Front Bumper Tow Cover		<i>RM</i> 20.00 ✓
1pc	Front Bumper Fog Lamp		405.00 ✓
2pcs	Front Bumper Corner Holders	16.90	33.80 ✓
1pc	Front Fender RH		<i>RM</i> 290.00 X
1pc	Support Panel		<i>RM</i> 542.00 ✓
1pc	Air Con Condenser		792.00 ✓
1pc	Radiator		<i>SM</i> 980.00 X
1pc	Air Cleaner Box Cold Air Intake Duct		<i>CM</i> 67.00 ✓
			8,904.80
	Less 20%		1,780.96
			7,123.84
1pc	Front Number Plate		<i>RM</i> 45.00 ✓ SN
1pc	Front Bumper Parking Sensors		<i>CM</i> 300.00 ✓ SN
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 <i>201</i>
	To Dismantle / Replace Front Parking Sensors, Module, Wiring, Bore Bumper Hole Etc		120.00 <i>501</i>
		C/F	7,618.84

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **03.09.2018**

Accident Date : 28.08.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Subaru Exiga" Reg. No. SJY7938Z Claiming Against Your Insured Reg. No. SLX5183D		
		B/F	7,618.84
	To Remove / Refit Air Con Condenser & Refill Gas		120.00 100
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		100.00 50
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 60
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, Bonnet Hinge, Cnt, Weld Support and Parts Replacement		1,000.00 600
	To Respray Affected Areas		950.00 800
	Total :		9,888.84

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: