

ASS. REC. BY:

REF:

CS/CTI 18016097/ Nsd30

Special Instruction:

Surround
menmen

Na2

ASSIGNMENT (Office)

From (Person):

Irene tay

of

CTI

Date/Time:

3/9/18 @ 2.31pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7185M

Insured:

YN9476G

at Workshop n/s

Kah Motor

Tel:

8288 6309

of

6A Mendell Estate

Policy No:

DMCVSN 3067781702

Claim No:

SNM18D04242C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/08/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9.59am @ 4/9/18

Person Contacted:

Jack

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLN 7185M-X

YN 9476G-NA/CTI 18015944/h4

DOA: 31/08/2018

08/03/19 wef

ASS. REC. BY:

NAZ

REF:

CPI

ASSIGNMENT

From

Date:

14/9/18

Estimated Cost

OR / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 7185M

at Workshop n/s

Kah Motor

of

GA Mendai Estate

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Juck 8288 6309

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

hps

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 7185M

Yr Regn:

16 MAR 2017

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA CIVIC 1.5 TURBO cc 1,498

Colour:

RED

A/C:

Insured / Std / NI / NA

Sp. Reading

19,017

T/Rating:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC1660HT000067

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215 / 50 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

5/5/18

D.O.A.

5/9/18

Survey held at

KAH MOTOR

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/3/19

FINALIZED


PART BY PART REPAIR

\$17,032.52

CTI PIP

(\$ 4,194.36 RL - 20%)

RECEIVED 8 MAR 2019



8/3/2019

Date/Time, File Pass to?

08/03/19

1)

Type 3

Date/Time, File Return to?

2)

☐

Prel. Report

☒

Final Report

Days Of Repair:

10

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$) 17,032.52 P/A

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2018		03 Sep 2018 14:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	M/S RUI GE ENTERPRISE (S) PTE LTD, Co. Reg. No.: -			
Main Claimant:	TEO CHENG YAN			
Vehicle Reg. No.:	SLN7185M	Date of Loss:	31/08/2018 14:00 - :59	
Claim Type:	TP / SNM18D04242C02	Policy/Cover Note No.:	DMCVSN3067781702 (Comprehensive)	
Vehicle Reg. No. (Insured):	YN9476G	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/09/2018]			
Adj Asg. Remarks:	EST \$21,181.88 , CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118016097/Nsd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9476G	Veh. Inspected	SLN 7185M
Policy No.	DMCVSN3067781702	Coverage (\$)	0.00
Claim No.	SNM18D04242C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	31/08/2018	Inspection Date	04/09/2018
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Shirley Hiew (LKK Auto)

From: Naz (LKKAuto) <Naz@lkkauto.com>
Sent: Thursday, 7 March 2019 4:53 PM
To: Anikka Lai
Cc: Shirley Hiew (LKK Auto); SUR
Subject: Re: SLN 7185M FINALIZATION
Attachments: FINALIZED.pdf

Dear Ms Lai,

Finalized Part by Part Repair \$17032.52 / 10 Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Tuesday, 8 January 2019 7:55 PM
To: Naz (LKKAuto)
Cc: Admin-D (LKKAuto)
Subject: RE: SLN7185M - FINALIZATION

Dear Naz,

Sorry for the delay. Attached pls find the photos for your reference, part no indicated.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Naz (LKKAUTO) <Naz@lkkauto.com>
Sent: Tuesday, 8 January, 2019 5:52 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Cc: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: Re: SLN7185M - FINALIZATION

Dear Anikka,

Kindly update me on the finalization.

Thank you.

Best Regards,
Naz | Technical Investigator
LKK Auto Consultants
Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Wednesday, 21 November 2018 3:25 PM
To: Naz (LKKAUTO)
Cc: Admin-D (LKKAUTO)
Subject: FW: SLN7185M - FINALIZATION

Dear Naz,

Any news? Pls advise.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Anikka Lai
Sent: Friday, 5 October, 2018 10:07 PM
To: 'Naz (LKKAUTO)' <Naz@lkkauto.com>
Subject: SLN7185M - FINALIZATION

Dear Naz,

We enclosed the total final repair costs for,

Vehicle No.	SLN7185M
Final Repair Costs (exclude GST)	\$17071.44
Repair Period* (Days)	11 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended

recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/09/2018 17:12
Date Of Accident	31/08/2018 14:00
Exact Location Of Accident	JUNCTION OF QUEENSWAY AND COMMONWEALTH DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN7185M
Insured/Policyholder	
Name Of Registered Owner	TEO CHENG YAN
NRIC No	S1800998F
Email Address	AGNESTEO888@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97811123
Alternative Phone No	OTHERS-97811123

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.5 TURBO VTIS SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10758533
Cover Note Number	N.A

Driver

Name of Driver	TEO CHENG YAN
NRIC No	S1800998F
Date Of Birth	01/09/1967
Occupation	INDOOR
Date Of Driving Pass	27/06/2006
Driving Experience	12 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97811123
Fax Number	
Contact Number	OTHERS-97811123
Email Address	AGNESTEO888@HOTMAIL.COM

Address	HDB WOODLANDS, 351 WOODLANDS AVENUE 1 #11-735
Postcode	730351
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My car SLN7185M was stationary at the traffic light junction of QUEENSWAY when a lorry YN9476G suddenly hit onto rear of my car SLN7185M. Due to the impact, my car SLN7185M had slight contact onto the front car SKA1554B. It was raining and the driver of YN9476G told me that his lorry brake was not working. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN9476G
Vehicle Make/Model/Colour	MITSUBISHI CANTER FEB21ER4SDEB (CBU)
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	THIRUNAVUKKARASU
NRIC/Passport Number	G8434551U
Contact Number	86187509
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKA1554B
-----------------------------	----------

Vehicle Make/Model/Colour	CHEVROLET CRUZE 1.6L AUTO / WHT
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	SIM CHIN CHYE
NRIC/Passport Number	S7125664B
Contact Number	97476369
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : MRS SIM (SPOUSE) GENDER: : FEMALE


Sketch Plan

IMPORTANT NOTICE

1. Please read the following conditions of the accident report form carefully.
2. The accident report form is provided by the Roadside Accident Reporting Authority (RARA).
3. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
4. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
5. Any information provided on this form is for the use of the Police for investigation.
6. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
7. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
8. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
9. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
10. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
11. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
12. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
13. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
14. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
15. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
16. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
17. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
18. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
19. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.
20. The accident report form is provided by RARA and is not to be used for any other purpose. It is not to be used for any other purpose.

VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZY BIN ISMAIL

Driver's Signature of driver is for all purposes / Date & Time: _____
Witnessed by Reporting Centre: _____
Particular:



ACCIDENT STATEMENT (2000 characters)

My car SLN7185M was stationary at the traffic light junction of QUEENSWAY when a lorry YN9476G suddenly hit onto rear of my car SLN7185M. Due to the impact, my car SLN7185M had slight contact onto the front car SKA1554B. It was raining & the driver of YN9476G told me that his lorry brake was not working. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

1 September 2018 10:40 am

Date/Time:

1 September 2018 10:40 am



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 Registration No : SLN7185M
 Chassis No : MRHFC1660HT000067
 Model : CIVIC 1.5 TURBO VTIS YM2017
 Owner's Name : TEO CHENG YAN
 Ins Policy No. :
 Date of Accident : 31/8/2018

Document No. : SQT18003672 Page 1
 Date : 1. Sep 2018
 Customer No. : WZC008
 Svc Advisor : ANIKKA LAI SWEE KAM
 Engine No : L15B72451256
 Date | Time : 1. Sep 2018 10:56:55 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEO CHENG YAN OWNER INSURER: AVIVA ACC DATE: 28/082018 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: YN 9476 G						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
71130-TEA-T00	BEAM COMPFR.BUMPER	1	335.80	25	251.85	17.63	269.48
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71102-TBA-A00	GRILLE, FR.BUMPER LOWER	1	72.40	25	54.30	3.80	58.10
71103-TEA-T10	GARNISHR.FR.BUMPER SIDE	1	13.80	25	10.35	0.72	11.07
71108-TEA-T10	GARNISHL.FR.BUMPER SIDE	1	13.80	25	10.35	0.72	11.07
71145-S21-000	BASEFR LIC PLATE	1	37.00	25	27.75	1.94	29.69
91505-TM8-003	CLIPBUMPER	22	2.00	25	33.00	2.31	35.31
71125-TEA-T01	MOLDINGFR.GRILLE	1	97.40	25	73.05	5.11	78.16
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	76.60	25	57.45	4.02	61.47
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE	1	83.20	25	62.40	4.37	66.77
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE	1	83.20	25	62.40	4.37	66.77
74146-TEA-T00	RUBBERHOOD SEAL	1	26.80	25	20.10	1.41	21.51
90113-SJA-A00	SCREWTAPPING 5X14	8	2.30	25	13.80	0.97	14.77
90113-SJA-A00	SCREWTAPPING 5X14	8	2.30	25	13.80	0.97	14.77
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
74127-TEA-T00	COVERFR.BULKHEAD	1	17.70	25	13.27	0.93	14.20

782.02



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLN7185M
Chassis No : MRHFC1660HT000067
Model : CIVIC 1.5 TURBO VTIS YM2017
Owner's Name : TEO CHENG YAN
Ins Policy No :
Date of Accident : 31/8/2018

Document No. : SQT18003672 Page 2
Date : 1. Sep 2018
Customer No. : WZC008
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B72451256
Date | Time : 1. Sep 2018 10:56:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33100-TEA-T11	HEADLIGHT ASSY,R.	1	1155.10	25	866.32	60.64	926.96
33150-TEA-T11	HEADLIGHT ASSYL.	1	1155.10	25	866.32	60.64	926.96
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
33505-TEA-T01	REFLECTOR ASSY,RR.	1	7.00	25	5.25	0.37	5.62
33555-TEA-T01	REFLECTOR ASSYL,RR.	1	7.00	25	5.25	0.37	5.62
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
71503-TEA-T00	GARNISH,RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10
71555-TBA-A00	BRACKETL,RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71505-TBA-A00	BRACKETR,RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
68610-TEA-T10ZZ	HINGE COMPR,TRUNK	1	43.50	25	32.62	2.28	34.90
68660-TEA-T10ZZ	HINGE COMPL,TRUNK	1	43.50	25	32.62	2.28	34.90
74865-TEA-T01	WEATHERSTRIP,TRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSY,TRUNK	1	72.20	25	54.15	3.79	57.94
74890-TEA-T11ZB	GARNISH ASSY,RR.LICENSE	1	97.70	25	73.27	5.13	78.40
75701-TBA-A10	EMBLEM,H-MARK	1	11.90	25	8.92	0.62	9.54
75724-TBA-A00	EMBLEM	1	23.50	25	17.62	1.23	18.85
75722-TBA-A00	EMBLEM SET,RR.	1	11.50	25	8.62	0.60	9.22
74829-S84-A00	STOPPER TRUNK LID	1	4.50	25	3.37	0.24	3.61
74880-TEA-T01	CABLE,TRUNK OPEN	1	19.20	25	14.40	1.01	15.41
66100-TEC-307ZZ	PANEL SET,RR.	1	236.00	25	177.00	12.39	189.39
66114-TBA-A00ZZ	STIFFENER,R,RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66154-TBA-A00ZZ	STIFFENERL,RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
04646-TEA-T00ZZ	PANEL SETL,RR.OUTSIDE	1	691.00	25	518.25	36.28	554.53
63322-TEA-T00ZZ	ADAPTER,RR.COMBINATION LIGHT	1	58.90	25	44.17	3.09	47.26
63722-TEA-T00ZZ	ADAPTERL,RR.COMBINATION LIGHT	1	58.90	25	44.17	3.09	47.26

Printed on 1/9/2018 3:06:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

3149.59

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLN7185M

Chassis No : MRHFC1660HT000067

Model : CIVIC 1.5 TURBO VTIS YM2017

Owner's Name : TEO CHENG YAN

Ins Policy No. :

Date of Accident : 31/8/2018

Document No. : SQT18003672 Page 3

Date : 1. Sep 2018

Customer No. : WZC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B72451256

Date | Time : 1. Sep 2018 10:56:55 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66154-TBA-A00ZZ	STIFFENER,L.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
65550-TED-P00ZZ	PAN COMPSPARE TIRE	1	210.40	25	157.80	11.05	168.85
72841-SH3-315	OILSHEET	3	39.90	25	89.77	6.28	96.05
34150-TEX-Y01	LIGHT ASSYL.LID	1	118.70	25	89.02	6.23	95.25
34155-TEX-Y01	LIGHT ASSYL.LID	1	118.70	25	89.02	6.23	95.25
33550-TEA-T01	TAILLIGHT ASSYL	1	273.10	25	204.82	14.34	219.16
33500-TEA-T01	TAILLIGHT ASSYL	1	253.80	25	190.35	13.32	203.67
08F13-TEA-7T0AX-1	TRUNK SPOILER,WING TYPE	1	572.70		572.70	40.09	612.79
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					6896.13	482.75	7,378.88
BOSUN	SUNDRIES	1	100.00		80	100.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		180	280.00	299.60
BKBU01R	REMOVE & RENEW FR BUMPER.	1	800.00		560	800.00	856.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	800.00		450	800.00	856.00
BOSUN	SUNDRIES	1	100.00		30	100.00	107.00
BOJSE	BODY JOINT SEALANT FOR REAR FENDER	1	100.00		80	100.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		80	100.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00		80	100.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		180	280.00	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA	1	320.00		280	320.00	342.40
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	380.00			380.00	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00			180.00	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	800.00		560	800.00	856.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	560.00			560.00	599.20
BKRP21M	CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN	1	5000.00		3,720	5000.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00		2700	3000.00	3210.00

Printed on 1/9/2018 3:06:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLN7185M
Chassis No : MRHFC1660HT000067
Model : CIVIC 1.5 TURBO VTIS YM2017
Owner's Name : TEO CHENG YAN
Ins Policy No. :
Date of Accident : 31/8/2018

Document No. : SQT18003672 **Page** 4
Date : 1. Sep 2018
Customer No. : WZC008
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B72451256
Date | Time : 1. Sep 2018 10:56:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Sum Labor					12900.00	903.00	13,803.00

Survey By : NAZ LKK
Date & Time : 5/9/18 1245
Excess :
Status :
Signature : 

Total Amount 19,796.13 1,385.75 21,181.88
Total (Inclusive of GST) 21,181.88

21,226.83

NAZ LKK
5/9/18 1245
P/P
9 DAYS


10/9/18

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BEFORE PAINT PHOTO

PARTS 5325.09

Printed on 1/9/2018 3:06:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004237	Page	1
	3 ANSON ROAD #16-00	Date	: 5, Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLN7185M	Engine No	: L15B72451256		
Chassis No	: MRHFC1660HT000067	Date Time	: 5, Oct 2018 7:40:56 PM		
Model	: CIVIC 1.5 TURBO VTIS YM2017	Surveyor Name	:		
Owner's Name	: TEO CHENG YAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/8/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
SUPPLEMENTARY PARTS:-							
65661-TEA-T00ZZ	FRAMEL.RR.	1	173.00	25 BT	129.75	9.08	138.83
65665-TEA-T00ZZ	STIFFENER BL.RR.FLOOR SIDE	1	26.50	25 SVC	19.87	1.39	21.26
65666-TEA-T00ZZ	FRAMEL.RR.FRAME.RR.UPPER	1	39.70	25 DEF	29.77	2.08	31.85
65669-TEA-T00ZZ	BRACKETL.RR.BUMPER BEAM	1	25.40	25 SVC	19.05	1.33	20.38
65676-TBA-A00ZZ	GUSSETL.RR.PANEL	1	20.10	25 BT	15.07	1.05	16.12
91626-STK-A01	GROMMETTAILLIGHT	1	0.40	25 MEL	0.30	0.02	0.32
90661-SC7-003	GROMMET SCREW	1	2.30	25 MEL	1.72	0.12	1.84
74862-TEA-003	STRIKERTRUNK LID	1	6.90	25 DEF	5.17	0.36	5.53
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60	25 DEF	5.70	0.40	6.10
04657-TED-T00ZZ	BRACKET SETL.RR.SILENCER MTG	1	32.60	25 BT	24.45	1.71	26.16
18305-TED-T02	SILENCER COMPL,EXHAUST	1	444.40	25	333.30	23.33	356.63
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.30	25 MEL	3.97	0.28	4.25
Sum Item					588.12	41.15	629.27
BG51R	REPLACE RR. L QTR GLASS.(N)	1	280.00	✓ A	280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00	✓ A	560.00	39.20	599.20
Sum Labor					840.00	58.80	898.80

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 1,428.12 99.95 1,528.07
Total (Inclusive of GST) 1,528.07

Printed on 5/10/2018 10:01:29 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
 Chassis No: MRHFC1660HT000067
 License No: SLN7185M
 Mileage: 19016
 Engine No: L15B72451256

Document No: SVO18052415
 Printed By: ANIKKALAI
 Order Date: 6. September 2018
 Order Time: 5:05:33 PM
 Service Advisor: ANIKKA LAI SWEE KAM

63322-TEA-T00ZZ	ADAPTERR.RR.COMBINATION LIGHT	0	58.90	25	0.00	0.00	0.00	X
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	0	26.00	25	0.00	0.00	0.00	X
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	0	26.00	25	0.00	0.00	0.00	X
65550-TED-P00ZZ	PAN COMPSPARE TIRE	1	210.40	25	157.80	11.05	168.85	/
72841-SH3-315	OILSHEET	3	39.90	25	89.77	6.28	96.05	/
34150-TEX-Y01	LIGHT ASSYR.LID	1	118.70	25	89.02	6.23	95.25	/
34155-TEX-Y01	LIGHT ASSYLLID	1	118.70	25	89.02	6.23	95.25	/
33550-TEA-T01	TAILLIGHT ASSYL	1	273.10	25	204.82	14.34	219.16	/
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80	25	190.35	13.32	203.67	/
08F13-TEA-7T0AX-1	TRUNK SPOILER,WING TYPE	1	572.70		572.70	40.09	612.79	/
NMR5-4P-TM3040L	4PCS ACT RR.SENSOR	0	320.00		0.00	0.00	0.00	X3W
65661-TEA-T00ZZ	FRAMEL.RR.	1	173.00	25	129.75	9.08	138.83	BT
65665-TEA-T00ZZ	STIFFENER BL.RR.FLOOR SIDE	1	26.50	25	19.57	1.39	21.26	X3W
65666-TEA-T00ZZ	FRAMEL.RR.FRAME RR.UPPER	1	39.70	25	29.77	2.08	31.85	DEF
65669-TEA-T00ZZ	BRACKETL.RR.BUMPER BEAM	1	25.40	25	19.05	1.33	20.38	XW
65676-TBA-A00ZZ	GUSSETL.RR.PANEL	1	20.10	25	15.07	1.05	16.12	BT
91626-STK-A01	GROMMETTAILLIGHT	4	0.40	25	1.20	0.08	1.28	NOL
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69	NOL
74862-TEA-003	STRIKERTRUNK LID	1	6.90	25	5.17	0.36	5.53	DEF
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10	DEF
04657-TED-T00ZZ	BRACKET SETL.RR.SILENCER MTG	1	32.60	25	24.45	1.71	26.16	BT
18305-TED-T02	SILENCER COMPL,EXHAUST	1	444.40	25	333.30	23.33	356.63	DEF
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.30	25	3.97	0.28	4.25	NOL
	SUM PARTS:				5,931.44	415.18	6,346.62	
BOSUN		1	80.00		80.00	5.60	85.60	/
	SUNDRIES							
BML011	1729	1	180.00		180.00	12.60	192.60	/
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)							
BKBU01R	1729	1	560.00		560.00	39.20	599.20	/
	REMOVE & RENEW FR BUMPER.							
BP03R	1718	1	450.00		450.00	31.50	481.50	/
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)							
BOSUN		1	30.00		30.00	2.10	32.10	/
	SUNDRIES							
BOJSE	1718	1	80.00		80.00	5.60	85.60	/
	BODY JOINT SEALANT FOR REAR FENDER							
BOJSE	1718	1	80.00		80.00	5.60	85.60	/
	BODY JOINT SEALANT END PANEL							
BOJSE	1718	1	80.00		80.00	5.60	85.60	/
	BODY JOINT SEALANT FLOOR PANEL							
BML021	1729	1	180.00		180.00	12.60	192.60	/
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)							
BOMISC1	1729	1	280.00		280.00	19.60	299.60	/
	REMOVE & INSTALL REAR VIEW CAMERA							
BOMISC1	1729	1	380.00		380.00	26.60	406.60	/
	RESET & CALIBRATE SMART ENTRY SYSTEM(N)							

1,445.31

5,992.52



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC1660HT000067
License No: SLN7185M
Mileage: 19016
Engine No: L15B72451256

Document No: SVO18052415
Printed By: ANIKKALAI
Order Date: 6. September 2018
Order Time: 5:05:33 PM
Service Advisor: ANIKKA LAI SWEE KAM

BA02R	1729	1	180.00	180.00	12.60	192.60
	REMOVE & RENEW REVERSE					
	SENSORS-4 PCS (N)					
BMI02D	1438	1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL SPEAKER BOARD					
	RR SEATS TRUNK					
	LININGS GARNISHES & ETC.(N)					
BKOT00R	1729	1	560.00	560.00	39.20	599.20
	REMOVE & RENEW RR FLOOR					
	INSULATOR.(N)					
BKRP21M	1729	1	3,920.00	3,920.00	274.40	4,194.40
	CUT OFF & RENEW RR PANEL RR L					
	FENDER. STRAIGHTEN					
	ALIGN RR CHASSIS & RENEW DAMAGE					
	PARTS.					
BP06R	1718	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS. (6P)					
BG51R		1	280.00	280.00	19.60	299.60
	REPLACE RR. L QTR GLASS.(N)					
BMI03D		1	560.00	560.00	39.20	599.20
	REMOVE & INSTALL REAR					
	COMPARTMENT LININGS					
	GARNISHES.(N)					

SUM LABOUR: 11,140.00 779.80 11,919.80

TOTAL SGD 17,071.44 1,194.98 18,266.42

Total Payable (SGD)

18,266.42

GST Amount is calculated from individual line(s)

PARTS \$5892.52
LABOUR \$11140.00
TOTAL \$17032.52 / 10 DAYS

FINALIZED PART BY PART REPAIR \$17,032.52 / 10 DAYS

NAZUK
N



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC1660HT000067
License No: SLN7185M
Mileage: 19016
Engine No: L15B72451256

Document No: SVO18052415
Printed By: ANIKKALAI
Order Date: 6. September 2018
Order Time: 5:05:33 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Incd	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEO CHENG YAN OWNER INSURER: AVIVA ACC DATE: 28/082018 SURVEYED BY: DATE: REF NO: SNM18D04242 (IRENE TAY) TP INSURER: CHINA TAIPING TP VEH: YN 9476 G							
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15	
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36	
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35	
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35	
91505-TM8-003	CLIPBUMPER	22	2.00	25	33.00	2.31	35.31	
71125-TEA-T01	MOLDINGFR.GRILLE	1	97.40	25	73.05	5.11	78.16	
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72	
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	76.60	25	57.45	4.02	61.47	
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE	1	83.20	25	62.40	4.37	66.77	
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE	1	83.20	25	62.40	4.37	66.77	
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05	
33100-TEA-T11	HEADLIGHT ASSY,R.	1	1,155.10	25	866.32	60.64	926.96	
33150-TEA-T11	HEADLIGHT ASSYL.	1	1,155.10	25	866.32	60.64	926.96	
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	0	45.00		0.00	0.00	0.00	
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30	
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66	
33505-TEA-T01	REFLECTOR ASSYR.RR.	1	7.00	25	5.25	0.37	5.62	
33555-TEA-T01	REFLECTOR ASSYL.RR.	1	7.00	25	5.25	0.37	5.62	
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	0	38.20	25	0.00	0.00	0.00	
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	0	7.60	25	0.00	0.00	0.00	
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	0	2.20	25	0.00	0.00	0.00	
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	0	2.20	25	0.00	0.00	0.00	
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	0	11.50	25	0.00	0.00	0.00	
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83	
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85	
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	0	43.50	25	0.00	0.00	0.00	
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	0	43.50	25	0.00	0.00	0.00	
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18	
74851-TEA-003	LOCK ASSYTRUNK	1	72.20	25	54.15	3.79	57.94	JAM
74890-TEA-T112B	GARNISH ASSYRR.LICENSE	1	97.70	25	73.27	5.13	78.40	CRK
75701-TBA-A10	EMBLEM,H-MARK	1	11.90	25	8.92	0.62	9.54	
75724-TBA-A00	EMBLEM	1	23.50	25	17.62	1.23	18.85	
75722-TBA-A00	EMBLEM SETRR.	1	11.50	25	8.62	0.60	9.22	
74829-S84-A00	STOPPER TRUNK LID	0	4.50	25	0.00	0.00	0.00	RSN
74880-TEA-T01	CABLETRUNK OPEN	0	19.20	25	0.00	0.00	0.00	RSN
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39	DD
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87	DD
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87	DD
04646-TEA-T00ZZ	PANEL SETL.RR.OUTSIDE	0	691.00	25	0.00	0.00	0.00	RSN

3947-21

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2018		03 Sep 2018 14:34 Edit Adj Rpt	S\$17,032.52 Edit Estimates	S\$17,032.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S RUI GE ENTERPRISE (S) PTE LTD, Co. Reg. No.: -								
Main Claimant:	TEO CHENG YAN								
Vehicle Reg. No.:	SLN7185M	Date of Loss:	31/08/2018 14:00 - :59 [15 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04242C02	Policy/Cover Note No.:	DMCVSN3067781702 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN9476G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 12/09/2018]								
Adj Asg. Remarks:	EST \$21,181.88 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN7185M (SNM18D04242C02)
[YN9476G]
TP
TEO CHENG YAN
Aug 31 2018 2:00PM
[M/S RUI GE ENTERPRISE (S) PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/08/18 17:32	Accident Statement	Load HTM	
2	03/09/18 11:57	Addendum Sheet	Load JPG	☒
3	03/09/18 11:57	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	31/08/18 17:32	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 22:08	General View	Load JPG	☒
2	06/09/18 22:08	General View	Load JPG	☒
3	06/09/18 22:08	General View	Load JPG	☒
4	06/09/18 22:08	General View	Load JPG	☒
5	06/09/18 22:08	General View	Load JPG	☒
6	06/09/18 22:08	General View	Load JPG	☒
7	06/09/18 22:08	General View	Load JPG	☒
8	06/09/18 22:08	General View	Load JPG	☒
9	06/09/18 22:08	General View	Load JPG	☒
10	06/09/18 22:08	General View	Load JPG	☒
11	06/09/18 22:08	General View	Load JPG	☒
12	06/09/18 22:08	General View	Load JPG	☒
13	06/09/18 22:08	General View	Load JPG	☒
14	06/09/18 22:08	General View	Load JPG	☒
15	06/09/18 22:08	General View	Load JPG	☒
16	06/09/18 22:08	General View	Load JPG	☒
17	06/09/18 22:08	General View	Load JPG	☒
18	06/09/18 22:08	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				☒
19	06/09/18 22:08	General View	 Load JPG	☒
20	06/09/18 22:08	General View	 Load JPG	☒
21	06/09/18 22:08	General View	 Load JPG	☒
22	06/09/18 22:08	General View	 Load JPG	☒
23	06/09/18 22:08	General View	 Load JPG	☒
24	06/09/18 22:08	General View	 Load JPG	☒
25	06/09/18 22:08	General View	 Load JPG	☒
26	06/09/18 22:08	General View	 Load JPG	☒
27	06/09/18 22:08	General View	 Load JPG	☒
28	06/09/18 22:08	General View	 Load JPG	☒
29	06/09/18 22:08	General View	 Load JPG	☒
30	06/09/18 22:08	General View	 Load JPG	☒
31	06/09/18 22:08	General View	 Load JPG	☒
32	06/09/18 22:08	General View	 Load JPG	☒
33	06/09/18 22:08	General View	 Load JPG	☒
34	06/09/18 22:08	General View	 Load JPG	☒
35	06/09/18 22:08	General View	 Load JPG	☒
36	06/09/18 22:08	General View	 Load JPG	☒
37	06/09/18 22:08	General View	 Load JPG	☒
38	06/09/18 22:08	General View	 Load JPG	☒
39	06/09/18 22:08	General View	 Load JPG	☒
40	06/09/18 22:08	General View	 Load JPG	☒
41	06/09/18 22:08	General View	 Load JPG	☒
42	06/09/18 22:08	General View	 Load JPG	☒
43	06/09/18 22:08	General View	 Load JPG	☒
44	06/09/18 22:08	General View	 Load JPG	☒
45	06/09/18 22:08	General View	 Load JPG	☒
46	06/09/18 22:08	General View	 Load JPG	☒
47	06/09/18 22:08	General View	 Load JPG	☒
48	06/09/18 22:08	General View	 Load JPG	☒
49	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
50	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
51	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
52	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
53	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
54	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
55	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
56	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
57	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
58	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
59	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
60	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
61	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
62	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
63	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
64	07/03/19 17:05	Dismantled Parts	Load JPG	☒
65	07/03/19 17:05	Dismantled Parts	Load JPG	☒
66	07/03/19 17:05	Dismantled Parts	Load JPG	☒
67	07/03/19 17:05	Dismantled Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
68	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
69	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
70	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
71	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
72	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
73	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
74	07/03/19 17:05	Dismantled Parts	 Load JPG	☒
75	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
76	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
77	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
78	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
79	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
80	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
81	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
82	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
83	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
84	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
85	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
86	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
87	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
88	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
89	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
90	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
91	07/03/19 17:05	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/09/18 14:34	EMAIL FM KAH	 Load PDF	
2	03/09/18 14:34	REPAIR EST	 Load PDF	
3	03/09/18 14:34	TP GIA	 Load PDF	
4	03/09/18 14:34	OI GIA	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/08/18 17:31	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	31/08/18 17:31	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
3	31/08/18 17:32	DRIVING DOC [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/08/18 17:32	Accident Statement	 Load HTM	
2	03/09/18 11:57	Addendum Sheet	 Load JPG	☒
3	03/09/18 11:57	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	31/08/18 17:32	Accident Photo	 Load JPG	☒
2	31/08/18 17:32	Accident Photo	 Load JPG	☒
3	31/08/18 17:32	Accident Photo	 Load JPG	☒
4	31/08/18 17:32	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
5	31/08/18 17:32	Accident Photo	 Load JPG	☒
6	31/08/18 17:32	Accident Photo	 Load JPG	☒
7	31/08/18 17:32	Accident Photo	 Load JPG	☒
8	31/08/18 17:32	Accident Photo	 Load JPG	☒
9	31/08/18 17:32	Accident Photo	 Load JPG	☒
10	31/08/18 17:32	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
1	31/08/18 17:31	Accident Sketch Plan	 Load JPG	☒
2	31/08/18 17:31	Accident Sketch Plan	 Load JPG	☒
3	31/08/18 17:32	DRIVING DOC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016097/NSD3E2

Date: 12/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3067781702

Claimant Vehicle No: SLN7185M Insured Vehicle No: YN9476G

Date of Loss: 31/08/2018 Nature of Claim: TP Claim No: SNM18D04242C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN7185M**

Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A) Engine No: L15B72451256

Reg. Date: 16/05/2017 (Man. Year: 2017) Chassis No: MRHFC1660HT000067

Colour: Red Odometer: 19017 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,686.88	6,002.52	1,684.36	21.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,540.00	11,030.00	2,510.00	18.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,226.88	17,032.52	4,194.36	19.76
+ GST 7.00/7.00% (S\$)	1,485.88	1,192.28	293.60	19.76
Nett Amount (S\$)	22,712.76	18,224.80	4,487.96	19.76

INSPECTION

Date of Assignment: 03/09/2018

Date Inspected: 05/09/2018 Inspected At: Kah Motor Co Sdn Bhd (HQ)
6A MANDAI ESTATE, SINGAPORE
729903
Singapore 729903

Estimated Period of Repair: 10.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2019)
Parts: 143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN7185M)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING	Cracked	45.00 FS	*45.00 FS
2	1		*FACEFR.BUMPER	Cracked	434.92 FS	*434.92 FS
3	1		*BEAM COMPFR.BUMPER	Serviceable	251.85 FS	*- FS
4	1		*SPACERR.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
5	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
6	1		*GRILLE, FR.BUMPER LOWER	Serviceable	54.30 FS	*- FS
7	1		*GARNISHR.FR.BUMPER SIDE	Serviceable	10.35 FS	*- FS
8	1		*GARNISHL.FR.BUMPER SIDE	Serviceable	10.35 FS	*- FS
9	1		*BASEFR LIC PLATE	Serviceable	27.75 FS	*- FS
10	1		*CLIPBUMPER (22PCS)	Necessary	33.00 FS	*33.00 FS
11	1		*MOLDINGFR.GRILLE	Cracked	73.05 FS	*73.05 FS
12	1		*EMBLEM	Necessary	10.95 FS	*10.95 FS
13	1		*BASE,FR.GRILLE CHROME	Distorted	57.45 FS	*57.45 FS
14	1		*EXTENSION ASSYR.FR.GRILLE	Distorted	62.40 FS	*62.40 FS
15	1		*EXTENSION ASSYL.FR.GRILLE	Distorted	62.40 FS	*62.40 FS
16	1		*RUBBERHOOD SEAL	Serviceable	20.10 FS	*- FS
17	8		*SCREW TAPPING 5X14	Serviceable	13.80 FS	*- FS
18	8		*SCREW TAPPING 5X14	Serviceable	13.80 FS	*- FS
19	1		*NUT PUSH 3MM (2PCS)	Necessary	2.85 FS	*2.85 FS
20	1		*COVERFR.BULKHEAD	Serviceable	13.27 FS	*- FS
21	1		*HEADLIGHT ASSY, R	Cracked	866.32 FS	*866.32 FS
22	1		*HEADLIGHT ASSYL	Cracked	866.32 FS	*866.32 FS
23	1		*NUMBER PLATE WITH CASING	Serviceable	45.00 FS	*- FS
24	1		*FACE ASSY.RR.BUMPER	Cracked	462.90 FS	*462.90 FS
25	1		*GARNISH, RR.BUMPER LOWER	Dented/Deformed	28.65 FS	*28.65 FS
26	1		*REFLECTOR ASSYR.RR.	Scratched	5.25 FS	*5.25 FS
27	1		*REFLECTOR ASSYL.RR	Scratched	5.25 FS	*5.25 FS
28	1		*GARNISH,RR.BUMPER LOWER	Not Necessary	28.65 FS	*- FS
29	1		*GARNISHR.RR.BUMPER SIDE	Serviceable	5.70 FS	*- FS
30	1		*BRACKETL.RR.BUMPER SIDE	Serviceable	1.65 FS	*- FS
31	1		*BRACKETR.RR.BUMPER SIDE	Serviceable	1.65 FS	*- FS
32	1		*SPACERR.RR.BUMPER SIDE	Serviceable	8.62 FS	*- FS
33	1		*BEAM COMP RR.BUMPER	Dented	129.75 FS	*129.75 FS
34	1		*LID COMP TRUNK	Dented	354.07 FS	*354.07 FS
35	1		*HINGE COMPR.TRUNK	Serviceable	32.62 FS	*- FS
36	1		*HINGE COMPL.TRUNK	Serviceable	32.62 FS	*- FS
37	1		*WEATHERSTRIP TRUNK LID	Deformed	52.50 FS	*52.50 FS
38	1		*LOCK ASSY TRUNK	Jammed	54.15 FS	*54.15 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*GARNISH ASSYRR.LICENSE	Cracked	73.27 FS	*73.27 FS
40	1		*EMBLEM,H-MARK	Necessary	8.92 FS	*8.92 FS
41	1		*EMBLEM	Necessary	17.62 FS	*17.62 FS
42	1		*EMBLEM SETRR	Necessary	8.62 FS	*8.62 FS
43	1		*STOPPER TRUNK LID	Serviceable	3.37 FS	*- FS
44	1		*CABLETRUNK OPEN	Serviceable	14.40 FS	*- FS
45	1		*PANEL SETRR	Dented	177.00 FS	*177.00 FS
46	1		*STIFFENER,R.RR.PANEL SIDE	Dented	19.50 FS	*19.50 FS
47	1		*STIFFENERL.RR.PANEL SIDE	Dented	19.50 FS	*19.50 FS
48	1		*PANEL SETL.RR.OUTSIDE	Serviceable	518.25 FS	*- FS
49	1		*ADAPTERR.RR.COMBINATION LIGHT	Serviceable	44.17 FS	*- FS
50	1		*ADAPTERL.RR.COMBINATION LIGHT	Serviceable	44.17 FS	*- FS
51	1		*STIFFENER,R.RR PANEL SIDE	Not Necessary	19.50 FS	*- FS
52	1		*PAN COMPSPARE TIRE	Deformed/Dented	157.80 FS	*157.80 FS
53	1		*OILSHEET (3PCS)	Necessary	89.77 FS	*89.77 FS
54	1		*LIGHT ASSYR.LID	Scratched	89.02 FS	*89.02 FS
55	1		*LIGHT ASSYL.LID	Scratched	89.02 FS	*89.02 FS
56	1		*TAILLIGHT ASSYL	Cracked	204.82 FS	*204.82 FS
57	1		*TAILLIGHT ASSYR	Cracked	190.35 FS	*190.35 FS
58	1		*TRUNK SPOILER, WING TYPE	Broken	572.70 FS	*572.70 FS
59	4		*ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
60	1		*SUNDRIES	Necessary	100.00 FS	*80.00 FS
61	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
62	1		*FRAMEL.RR.	Bent	129.75 FS	*129.75 FS
63	1		*FRAMEL.RR.FRAME RR.UPPER	Deformed	29.77 FS	*29.77 FS
64	1		*BRACKETL.RR.BUMPER BEAM	Serviceable	19.05 FS	*- FS
65	1		*GUSSETL.RR.PANEL	Bent	15.07 FS	*15.07 FS
66	4		*GROMMETTAILLIGHT	Necessary	1.20 FS	*1.20 FS
67	1		*GROMMET SCREW (2PCS)	Necessary	3.45 FS	*3.45 FS
68	1		*STRIKERTRUNK LID	Deformed	5.17 FS	*5.17 FS
69	1		*GARNISHL.RR.BUMPER SIDE	Deformed	5.70 FS	*5.70 FS
70	1		*BRACKET SETL.RR.SILENCER MTG	Bent	24.45 FS	*24.45 FS
71	1		*SILENCER COMPL, EXHAUST	Deformed/Dented	333.30 FS	*333.30 FS
72	1		*CLIPAMBIENT SENSOR	Necessary	3.97 FS	*3.97 FS
73	1		*STIFFENERL.RR.PANEL SIDE	Not Necessary	19.50 FS	*- FS
74	1		*STIFFENER BL.RR.FLOOR SIDE	Serviceable	19.87 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	7,686.88	6,002.52
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	280.00	180.00
2	REMOVE & RENEW FR BUMPER	New	800.00	560.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	800.00	450.00
4	BODY JOINT SEALANT FOR REAR FENDER	New	100.00	80.00
5	BODY JOINT SEALANT END PANEL	New	100.00	80.00
6	BODY JOINT SEALANT FLOOR PANEL	New	100.00	80.00
7	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	280.00	180.00
8	REMOVE & INSTALL REAR VIEW CAMERA	New	320.00	280.00
9	RESET & CALIBRATE SMART ENTRY SYSTEM	New	380.00	380.00
10	REMOVE & RENEW REVERSE SENSORS-4PCS	New	180.00	180.00
11	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	800.00	560.00
12	REMOVE & RENEW RR FLOOR INSULATOR	New	560.00	560.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,000.00	2,700.00
14	REPLACE RR.L QTR GLASS	New	280.00	280.00
15	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
16	CUT OFF & RENEW RR PANEL RR L FENDER. STRAIGHTEN	New	5,000.00	3,920.00
Gross Labour Cost (S\$)			13,540.00	11,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >