

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 7685C

DATE 3/9/2018 11:00

MAKE :

*Like*

*Sum*  
*AXA*

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x rpa</i>			\$ 544.50
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) ✓			\$ 566.30
	Front Fender Shield (LH) ✗			\$ 175.90
	Front Fender Retainer ✗			\$ 24.60
	Front Wheel Hub Cap (LH) ✓			\$ 107.10
	<b>SUB TOTAL</b>			<b>\$ 1,465.40</b>
	<b>LESS 20%</b>			<b>\$ 293.08</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,172.32</b>
	<b>Labour Charge</b>			<i>300</i>
	Panel Beating			\$ <del>560.00</del>
	Spray Painting Charge			\$ <del>500.00</del> <i>400</i>
	Wiring			\$ <del>30.00</del> ✗
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Frt Wheel Alignment			\$ <del>80.00</del> ✗
	<b>TOTAL LABOUR</b>			<b>\$ 1,220.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,392.32</b>

*Kalve 10/11/18*  
*4/9/18 10:16h*  
*2 hrs*  
*4/5*  
*After Repair*

LKK Auto Consultants, hence notify the Repairer of the following:

- To resurvey before/after epoxy painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.