

Your Ref: TP/IP/43085/2018
Our Ref :CI/TPD18016114/Z

16th October 2018

Fatal Accident Investigation Team

Traffic Police Department
Singapore Police Force
10 Ubi Avenue 3
Singapore 408865

MECHANICAL INSPECTION REPORT OF MOTORCYCLE FS 7646U

1. We refer to your request dated 01st September 2018 to conduct a physical inspection of a motorcycle bearing registration number FS 7646U (herein referred to as "**Motorcycle**"), which was involved in a fatal road traffic accident on 31st July 2018.
2. The purpose of this inspection is to primarily determine if there was any possible mechanical failure to the Motorcycle that may have contributed to the accident.
3. Following the request, we had carried out a physical inspection of the Motorcycle on 01st October 2018 at the premises of Traffic Police vehicle pound, 517 Airport Road Singapore 539942. We now set out below our observations and comments with respect to this inspection.

General Condition

4. The mileage of the Motorcycle at the time of our inspection was 020252km.
5. The Motorcycle was observed to have sustained damages at the frontal portion & along its right side. The body parts that were found to have been damaged include its front headlamp & small lamp assembly, left & right wing mirrors, front right fairing, right foot brake pedal, dented fuel tank and cracked mud guard amongst others. Its handle bar was also observed to be dislocated as a result of the accident.
6. This was consistent with the accident's case facts that the motorcyclist was riding along Tampines Avenue 2 towards Tampines Avenue 9 near lamp post 34A on the centre lane of a 3 lanes road where he lost control of his motorcycle and self-skidded. See photo 1 to 8 below.