

(08/11/13)

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH A 600 64 Yr Regn: 17 Apr, 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 240 c.c. 1685Colour: Blue A/C: Ins / Std / NI / NASp. Reading: 458933 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KM410414MB1053757Gen. Cond: Good / Fb / Poor / BurntSteering: In order / J / Jammed / Leaked / Burnt orBrake: In order / J / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 205 / 60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wst / LkFront: 7 mmR/Bal. 7 mmL/Bal. 7 mmD.O.A. 3/9/8 D.O.I. 4/9/8Survey held at (DHE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$580.00.
 (Cero: \$1,889.00 / 73%)

Loyang
45

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/LPC18016133/K1ha3

Date: 05.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 6006U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.09.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) have the following to report:-

Workshop Estimate Amount	: S\$	2,439.06
Revised Estimate Amount	: S\$	1,160.96
"Check" Items Amount	: S\$	642.40
Total (Including Check Items)	: S\$	1,803.36
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6006U

DATE 3/9/2018 11:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x Mark</i>			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>x</i>			\$ 22.00
	Rear Bumper Bracket ?	\$	35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover <i>x</i>			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Advertisement Logo <i>✓</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>✓</i>	\$	100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor <i>x</i>			\$ 135.70 Nett
				\$ 385.70
	Labour Charge			
	Panel Beating			\$ 380.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,439.06

Kalin LKK

4/9/18 1020h.

2 Rps

L/S

After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey and calculate the final bill
- To display damaged parts for final survey
- Parts prices will be on a "without prejudice" basis
- Third party survey and repair is allowed
- No illegal modification will be resurveyed and
- Supplier (the repairer) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE*

VEHICLE NO : SHA 6006U

DATE 3/9/2018 11:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Rep</i>			\$ 553.00
	Rear Bumper Reinforcement <i>X su</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X su</i>	\$	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>X su</i>			\$ 22.00
	Rear Bumper Bracket <i>X su</i>	\$	35.60	\$ 71.20
	Rear Bumper Sponge <i>X su</i>			\$ 103.50
	Rear Bumper Under Cover <i>X su</i>			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Advertisement Logo <i>— me</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>— me</i>	\$	100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor <i>X su</i>			\$ 135.70 Nett
				\$ 385.70
	Labour Charge			
	Panel Beating			\$ 380.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X su</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X su</i>
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,439.06
<i>Kalin Uck</i> <i>4/9/8 1020 L.</i> <i>2 Rep</i> <i>L/S</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey by and after spray painting • To display damaged parties during resurvey • Parts prices are subject to confirmation • Third party survey is on a "No Fault" "No Prejudice" basis • No illegal modification is allowed • Supplementary work must be surveyed and is subject to the approval from Insurance Company Acknowledged by Repairer: Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305207954
REGN NO : SHA6006U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.04.2014
DATE/TIME IN : 03.09.2018 11:15
ACCIDENT DATE : 03.09.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 L	PANEL BEATING	100.00	
0001 L	SPRAY PAINTING CHARGE	200.00	
0002 20-05	RENEW ADVERTISMENT REAR BUMPER		50.00
0003 20-05	RENEW ADVERTISMENT REAR FENDER RH		100.00
0004 20-05	RENEW ADVERTISMENT REAR FENDER LH		100.00
SUB-TOTAL :			550.00
TOTAL :			550.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305207954
Date : 06.09.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN

Fax :

Vehicle Reg No. : SHA6006U Date of Accident : 03.09.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC --- SLB2274K
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$0.00
(b) Labour Charges	\$550.00
Total for Part-By-Part Repair Cost	\$550.00
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	\$0.00
Final Lumpsum Repair cost	\$0.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kalvin
Date : 6/9/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3853406

JC NO.: 305207954

CUSTOMER

COMFORT TRANSPORTATION PTE LTD

MS 7010045

CUSTOMER NO. 383 SIN MING DRIVE

ADDRESS Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

REGN NO.: SHA6006U

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN 03.09.2018 11:15

YR OF MANU 17.04.2014

TARGET DATE

CHASSIS CODE KMHLB41UMEU053757

COMPLETION DATE/TIME:

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 03.09.2018

NATURE: 3P 03.09.18/B

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA6006U FZ LONPAC

Vehicle No.: SHA6006U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 4 September 2018 9:07 AM
To: assignments@lkkauto.com; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VP05/020875 Accident involving SLB2274K & SHA6006U on 3/9/18
Attachments: 04092018085700.pdf

q-57am@11/9/18
vehicle in
SUR@Kalvin

Dear Nivitha/Catherine

Please refer to the attached and arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 6 September, 2018 9:08 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VP05/020875 Accident involving SLB2274K & SHA6006U on 3/9/18
Attachments: 06092018090330.pdf
Categories: HMK

Dear Mei Kwan,

Attached copy of insured's report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 5 September, 2018 5:23 PM
To: ONG LI LI
Cc: MT_Claim_SG; Vic (LKKAUTO); Admin A
Subject: RE: Our Ref: 18/18/18/VP05/020875 Accident involving SLB2274K & SHA6006U on 3/9/18

WITHOUT PREJUDICE

LPC ref: TBA
LKK REF: CC4/LPC18016133/K1ha3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SHA 6006U

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969



LONPAC/SLB2274K

Our Ref: 305207954
Date: 319118
Time of Fax: 1750h

Via Fax: 62962706
Your Insured: SLB2274K
Date of Acc: 3-9-18

Attn: Motor Claims Department
Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 60064

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our Initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

• Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811
• Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824
• Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
• Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006
• Jumanli Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
• Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176

Fax no. 6546 8156

Fauzy.

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING

CDGE Taxi Claims Dept.

59 Loyang Drive
4th Floor
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

06th December 2018

PRIVATE AND CONFIDENTIAL

LKK Auto Consultants Pte Ltd
Blk 51, Paya Ubi Industrial Park
#02-25,
Ubi Avenue 1
Singapore 408933

Attn: Mr Vic Alpeh (Motor Claims Dept.)

Dear Sir or Madam:

RETURNED OF DULY EXECUTED DISCHARGE VOUCHER/S

We enclosed the following duly executed original discharge voucher/s
for your attention.

<u>Your Ref</u>	<u>Our Client's No</u>	<u>Acc. Date</u>	<u>Settled Amt</u>
CC4/LPC18016133/K1ha3	SHA 6006U	03.09.18	\$1,000.00

Kindly let us have your payment within the next 14 days.

Thank you.

Yours sincerely

Kazali Hj Selahudin
Claims Department
DID: 6214 8736
Fax: 6214 1843

A member of

COMFORTDELGRO

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18016133/K1ha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 20-12-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 2274K	Veh. Inspected	SHA 6006U
Policy No.	Z18VP05017694	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020875	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/09/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHLB41UMEU053757	Colour	BLUE
Odometer	458933	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2018	Inspection Date	04/09/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6006U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	SERVICEABLE	160.60	-
10	REAR BUMPER CLIP	NOT NECESSARY	22.00	-
2	REAR BUMPER BRACKET @\$35.60	SERVICEABLE	71.20	-
1	REAR BUMPER SPONGE	SERVICEABLE	103.50	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	228.00	-
	LESS 20% DISCOUNT		-313.34	-
			1,253.36	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
			385.70	250.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		380.00	100.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			800.00	300.00
GRAND TOTAL			2,439.06	550.00
RECOMMENDED COST OF REPAIRS				550.00

Report Ref No. CC4/LPC18016133/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.