From (Perso	Admon Chin lee Ying	ASSIGNM	MENT (Office)	F. 1. W.	19/18@ 1.19pm
Estimated C	ost		Bill to	Date/It	me 4191160 1 1971
OIL/TD/V	STTP RESTOD REST	EVA/INV/MV	CS		
at Workshop	tehicle No: The Kerki BK-	2th 05	IAK	Insured:	31V 701B
of	2 Kin	un Hugo	,, ,	Tel: C	1839 1666
Dallan No.	& Keiki BKH	Ave 4 7	705-23	premier	
1 Only I'm	14000 897746		Claim No:	0849414	02060
Sum Insured			Excess:		
Make of Vel (Client's Recon				D.O.A.	01/09/2018
CA / REV	/ REP. / REV 24 HRS	up			
Table Code 1	2.08pm@ 4/9/18	D	Fabia	2	Findorsement
Date/Time:		rerson Contacted) Vehic, I	MIL.)
Date/Time	Action/Instruction (×) Estimat	ę		
		×) Estimat	£		
	Action/Instruction (×) Estimat ×	Į.		
	Action/Instruction (8LP 644R -> 8JV 70113 ->	×	Į.		
	Action/Instruction (8LP 644R -)	×	ę		

Veh No: SLP644R. Yr Regn: 2017 / M49 Type M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: / Handa Jazz c.c 1318 Colour Pracapt A/C: Insured / Std / NI / NA Sp.Reading 5127. T/Radio: Insured / Std / NI / NA Eng/No: C/No: JHMGK3850HX200280 Gen. Condy Goog/ Fair / Poor / Burnt
Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: / Handa Jazz c.c 1318 Colour Placan A/C: Insured / Std / NI / NA Sp.Reading 5127. T/Radio: Insured / Std / NI / NA Eng/No: C/No: JHMGK3850HX200280
Steering: Inorder/ Jammed / Leaked / Burnt or Brake: Inorder/ Jammed / Leaked / Burnt or Modi: Nil S/Rim / STD A/Rim or Tyre Size: F: 2055 P46 R: 2055 P46 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front Rear R/Bal. 06 mm R/Bal. 06 mm L/Bal. 06 mm D.O.A. D.O.I. 05/09/8 Survey held at 200 N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.
Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: S+RS,_SI Interview (\$) Tech. Invs (\$) Weekend (\$) TOTAL 200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Α	IG ASIA PACIFIC INSURANC	CE DIE LID	nternationale Des E		
	· · · · · · · · · · · · · · · · · · ·	SEPTELID	Ref :	CS3/AIG1801	6156/Acd3
C	3 SHENTON WAY #08-16 HARTIS BUILDING NGAPORE 079120		Date :	04-09-2018	
4			Code:	AIG	
1.		Policy Partic	ulars :- (THIRD	PARTY CLA	IM)
_	Insured Veh. SJV 701	IB	Veh. Ins		SLP 644R
	Policy No.		Coverag		0.00
_	Claim No.		Excess		0.00
	Assign From CHIN LE	E YING	Assign [
		Vehicle	Particulars & C		04/09/2018
	Make & Model		c.c	ondition	STORY OF THE STORY
	Engine No. HIDDEN				0
	Chassis No.		Year of F	keg.	
	Odometer -		10,000,000		
	Brakes		Steering		
	General		Modificat	ion	
H S		0-			
	Size	Co	nditions of Tyre	9S	A STATE OF
	R/H Front Tyre		Make		Balance
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
T	L/H Rear Tyre				mm
					mm
		Descr	ription of Dama	ges	
	A. A. San Street Company	Market St.			
	Accident Date 01/09/2018	Gen	eral Informatio		
			Inspection	Date	05/09/2018
	0.55	KIT AVE 4# 05-23	3		
	Mepaner AIN YUN A	UTO PTE LTD			
1	A) THE INSPECTION WAS SEEN		Remarks		
- 1	A) THE INSPECTION WAS COM B) THE REPAIR ESTIMATE WA THE REPAIRER WAS TOLD TO C) ENCLOSED PLEASE FIND D	DDEDADE	LED AT THE TIME	OF INSPECTI	ON.

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE ...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Fong, Andy-SY, Fan, Winnie-LW

Sent: 4/9/2018 1:19:06 PM

Attachments: Police Report.pdf PRS Letter to AIG 03092018.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Regards, Lee Ying

From: pri@satwantlaw.com [mailto:pri@satwantlaw.com]

Sent: Tuesday, September 04, 2018 9:51 AM

To: Chan, Yoke Shi **Cc:** pri@satwantlaw.com

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJV701B AND

SLP644R ON 01/09/2018

Hi Yokeshi,

We have instructions to reject using your motor surveyor and propose using our surveyor, Sincere Appraisal Services.

Kindly see our attached letter and the workshop details as below:-

Workshop Name: Xin Yun Auto Private Limited

Address: Blk 8 Kaki Bukit Ave 4 #05-23 Premier @ Kaki Bukit (S) 415675

Contact No.: Yi Xin (9839 1555) / Fabian (9839 1666)

Kindly liaise directly with the workshop for the PRS on an urgent basis. Thank you.

Regards, Spencer

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2393Z
ehicle Details	
ehicle No.:	SLP644R
ehicle to be Exported:	No
ntended Deregistration Date:	11 Sep 2018
'ehicle Make:	HONDA
'ehicle Model:	JAZZ 1.3 CVT ABS D/AIRBAG 2WD
rimary Colour:	Purple
Manufacturing Year:	2016
ingine No.:	L13B11020200
Chassis No.:	JHMGK3850HX200280
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,462.00
Original Registration Date:	25 May 2017
irst Registration Date:	25 May 2017
ransfer Count:	0
Actual ARF Paid: DPC Cash Rebate Details	\$11,462.00
OPC Cash Rebate Eligibility:	No
DPC Cash Rebate Eligibility Expiry Date:	
OPC Cash Rebate Amount: ntended PARF Rebate Details	-
ARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2027
PARF Rebate Amount: ntended COE Rebate Details	\$8,596.00
COE Expiry Date:	24 May 2027
OE Category:	A - Car up to 1600cc & 97kW (130bhp)
OE Period(Years):	10
QP Paid:	\$34,600.00
COE Rebate Amount:	\$30,107.00
Total Rebate Amount:	\$38,703.00

The information contained herein is correct as at 11 Sep 2018

OK

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 04/09/2018 16:54

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 by the loagement of this report to the insurers, year aforesaid. 	ou hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	04/09/2018 16:39
Date Of Accident	02/09/2018 13:55
Exact Location Of Accident	BLK 9 TOH YI MSCP
Country/State of Loss	SINGAPORE
三位 200 N 100 N	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLP644R
Insured/Policyholder	
Name Of Registered Owner	WONG LOOK SING
NRIC No	S7072393Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84878882
Alternative Phone No	OTHERS-84878882
Vehicle Particulars	
Manufacturer	HONDA

HONDA

Model JAZZ 1.3 CVT ABS D/AIRBAG 2WD

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE-OFF PEAK

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5100584624

Cover Note Number

Driver

Name of Driver WONG LOOK SING

NRIC No S7072393Z Date Of Birth 02/01/1970 Occupation INDOOR Date Of Driving Pass 31/03/1999

Driving Experience 19 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-84878882

Fax Number

Contact Number OTHERS-84878882

EMail Address NOEMAIL Address

BLK 9 #09-325 TOH YI DRIVE

Postcode

590009

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT TIMAH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 1 TOH YI DRIVE , POSTCODE: 590001 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4689999 - FAX NO: 64623782

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20180902/2045

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJV701B

Vehicle Make/Model/Colour

TOYOTA COROLLA ALTIS

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KWAN WAI MENG

NRIC/Passport Number

S1502782G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 4

Driver's Signature (If driver is not the policyholder) Date & Time:

IDAC KAKI BUKIT(VAC) 23 KAKI BUKIT AVE 4 Singapore 415933

Tel: 67416697

Reporting Centre Personner Signature Numenial Lynckhaisingnet.com.sg

NRIC/FIN No.

0 4 SEP 2018

KETCH PLAN	Carpark lots
	[A]
A: SLP644R	
(Parking/ Stationary)	B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to public report	
CLARATION	

(pregoing particulars are true in every respect.

Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Reporting Centre Para 67492205 pre
Name: Email: vackb@singnet.com.sg

MRIC/FIN No.

0 4 SEP 2018

Fro	nt Portion	shoc warking			***	
NA	C INC		C	M	AC	Qt
-	01 99188	6 Frt Number Plate	B		V	QI,
-	02 99188	7 Frt Number Plate Base	B		V	
_	03 99188	9 Frt Number Plate Gamish				
	05 00234	0 Frt Bumper 1 Frt Bumper Clips	BI		V	
100	06 99132	Frt Bumper Clips Frt Bumper Bracket	No		V	
100	07 991462	2 Frt Bumper Side Retainer	BA	2	V	2
100	08 991433	3 Frt Bumper Reinforcement	-	-		
100	9 991318	B Frt Bumper Beam	B7		V,	
101	0 991468	Frt Bumper Sponge	B7	+	/	_
101	1 991427	Frt Bumper Protector	-	+		
101	2 991420	Frt Bumper Pad	+	+	-	
101	3 991363	Frt Bumper Grille	BR	-	/	
101	4 991301	Frt Bumper Moulding		7		
101	5 991407	Frt Bumper Lower Spoiler				
101		Frt Bumper Sensor				
101	8 001355	Frt LH Bumper Fog Lamp Cover				
101	9 995079	Frt RH Bumper Fog Lamp Cover Frt LH Bumper Fog Lamp	CF		/	
102	0 995080	Frt RH Bumper Fog Lamp	-	+	1	
102	1 991793	Frt Grille	Pr	-		
102	2 991328	Frt Grille Emblem	BR		/	-
102	3 991799	Frt Grille Chrome Moulding	BR		-	\dashv
102	4 991222	Frt Apron Panel	105	+	+	1.6
102	5 992013	Frt Support Panel	BT	1	7	
102	6 992025	Frt Support Panel Top Garnish Cover	BR	V	-	
102	/ 992416	Horn				
102	0 9912//	Frt Brace Panel Frt LH Headlamp Assy	-			
103	991821	Frt RH Headlamp Assy	BR	V	-	_
103	995088	Fr: LH Side Lamp	BR	V	4	_
1033	2 995089	Fri RH Side Lamp	+	+	+	-
103	990248	Bonnet	DD	2	1	\dashv
1034	991328	Bonnet Emblem	NEC	-	4	\neg
1033		Bonnet Lock	B7	V		
1030	990283	Bonnet Insulator				
1038	990273	Bonnet Hinge Bonnet Damper	BJ	V	4	2
1039	990305	Bonnet Rubber		-	1	_
1040	990252	Bonnet Cable	CuT	V	+	_
1041	990311	Bonnet Stand	DD	V	+	\dashv
1042	990119	Air Con Condenser	cut	1	+	-
1043	990122	Air Con Fan Assy	BR	V		\dashv
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	V	1	\exists
1045	1 990118	Air Con Suction Hose	BT	1	1	
1047	990133	Air Con Discharge Pipe (High Pressure)	B7 B7	V		
1048		Air Con Discharge Hose Air Con Liquid Pipe	BT	V		
1049	995066	Air Con Receiver Drier	-	-	1	_
1050		Air Con Compressor Assy	DD	V	+	\dashv
1051	995294	Air Con Belt		-	+	\dashv
1052	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Radiator	DD	V	+	-
1053	992738	Radiator Cowling	BR	V	1	-
1054	992742	Radiator Fan Assy				
1056	002759	Radiator Fan Clutch				
1057	992757	Radiator Hose Top Radiator Hose Bottom	Cut	V		
1058	992741	Radiator Expansion Tank	CUT	V		
1059	990151	Air Duct	-		-	_
1060	990070	Air Cleaner Assy	CR	~	-	_
1061	990056	Air Cleaner Hose	-		-	_
1062	990089	Air Cleaner Resonator		-	+	
1063	991712	rt Exhaust Manifold			+	-
1064	991713 1	rt Exhaust Manifold Cover			-	-
1065	991054	rt Exhaust Manifold Sensor (Oxygen)			-	
1066	991714 F	ront Exhaust Pipe		-	-	-
1067	990219 E	Battery		- #	-	-
1068		Battery Cover				
1000	990223 8	artery Bracket				
1070	290229 E	lattery Tray				

NAC	INC	Item	100	MIA	do
1071	99220.		_ 0	NA	CQ
1072	99401			-	+
1073			5.0		-
1074			BT	V	1_
1075	990159	Alternator Assy	-	\perp	1_
1076	990160		BR	V	
1077					
	992688				
1078	992669				
1079	994431	The state of the s			
1080	992692				
1081	990010	ABS Pump Control Unit		1	+
1082	990427	Brake Master Pump Assy		+	+
1083	990403	Brake Booster Pump Assy	_	+-	+
1084	991005	Engine Top Cover		+	╁
1085	991011	Engine Under Cover	to in	+	-
1086	990946	Engine Mounting	BR	1	-
1087	990949	Tarigate trie titting	+	-	-
1088	990950	Engine Mounting LH	-	1	2
1089	990952		BT	V	
1090-	990951		-	Γ.	
1091				-	
1091	001500	Gear Box Mounting		1	
1092	991520	Frt LH Chassis Member	BT	V	
	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member		1	
1096		Frt LH Fender	DD	V	
1097	995072	Frt LH Fender Inner Panel		1	
1098	995147	Frt LH Fender Lamp		+	
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	THI	1	
1101	995179	Frt LH Mudflap	1111	V	_
102	995170	Frt LH Wheel Rim			-
103	994025	Frt LH Rim Cover			-
104	995065	Frt LH Tyre	_	-	-
105	995071	Frt RH Fender	_		
106	991739	Frt RH Fender Inner Panel	-	\vdash	_
107	991744	Frt RH Fender Lamp	-		_
	991752	Frt RH Fender Protector			
109	991740	Frt RH Fender Inner Shield	100	-	
110	991884	Frt RH Mudflap			
111	992087	Frt RH Wheel Rim			_
112					
		Frt RH Rim Cover			
114		Frt RH Tyre			
	992093	Frt Windscreen Glass			
		Frt Windscreen Rubber			
	992108	Frt Windscreen Moulding	DU	1	2
	992098	Frt Windscreen Sealant			
		ERP Bracket			
		ERP Unit			
		Frt Wiper Arm			
		Frt Wiper Blade			
	995045	Wiper Panel Garnish	-	-	
123	991126	Firewall Panel		-	
		Dashboard Assy			-
		Glove Box Cover		-	
		Glove Box Compartment	-	-	-
_	994483	Steering Wheel Airbag	-	-	
-	994485	Steering Wheel All Co		_	
		Steering Wheel Airbay Sensor		-	
		Dashboard Airbag			
	990750	Dashboard Airbag Sensor	11		4
	990029	Airbag Control Unit	h	DOW	X
		Frt Driver Seat	1		1
	991922	Frt RH Seat Belt Assy	11		V
	91899	Frt Passenger Seat	7		1
35 9	95182	Frt LH Seat Belt Assy	\		-
		Sticker - 24	91	20	TB
				-	M

Tain


WW 24/9/18

MOTORCAR (Rear) (1)Replace (1) (2)Repairs (3)Check (7) (4)Not Consistent (RC)

271 -		Vehicle No: SLP 6			1
NAC			CON	AC	Q
1202	. 993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	_		
		Spare Tyre	-		
		Spare Tyre Lock Screw	-		
		Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
		CD Changer Assy			
1209		Antenna			
1210		Centre Exhaust Pipe Assy			
1211		Centre Exhaust Mounting			
		Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
		Rear LH Fender			
		Rear LH Fender Protector			
		Rear LH Fender Inner Panel			
		Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
		Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover		_	_
1227	995065	Rear LH Tyre		_	
		Rear RH Fender		_	
1229	993450	Rear RH Fender Protector	-	4	_
		Rear RH Fender Inner Panel		-	_
		Rear RH Fender Inner Trim		-	
1232	993415	Rear RH Fender Inner Garnish		-	_
1233	993423	Rear RH Fender Inner Shield Rear RH Mudflap	\vdash	-	_
1234	003024	Rear RH Wheel Rim		-	_
		Rear RH Rim Cover	\vdash	-	
1237	995065	Rear RH Tyre	\vdash	\dashv	_
1238	995162	Rear Fender Extension Panel LH	-	\dashv	_
1239	993401	Rear Fender Extension Panel RH		+	-
		Rear Fender Inner Top Garnish		\dashv	_
1241		Rear Fender 1/4 Glass		_	-
1242		Rear Fender 1/4 Glass Rubber		_	
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
		Rear Windscreen Rubber			
	993961	Rear Windscreen Moulding			
		Rear Windscreen Sealant			
		Third Brake Light			
		Rear Fender Air Grille			
		Fuel Lid	- 1		
		Fuel Neck			
		Fuel Tank			
		Fuel Tank Bracket			
		Fuel Tank Float			
1136	990247				
		more	N		
			1		
				\neg	
		, , ,			
		X4 9/201	8		

NAC	INC	Item	CON	AC	Qt
1137		Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	V	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	1		
1144		Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
		Rear Bumper Clips	MEC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BR.	/	
1150	993043	Rear Bumper Reinforcement Rear Bumper Beam	-		
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper	-		
1153		Rear Bumper Protector	-		_
	993036	Rear Bumper Pad	-		_
1155	993026	Rear Bumper Moulding	-	-	_
1156	993044	Rear Bumper Reflector	-		
1157	993023	Rear Bumper Lower Spoiler		-	
1158	994023	Reverse Sensor	SCR.	1	
1159	993327	Rear End Panel	DD.	1	-
1160	993339	Rear End Panel Top Garnish	BR	Ž	_
1161	993333	Rear End Panel Inner Trim	20	~	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	1	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	2		
1166	995116	Rear RH Taillamp	SCR	V	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1170	993334	Rear Apron Panel		-	_
		Bootlid Emblem		-	
1172	990356	Bootlid Handle		-	_
1173	995250	Bootlid Moulding		+	
1174	990376	Bootlid Reflector		\neg	
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177		Bootlid Lock	,		
1178	990377	Bootlid Rubber			
1179		Bootlid Hinge			
1180		Bootlid Spoiler	1		
1181		Tailgate	DD	/	
1182	991328	Tailgate Emblem	NEC	V	
1183	994643	Tailgate Outer Handle			
1185	994640	Tailgate Moulding			
1186	994343	Tailgate Garnish Tailgate Reflector		_	_
1187		Tailgate Lamp		-	_
1188		Tailgate Protector		-	_
1189	994676	Tailgate Wiper Arm		-	_
1190	994677	Tailgate Wiper Blade	-	+	-
1191	994679	Tailgate Wiper Nozzle		-	-
1192	994555	Tailgate Wiper Motor		-	-
1193	994602	Tailgate Glass .		-	_
1194		Tailgate Glass Rubber		-	_
1195	994604	Tailgate Glass Moulding	112.0		_
1196	994607	Tailgate Glass Sealant	NEC	V	-
1197	994629	Tailgate Cock	NEC	V	-
1198	994651	Tailgate Rubber	BT DIS	1	\dashv
1199	994611	Tailgate Hinge	NO	V	\dashv
1200	994594	Tailgate Damper		+	\dashv
1201		Tailgate Inner Board	BR	1	-
		- Sare milet Dodlo	DW.	/	

do of Items: 13	Assessor:	



Condition (CON) (01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

ALTIUNIALI (1)Replace (🗸) (4)Not Consistent (NC)


(2)Repair (X) (3)Check (?)

Undercarriage CON AC Qty NAC INC Item 995163 Frt LH Shock Absorber 1372 991944 Frt LH Shock Absorber Mounting 1373 MI 1374 990632 Frt LH Coil Spring 1375 | 995198 Frt LH Knuckle Arm 1376 995199 Frt LH Knuckle Arm Bearing JM 1377 995178 Frt LH Lower Arm 1378 | 995169 | Frt LH Upper Arm 1379 995183 Frt LH Tie Rod 1380 | 995143 | Frt LH Drive Shaft 1381 | 990661 | Frt LH Control Arm 1382 | 992062 | Frt LH Trailing Arm 1383 991848 Frt LH Leaf Spring 1384 991293 Frt LH Brake Disc Rotor 1385 991281 Frt LH Brake Caliper 1386 991292 Frt LH Brake Pipe 1387 991287 Frt LH Brake Hose 1388 991295 Frt LH Brake Sensor Wire 1389 991989 Frt Stay Bar Bracket 1390 994455 Steering Rack & Pinion 1391 994435 Steering Cross Member 1392 994519 Frt Sub Frame 1393 | 992003 | Frt Sub Frame Mounting 1394 991217 Frt Anti Roll Bar 1395 991219 Frt Anti Roll Bar Linkage 990887 Engine Block 1396 990890 Engine Block Gasket 1397 1398 990972 Engine Oil Sump 1399 990960 Engine Oil 1400 992224 Gear Box Assy 1401 992229 Gear Box Gasket 1402 992241 Gear Box Oil Sump 1403 | 992257 | Gear Oil 1210 990534 Centre Exhaust Pipe Assy 1211 990532 Centre Exhaust Mounting 1404 991134 Floor Panel 1405 993719 Rear LH Shock Absorber 1406 | 993723 | Rear LH Shock Absorber Mounting 1407 993170 Rear LH Coil Spring 1408 993550 Rear LH Knuckle Arm 1409 993551 Rear LH Knuckle Arm Bearing 1410 993597 Rear LH Lower Arm 1411 993884 Rear LH Upper Arm 1412 | 995161 | Rear L.H. Drive Shaft 1413 995216 Rear LH Control Arm 1414 993881 Rear LH Trailing Arm 1415 993573 Rear LH Leaf Spring 1416 992941 Rear LH Brake Disc Rotor 1417 992937 Rear LH Brake Caliper Assy 1418 990434 Rear LH Brake Pipe 1419 992946 Rear LH Brake Hose 1420 993819 Rear Sub Frame 1421 993820 Rear Sub Frame Mounting 1422 992813 Rear Anti Roll Bar 1423 | 990168 | Rear Anti Roll Bar Linkage 1424 | 990202 | Axle Beam 990170 Rear Axle Panhard Rod 1425 990810 Differential Assy 1426 1427 992706 Propeller Shaft

		Vehicle No: SLP 644 K Item	ટ `		_
NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting	CUT	/	
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing	JM	1	
1433	991851	Frt RH Lower Arm			
		Frt RH Upper Arm			
		Frt RH Tie Rod			
		Frt RH Drive Shaft			
		Frt RH Control Arm			
_		Frt RH Trailing Arm			\Box
		Frt RH Leaf Spring	1		
1440		Frt RH Brake Disc Rotor			
1441		Frt RH Brake Caliper	1		\vdash
			+		\vdash
		Frt RH Brake Pipe			\vdash
		Frt RH Brake Hose	-	-	\vdash
		Frt RH Brake Sensor Wire	-	-	\vdash
		Rear RH Shock Absorber	1	-	-
		Rear RH Shock Absorber Mounting	+	_	\vdash
		Rear RH Coil Spring		_	
		Rear RH Knuckle Arm		<u> </u>	
		Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft		1	
		Rear RH Control Arm			
		Rear RH Trailing Arm		-	
		Rear RH Leaf Spring			
		Rear RH Brake Disc Rotor			
		Rear RH Brake Caliper Assy		1	
		Rear RH Brake Pipe		1	
		Rear RH Brake Hose	_	T	\top
1433	332341	Real Ref Blake 11666		+	
	-		+	+	
	-		+	+	+
	-			+	+-
_	-	1 Atu		+	+
		months.	_	+	+
_	-	1 1		+	+
				+	+
				+	-
		=10/0/2018		+	-
		24/4/24/1	_	+	
		, , ,		1	
	1			\top	1
-		1	-	+	+
_	+	-	_	+	+
-	-		-	-	+
_	-		-	+	-
_	-		-	+	-
_	_			+	-
_			+	+	-
_	-		-	+	

No of Items:

Assessor:



Page 1 of 1 Merimen e-Claims

\dots CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUBFO	DLDER TRA	CKING							
Case N	otified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main 0:	3 Sep 2018 Edit Reg		04 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	1	0.00 ew Rpt		Pending for Surve Report Cancel Case	
М	ain	R	eference	Clai	m Details	\Box	Documents		Show All
CLAIM SUBI	FOLDER DE	TAILS				[Created	by adjuster]		
nsured:	KWAN WA	AI MENG, ID: S	1502782G						
Main Claimant:	=								
/ehicle Reg. No.:	SLP644I	R		Da	ate of Loss:		3 00:00 - :59 and 7 Days From L	TA Reg Date	(Man Yr)]
Claim Type:	TP / 084	9414020SG		77.54	olicy/Cover ote No.:	170008257	6 (Comprehensive)		
/ehicle Reg. Vo. Insured):	SJV701B				licy No. laimant):				
				Ex	cess:				
Repairer:	Xin Yun A	uto Pte Ltd (HQ) BLK 8 KAKI BUKIT	AVE 4 #05-23	PREMIER (@KAKI BUKIT	, 415675 Kaki Bukit	- Tel:	
fandling nsurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	ss) - Tel: 65-6	419-3000 .	[Handled b	y MdNoor, Norsiah] Norsiah.M	dNoor@aig.cor
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [H	andled by A	DRIAN LIN	G] [Final Rpt	due 13/09	/2018]
Claimant's Solicitor:	SATWANT	& ASSOCIATES	- Tel: 62216114						
SSOCIATE	D MAIL RE	CEIVED					View /	All Comp	ose Case Mail
AIG_SG (0	5/09/2018):	Request To Up	load TP GIA Repor	t					
ALL ASSOC	IATED TAS	ks⊟			10	View All S	earch Tasks Crea	ate New Task	Complete
Due Date No results.	Priority	Type Task	Group Subject	t Handler	Assign	ned By	Completed On	Created	On Done?
AIG_SG (0 ALL ASSOC Due Date	05/09/2018):	Request To Up			_		earch Tasks Crea	ate	

Merimen e-Claims Page 1 of 5

Claim Documents

*SLP644R (0849414020SG) [SJV701B] TP

> Sep 1 2018 12:00AM [KWAN WAI MENG] Xin Yun Auto Pte Ltd

Ass	essment Reports		1 per page	7
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbna	ail Print
1	05/09/18 10:17	Accident Statement From:OD - Reg. No: SJV701B, Claimant: KWAN WAI MENG	1 Load HTI	М
Pho	otos/Images		3 per page	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	ail Print
1	06/09/18 16:12	General View	1 Load JPC	3 🗸
2	06/09/18 16:12	General View	Load JPC	5 ⊻
3	06/09/18 16:12	General View	D Load JPC	3 🗸
4	06/09/18 16:12	General View	1 Load JPC	i 🗸
5	06/09/18 16:12	General View	1 Load JPC	3 2
6	06/09/18 16:12	General View	£ Load JPC	4
7	06/09/18 16:12	General View	1 Load JPC	3
8	06/09/18 16:12	General View	1 Load JPC	G 🗸
9	06/09/18 16:12	General View	1 Load JPC	5 V
10	06/09/18 16:12	General View	1 Load JPC	3 🗸
11	06/09/18 16:12	General View	1 Load JPC	V
12	06/09/18 16:12	General View	1 Load JPC	3 3
13	06/09/18 16:12	General View	1 Load JPC	3 V
14	06/09/18 16:12	General View	1 Load JPC	i 🗸
15	06/09/18 16:12	General View	£ Load JPC	3 V
16	06/09/18 16:12	General View	1 Load JPC	V
17	06/09/18 16:12	General View	1 Load JPC	· 🗸
18	06/09/18 16:12	General View	1 Load JPC	V
19	06/09/18 16:12	General View	1 Load JPC	i 🗸
20	06/09/18 16:12	General View	1 Load JPC	· 🗸
21	06/09/18 16:12	General View	1 Load JPC	V
22	06/09/18 16:12	General View	1 Load JPC	V
23	06/09/18 16:12	General View	1 Load JPC	V
24	06/09/18 16:12	General View	1 Load JPC	· 🗸
25	06/09/18 16:12	General View	1 Load JPC	· 🗸
26	06/09/18 16:12	General View	1 Load JPC	5 V
27	06/09/18 16:12	General View	1 Load JPC	
28	06/09/18 16:12	General View	1 Load JPC	-
29	06/09/18 16:12	General View	Load JPC	· •
30	06/09/18 16:12	General View	1 Load JPC	
31	06/09/18 16:12	General View	1 Load JPC	-
32	06/09/18 16:12	General View	■ Load JPC	
33	06/09/18 16:12	General View	■ Load JPC	dament .

Ass	essment Reports			_	¥
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbr	-	rin
34	06/09/18 16:12	General View	1 Load JF		V
35	06/09/18 16:12	General View	■ Load JP		V
36	06/09/18 16:12	General View	1 Load JF	_	✓
37	06/09/18 16:12	General View	1 Load JP	_	Y
38	06/09/18 16:12	General View	1 Load JP	_	4
39	06/09/18 16:12	General View	1 Load JF		~
40	06/09/18 16:12	General View	1 Load JF	G E	Y
41	06/09/18 16:12	General View	1 Load JP	_	V
42	06/09/18 16:12	General View	1 Load JP	G E	Y
43	06/09/18 16:12	General View	1 Load JP	G E	V
44	06/09/18 16:12	General View	1 Load JF	G E	4
45	06/09/18 16:12	General View	1 Load JF	G E	4
46	06/09/18 16:12	General View	1 Load JF	G E	V
47	06/09/18 16:12	General View	1 Load JF	G E	4
48	06/09/18 16:12	General View	1 Load JF	G E	V
49	06/09/18 16:12	General View	1 Load JF	G E	~
50	06/09/18 16:13	Photographs of Damaged Parts	Load JF	_	V
51	06/09/18 16:13	Photographs of Damaged Parts	Load 3F		~
52	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	-	V
53	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF		V
54	06/09/18 16:13	Photographs of Damaged Parts	■ Load JF		V
			1 Load JF		V
55	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	_	V
56	06/09/18 16:13	Photographs of Damaged Parts	The second secon		
57	06/09/18 16:13	Photographs of Damaged Parts		_	✓ ✓
58	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF		
59	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF		V
60	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	-	V
61	06/09/18 16:13	Photographs of Damaged Parts	■ Load JP		~
52	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	_	V
53	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP		Y
54	06/09/18 16:13	Photographs of Damaged Parts	€ Load JF	_	Y
65	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP		V
56	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G E	¥
57	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	_	V
58	06/09/18 16:13	Photographs of Damaged Parts	■ Load JP	G E	Y
59	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G E	V
70	06/09/18 16:13	Photographs of Damaged Parts	■ Load JP	G E	V
71	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G E	¥
72	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G E	V
73	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G E	V
74	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G E	V
75	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G E	V
76	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP		V
77	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G E	V
78	06/09/18 16:13	Photographs of Damaged Parts	Load JF		V
79	06/09/18 16:13	Photographs of Damaged Parts	Load JF		V
30	06/09/18 16:13	Photographs of Damaged Parts	Load JP	_	~
31	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF		V
32	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP		V
46	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	_	V

Ass	essment Reports		1 per page	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbr	
84	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	1 100
85	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
86	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	-
87	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
88	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🔽
89	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
90	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🗸
91	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🗸
92	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
93	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🗸
94	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
95	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🗸
96	06/09/18 16:13	Photographs of Damaged Parts	1 Load JF	G 🗸
97	06/09/18 16:13	Photographs of Damaged Parts	■ Load JF	
98	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
99	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
100	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
101	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
	NEVEL UNIT COST	100 10 107 1000 1000 000	1 Load JP	-
102	06/09/18 16:13	Photographs of Damaged Parts	D Load JP	
103	06/09/18 16:13	Photographs of Damaged Parts		
104	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	1000
105	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
106	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	1000
107	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	-
108	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
109	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
110	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
111	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
112	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🔽
113	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
114	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🔽
115	06/09/18 16:13	Photographs of Damaged Parts	■ Load JP	G 🔽
116	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🔽
117	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🔽
118	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
119	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
120	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗸
121	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
122	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
123	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
124	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
125	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
126			1 Load JP	
127	06/09/18 16:13	Photographs of Damaged Parts		
128	06/09/18 16:13	Photographs of Damaged Parts		
129	06/09/18 16:13	Photographs of Damaged Parts		
130	06/09/18 16:13	Photographs of Damaged Parts	Load JP	
131	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	-
132	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	
133	06/09/18 16:13	Photographs of Damaged Parts	1 Load JP	G 🗹

Assessment Repor	ts	1 per page	V	4
No Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		ASSESSMENT OF THE PARTY OF THE	Print
134 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	✓
135 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	✓
136 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	✓
137 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	✓
138 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
139 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
140 06/09/18 16:13	Photographs of Damaged Parts	€ Load	JPG	V
141 06/09/18 16:13	Photographs of Damaged Parts	€ Load	JPG	V
142 06/09/18 16:13	Photographs of Damaged Parts	€ Load	JPG	V
143 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
144 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
145 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
	Photographs of Damaged Parts		JPG	V
	SUSTRICT NO. WAYS TO VISION TO THE PROPERTY OF		JPG	V
147 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
148 06/09/18 16:13	Photographs of Damaged Parts			
149 06/09/18 16:13	Photographs of Damaged Parts		JPG	∀
150 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
151 06/09/18 16:13	Photographs of Damaged Parts		I JPG	✓
152 06/09/18 16:13	Photographs of Damaged Parts		JPG	~
153 06/09/18 16:13	Photographs of Damaged Parts		I JPG	V
154 06/09/18 16:13	Photographs of Damaged Parts		I JPG	✓
155 06/09/18 16:13	Photographs of Damaged Parts	1 Load	I JPG	~
156 06/09/18 16:13	Photographs of Damaged Parts	€ Load	JPG	V
157 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
158 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	✓
159 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
160 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	~
161 06/09/18 16:13	Photographs of Damaged Parts	€ Load	JPG	~
162 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	~
163 06/09/18 16:13	Photographs of Damaged Parts	■ Load	JPG	~
164 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	4
165 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	V
166 06/09/18 16:13	Photographs of Damaged Parts	₤ Load	JPG	V
167 06/09/18 16:13	Photographs of Damaged Parts		JPG	4
168 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	~
169 06/09/18 16:13	Photographs of Damaged Parts		JPG	~
170 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
171 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
172 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
173 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
	Photographs of Damaged Parts		JPG	<u>v</u>
The state of the s	participation of the property of the property of the property of the participation of the par		JPG	<u>v</u>
175 06/09/18 16:13	Photographs of Damaged Parts	- 46.		
176 06/09/18 16:13	Photographs of Damaged Parts		JPG JPG	√
177 06/09/18 16:13	Photographs of Damaged Parts		JPG IDG	V
178 06/09/18 16:13	Photographs of Damaged Parts		JPG I	V
179 06/09/18 16:13	Photographs of Damaged Parts	① Load		V
180 06/09/18 16:13	Photographs of Damaged Parts	1 Load		∀
181 06/09/18 16:13	Photographs of Damaged Parts	1 Load	_	~
182 06/09/18 16:13	Photographs of Damaged Parts		JPG	V
183 06/09/18 16:13	Photographs of Damaged Parts	1 Load	JPG	Y

Ass	essment Reports		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	-
184	06/09/18 16:13	Photographs of Damaged Parts	0	Load JPG	✓
185	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
186	24/09/18 18:18	Photo After Spray	0	Load JPG	☑
187	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
188	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
189	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
190	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
191	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
192	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
193	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
194	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
195	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
196	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
197	24/09/18 18:18	Photo After Spray	0	Load JPG	V
198	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
199	24/09/18 18:18	Photo After Spray	0	Load JPG	~
200	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
201	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
202	24/09/18 18:18	Photo After Spray	0	Load JPG	V
203	24/09/18 18:18	Photo After Spray	0	Load JPG	~
204	24/09/18 18:18	Photo After Spray	0	Load JPG	V
205	24/09/18 18:18	Photo After Spray	0	Load JPG	✓
206	24/09/18 18:18	Photo After Spray	0	Load JPG	~
207	24/09/18 18:18	Photo After Spray	0	Load JPG	V
208	24/09/18 18:18	Photo After Spray	0	Load JPG	~
209	24/09/18 18:18	Photo After Spray	0	Load JPG	V
210	24/09/18 18:18	Photo After Spray	0	Load JPG	V
211	24/09/18 18:18	Photo After Spray	0	Load JPG	~

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18016156/ACD3E2

Date:

27/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700082576

Claimant Vehicle

SLP644R

Insured Vehicle No:

SJV701B

No: Date of Loss:

01/09/2018

Nature of Claim:

TP

Claim No: 0849414020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLP644R

Make & Model:

HONDA JAZZ, 1.3 CVT (A) 25/05/2017 (Man. Year: 2016) Engine No: Chassis No: L13B11020200

Reg. Date: Colour:

Maroon

Odometer:

JHMGK3850HX200280 5127 km

Engine Capacity:

1318 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Yokohama 6 mm

Rear Left Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

Front Right Side: Yokohama 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

04/09/2018

Date Inspected:

05/09/2018 Inspected At:

Xin Yun Auto Pte Ltd (HQ)

BLK 8 KAKI BUKIT AVE 4 #05-23

PREMIER @KAKI BUKIT

Singapore 415675

Estimated Period of Repair:

15.0 days

CELINE FONG Adjuster: **ADRIAN LING** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

	eco	mm	on	40	4 [201	+0
\Box	eco	11111	IEII	ue	uг	aı	LO

No.	Qty Part No	. Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1	*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1	*FRT BUMPER	Broken	0.00 F	*-F
1	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	2	*FRT BUMPER BRACKET	Broken	0.00 F	*- F
3	1	*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1	*FRT BUMPER BEAM	Bent	0.00 F	*- F
3	1	*FRT BUMPER GRILLE	Broken	0.00 F	*- F
9	1	*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*-F
10	1	*FRT GRILLE	Broken	0.00 F	*- F
11	1	*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
12	1	*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F
13	1	*FRT SUPPORT PANEL	Bent	0.00 F	*-F
14	1	*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*- F
					*-F
15	1	*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
16	1	*FRT RH HEADLAMP ASSY	Broken	0.00 F	
17	1	*BONNET	Dented	0.00 F	*-F
18	1	*BONNET EMBLEM	Necessary	0.00 F	*- F
19	1	*BONNET LOCK	Bent	0.00 F	*-F
20	1	*BONNET HINGE	Bent	0.00 F	*- F
21	1	*BONNET RUBBER	Cut	0.00 F	*- F
22	1	*BONNET CABLE	Dented	0.00 F	*-F
23	1	*AIR CON CONDENSER	Cut	0.00 F	*- F
24	1	*AIR CON FAN ASSY	Broken	0.00 F	*- F
25	1	*AIR CON SUCTION PIPE (LOW PRESSURE)	Bent	0.00 F	*- F
26	1	*AIR CON SUCTION HOSE	Bent	0.00 F	*- F
27	1	*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Bent	0.00 F	*- F
28	1	*AIR CON DISCHARGE HOSE	Bent	0.00 F	*- F
29	1	*AIR CON RECEIVER DRIER	Dented	0.00 F	*- F
30	1	*RADIATOR	Dented	0.00 F	*- F
31	1	*RADIATOR COWLING	Broken	0.00 F	*-F
32	1	*RADIATOR HOSE TOP	Cut	0.00 F	*-F
33	1	*RADIATOR HOSE BOTTOM	Cut	0.00 F	*- F
34	1	*AIR DUCT	Cracked	0.00 F	*- F
35	1	*WIPER WASHER TANK	Bent	0.00 F	*-F
36	1	*ALTERNATOR ASSY	Broken	0.00 F	*-F
37	1	*ENGINE UNDER COVER	Broken	0.00 F	*- F
38	Č.	*ENGINE MOUNTING LH	Bent	0.00 F	*- F
	1		To Post of the Pos		*-F
39	1	*FRT LH CHASSIS MEMBER	Bent	0.00 F	
40	1	*FRT LH FENDER	Dented	0.00 F	*-F
41	1	*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
42	2	*FRT WINDSCREEN MOULDING	Dislodged	0.00 F	*-F
43	1	*REAR BUMPER	Dented	0.00 F	*-F
44	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
45	1	*REAR BUMPER SIDE RETAINER LH	Broken	0.00 F	*- F
46	1	*REVERSE SENSOR	Scratched	0.00 F	*- F
47	1	*REAR END PANEL	Dented	0.00 F	*-F
48	1	*REAR END PANEL TOP GARNISH	Broken	0.00 F	*-F
49	1	*REAR LH TAILLAMP	Broken	0.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
51	1		*TAILGATE	Dented	0.00 F	*- F
52	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
53	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
54	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
55	1		*TAILGATE LOCK	Bent	0.00 F	*- F
56	1		*TAILGATE RUBBER	Distorted	0.00 F	*-F
57	1		*TAILGATE INNER BOARD	Broken	0.00 F	*- F
58	1		*FRT LH SHOCK ABSORBER MOUNTING	Cut	0.00 F	*- F
59	1		*FRT LH KNUCKLE ARM BEARING	Jammed	0.00 F	*- F
60	1		*FRT LH LOWER ARM	Bent	0.00 F	*-F
61	1		*FRT RH SHOCK ABSORBER MOUNTING	Cut	0.00 F	*- F
62	1		*FRT RH KNUCKLE ARM BEARING	Jammed	0.00 F	*-F
F=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >