


Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 10 DEC 2017 AT ABOUT 1530 HRS I WAS DRIVING MY VEHICLE SLS6565E ALONG ORCHARD ROAD. I WAS FOLLOWING BEHIND VEHICLE B - SLS4348D WITH SAFELY DISTANCE. WE WERE TRAVELLING ON LANE 5. SUDDENLY VEHICLE B MADE AN EMERGENCY BRAKE AND STOPPED IN THE MIDDLE OF THE ROAD. I ALSO APPLIED E-BRAKE BUT COULDN'T STOP AS FAST. AND COLLIDED ON VEHICLE B. AT THAT POINT, I REALISED VEHICLE C MADE A LANE CHANGE FROM LANE 5 TO LANE 6, VEHICLE C DID NOT COMPLETE THE LANE CHANGE.

I WAS UNABLE TO MAKE THIS REPORT ON 11 DEC 17 WAS DUE TO WORK COMMITMENT AND MEETING APPOINTMENTS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	20 Jan 2004
---------	--	-------------

NP 428A




LONPAC INSURANCE BHD (598FC6836C)

 (Incorporated in Malaysia)
 Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199580.
 Tel: (65) 6250 7360 Fax: (65) 3296 3707 Website: www.lonpac.com.sg
 GST Reg No.: P9-0066635-C

MX1

CERTIFICATE OF INSURANCE

 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION ACT (CAP 189) REPUBLIC OF SINGAPORE,
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE),
 ROAD TRANSPORT ACT 1987 (MALAYSIA),
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No.	: 7/17/VP05/014593-001	Type of Cover	: COMPREHENSIVE
1. Index Mark and Vehicle Registration Number	FIAT - NLS 6565F		
2. Name of Policy Holder	LIN KEE HOU JOHNATHAN		
3. Effective date of the Commencement of Insurance for the purpose of the Act.	21/08/2017		
4. Date of Expiry of the Insurance	08/08/2018		
5. Persons or Classes of Persons entitled to drive.	(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6. Limitations as to use	USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.		
Excess	S\$ 0.00 (SECTION 1) INSURED / NAMED DRIVERS S\$ 1000.00 (SECTION 1) UNNAMED DRIVERS S\$ 3000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS S\$ 100.00 WINDSCREEN EXCESS		
Condition	: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS		

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

We hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : HONG LEONG FINANCE LIMITED

CHIEF EXECUTIVE
(Singapore Branch)

User ID : edinyeo / hazochee
Date issued : 30-06-2017

7-88186-1 Part 17/08/2018/014593-001

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131

Report No: 0474-18-N51

30 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLS4348D	<i>Odometer:</i>	19088km
<i>Make & Model:</i>	Toyota Prius Alpha 1.8A	<i>Colour:</i>	Silver
<i>Chassis number:</i>	ZVW400026200	<i>Date of accident:</i>	10/12/2017
<i>Year of Regn.:</i>	25/09/2017	<i>Date inspected:</i>	12/12/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	18/12/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Report No: 0474-18-N51

30 July 2018

ACCIDENT VEHICLE SURVEY REPORT

Darwin-51 Car Rental Pte Ltd
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SLS4348D	Odometer:	19088km
Make & Model:	Toyota Prius Alpha 1.8A	Colour:	Silver
Chassis number:	ZVW400026200	Date of accident:	10/12/2017
Year of Regn.:	25/09/2017	Date inspected:	12/12/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	18/12/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Yokohama	5mm/Yokohama	205/60R16
Rear:	5mm/Yokohama	5mm/Yokohama	205/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

SLS 2339 T

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BUMPER	1	squashed	350.00	350.00 DD✓
REAR BUMPER INNER SIDE SHIELD CLIPS L/R	6	necessary	39.00	39.00 NEC✓
REAR BUMPER INNER SIDE SHIELD L/R	1 2	warped - LH	342.80 171.40	342.80 BR✓
REAR BUMPER REFLECTOR L/R	1 2	fractured LH	264.50 132.25	264.50 BR✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	120.00	120.00 NEC✓
REAR END PANEL	1	buckled	781.45	781.45 DD✓
REAR END PANEL INNER TOP GARNISH	1	fractured	210.00	210.00 CUT
REAR END PANEL INNER TOP GARNISH CLIPS	4	necessary	26.00	26.00 NEC✓
REAR END PANEL LOCK STRIKER	1	bent	61.10	61.10 BT ✓ XND
REAR EXHAUST GASKET	1	necessary	30.00	30.00 NEC✓ XND
REAR EXHAUST RUBBER MOUNTING	2	distorted	70.00	70.00 } SVC X
REAR EXHAUST SILENCER BOX	1	bent	790.00	790.00 } SVC X
REAR FENDER INNER TRIM BOARD L/R @663.30	2	fractured	1,563.80 1,326.40	1,563.80 CUT ✓
REAR SPARE TYRE PANEL	1	repair	1,245.10	0.00
REAR SPARE TYRE PANEL INNER TOP STORAGE BOX	1	deformed	645.80	645.80 CUT ✓
REAR SPARE TYRE PANEL TOP UPHOLSTERY BOARD	1	deformed	381.55	381.55 SVC
REAR SPARE TYRE SIDE PANEL L/R	2	repair	696.60	0.00
REAR SPARE TYRE SIDE PANEL LH TOP STORAGE BOX	1	deformed	295.10	295.10 } SVC X
RR SPARE TYRE SIDE PANEL LH TOP UPHOLSTERY BOARD	1	deformed	481.40	481.40 } SVC X
REAR SUB CHASSIS FRAME L/R	2	repair	1,560.70	0.00
REAR TAILGATE	1	buckled	580.00	580.00 DD✓
REAR TAILGATE 'HYBRID' EMBLEM	1	necessary	121.35	121.35 } NEC✓
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	61.10	61.10 } NEC✓
REAR TAILGATE 'PRIUS' EMBLEM	1	necessary	50.00	50.00 } NEC✓
REAR TAILGATE DAMPER L/R	2	bent	320.00	320.00 SVC X
REAR TAILGATE HINGES L/R	2	bent	160.00	160.00 } SVC X
REAR TAILGATE INNER HANDLE	1	warped	123.05	123.05 } SVC X
REAR TAILGATE INNER TRIM BOARD	1	fractured	781.10	781.10 } SVC X
REAR TAILGATE MECHANISM LOCK	1	bent	320.00	320.00 } SVC X
REAR TAILGATE NUMBER PLATE LAMP L/R	2	fractured	460.96	460.96 BR ✓ XND
REAR TAILGATE OUTER GARNISH	1	fractured	365.00	365.00 NN X
REAR TAILGATE OUTER GARNISH CLIPS	4	necessary	26.00	26.00 NEC✓
REAR TAILGATE OUTER LOCK HANDLE SWITCH	1	shorted	245.30	245.30 CUT ✓
REAR TAILGATE RUBBER GUIDE STOPPER	2	deformed	60.00	60.00 NN X
REAR TAILGATE WEATHERSTRIP	1	deformed	195.00	195.00 CUT ✓
REAR TAILGATE WINDSCREEN INNER GARNISH 'CENTER'	1	fractured	195.00	195.00 CUT ✓ XND
REAR TAILGATE WINDSCREEN INNER GARNISH L/R	2	fractured	224.00	224.00 CUT ✓ XND
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	178.85	178.85 NEC✓
REAR TAILGATE WIPER ARM	1	reuse	165.00	0.00
REAR TAILGATE WIPER ARM COVER	1	reuse	75.00	0.00
REAR TAILGATE WIPER ARM MOTOR	1	shorted	445.20	445.20 SVC X
REAR TAILLAMP BACK RUBBER GASKET L/R	2	necessary	50.00	50.00 NEC ✓ XND

6280.20

REAR TAILLAMP CLIPS L/R	8	necessary	52.00	52.00	NECV
REAR TAILLAMP INNER PANEL L/R	2	repair	749.70	0.00	
REAR TAILLAMP L/R	2	fractured	760.00	760.00	BRV
REAR TAILLAMP LOWER BRACKET L/R	2	bent	92.00	92.00	BTXNN
Subtotal before discount			S\$ 16,810.51	S\$ 12,318.41	7184.20
Percentage discount 25% and 25%			S\$ 4,202.63	S\$ 3,079.60	1796.05
Sub-total 1			S\$ 12,607.88	S\$ 9,238.81	5,388.15
ANTENNA SENSOR	1	shorted	380.00	380.00	SVCX
Subtotal before discount			S\$ 380.00	S\$ 380.00	
Percentage discount 10% and 10%			S\$ 38.00	S\$ 38.00	
Sub-total 2			S\$ 342.00	S\$ 342.00	
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00	NECV
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00	CUTV
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	necessary	60.00	60.00	NECV
REAR SPARE TYRE PANEL INSULATOR MAT	1	necessary	350.00	350.00	NECV
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00	NECV
REAR TAILGATE NUMBER PLATE	1	bent	25.00	25.00	NNX
REAR TAILGATE NUMBER PLATE HOLDER	1	bent	50.00	50.00	
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	800.00	SVCX
REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET	1	necessary	30.00	30.00	
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	SD
Subtotal before discount			S\$ 1,845.00	S\$ 1,845.00	950.00
Sub-total 3			S\$ 1,845.00	S\$ 1,845.00	950.00
Parts-total			S\$ 14,794.88	S\$ 11,425.81	5730.15

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00	50.00	80.00	
To remove, reinstall tailgate windscreen	300.00	20.00	120.00	120
To remove, reinstall rear suspension and undercarriage part. (to FR)	450.00		0.00	
To road test driving, check and resetting wheel alignments system.	180.00		0.00	
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00		60.00	
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	2,000.00		1,320.00	600.00 + 300 X
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	80.00	120.00	X
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,750.00		1,250.00	600 + 200 X
To mount vehicle on to Car 'O' Liner.	400.00		400.00	NNX
To apply anti-rust chemical on repaired and replaced panel.	120.00	50.00	90.00	
Labour Total	SS 6,620.00	SS 3,440.00		1520.00
Parts & Labour Total	SS 21,414.88	SS 14,865.81		7250.15

PAR Automotive Consultancy

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 12,600.00
and the recommended number of working days for the repairs is within 9 day(s).



B J Loi (I Eng., MIMI, AIRTE)

Automotive Appraiser

L/S 5,800/2

Repair days 7

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC17023528/Bvd3s2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 26-09-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 6565E	Veh. Inspected	SLS 4348D
Policy No.		Coverage (\$)	0.00
Claim No.	17/17/17/VP05/020268	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW400026200	Colour	SILVER
Odometer	19088	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	YOKOHAMA	4 mm
L/H Front Tyre	205/60R16	YOKOHAMA	4 mm
R/H Rear Tyre	205/60R16	YOKOHAMA	4 mm
L/H Rear Tyre	205/60R16	YOKOHAMA	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/12/2017	Inspection Date	12/12/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 4348D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	350.00	350.00
6	REAR BUMPER INNER SIDE SHIELD CLIPS L/R	NECESSARY	39.00	39.00
2	REAR BUMPER INNER SIDE SHIELD L/R	N/S BROKEN	342.80	171.40
2	REAR BUMPER REFLECTOR L/R	N/S BROKEN	264.50	132.25
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	120.00	120.00
1	REAR END PANEL	DENTED	781.45	781.45
1	REAR END PANEL INNER TOP GARNISH	CUT	210.00	210.00
4	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	26.00	26.00
1	REAR END PANEL LOCK STRIKER	NOT NECESSARY	61.10	-
1	REAR EXHAUST GASKET	NOT NECESSARY	30.00	-
2	REAR EXHAUST RUBBER MOUNTING	SERVICEABLE	70.00	-
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	790.00	-
2	REAR FENDER INNER TRIM BOARD L/R	CUT	1,563.80	1,326.60
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,245.10	-
1	REAR SPARE TYRE PANEL INNER TOP STORAGE BOX	CUT	645.80	645.80
1	REAR SPARE TYRE PANEL TOP UPHOLSTERY BOARD	SERVICEABLE	381.55	-
2	REAR SPARE TYRE SIDE PANEL L/R	TO REPAIR SEE LABOUR	696.60	-
1	REAR SPARE TYRE SIDE PANEL LH TOP STORAGE BOX	SERVICEABLE	295.10	-
1	RR SPARE TYRE SIDE PANEL LH TOP UPHOLSTERY BOARD	SERVICEABLE	481.40	-
2	REAR SUB CHASSIS FRAME L/R	TO REPAIR SEE LABOUR	1,560.70	-
1	REAR TAILGATE	DENTED	580.00	580.00
1	REAR TAILGATE 'HYBRID' EMBLEM	NECESSARY	121.35	121.35
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	61.10	61.10
1	REAR TAILGATE 'PRIUS' EMBLEM	NECESSARY	50.00	50.00
2	REAR TAILGATE DAMPER L/R	SERVICEABLE	320.00	-
2	REAR TAILGATE HINGES L/R	SERVICEABLE	160.00	-
1	REAR TAILGATE INNER HANDLE	SERVICEABLE	123.05	-
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	781.10	-
1	REAR TAILGATE MECHANISM LOCK	SERVICEABLE	320.00	-
2	REAR TAILGATE NUMBER PLATE LAMP L/R	NOT NECESSARY	460.96	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	365.00	-

Report Ref No. CS3/LPC17023528/Bvd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR TAILGATE OUTER GARNISH CLIPS	NECESSARY	26.00	26.00
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH	CUT	245.30	245.30
2	REAR TAILGATE RUBBER GUIDE STOPPER	NOT NECESSARY	60.00	-
1	REAR TAILGATE WEATHERSTRIP	CUT	195.00	195.00
1	REAR TAILGATE WINDSCREEN INNER GARNISH 'CENTER'	NOT NECESSARY	195.00	-
2	REAR TAILGATE WINDSCREEN INNER GARNISH L/R	NOT NECESSARY	224.00	-
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	178.85	178.85
1	REAR TAILGATE WIPER ARM	REUSE	165.00	-
1	REAR TAILGATE WIPER ARM COVER	REUSE	75.00	-
1	REAR TAILGATE WIPER ARM MOTOR	SERVICEABLE	445.20	-
1	REAR TAILLAMP BACK RUBBER GASKET L/R	NOT NECESSARY	50.00	-
8	REAR TAILLAMP CLIPS L/R	NECESSARY	52.00	52.00
2	REAR TAILLAMP INNER PANEL L/R	TO REPAIR SEE LABOUR	749.70	-
2	REAR TAILLAMP L/R	BROKEN	760.00	760.00
2	REAR TAILLAMP LOWER BRACKET L/R	NOT NECESSARY	92.00	-
	LESS 25% DISCOUNT		-4,202.63	-1,518.02
			12,607.88	4,554.08
	NETT ITEMS			
1	ANTENNA SENSOR (N)	SERVICEABLE	380.00	-
	LESS 10% DISCOUNT		-38.00	-
			342.00	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	CUT	350.00	200.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R (SN)	NECESSARY	60.00	40.00
1	REAR SPARE TYRE PANEL INSULATOR MAT (SN)	NECESSARY	350.00	180.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE REVERSE CAMERA (SN)	SERVICEABLE	800.00	-
1	SET REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
			1,845.00	540.00

Report Ref No. CS3/LPC17023528/Bvd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	50.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	120.00
	TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART. (TO FR)	NOT NECESSARY	450.00	-
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		2,000.00	900.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL, REAR SPARE TYRE SIDE PANEL L/R, REAR SUB CHASSIS FRAME L/R AND REAR TAILLAMP INNER PANEL L/R.		2,750.00	800.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	50.00
			6,620.00	1,980.00
	GRAND TOTAL		21,414.88	7,074.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,650.00

Report Ref No. CS3/LPC17023528/Bvd3s2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.