

Trans-cab Auto Services Pte Ltd

AAD1809-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

Not Notarized
Recovery By paint

Vehicle No.:

SHD 721L

Chassis No.:

VF1ABL15AUC283314

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident:

1.9.2018

Third Party Insurer:

AXA**PART****LIST**

1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66	—
1	FENDER PANEL REAR LH	\$	<i>B</i> 3,299.13	—
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45	X
1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	X
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sn</i> 466.51	X
1	ROCKER PANEL INNER LH	\$	<i>n</i> 1,024.79	X
1	ROCKER PANEL CENTER LH	\$	<i>n</i> 990.25	X
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	} X
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	
1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
1	BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	
1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	
1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95	
1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43	

\$ 14,694.03

10% **\$ 1,469.40**

\$ 13,224.63

Special Nett

1	REAR DOOR STICKER '6555 3333'	\$	<i>n</i> 80.00	<i>base</i>
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	X
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85	X

\$33,587.12

Trans-cab Auto Services Pte Ltd**AAD1809-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

1	DOOR HINGE BOLT	\$	nn	10.85	}	X
1	DOOR HINGE NUT RH	\$	nn	14.60		
1	DOOR CHECK BOLT	\$	sn	22.69		
1	DOOR CHECK NUT	\$	sn	3.75		
1	DOOR LOCK SCREW L70Y	\$	sn	6.12		
1	DOOR CATCH SCREW L70Y	\$	sn	10.06		
1SET	PARKING AID	\$	sn	700.00	}	
1SET	REAR BUMPER CLIP	\$	nn	66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	}	X
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00		
1SET	BUMPR RETAINER RH CLIP RR	\$	nn	20.00		
1SET	BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00		
1SET	BUMPR RETAINER CLIP LH RR	\$	nn	20.00		
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00		

TOTAL	\$	1,128.63
--------------	-----------	-----------------

TOTAL PARTS	\$	14,353.26
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	12001
Putty and spray painting of the affected portion.	\$	3,000.00	8801
To rust-proofing of the affected areas.	\$	170.00	901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 721L

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$ ~ ~ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 380.00 601

Towing Fees.

\$ 120.00 301

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ ~ ~ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ ~ ~ 380.00 X

TOTAL \$ 9,130.00

Over All Total \$ 23,483.26

Part - By - Part

(REPAIR DAY)**10 DAYS**

33,587.12A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: