

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6639M

DATE 5/9/2018 10:35

MAKE :

*AXIA
Left Front*

Fauzy *FZ*

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 544.50
	Front Bumper Sponge ?			\$ 99.20
	Front Bumper Reinforcement ?			\$ 402.10
	Front Bumper Grille (LH) <i>X</i>			\$ 41.60
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) <i>X repair</i>			\$ 566.30
	Front Fender Shield (LH) <i>X</i>			\$ 175.90
	Front Fender Retainer <i>X</i>			\$ 24.60
	Frnt Wheel Hub Cap, LH <i>X</i>			\$ 107.10
	<i>Front LH Headlamp -</i>			
	SUB TOTAL			\$ 2,008.30
	LESS 20%			\$ 401.66
	DISCOUNTED TOTAL			\$ 1,606.64
	Front Number Plate <i>X</i>			\$ 25.00 Nett
	Front No Plate Trim Cover <i>X</i>			\$ 30.00 Nett
	Front Fender Advertisement Logo (LH) <i>✓</i>			\$ 100.00 Nett
				\$ 155.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>200</i>
	Spray Painting Charge			\$ 500.00 <i>400</i>
	Wiring			\$ 50.00 <i>200</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Towing Fees			\$ 60.00 <i>✓</i>
	Frnt Wheel Alignment			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 1,300.00
	ESTIMATE TOTAL			\$ 3,061.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged part(s) during spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kaluh LKK
5/9/18 1350 hrs
2 Reps
L/S
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.