

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7661R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT FENDER LINER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LINER LH	SERVICEABLE	47.00	-
1	FRONT FENDER LINER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT BUMPER	BUCKLED / CRACKED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	356.00	356.00
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	DENTED	78.00	78.00
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	-
1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	-
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	-
1	BONNET	BUCKLED	1,250.00	1,250.00
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	36.00	-
1	BONNET MOULDING	DENTED	161.97	161.97
1	BONNET LOCK	BENT	60.00	60.00
1	BONNET CABLE	JAMMED	125.00	125.00
1	FRONT SUPPORT PANEL ASSY	BUCKLED	1,222.32	1,222.32



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	HEADLAMP RH	MTG CRACKED	816.00	816.00
1	HEADLAMP LH	MTG CRACKED	816.00	816.00
1	WINDSCREEN WASHER TANK - FILLER NECK	SERVICEABLE	4.80	-
1	WINDSCREEN WASHER TANK	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	51.00	-
1	WASHER TANK HOSE	SERVICEABLE	21.00	-
1	RADIATOR ASSEMBLY	BENT	618.00	618.00
1	RADIATOR UPPER HOSE	SERVICEABLE	30.00	-
1	RADIATOR LOWER HOSE	SERVICEABLE	120.00	-
1	RADIATOR GRILLE (GRILLE A-RAD)	CRACKED	367.00	367.00
1	RADIATOR GRILLE TOP COVER	DISTORTED	45.02	45.02
1	FAN BLADE (A/C)	CRACKED	536.00	536.00
1	FAN BLADE (RADIATOR)	SERVICEABLE	634.00	-
1	AIRCON CONDENSER	PUNCTURE	600.00	600.00
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	450.00	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	624.00	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	580.00	-
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	450.00	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	624.00	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	580.00	-
1	AIRCON COMPRESSOR - PUMP	SERVICEABLE	1,847.95	-
1	AIRCON COMPRESSOR BRACKET	TO REPAIR SEE LABOUR	245.30	-
1	AIRCON CONDENSER BOTTOM BUSHING	SERVICEABLE	119.00	-
1	AIR CLEANER ASSEMBLY (CLEANER A-AIR)	SERVICEABLE	112.00	-
1	AIR FILTER (ELEMENT A-AIR CLEANER)	SERVICEABLE	39.00	-
1	AIR-CLEANER INTAKE DUCT	SERVICEABLE	89.25	-
1	AIR-CLEANER INTAKE DUCT HOSE (TOP)	SERVICEABLE	75.85	-
1	AIR INTAKE RESONATOR TOP (SQUARE)	SERVICEABLE	14.52	-
1	AIR INTAKE RESONATOR (BESIDE FENDER)	SERVICEABLE	20.01	-
1	AIR INTAKE RESONATOR HOSE (BOTTOM)	SERVICEABLE	60.90	-
1	AIR INTAKE RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	45.00	-
1	RESONATOR A-A/CL	SERVICEABLE	137.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Estimate By Our Adjusted Condition Qty **Description of Parts** Workshop (\$)) (\$) **SERVICEABLE** 1,040.00 1 ALTERNATOR ASSEMBLY 1 BATTERY (BATTERY A) **SERVICEABLE** 405.00 BATTERY TRAY **SERVICEABLE** 65.00 TO REPAIR SEE 1 BATTERY FASTENER BRACKET 23.50 **LABOUR** 1 BATTERY FASTENER BOLT SERVICEABLE 46.00 1 FRONT FUSE BOX (SUPPORT PANEL TOP) **SERVICEABLE** 215.00 1 FRONT FUSE TOP COVER SERVICEABLE 25.00 **SERVICEABLE** 716.00 1 FUSE BOX 1 FUSE BOX TOP (COVER) **SERVICEABLE** 250.00 1 FUSE BOX LOWER **SERVICEABLE** 60.00 1 FUSE BOX CENTRE COVER 380.00 **SERVICEABLE** 1 ENGINE MAIN HARNESS WIRE **SERVICEABLE** 1.500.00 1 GEAR BOX ASSY **SERVICEABLE** 20,800.00 1 CROSS MEMBER **SERVICEABLE** 1,030.71 1 GEAR BOX CROSS MEMBER BRACKET TO REPAIR SEE 450.00 LABOUR 1 GEAR BOX MOUNTING RH **SERVICEABLE** 142.50 1 ENGINE BLOCK **SERVICEABLE** 28,895.40 1 ENGINE MOUNTING SIDE **SERVICEABLE** 175.00 1 ENGINE LOWER SPLASHIELD COVER **SERVICEABLE** 240.00 1 FRONT CENTRE CROSS MEMBER **SERVICEABLE** 763.50 1 FRONT CENTRE MEMBER (MEMBER A-FRT SUSP, CTR) TO REPAIR SEE 265.63 LABOUR 1 ENGINE SUSPENSION CROSS MEMBER TO REPAIR SEE 344.07 LABOUR 1 ENGINE OIL SUMP **SERVICEABLE** 500.00 1 ENGINE OIL SUMP STRAINER **SERVICEABLE** 125.60 1 ENGINE OVERHAUL GASKET **SERVICEABLE** 98.70 1 ENGINE OIL SUMP SEALANT **SERVICEABLE** 45.00 1 ENGINE SPLASH COVER RH (COVER A-ENGINE) **SERVICEABLE** 168.00 1 ENGINE SPLASH COVER LH (COVER A-ENGINE) SERVICEABLE 168.00 1 ECU ASSY **SERVICEABLE** 4,575.65 1 ABS PUMP **SERVICEABLE** 5,547.45



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	ABS PUMP PIPE	SERVICEABLE	325.33	-
1	STEERING RACK & PINION ASSY (GEAR A-STRG)	SERVICEABLE	905.51	-
1	STEERING RACK END (SPRING A-CLOCK)	SERVICEABLE	88.56	-
1	STEERING TIE-ROD END (END - TIE ROD)	SERVICEABLE	67.00	-
1	STEERING WHEEL ASSY (WHEEL A-STRG)	SERVICEABLE	258.41	-
1	POWER STEERING PUMP	SERVICEABLE	1,755.31	-
1	POWER STEERING RESERVOIR TANK	SERVICEABLE	120.00	-
1	POWER STEERING INLET / OUTLET PIPE	SERVICEABLE	65.00	-
1	POWER STEERING PUMP PULLEY	SERVICEABLE	66.00	-
1	POWER STEERING HOSE - PRESSURE	SERVICEABLE	256.00	-
1	POWER STEERING HOSE - NON PRESSURE	SERVICEABLE	312.11	-
1	DASH BOARD LOWER FUSE BOX ASSY	SERVICEABLE	545.60	-
1	WIPER / SIGNAL SWITCH	SERVICEABLE	108.20	-
1	GLOVE BOX	SERVICEABLE	61.00	-
1	CONSOLE BOX TOP COVER	SERVICEABLE	250.00	-
1	CONSOLE BOX FRONT	SERVICEABLE	213.00	-
1	FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	SERVICEABLE	48.32	-
1	FRONT SHOCK ABSORBER ASSY LH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM RH	SERVICEABLE	283.00	-
1	FRONT LOWER ARM LH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	230.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	230.00	-
1	FRONT HUB UNIT	SERVICEABLE	376.00	-
1	FRONT DISC BRAKE RH	SERVICEABLE	157.55	-
1	FRONT DISC BRAKE LH	SERVICEABLE	157.55	-
1	FRONT STRUT BAR BRACKET LH	SERVICEABLE	235.01	-
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	-
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR LINK LH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET RH	SERVICEABLE	105.75	-
1	FRONT STABILIZER BAR BRACKET LH	SERVICEABLE	105.75	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

	rteg. No. 155007 15017 Co 1 1709. No. 15-5007 150-17			
Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT STABILIZER BAR BUSH RH	SERVICEABLE	66.00	-
1	FRONT STABILIZER BAR BUSH LH	SERVICEABLE	66.00	-
1	FRONT BEAM A - IMPACT RH	SERVICEABLE	214.00	-
1	FRONT BEAM A - IMPACT LH	SERVICEABLE	214.00	-
1	DRIVE SHAFT RH	SERVICEABLE	900.00	-
1	DRIVE SHAFT LH	SERVICEABLE	900.00	-
1	INTERN AXLE SHAFT (CENTRE)	SERVICEABLE	241.14	-
1	FRONT SEAT BELT RH	SERVICEABLE	402.50	-
1	FRONT SAFETY BELT COVER GARNISH	SERVICEABLE	125.00	-
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	CRACKED	119.74	119.74
1	REAR BUMPER REFLECTORS LH	BROKEN	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	REAR LUGGAGE FLOOR PANEL	BENT / BUCKLED	973.00	973.00
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NECESSARY	63.50	63.50
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK - TOP	DENTED	466.56	466.56
1	BOOTLID 'CHEVROLET' BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID 'EPICA LT' BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	CRACKED	128.40	128.40
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	REAR TAIL LAMP RH	СИТ	479.30	479.30
1	REAR TAIL LAMP LH	CRACKED	479.30	479.30



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

	10g. No. 105007 10017 GOT 10g. No. 105007 100-1			
Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-11,358.79	-1,522.18
			102,229.17	13,699.67
1	BOOTLID WEATHERSTRIP (@ \$344.28 DISC 50%) (SN)	CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	_
			309.85	172.14
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
2	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NECESSARY	10.00	10.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	192.00	25.00
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	35.00	35.00
1	SET FRONT FENDER LINER CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	-
2	BONNET STOPPER (SN)	NOT NECESSARY	15.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	300.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,766.74	438.00
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH, FRONT FENDER LINER WHEEL HOUSE PANEL RH, FENDER LH, FRONT FENDER LINER WHEEL HOUSE PANEL LH, FRONT BUMPER LOWER STIFFENER, FRONT BUMPER BRACKET LH, FRONT BUMPER BRACKET LH, FRONT BUMPER BRACKET RH, BONNET HINGE RH, BONNET HINGE LH, AIRCON COMPRESSOR BRACKET, AIR INTAKE RESONATOR TANK TOP BRACKET, BATTERY FASTENER BRACKET, GEAR BOX CROSS MEMBER BRACKET, }		7,500.00	2,000.00
	FRONT CENTRE MEMBER (MEMBER A-FRT SUSP, CTR), ENGINE SUSPENSION CROSS MEMBER, REAR EXHAUST BOX (MUFFLER A-EXH,RR), REAR FENDER RH AND REAR FENDER LH. }		-	-
	TOWING FEES.		120.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,600.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	440.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.		380.00	100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	150.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 8

14,900.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP OIL, COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
			19,700.00	4,340.00
	GRAND TOTAL		124,005.76	18,649.81

Report Ref No. CC3/CTI18016197/Kha3s2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.