



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 8009U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	708.00	708.00
1	REAR BUMPER SIDE RETAINER LHS	NECESSARY	26.00	26.00
1	REAR BUMPER SIDE RETAINER RHS	NECESSARY	26.00	26.00
1	REAR BUMPER REFLECTOR LHS	NOT NECESSARY	20.00	-
1	REAR BUMPER REFLECTOR RHS	NOT NECESSARY	20.00	-
1	BOOTLID	BENT	828.00	828.00
1	BOOTLID "ATTRAGE" EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID "MIT" LOGO EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID OUTER CHROME GARNISH	NOT NECESSARY	318.00	-
1	BOOTLID HINGE LHS	SERVICEABLE	192.00	-
1	BOOTLID HINGE RHS	SERVICEABLE	192.00	-
1	BOOTLID LOCK	SERVICEABLE	206.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	402.00	-
1	REAR END PANEL WEATHERSTRIP	SERVICEABLE	148.00	-
1	REAR FENDER MUDFLAP LHS	SERVICEABLE	39.00	-
1	REAR FENDER MUDFLAP RHS	SERVICEABLE	39.00	-
1	REAR END PANEL AIR DUCT	SERVICEABLE	27.00	-
1	REAR END PANEL AIR DUCT COVER TRIM	SERVICEABLE	36.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	906.00	-
1	TAIL LAMP LHS	NOT NECESSARY	276.00	-
1	TAIL LAMP RHS	NOT NECESSARY	276.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	65.00	-
	LESS 10% DISCOUNT		-482.90	-166.70
			4,346.10	1,500.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	260.00	200.00
1	REAR NUMBER PLATE & CASING (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/AWA18016217/T1vbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	35.00	-
			420.00	235.00
	<b>LABOUR</b>			
	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SPARE TYRE PANEL.		800.00	500.00
	TO SPRAY REAR BUMPER.		250.00	200.00
	TO SPRAY REAR END PANEL.		250.00	200.00
	TO SPRAY REAR BOOTLID.		250.00	200.00
	TO ADJUST TAIL LAMP & CHECK WIRING.		120.00	30.00
	RUST PROOFING.		120.00	30.00
	TO REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER TRIM LHS & RHS, SPARE TYRE BOARD, CUSHION AND ETC.		130.00	40.00
	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY.		130.00	30.00
	R & R BOOTLID COMPONENTS.		120.00	60.00
			2,170.00	1,290.00
<b>GRAND TOTAL</b>			<b>6,936.10</b>	<b>3,025.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,400.00</b>

Report Ref No. CS/AWA18016217/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.