



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18016217/T1vbe2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 18-10-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|------------------|-----------------------|------------|
| Insured Veh. | PC 4853Z | Veh. Inspected | SLG 8009U |
| Policy No. | BVBPSB0005921800 | Coverage (\$) | 0.00 |
| Claim No. | NSV1800500/KW | Excess (\$) | 0.00 |
| Assign From | KIN WONG | Assign Date | 05/09/2018 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------------------|---------------------|------------|
| Make & Model | MITSUBISHI ATTRAGE | c.c | 1193 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | MMBSTA13AHH002788 | Colour | BLACK |
| Odometer | 43160 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 185/55 R16 | ROADSTONE | 6 mm |
| L/H Front Tyre | 185/55 R16 | ROADSTONE | 6 mm |
| R/H Rear Tyre | 185/55 R16 | ROADSTONE | 6 mm |
| L/H Rear Tyre | 185/55 R16 | ROADSTONE | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|-------------------|------------------------|------------|
| Accident Date | 31/08/2018 | Inspection Date | 06/09/2018 |
| Survey held at | 249 JLN BOON LAY | | |
| Repairer | DING AUTO PTE LTD | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|-----------------------|