

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI18016220/T1TBE2  
**Date:** 16/05/2019

**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1808841800
Claimant Vehicle No :	GBD8420Z	Insured Vehicle No :	GBH2105C
Date of Loss:	16/08/2018	Nature of Claim:	TP
			Claim No: SNM18D04315C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBD8420Z</b>		
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Engine No:	ZD30348142K
Reg. Date:	08/06/2015 (Man. Year: 2014)	Chassis No:	JN1SC2F24Z0857113
Colour:	Silver	Odometer:	95120 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R13
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	126.27	126.27	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	100.00	50.00	50.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>226.27</b>	<b>176.27</b>	<b>50.00</b>	<b>22.10</b>
<b>+ GST 7.00/7.00% (S\$)</b>	15.84	12.34	3.50	22.10
<b>Nett Amount (S\$)</b>	<b>242.11</b>	<b>188.61</b>	<b>53.50</b>	<b>22.10</b>

**INSPECTION**

Date of Assignment:	05/09/2018			
Date Inspected:	06/09/2018	Inspected At:	Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723	
Estimated Period of Repair:	1.0 days			

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Jan 2019)
<b>Parts:</b>	N/A NISSAN CABSTAR 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/GBD8420Z/16/05/2019 10:09</b>
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RT SIDE MIRROR	Cracked	140.30 FN	*140.30 FN
					<b>Sub Total (S\$)</b>	<b>140.30</b>
					<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	<b>14.03</b>
					<b>Total Parts (S\$)</b>	<b>126.27</b>

F=Franchise part. N=NettItemDisc.

LKK Auto Consultants Pte Ltd/GBD8420Z/16/05/2019 10:09. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REPLACE ABOVE PARTS, TEST AND ASSEMBLY	New	100.00	50.00
			<b>Gross Labour Cost (\$)</b>	<b>50.00</b>

LKK Auto Consultants Pte Ltd/GBD8420Z/16/05/2019 10:09. Not valid without Reference section.

< END OF ESTIMATES >