

ASS. REC. BY:

REF:

CS/FCL18016245 / Ksbm2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS May Chua

of

FCL

Date/Time: 05092018 4:54pm

Estimated Cost:

Bill to:

OD / EV / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 4555D

Insured:

SH 9400C

at Workshop m/s

Seng Kin

Tel:

6453 6238

of

Bik 1 Sin Ming Ind Est #01-131

Policy No:

Claim No:

DIS006601MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

06092018 @ 11am

H.O.D. Endorsement:

Date/Time:

05092018 4:58pm

Person Contacted:

Ms. Lee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 4555D - X
	SH 9400C - NS/INCL 3007019 / Ksbm2
07/09/18	@ 14:24 p.m. revised PA to May Chua via email.
23/9	@ 3:20a email to car firm

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From:

Date: 06/09/2018

Veh No:

SKA 4555D Yr Regn: 03, 11

Estimated Cost:

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SKA 4555 D

Make:

Mer 8250 Cricc 1796

at Workshop m/s

Seng Kin

Colour

M. Grey

A/C: Insured / Std / NI / NA

of BKL Sin Ming Ind. Est #01-131

Sp. Reading

83869

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

11 am

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

245/45R17

R:

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Bal. or Market Value:

862k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

9 mm

R/Bal.

9 mm

GIA / PR. Seen:

Consistent? : Yes or No

L/Bal.

9 mm

L/Bal.

9 mm

Est. Repairs:

04 days

Res.: Yes or No

D.O.A.

4/9/18

D.O.I.

6/9/18

Lum Sum:

1-B.1 %

3 Val.: Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS ^{lup}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm N/S

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/9 File pass to Nivite

26/09/18 Confirmed L/S \$3,200/- @ 4 days with Kenneth.
(\$1,623.90 Red - 34%)

RECEIVED 26 SEP 2018

Date/Time, File Pass to?

26/09/18

1)

Typ.st

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

135

50

50

15

250

Report Format :

Lump Sum / I.B.I: (\$ 3,200/- 4/5)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016245/Ksb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9400C	Veh. Inspected	SKA 4555D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006601MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/09/2018	Inspection Date	06/09/2018	
Survey held at	SENG KIN MOTOR WORKS BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006601MFSH

Date: 07 September 2018

Our Ref: CS/FCI18016245/Ksb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKA 4555D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/09/2018 at the premises of M/s Seng Kin Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$ 4,823.90
Revised Estimate Amount	: S\$ 4,034.90
"Check" Items Amount	: S\$ 279.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-09-2018	Our Ref No. D18006601MFSH
Accident Date	04-09-2018	Claim Type. Third Party
Insured Vehicle	SH9400C	Third Party Vehicle. SKA4555D
Survey Location	BLK 1 SIN MING IND ESTATE #01-131	
Contact Person.	SUNIL DEEP VELAYIL ASOKAN	
Contact No.	64536238/ 64536238	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SENG KIN MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 September 2018 2:24 PM
To: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006601MFSH/1
Attachments: SKA 4555D - Preli Advise.pdf

Dear May,

Enclosed herewith preliminary advice of SKA 4555D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 5 September 2018 5:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006601MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 5 September, 2018 4:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006601MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



成金摩多 Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532961 FAX: 64580453
B. Reg. No. 111182/OOW

SUNIL DEEP VELAYIL ASOKAN
BLK. 209 TOA PAYOH NORTH #08-1279
SINGAPORE 310209

Attention : Motor Claim Department

Contact : 92332259

Estimate : ES000096

Date : 04/09/2018
Vehicle Num. : SKA 4555D
Make/Model : MERCEDES BENZ E250
Chassis/Eng# : WDD2120472A377775
Accident Date : 04/09/2018
Claim No. :
Reference : TP/SK/2018/010
Policy No. : V8008867

*Not Authorised
+ Lab
Return by pain
11/09/2018 832001 4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PCE	NETT ITEMS :		
2.	1 PCE	FRT. N/S FENDER		
3.	1 PCE	FRT. N/S HEADLAMP		
4.	1 PCE	FRT. N/S HEADLAMP HOUSING		
5.	1 PCE	FRT. BUMPER		
6.	1 PCE	FRT. BUMPER INNER BRACKET		
6.	2 PCS	FRT. O/S & N/S BUMPER CHROME MOULDING		

Nett Total S\$:

10.00% Discount S\$:

950.00

1,020.00

240.00

1,335.00

70.00

156.00

78.00

3,771.00

377.10

3,393.90

LABOUR :

LABOUR CHARGES TO KNOCK AND STRAIGHTEN FRT. SUPPORT
PANEL, FRT. N/S FENDER INNER PANEL & DISTORTED PARTS.

TO REMOVE BODY DAMAGED PARTS, REPLACE NEW & REFIX SAME.

TO PUTTY AND SPRAY PAINT

TO CHECK WIRING AND FOCUS HEADLAMP

650.00

700.00

80.00

Labour Total S\$:

1,430.00

E. & O.E.

Total S\$:

4,823.90

[Signature]

for Seng Kin Motor Works

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18016245/Ksbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9400C	Veh. Inspected	SKA 4555D
Policy No.		Coverage (\$)	0.00
Claim No.	D18006601MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	05/09/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES E 250 CGI (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2120472A377775	Colour	METALLIC GREY
Odometer	83869	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R17	HANKOOK	9 mm
L/H Front Tyre	245/45 R17	HANKOOK	9 mm
R/H Rear Tyre	245/45 R17	HANKOOK	9 mm
L/H Rear Tyre	245/45 R17	HANKOOK	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/09/2018	Inspection Date	06/09/2018
Survey held at	SENG KIN MOTOR WORKS BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 4555D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT N/S FENDER (N)	BUCKLED	950.00	950.00
1	FRT N/S HEADLAMP (N)	CRACKED	1,020.00	1,020.00
1	FRT N/S HEADLAMP HOUSING (N)	SERVICEABLE	240.00	-
1	FRT BUMPER (N)	BUCKLED	1,335.00	1,335.00
1	FRT BUMPER INNER BRACKET (N)	SERVICEABLE	70.00	-
2	FRT O/S & N/S BUMPER CHROME MOULDING @\$78.00 (N)	NECESSARY	156.00	156.00
	LESS 10% DISCOUNT		-377.10	-346.10
			3,393.90	3,114.90
	LABOUR			
	LABOUR CHARGES TO KNOCK AND STRAIGHTEN FRT SUPPORT PANEL, FRT N/S FENDER INNER PANEL & DISTORTED PARTS. TO REMOVE BODY DAMAGED PARTS, REPLACE NEW & REFIX SAME.		650.00	400.00
	TO PUTTY AND SPRAY PAINT.		700.00	500.00
	TO CHECK WIRING AND FOCUS HEADLAMP.		80.00	20.00
			1,430.00	920.00
	GRAND TOTAL		4,823.90	4,034.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/FCI18016245/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.