

08/11/13 wof
ASS. REC. BY:

REF: AIG

ASSIGNMENT

From: Date: 06/09/18

Estimated Cost:

OD: ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SH 2163H
at Workshop m/s: Tan Jim Motor
of: 51 Defu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{hps}

50291
Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SH 2163H Yr Regn: 10 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota prius C.C. 1797

Colour: Yellow / black A/C: Insured / Std / NI / NA

Sp. Reading: 704936 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size: F: 195/65-215
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/9/18 D.O.I. 6/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4 yrs.

L/S \$6,250

R (\$11,981.73/66%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18016247/Ujb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-09-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 6360M	Veh. Inspected	SH 2163H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/09/2018	Inspection Date	06/09/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



陳林摩摩私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLC6360M
Date of Accident : 04 September 2018

Mr Ang Teck Loong

Date : 05 September 2018

Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8LA
Chassis No : LXS120026597

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	right rear lamp <i>CM</i>	\$ 433.70
02	3 ps	right rear lamp clip holders @ \$85.00 <i>17</i>	\$ 255.00
03	1 pc	right rear fender <i>Sub 50</i>	\$ 775.70
04	1 pc	right rear fender inner liner <i>To 1</i>	\$ 142.50
05	4 ps	right rear fender inner liner clips @ \$4.50 <i>nee</i>	\$ 18.00
06	1 pc	right rear fender 1/4 glass weatherstrip <i>nee</i>	\$ 89.00
07	1 pc	right rear fender air vent <i>520</i>	\$ 71.00
08	1 pc	right rear fender inner trim <i>566.10</i>	\$ 814.40
09	4 ps	right rear fender inner trim clips @ \$4.50 <i>17</i>	\$ 18.00
10	1 pc	right rear fender inner extension panel <i>Sub 50</i>	\$ 308.10
11	1 pc	battery tray <i>17</i>	\$ 80.00
12	1 pc	battery brackets <i>17</i>	\$ 35.00
13	1 pc	rear bumper <i>D-5</i>	\$ 552.30
14	1 pc	right rear bumper side retainer <i>CM</i>	\$ 111.50
15	1 pc	right rear bumper side holder <i>Sub</i>	\$ 45.00
16	10 ps	rear bumper clips @ \$4.50 <i>nee</i>	\$ 45.00
17	1 pc	right rear bumper end splashshield cover <i>To 1</i>	\$ 115.80
18	1 pc	rear luggage floor panel <i>17</i>	\$ 998.00
19	1 pc	right rear luggage floor panel side trim <i>17</i>	\$ 102.10
20	2 ps	rear bumper screw spacer @ \$4.30 <i>17</i>	\$ 8.60
21	2 pc	rear bumperspace screw @ \$4.50 <i>17</i>	\$ 9.00
22	1 pc	rear end panel <i>3.600</i>	\$ 602.10
23	1 pc	rear end panel inner trim <i>17</i>	\$ 121.10
24	1 pc	rear exhaust box <i>17</i>	\$ 1,113.80
25	1 pc	rear exhaust box heat shield <i>17</i>	\$ 122.20
26	2 ps	rear exhaust box mounts @ \$41.10 <i>17</i>	\$ 82.20
27	1 pc	right rear shock absorber <i>17</i>	\$ 116.80
28	1 pc	right rear wheel bearing with hub <i>17</i>	\$ 610.20
29	1 pc	front bumper <i>To 1 655.110</i>	\$ 1,569.00
30	1 pc	front bumper reinforcement <i>Sub</i>	\$ 691.00
31	1 pc	front bumper tow cover <i>To 1</i>	\$ 45.00
32	1 pc	front bumper absorber foam <i>To 1</i>	\$ 125.00
33	1 pc	front bumper lower beam <i>17</i>	\$ 110.00
34	2 ps	front bumper lower beam brackets @ \$75.00 <i>17</i>	\$ 150.00
35	1 pc	front bumper lower beam garnish <i>17</i>	\$ 85.00
36	2 ps	front bumper side retainer @ \$95.00 <i>Sub</i>	\$ 190.00
37	1 pc	right front bumper indicator lamp <i>17</i>	\$ 511.80
38	1 pc	right front bumper lower centre air grille <i>17</i>	\$ 168.00
39	1 pc	front bumper emblem badge <i>nee</i>	\$ 78.00

AIGAsia Insured's Veh No : SLC6360M

Date of Accident : 04 September 2018

Mr Ang Teck Loong

Plants hence notify the following:

after spray painting and (artist) during resurvey

subject to confirmation

• No, delamination, peeling, or allowed

• Surface, all repair must be resurveyed and is subject to final approval from Insurance Company

Signature of Repairer

Date : 05 September 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No. : M2-8922054-2

Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8L A

Chassis No : LXS120026597

S/No	Quantity	Description	Amount
LIST ITEMS			
40	3 ps	front bumper emblem badge clips @ \$45.00 <i>11</i>	\$ 135.00 <i>X</i>
41	1 pc	right front bumper air guide <i>11</i>	\$ 125.60 <i>X</i>
42	1 pc	front bumper lower splashshield cover <i>11</i>	\$ 178.30 <i>X</i>
43	1 pc	front bumper upper centre air grille <i>11</i>	\$ 148.60 <i>X</i>
44	1 pc	front bumper upper weatherstrip <i>11</i>	\$ 128.60 <i>X</i>
45	6 ps	front bumper upper weatherstrip clips @ \$4.50 <i>11</i>	\$ 27.00 <i>X</i>
46	1 pc	right headlamp <i>CR</i> <i>199.01</i>	\$ 3,380.30 <i>X</i>
Less 25 %			\$ 15,642.30 <i>645891</i>
			\$ 3,910.58
			\$ 11,731.73
SPECIAL NETT ITEMS			
47	1 pc	right rear fender 1/4 glass sealant <i>me</i>	\$ 100.00 <i>KO</i>
48	1 pc	battery <i>11</i>	\$ 250.00 <i>X</i>
49	1 set	rear bumper parking sensor <i>sumb</i>	\$ 450.00 <i>200</i>
50	1 pc	right rear wheel rim <i>DD</i>	\$ 380.00 <i>200</i>
51	1 pc	right rear wheel tyre <i>SVC</i>	\$ 280.00 <i>X</i>
			\$ 1,460.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 60.00 <i>20</i>
02		To reinstall of rear bumper parking sensor.	\$ 150.00 <i>50</i>
03		To remove and refit rear fender 1/4 window glass.	\$ 100.00 <i>60</i>
04		To rust-proofing of the affected areas.	\$ 180.00 <i>100</i>
05		To check steering geometry and computer wheel alignment.	\$ 120.00 <i>60</i>
06		To drop rear exhaust box and renew the same.	\$ 150.00 <i>X</i>
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00 <i>80</i>
08		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 400.00 <i>X</i>
09		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 550.00 <i>X</i>
10		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,950.00 <i>1200</i>
11		Putty and spray painting of the affected portion.	\$ 1,200.00 <i>1000</i>
			\$ 5,040.00 <i>3000</i>
Total			\$ 18,231.73



Date of Accident : 04 September 2018

Date : 05 September 2018

Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8L A
Chassis No : LXS120026597

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	right rear lamp	\$ 433.70
02	3 ps	right rear lamp clip holders @ \$85.00	\$ 255.00
03	1 pc	right rear fender	\$ 775.70
04	1 pc	right rear fender inner liner	\$ 142.50
05	4 ps	right rear fender inner liner clips @ \$4.50	\$ 18.00
06	1 pc	right rear fender 1/4 glass weatherstrip	\$ 89.00
07	1 pc	right rear fender air vent	\$ 71.00
08	1 pc	right rear fender inner trim	\$ 814.40
09	4 ps	right rear fender inner trim clips @ \$4.50	\$ 18.00
10	1 pc	right rear fender inner extension panel	\$ 308.10
11	1 pc	battery tray	\$ 80.00
12	1 pc	battery brackets	\$ 35.00
13	1 pc	rear bumper	\$ 552.30
14	1 pc	right rear bumper side retainer	\$ 111.50
15	1 pc	right rear bumper side holder	\$ 45.00
16	10 ps	rear bumper clips @ \$4.50	\$ 45.00
17	1 pc	right rear bumper end splashshield cover	\$ 115.80
18	1 pc	rear luggage floor panel	\$ 998.00
19	1 pc	right rear luggage floor panel side trim	\$ 102.10
20	2 ps	rear bumper screw spacer @ \$4.30	\$ 8.60
21	2 pc	rear bumperspacer screw @ \$4.50	\$ 9.00
22	1 pc	rear end panel	\$ 602.10
23	1 pc	rear end panel inner trim	\$ 121.10
24	1 pc	rear exhaust box	\$ 1,113.80
25	1 pc	rear exhaust box heat shield	\$ 122.20
26	2 ps	rear exhaust box mounts @ \$41.10	\$ 82.20
27	1 pc	right rear shock absorber	\$ 116.80
28	1 pc	right rear wheel bearing with hub	\$ 610.20
29	1 pc	front bumper	\$ 1,569.00
30	1 pc	front bumper reinforcement	\$ 691.00
31	1 pc	front bumper tow cover	\$ 45.00
32	1 pc	front bumper absorber foam	\$ 125.00
33	1 pc	front bumper lower beam	\$ 110.00
34	2 ps	front bumper lower beam brackets @ \$75.00	\$ 150.00
35	1 pc	front bumper lower beam garnish	\$ 85.00
36	2 ps	front bumper side retainer @ \$95.00	\$ 190.00
37	1 pc	right front bumper indicator lamp	\$ 511.80
38	1 pc	right front bumper lower centre air grille	\$ 168.00
39	1 pc	front bumper emblem badge	\$ 78.00



AIG Asia Insured's Veh No : SLC6360M

Date of Accident : 04 September 2018

Plaintiffs hence notify

the following:

Water spray painting

(and parts) during resurvey

is subject to confirmation

by the surveyor on a "Without Prejudice" basis

* No deduction for paint is allowed

* Surveys on parts must be resurveyed and

is subject to final approval from Insurance Company

陳林摩多私人有限公司

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Ang Teck Loong

Date : 05 September 2018

Estimate To Repair SH2163H - Toyota PRIUS HYBRID 1.8LA

Chassis No : LXS120026597

S/No	Quantity	Description	Amount
LIST ITEMS			
40	3 ps	front bumper emblem badge clips @ \$45.00 ✓	\$ 135.00
41	1 pc	right front bumper air guide 11	\$ 125.60
42	1 pc	front bumper lower splashshield cover 11	\$ 178.30
43	1 pc	front bumper upper centre air grille 11	\$ 148.60
44	1 pc	front bumper upper weatherstrip 11	\$ 128.60
45	6 ps	front bumper upper weatherstrip clips @ \$4.50 11	\$ 27.00
46	1 pc	right headlamp	\$ 3,380.30
			\$ 15,642.30
Less 25 %			\$ 3,910.58
			\$ 11,731.73
SPECIAL NETT ITEMS			
47	1 pc	right rear fender 1/4 glass sealant 11	\$ 100.00
48	1 pc	battery 11	\$ 250.00
49	1 set	rear bumper parking sensor 11	\$ 450.00
50	1 pc	right rear wheel rim 11	\$ 380.00
51	1 pc	right rear wheel tyre SVC	\$ 280.00
			\$ 1,460.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 150.00
03		To remove and refit rear fender 1/4 window glass.	\$ 100.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To check steering geometry and computer wheel alignment.	\$ 120.00
06		To drop rear exhaust box and renew the same.	\$ 150.00
07		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
08		To drop rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	\$ 400.00
09		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 550.00
10		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,950.00
11		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 5,040.00
Total			\$ 18,231.73



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016425/Nub3 & CC6/AIG18016247/Ujb3

13 September, 2018

MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD

26 Tai Seng Street

#07-02

Singapore 534057

Dear Sirs,

**ACCIDENT INVOLVING SLC 6360M AND SHD 6219G AND SH 2163H ON 04/09/2018
ALONG / AT CTE TOWARDS SLE (NEAR WHAMPOA)**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Thin Thin

Claims

Tel : 6841 2360

Fax: 6741 4108

Email : thinthin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP007092018

Date : 24-09-2018

Your Ref : CC6/A1418016247/4563

WITHOUT PREJUDICE

Claims Department - Motor Claims LKK
c/o AIR ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SH2163H & SLC6360M ON 04-09-2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- | | |
|---|---|
| ☐ Original survey report / _____ copies of photographs _____ | ☐ Original rental invoice number _____ |
| ☒ Original Tax-invoice number TP09181013 | ☐ police result _____ |
| ☒ SAS / AS & IS / police report | ☐ Vehicle search result _____ |
| ☐ Certificate Of Insurance | ☐ _____ |
| ☒ Authorisation To Act | |

*Survey under insurance instruction - LKK

a)	Cost of repair (inclusive GST)	\$	6,687.50
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [150 x 10 days]	\$	1,500.00
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)		\$	
Total			\$ 8,194.99

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlimotor.com.sg



TAX-INVOICE
NUMBER: TP0918/013

(Please quote our reference number SM007092018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Ang Teck Loong

Date: 14/09/2018

Vehicle No: SH 2163H
Model: TOYOTA PRIUS HYBIRD

Description	Amount
To lump sum repair as recommended by surveyor.	\$6,250.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$6,257.00
Add 7% GST	\$437.99
Total	\$6,694.99


Tan Lim Motor Pte Ltd



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ang Teck Loung ("the third party claimant")
of Block 406 Sin Ming Avenue #07-247 Singapore 570406 (address),
owner of SH 2163H (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SH 2163H that was
damaged pursuant to the accident which occurred on 04/09/2018 (date) along
Junction of Ang Mo Kio Avenue 1 and Ang Mo Kio Avenue 8 (location)
involving vehicle no/s SLC 6360M ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 05 day of Sep (month) 20 18 (year)

Signed by "the third party claimant"


Signed by "the workshop"

Enquire Vehicle & Owner Information (Vehicle No. SLC6360M As At 04 Sep 2018 / 23:20:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SRSTPSH2163H.TLM

Current Owner Details

Owner ID Type: Company
Owner ID: 199403356Z
Owner Name: MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 26
Registered Street Name: TAI SENG STREET
Registered Unit No.: #01 - 03A
Registered Building Name: J'FORTE
Registered Postal Code: 534057
Current Vehicle Details

Vehicle No.: SLC6360M ✓
Make Description/Model: HONDA / VEZEL 1.5X A
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Joy Irene (LKKAUTO)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Thursday, 4 October 2018 3:54 PM
To: Joy Irene (LKKAUTO)
Cc: CS A Team; Admin A
Subject: RE: Case Assignment TP - SH2163H - 04/09/2018 - *LKK REF: CC6/AIG18016247/Ujb3

Dear Joy,

For an update, we have repudiated liability for this matter due to breach of policy condition. Please inform repairer accordingly.

thank you,

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

saliha.syed-yusoff@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Friday, September 07, 2018 11:41 AM
To: Syed-Yusoff, Saliha; Joy Irene (LKKAUTO)
Cc: CS A Team; Admin A
Subject: RE: Case Assignment TP - SH2163H - 04/09/2018 - *LKK REF: CC6/AIG18016247/Ujb3
Importance: High

Hi Saliha,

Contents noted.

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Thursday, 4 October 2018 4:04 PM
To: Johnson Chua
Cc: Admin A; Hsiao Tong (LKKAUTO); 'Wei Shong'
Subject: RE: TLM Ref: TP007092018; LKK Ref: CC6/AIG18016247/Ujb3; Accident involving SH2163H (TLM) & SLC6360M (AIG) on 04.09.2018

WITHOUT PREJUDICE

Dear Johnson,

We refer to the subject.

We would like to inform you that our principal M/s AIG have repudiated liability for this matter due to breach of policy condition.

We will be proceeding to close file.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Johnson Chua [mailto:johnson.chua@tlmotor.com.sg]
Sent: Monday, 24 September 2018 4:42 PM
To: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; 'Wei Shong' <wei.shong@tlmotor.com.sg>
Subject: TLM Ref: TP007092018; LKK Ref: CC6/AIG18016247/Ujb3; Accident involving SH2163H (TLM) & SLC6360M (AIG) on 04.09.2018
Importance: High

Dear Joy,

We enclose our client's Letter of Demand together with the supporting documents for your attention.

Please acknowledge our email and make your offer to us within the next fourteen (14) days upon receipt.

Regards,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018 Edit Reg		06 Sep 2018 00:00 Edit Adj Rpt	S\$6,250.00 Edit Estimates	S\$6,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD , Co. Reg. No.: 199403356Z								
Main Claimant:	ANG TECK LOONG , ID: S07650291								
Vehicle Reg. No.:	SH2163H	Date of Loss:	04/09/2018 23:00 - :59 [46 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5027151932SG	Policy/Cover Note No.:	2100509471-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLC6360M	Policy No. (Claimant):	D-170088881MSH						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/09/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- AIG_SG (06/09/2018): Request To Upload TP GIA Report - AIG_SG (06/09/2018): No OI GIA Report (SLC6360M VS SH2163H)									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SH2163H (5027151932SG)**
[SLC6360M]

TP

ANG TECK LOONG

Sep 4 2018 11:20PM

[MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD]

Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 18:01	Odometer Reading	 Load JPG	☒
2	06/09/18 18:01	Chassis Number	 Load JPG	☒
3	06/09/18 18:02	General View	 Load JPG	☒
4	06/09/18 18:02	General View	 Load JPG	☒
5	06/09/18 18:02	General View	 Load JPG	☒
6	06/09/18 18:02	General View	 Load JPG	☒
7	06/09/18 18:02	General View	 Load JPG	☒
8	06/09/18 18:02	General View	 Load JPG	☒
9	06/09/18 18:02	General View	 Load JPG	☒
10	06/09/18 18:02	General View	 Load JPG	☒
11	06/09/18 18:02	General View	 Load JPG	☒
12	06/09/18 18:02	General View	 Load JPG	☒
13	06/09/18 18:02	General View	 Load JPG	☒
14	06/09/18 18:02	General View	 Load JPG	☒
15	06/09/18 18:02	General View	 Load JPG	☒
16	06/09/18 18:02	General View	 Load JPG	☒
17	06/09/18 18:02	General View	 Load JPG	☒
18	06/09/18 18:02	General View	 Load JPG	☒
19	06/09/18 18:02	General View	 Load JPG	☒
20	06/09/18 18:02	General View	 Load JPG	☒
21	06/09/18 18:02	General View	 Load JPG	☒
22	06/09/18 18:02	General View	 Load JPG	☒
23	06/09/18 18:02	General View	 Load JPG	☒
24	06/09/18 18:02	General View	 Load JPG	☒
25	06/09/18 18:02	General View	 Load JPG	☒
26	06/09/18 18:02	General View	 Load JPG	☒
27	06/09/18 18:02	General View	 Load JPG	☒
28	06/09/18 18:02	General View	 Load JPG	☒
29	06/09/18 18:02	General View	 Load JPG	☒
30	06/09/18 18:02	General View	 Load JPG	☒
31	06/09/18 18:02	General View	 Load JPG	☒
32	06/09/18 18:02	General View	 Load JPG	☒
33	06/09/18 18:02	General View	 Load JPG	☒
34	06/09/18 18:02	General View	 Load JPG	☒
35	06/09/18 18:02	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/09/18 18:02	General View	 Load JPG	☒
37	06/09/18 18:02	General View	 Load JPG	☒
38	06/09/18 18:02	General View	 Load JPG	☒
39	06/09/18 18:02	General View	 Load JPG	☒
40	06/09/18 18:02	General View	 Load JPG	☒
41	06/09/18 18:02	General View	 Load JPG	☒
42	06/09/18 18:02	General View	 Load JPG	☒
43	06/09/18 18:02	General View	 Load JPG	☒
44	06/09/18 18:02	General View	 Load JPG	☒
45	06/09/18 18:02	General View	 Load JPG	☒
46	06/09/18 18:02	General View	 Load JPG	☒
47	06/09/18 18:02	General View	 Load JPG	☒
48	06/09/18 18:02	General View	 Load JPG	☒
49	06/09/18 18:02	General View	 Load JPG	☒
50	06/09/18 18:02	General View	 Load JPG	☒
51	06/09/18 18:02	General View	 Load JPG	☒
52	06/09/18 18:02	General View	 Load JPG	☒
53	06/09/18 18:02	General View	 Load JPG	☒
54	06/09/18 18:02	General View	 Load JPG	☒
55	06/09/18 18:02	General View	 Load JPG	☒
56	06/09/18 18:02	General View	 Load JPG	☒
57	06/09/18 18:02	General View	 Load JPG	☒
58	06/09/18 18:02	General View	 Load JPG	☒
59	06/09/18 18:02	General View	 Load JPG	☒
60	06/09/18 18:02	General View	 Load JPG	☒
61	06/09/18 18:02	General View	 Load JPG	☒
62	06/09/18 18:02	General View	 Load JPG	☒
63	06/09/18 18:02	General View	 Load JPG	☒
64	06/09/18 18:02	General View	 Load JPG	☒
65	06/09/18 18:02	General View	 Load JPG	☒
66	06/09/18 18:02	General View	 Load JPG	☒
67	06/09/18 18:02	General View	 Load JPG	☒
68	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
69	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
70	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
71	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
72	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
73	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
74	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
75	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
76	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
77	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
78	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
79	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
80	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
81	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
82	11/09/18 15:56	Reinspection Photo	 Load JPG	☒
83	11/09/18 15:56	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/09/18 15:56	Reinspection Photo	Load JPG	✓
85	13/09/18 17:33	Reinspection Photo	Load JPG	✓
86	13/09/18 17:33	Reinspection Photo	Load JPG	✓
87	13/09/18 17:33	Reinspection Photo	Load JPG	✓
88	13/09/18 17:33	Reinspection Photo	Load JPG	✓
89	13/09/18 17:33	Reinspection Photo	Load JPG	✓
90	13/09/18 17:33	Reinspection Photo	Load JPG	✓
91	13/09/18 17:33	Reinspection Photo	Load JPG	✓
92	13/09/18 17:33	Reinspection Photo	Load JPG	✓
93	13/09/18 17:33	Reinspection Photo	Load JPG	✓
94	13/09/18 17:33	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/18 17:59	TP ESTIMATE- MARKED	Load PDF	
2	10/09/18 17:59	TP GIA REPORT	Load PDF	
3	13/09/18 19:19	Non reporting letter	Load PDF	
4	04/10/18 16:07	EMAIL FROM AIG-REPUDIATED	Load PDF	
5	04/10/18 16:07	EMAIL TO TP REPAIRER	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/09/18 11:47	Third Party E-filed GIA report (SH2163H)	Load PDF	
2	07/09/18 11:47	Third Party E-filed GIA report (GBD9799A)	Load PDF	
3	07/09/18 11:47	Third Party E-filed GIA report(SJV3487A)	Load PDF	
4	07/09/18 11:47	Third Party E-filed GIA report (SLJ4077H)	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016247/UJB3S2

Date: 22/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100509471-01
 Claimant Vehicle No: SH2163H Insured Vehicle No: SLC6360M
 Date of Loss: 04/09/2018 Nature of Claim: TP Claim No: 5027151932SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH2163H
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR6124592
 Reg. Date: 27/10/2014 (Man. Year: 2014) Chassis No: ZVW301844098
 Colour: Yellow/Black Odometer: 704936 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,191.72	5,284.18	7,907.54	59.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	2,570.00	2,470.00	49.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,231.72	7,854.18	10,377.54	56.92
Approved Total (Overridden) (S\$)		6,250.00		
(S\$)	18,231.72	6,250.00	11,981.72	65.72
+ GST 7.00/7.00% (S\$)	1,276.22	437.50	838.72	65.72
Nett Amount (S\$)	19,507.94	6,687.50	12,820.44	65.72

INSPECTION

Date of Assignment: 06/09/2018
 Date Inspected: 06/09/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=740342&extid=282090&CFID=42635383&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT REAR LAMP	Cracked	433.70 FL	*433.70 FL
2	3		*RIGHT REAR LAMP CLIP HOLDERS	Not Necessary	255.00 FL	*- FL
3	1		*RIGHT REAR FENDER	Badly Dented	775.70 FL	*775.70 FL
4	1		*RIGHT REAR FENDER INNER LINER	Torn	142.50 FL	*142.50 FL
5	4		*RIGHT REAR FENDER INNER LINER CLIPS	Necessary	18.00 FL	*18.00 FL
6	1		*RIGHT REAR FENDER 1/4 GLASS WEATHERSTRIP	Necessary	89.00 FL	*89.00 FL
7	1		*RIGHT REAR FENDER AIR VENT	Broken	71.00 FL	*71.00 FL
8	1		*RIGHT REAR FENDER INNER TRIM	Deformed	814.40 FL	*566.10 FL
9	4		*RIGHT REAR FENDER INNER TRIM CLIPS	Not Necessary	18.00 FL	*- FL
10	1		*RIGHT REAR FENDER INNER EXTENSION PANEL	Badly Dented	308.10 FL	*308.10 FL
11	1		*BATTERY TRAY	Not Necessary	80.00 FL	*- FL
12	1		*BATTERY BRACKETS	Not Necessary	35.00 FL	*- FL
13	1		*REAR BUMPER	Distorted	552.30 FL	*552.30 FL
14	1		*RIGHT REAR BUMPER SIDE RETAINER	Cracked	111.50 FL	*111.50 FL
15	1		*RIGHT REAR BUMPER SIDE HOLDER	Bent	45.00 FL	*45.00 FL
16	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
17	1		*RIGHT REAR BUMPER END SPLASHIELD COVER	Torn	115.80 FL	*115.80 FL
18	1		*REAR LUGGAGE FLOOR PANEL	Repair	998.00 FL	*- FL
19	1		*RIGHT REAR LUGGAGE FLOOR PANEL SIDE TRIM	Not Necessary	102.10 FL	*- FL
20	2		*REAR BUMPER SCREW SPACER	Not Necessary	8.60 FL	*- FL
21	2		*REAR BUMPERSPACER SCREW	Not Necessary	9.00 FL	*- FL
22	1		*REAR END PANEL	Badly Dented	602.10 FL	*602.10 FL
23	1		*REAR END PANEL INNER TRIM	Not Necessary	121.10 FL	*- FL
24	1		*REAR EXHAUST BOX	Not Necessary	1,113.80 FL	*- FL
25	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	122.20 FL	*- FL
26	2		*REAR EXHAUST BOX MOUNTS	Not Necessary	82.20 FL	*- FL
27	1		*RIGHT REAR SHOCK ABSORBER	Not Necessary	116.80 FL	*- FL
28	1		*RIGHT REAR WHEEL BEARING WITH HUB	Not Necessary	610.20 FL	*- FL
29	1		*FRONT BUMPER	Torn	1,569.00 FL	*655.10 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	691.00 FL	*691.00 FL
31	1		*FRONT BUMPER TOW COVER	Torn	45.00 FL	*45.00 FL
32	1		*FRONT BUMPER ABSORBER FOAM	Torn	125.00 FL	*125.00 FL
33	1		*FRONT BUMPER LOWER BEAM	Not Necessary	110.00 FL	*- FL
34	2		*FRONT BUMPER LOWER BEAM BRACKETS	Not Necessary	150.00 FL	*- FL
35	1		*FRONT BUMPER LOWER BEAM GARNISH	Not Necessary	85.00 FL	*- FL
36	2		*FRONT BUMPER SIDE RETAINER	Bent	190.00 FL	*190.00 FL
37	1		*RIGHT FRONT BUMPER INDICATOR LAMP	Not Necessary	511.80 FL	*- FL
38	1		*RIGHT FRONT BUMPER LOWER CENTRE AIR GRILLE	Not Necessary	168.00 FL	*- FL
39	1		*FRONT BUMPER EMBLEM BADGE	Necessary	78.00 FL	*78.00 FL
40	3		*FRONT BUMPER EMBLEM BADGE CLIPS	Not Necessary	135.00 FL	*- FL
41	1		*RIGHT FRONT BUMPER AIR GUIDE	Not Necessary	125.60 FL	*- FL
42	1		*FRONT BUMPER LOWER SPLASHIELD COVER	Not Necessary	178.30 FL	*- FL
43	1		*FRONT BUMPER UPPER CENTRE AIR GRILLE	Not Necessary	148.60 FL	*- FL
44	1		*FRONT BUMPER UPPER WEATHERSTRIP	Not Necessary	128.60 FL	*- FL
45	6		*FRONT BUMPER UPPER WEATHERSTRIP CLIPS	Not Necessary	27.00 FL	*- FL
46	1		*RIGHT HEADLAMPS	Cracked	3,380.30 FL	*799.01 FL
47	1		*RIGHT REAR FENDER 1/4 GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
48	1		*BATTERY	Not Necessary	250.00 FS	*- FS
49	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
50	1		*RIGHT REAR WHEEL RIM	Dented	380.00 FS	*200.00 FS
51	1		*RIGHT REAR WHEEL TYRE	Serviceable	280.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=\$pcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,102.30	6,898.91
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,910.58	1,614.73
Total Parts (\$\$)					13,191.72	5,284.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	60.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	New	150.00	50.00
3	TO REMOVE AND REFIT REAR FENDER 1/4 WINDOW GLASS.	New	100.00	60.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	180.00	100.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	120.00	60.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.	New	150.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	New	180.00	80.00
8	TO DROP REAR AXLE AND SUSPENSION ASSY, REMOVE AND RENEWAL OF NECESSARY PARTS, TO CONDUCT FINAL CHECKING AND TESTING.	New	400.00	0.00
9	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK.	New	550.00	0.00
10	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	1,950.00	1,200.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			5,040.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >