

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016304/AVD3N2**Date:** 13/12/2018REFERENCE

Insured/Claimant: LEE SIANG KHENG BERT Policy No: 2100497023
Date of Loss: 02/09/2018 Nature of Claim: OD Claim No: 6204618002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EY668H**
Make & Model: AUDI A5, 1.8 SPORTSBACK TFSI MU (A) Engine No: CDH101824
Reg. Date: 04/11/2010 (Man. Year: 2010) Chassis No: WAUZZZ8T2BA009373
Colour: Black Odometer: 82245 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$50,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,771.60	7,637.32	7,134.28	48.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,632.00	3,982.00	1,650.00	29.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,403.60	11,619.32	8,784.28	43.05
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	19,603.60	10,819.32	8,784.28	44.81
+ GST 7.00/7.00% (S\$)	1,372.25	757.35	614.90	44.81
Nett Amount (S\$)	20,975.85	11,576.67	9,399.18	44.81

INSPECTION

Date of Assignment: 06/09/2018
Date Inspected: 05/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,584.00 FS	*1,267.20 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Not Necessary	222.00 FS	*- FS
3	1		*SIDE REINFORCEMENT	Not Necessary	770.00 FS	*- FS
4	2		*SUPPORT-LH/RH	Not Necessary	48.00 FS	*- FS
5	1		*GUIDE PIECE	Damaged	37.00 FS	*29.60 FS
6	2		*SECURING STRIP-LH/RH	Not Necessary	60.00 FS	*- FS
7	1		*CLOSING ELEMENT-LOWER CENTRE	Not Necessary	180.00 FS	*- FS
8	1		*FOAM FILLER PIECE	Not Necessary	109.00 FS	*- FS
9	1		*AIR GUIDE GRILLE-LH	Not Necessary	118.00 FS	*- FS
10	1		*TRIM FOR FOG LAMP CHROME	Not Necessary	61.00 FS	*- FS
11	1		*PULL STRAP COVER-LOWER	Not Necessary	44.00 FS	*- FS
12	1		*FRONT FENDER-LH	Distorted	930.00 FS	*744.00 FS
13	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	49.00 FS	*- FS
14	1		*BRACKET FOR FENDER-LH FRONT	Bent	50.00 FS	*40.00 FS
15	1		*BRACKET FOR FENDER-LH REAR	Not Necessary	50.00 FS	*- FS
16	1		*BRACE	Bent	106.00 FS	*84.40 FS
17	1		*WHEEL HOUSING LINER	Torn	163.00 FS	*130.00 FS
18	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	38.00 FS	*- FS
19	2		*HEADLIGHT FOR GAS DISCHARGE LAMP-LH/RH	Cut	4,190.00 FS	*3,352.00 FS
20	2		*CONTROL UNIT FOR HEADLIGHT	Not Necessary	2,036.00 FS	*- FS
21	2		*GAS DISCHARGE LAMP	Not Necessary	787.00 FS	*- FS
22	1		*MOUNTING FOR HEADLIGHT-LH/RH	N/s Damaged	218.00 FS	*87.20 FS
23	1		*SIGNAL HORN-LH HIGH TONE	Not Necessary	178.00 FS	*- FS
24	1		*SPRING SHACKLE-LH HIGH TONE	Not Necessary	22.00 FS	*- FS
25	1		*LIFT CYLINDER FOR HEADLIGHT-LH	Damaged	241.00 FS	*192.40 FS
26	1		*REFRIGERANT PIPE	Not Necessary	312.00 FS	*- FS
27	1		*REPAIR KIT FOR QUICK RELEASE COUPLING	Not Necessary	60.00 FS	*- FS
28	1		*HALOGEN FOG LAMP	Cracked	224.00 FS	*179.20 FS
29	1		*FLAT CONTACT HOUSING	Not Necessary	43.00 FS	*- FS
30	1		*SET SINGLE WIRES EACH WITH 2 CONTACTS	Not Necessary	33.00 FS	*- FS
31	1		*CAR PLATE-FRONT	Necessary	25.00 FS	*25.00 FS
32	1		*FRONT RIM-LH	Cut	911.20 FS	*911.20 FS
33	1		*SUNDRIES	Necessary	300.00 FS	*22.72 FS
34	1		*RADIATOR GRILLE	Cracked	485.20 FS	*485.20 FS
35	1		*BUMPER TOP COVER	Cracked	87.20 FS	*87.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,771.60** **7,637.32**

LKK Auto Consultants Pte Ltd/EY668H/13/12/2018 08:17

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND BOTH HEADLIGHT.REPAIR BONNET.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,700.00	1,500.00
3	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET	New	2,100.00	1,650.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,632.00	3,982.00

LKK Auto Consultants Pte Ltd/EY668H/13/12/2018 08:17

< END OF ESTIMATES >