

ASS. REC. BY:

REF: CS/C11/80/6320/Tlr d3/n2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Jaayn tay

of

CPI

Date/Time: 6/9/18 @ 4pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YL 3637J

Insured:

YP 8253D

at Workshop m/s

Falcon-Air Auto

Tel:

6779 5665

of

No 8 Pardon loop (Blk K/1)

Policy No: DMCVSN 3005121 800

Claim No:

SNM18D0432502

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

kup?

H.O.D. Endorsement:

Date/Time: 4:48pm @ 6/9/18

Person Contacted:

Andy

Vehicle: IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

YL 3637J - X

YP 8253D - X.

1/11/18

Confirm with Andy L/S \$1950.00 @ 3 days
(Red: \$798.46, 29%)

Summit

Taufik

REF:

CT1

ASSIGNMENT

Lot 2023 Aceh

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

RECEIVED 02 NOV 2018

Veh No:

YL3637 J

Yr Regn:

2003 Mach

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi FE637

C.C.

3908

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

83973

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FE639C 440443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00 R16

R:

7.00 (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kenda

Front

R/Bal.

6

mm

Rear

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

D.O.I.

12/9/18

Survey held at

Falcon Air Pandan.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt to Ls

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) typat



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format :

TP

Lump Sum / I.B. (\$

1950.00

TOTAL

320

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		06 Sep 2018 16:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	JURONG MARINE COLD STORAGE PTE LTD		
Vehicle Reg. No.:	YL3637J	Date of Loss:	05/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04325C02	Policy/Cover Note No.:	DMCVSN3005121800
Vehicle Reg. No. (Insured):	YP8253D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Falcon-air Auto Services Pte Ltd (pandan Loop) (HQ) No. 8 Pandan Loop (Blk K / Blk 1), 128226 West Coast - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]		
Adj Asg. Remarks:	EST \$2748.46, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, November 01, 2018 5:02 PM
To: 'ANDY'
Cc: Taufikh (LKKAUTO)
Subject: RE: YL 3637J

Dear Andy,

Confirm L/S \$ 1,950.00, 3 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANDY [<mailto:andy@falconair.com.sg>]
Sent: Monday, October 29, 2018 4:41 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: YL 3637J

Please Confirm finalise

L/S \$ 1850.00 3 days

Thanks
Andy
Tel # 67795665

From: Janice Lee (LKKAUTO) [<mailto:JaniceLee@lkkauto.com>]
Sent: Monday, October 29, 2018 4:36 PM
To: andy@falconair.com.sg
Subject: YL 3637J

Dear Andy,

Kindly help to check the claim status

- YL 3637J DOA : 05/09/2018

Have the vehicle been repair ? if yes, any finalize and resurvey photo?

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

» Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

0583D

Vehicle Details

Vehicle No.:

YL3637J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

05 Sep 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

FE639C6SRDEA

Primary Colour:

White

Manufacturing Year:

2003

Engine No.:

4D34J38025

Chassis No.:

FE639CA40443

Maximum Power Output:

-

Open Market Value:

\$26,325.00

Original Registration Date:

27 Mar 2003

First Registration Date:

27 Mar 2003

Transfer Count:

0

Actual ARF Paid:

\$1,317.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

28 Feb 2023

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$60,273.00

COE Rebate Amount:

\$27,033.00

Total Rebate Amount:

\$27,033.00

The information contained herein is correct as at 05 Sep 2018

OK



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

JURONG MARINE COLD STORAGE PTE LTD
11 FISHERY PORT ROAD SINGAPORE
619733

Attention : Motor Claim Department
Contact : 62656761 96781298 MR LEE

Estimate : ES003272

Date : 05/09/2018
Vehicle Num. : YL3637J
Make/Model : MITSUBISHI CANTER-FEB 2023 COE
Chassis/Eng#: FE639CA40443
Accident Date : 05/09/2018
Claim No. :
Reference : TP TMIS VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	RH FRONT DOOR		1,794.00 <i>bt</i>
2.	1	RH FRONT DOOR OUTER GARNISH		77.50 <i>mis</i>
3.	1	RH FRONT DOOR REGULATOR		315.58 <i>7.bf</i>
4.	1	RH FRONT DOOR LAMP		148.50 <i>cm</i>
List Total S\$:				2,335.58
20.00% Discount S\$:				467.12
				1,868.46

LABOUR :		
TO TRANSFER DOOR PARTS/MECHANISMS		50.00 <i>40.</i>
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		480.00 <i>300</i>
TO REPAIR DOOR FRONT RH PILLAR, RH CORNER PANEL		350.00 <i>250</i>
INCLUDES KNOCKING AND REPLACEMENT OF PARTS		
Labour Total S\$:		880.00

E. & O.E.

Total S\$: **2,748.46**



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD


(a subsidiary of Falcon Air Holdings Pte Ltd)

Tanfikh 97495749
12/9/18 @ 12pm.
3 days
sur elkhanto.com
Resurvey after repair.

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES003272

Date : 05/09/2018
Vehicle Num. : YL3637J
Make/Model : MITSUBISHI CANTER-FEB 2023 CO
Chassis/Eng# : FE639CA40443
Accident Date : 05/09/2018
Claim No. :
Reference : TP TMIS VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	RH FRONT DOOR		1,794.00
2.	1	RH FRONT DOOR OUTER GARNISH		77.50
3.	1	RH FRONT DOOR REGULATOR		315.58
4.	1	RH FRONT DOOR LAMP		148.50
		List TotalS\$:		2,335.58
		20.00% Discount S\$:		467.12
				1,868.46
		LABOUR :		
		TO TRANSFER DOOR PARTS/MECHANISMS		40.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		300.00
		TO REPAIR DOOR FRONT RH PILLAR, RH CORNER PANEL		
		INCLUDES KNOCKINGAND REPLACEMENT OF PARTS		250.00
		Labour Total S\$:		590.00

E. & O.E.

Total S\$: 2,458.46

for FALCON AIR AUTO SERVICES PTE LTD

less 20% - 497.00

1988.00

L/S 1950.00



FALCON-AIR

JURONG MARINE COLD STORAGE PTE LTD
11 FISHERY PORT ROAD SINGAPORE
619733

Attention : Motor Claim Department

Contact : 62656761 96781298 MR LEE

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

SNM18D04325C02 Jewyn 21/19

Clear

Estimate : ES003272

Date : 05/09/2018

Vehicle Num. YL3637J

Make/Model MITSUBISHI CANTER-FEB 2023 COE

Chassis/Eng# FE639CA40443

Accident Date 05/09/2018

Claim No.

Reference TP TMIS VS CHINA

Policy No.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		1,794.00 <i>bt</i>
2.	1	RH FRONT DOOR		77.50 <i>mis</i>
3.	1	RH FRONT DOOR OUTER GARNISH		315.58 <i>7</i>
4.	1	RH FRONT DOOR REGULATOR		148.50 <i>cm</i>
		RH FRONT DOOR LAMP		
		List Total S\$:		2,335.58
		20.00% Discount S\$:		467.12
				1,868.46

LABOUR :
TO TRANSFER DOOR PARTS/MECHANISMS
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
TO REPAIR DOOR FRONT RH PILLAR, RH CORNER PANEL
INCLUDES KNOCKING AND REPLACEMENT OF PARTS

50.00 *40*
480.00 *300*
350.00 *250*
880.00

Labour Total S\$:

E. & O.E.

Total S\$: 2,748.46

for FALCON AIR AUTO SERVICES PTE LTD

Tan Jiah 97491149

12/9/18 @ 12pm

3 days

sur elkhando.com

Resny after repair

LKK

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016320/T1RD3N2

Date: 05/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3005121800
Claimant Vehicle No :	YL3637J	Insured Vehicle No :	YP8253D
Date of Loss:	05/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04325C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YL3637J	Engine No:	4D34J38025
Make & Model:	MITSUBISHI CANTER, 3.9 D FE639C6SRDEA (M)	Chassis No:	FE639CA40443
Reg. Date:	27/03/2003 (Man. Year: 2003)	Odometer:	83973 km
Colour:	White		
Engine Capacity:	3908 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	Kenda 6 mm	Rear Left Side:	Kenda 6/6 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	Kenda 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,868.46	1,868.46	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	590.00	290.00	32.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,748.46	2,458.46	290.00	10.55
Approved Total (Overridden) (\$\$)		1,950.00		
(\$\$)	2,748.46	1,950.00	798.46	29.05
+ GST 7.00/7.00% (\$\$)	192.39	136.50	55.89	29.05
Nett Amount (\$\$)	2,940.85	2,086.50	854.35	29.05

INSPECTION

Date of Assignment: 06/09/2018
 Date Inspected: 12/09/2018 Inspected At:

Falcon-air Auto Services Pte Ltd
 (pandan Loop) (HQ)
 No. 8 Pandan Loop (Blk K / Blk 1)
 Singapore 128226

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Nov 2018)
Parts: N/A MITSUBISHI CANTER 3.9 D FE639C6SRDEA (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YL3637J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR	Bent	1,794.00 FL	*1,794.00 FL
2	1		*RH FRONT DOOR OUTER GARNISH	Missing	77.50 FL	*77.50 FL
3	1		*RH FRONT DOOR REGULATOR	Bent	315.58 FL	*315.58 FL
4	1		*RH FRONT DOOR LAMP	Cracked	148.50 FL	*148.50 FL
					Sub Total (\$\$)	2,335.58
					- List Item Discount on L Items 20.00/20.00% (\$\$)	467.12
					Total Parts (\$\$)	1,868.46

F=Franchise part L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER DOOR PARTS/MECHANISMS	New	50.00	40.00
2	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	New	480.00	300.00
3	TO REPAIR DOOR FRONT RH PILLAR,RH CORNER PANEL INCLUDES KNOCKING AND REPLACEMENT OF PARTS	New	350.00	250.00
Gross Labour Cost (\$\$)			880.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >