

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 10 Sep 2018

Preliminary Advice

Vehicle No	: SJG9799P	Accident Date	: 29/08/2018
Make	: HONDA AIRWAVE	Policy No.	: DMPCSN3032711804
Assignment Date	: 06/09/2018	Excess	: S\$3,500.00
Date of Inspection	: 07/09/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion. The body structure badly affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,322.49
Revised Amount	:S\$	9,030.49
Check Items (Estimated)	:S\$	1,082.00
Total	:S\$	10,112.49
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	36,735.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,265.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The front chassis badly bent, our surveyor recommended vehicle to be "Total Loss".