


REP:

ASSIGNMENT

COE 2025 July

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / HV / MV
 to be used Vehicle No: _____
 at Workshop no: _____
 of _____
 located _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **8HC 1341Z** Yr Reg: **July 2017**
 Type: **M, Car / M, Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or
 Make: **Toyota Prius** CC: **1798**
 Colour: **Blue** ACC: Insured / Std / NI / HA
 Sp. Branding: **216862** RT Radio: Insured / Std / NI / HA
 Eng No: **J2R3054195**
 Ch No: **5TOKB3FU503560593**
 Gen. Cond: **G** / Fair / Poor / Burnt
 Steering: **G** / Inoper / Jammed / Leaked / Burnt or
 Brake: **G** / Inoper / Jammed / Leaked / Burnt or
 Mod: **N** / STD A/Rim or
 Tyre Size: F: **195/65 R15**
 R: **— " —**



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or **Wastlake**

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Book: _____ Consistent? : Yes or No
 Est. Repairs: **14** days Res.: Yes or No
 Lump Sum: **20** % 3 Val: Yes or No

Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **05/09/2018** D.O.I: **10/09/2018**
 Survey held at **Chunni AMC**

CA / REV / REP. / 24 HRS

Dis. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
L/S Front of N/S Body of N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____
Lumpac 8GT 6676X

07/11/18 **known L/S 149501 - with 14 days of repair**

R (\$ 9,202.60 / 38%)

5 PDA w 198
 6 f 209
 7 F 2116
 8 22
 9 23/11
 M 10-2016 M 2415
 T 118 F 2514
 W 128
 T 134
 F 142
 15
 16
 M 176
 18 7

Date/Time, 120 Days for: : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

1) _____
 2) _____
 Report Format : _____
 Lump Sum / L.S.I. (\$) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos: _____
 Other: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18016364/jb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 07-09-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGY 6676X	Veh. Inspected	SHC 1341Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/09/2018	Inspection Date	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18016364/Djb3

Date: 25.09.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC1341Z

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.09.2018 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	24,152.60
Revised Estimate Amount	: S\$	19,784.12
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion & O/S Body & N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 12 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

Survey by LKK

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

LONPAC

VEHICLE NO: SHC 1341Z

DATE : 6.09.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FENDER SUB-ASSY, FRONT LH <i>Dental</i>			S 945.30	✓
FRONT FENDER SHIELD, LH <i>dentured</i>			S 196.60	✓
FRONT FENDER SHIELD CLIP <i>Nec</i>			S 3.80	✓
FRONT FENDER HYBRID EMBLEM, LH <i>Nec</i>			S 53.50	✓
PANEL SUB-ASSY, FRONT DOOR, LH <i>Dental</i>			S 1,238.50	✓
FRONT DOOR TRIMBOARD, LH <i>crack</i>			S 725.00	✓
FRONT DOOR WHETHER STRIP, LH <i>Nec</i>			S 226.80	✓
MOTOR ASSY, POWER WINDOW REGULATOR, FRT. LH <i>NAL</i>			S 768.90	X
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH <i>BT</i>			S 228.40	✓
MIRROR ASSY, OUTER REAR VIEW, LH <i>crack</i>			S 1,374.00	✓
COVER, OUTER MIRROR, LH <i>new</i>			S 141.90	X
MIRROR OUTER, LH <i>new</i>			S 212.80	X
ROCKER PANEL OUTER, LH <i>cut</i>			S 559.20	✓
FRONT PILLAR UPPER COVER, LH <i>NAL</i>			S 96.00	X
FRONT WHEEL RIM (LH) <i>cut</i>			S 1,555.10	✓
FRONT WHEEL HUB BEARING (LH) <i>Dem</i>			S 560.10	✓
FRONT SHOCK ABSORBER (LH) <i>distorted</i>			S 401.80	✓
FRONT SUSPENSION LOWER ARM (LH) <i>distorted</i>			S 637.50	✓
FRONT DRIVE SHAFT (LH) <i>distorted</i>			S 1,186.20	X
RACK & PINION ASSY <i>Dem</i>			S 1,621.30	X
LINK ASSY, FRONT STABILIZER, LH <i>distorted</i>			S 199.00	✓
KNUCKLE, STEERING, LH <i>distorted</i>			S 562.30	✓
END SUB-ASSY, TIE ROD, LH <i>distorted</i>			S 158.10	✓
			SUB TOTAL	
			25% LESS 20%	
			DISCOUNTED TOTAL	
			S 13,652.10	
			S 2,730.42	
			S 10,921.68	
FRONT DOOR COMFORT LOGO <i>Nec</i>			S 75.00	NETT ✓
FRONT TYRE (LH) <i>NAL</i>			S 216.00	NETT X
			S 291.00	

Q 0046
12432.50
9324.37

Q 75
75.00

SHC 1341Z

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER <i>new</i>			\$ 458.60	X
REAR BUMPER CLIPS <i>new</i>			\$ 22.00	✓
REAR FENDER, LH <i>Dented</i>			\$ 817.50	✓
REAR FENDER SHEILD (LH) <i>new</i>			\$ 134.20	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Dented</i>			\$ 1,227.00	✓
RAER DOOR RUBBER SEAL, LH <i>SVC</i>			\$ 257.90	X
REAR TYRE RIM ,LH <i>Scratched</i>			\$ 1,555.00	✓
REAR WHEEL BEARING ING & HUB , LH <i>new</i>			\$ 560.10	✓
REAR CROSS MEMBER <i>2 distorted</i>			\$ 2,179.40	✓
REAR SHOCK ABSORBER, LH <i>2 distorted</i>			\$ 118.30	✓
REAR SHOCK ABSORBER MOUNTING, L <i>new</i>			\$ 125.30	✓
REAR LOWER ARM, LH <i>2 distorted</i>			\$ 345.70	✓
REAR UPPER ARM, LH <i>2 distorted</i>			\$ 348.80	✓
REAR KNUCKLE ARM, LH <i>2 distorted</i>			\$ 810.60	✓
REAR STABILIZER BAR <i>2 distorted</i>			\$ 311.50	✓
REAR STABILIZER LINK, LH <i>2 distorted</i>			\$ 151.60	✓
REAR TRAILING ARM, LH <i>2 distorted</i>			\$ 314.20	✓
REAR ASSIST ARM, LH <i>2 distorted</i>			\$ 342.20	✓
			SUB TOTAL	
			<i>25% LESS 20%</i>	
			DISCOUNTED TOTAL	
			\$ 10,079.90	
			\$ 2,015.98	
			\$ 8,063.92	
REAR DOOR COMFORT & APPS STICKER <i>new</i>			\$ 80.00	NETT ✓
REAR TYRE ,LH <i>new</i>			\$ 216.00	NETT X
			\$ 296.00	
LABOUR CHARGE				
Panel Beating			\$ 1,500.00	800/-
Spray Painting Charge			\$ 1,700.00	1000/-
Wiring Charge			\$ 50.00	new
Tuff Kote			\$ 100.00	40/-
Towing Charge			\$ 50.00	new
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
Remove/Refix Reverse Sensor			\$ 120.00	new
Remove/Refix Undercarriage (FRT)			\$ 200.00	new 150/-
Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
Remove/Refix Fuel Tank			\$ 150.00	new
Transfer of Door		\$ 120.00	\$ 240.00	120/-
Four Wheel Alignment			\$ 120.00	60/-
			TOTAL LABOUR	
			\$ 18,707.29	
			ESTIMATE TOTAL	
			\$ 24,152.60	

LKK Auto Consultants Please note the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *[Signature]*
Date: *[Date]*

Approved
9103.90
6827.92

80.00

10/09/2018 @ 1300h
not Antrol
L/Sant
14 days

2400/-

[Signature]

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 1341 Z

Technician:

Mileage: 216855

Time Printed 7.9.18 4:01 PM

TOYOTA PRIUS

Front : Left

Actual	BEFORE	Specified Range
4°32'		-1°20' 0°10'
6°24'		2°25' 3°55'
-22°16'		-0°06' 0°06'
18°30'		11°50' 13°20'
23°02'		10°30' 13°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-9°45'		-1°20' 0°10'
6°28'		2°25' 3°55'
-0°03'		-0°06' 0°06'
26°11'		11°50' 13°20'
16°26'		10°30' 13°30'

Front

	Actual	BEFORE	Specified Range
Cross Camber	14°17'		-0°45' 0°45'
Cross Caster	-0°05'		-0°45' 0°45'
Cross SAI	-7°41'		-0°45' 0°45'
Total Toe	-22°19'		-0°12' 0°12'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
11°48'		-2°00' -1°00'
25°57'		0°02' 0°17'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°09'		-2°00' -1°00'
-0°04'		0°02' 0°17'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	11°58'		-0°30' 0°30'
Total Toe	25°54'		0°03' 0°33'
Thrust Angle	13°00'		

Shu Pei (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 21 September 2018 9:31 AM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG; Joy Irene (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC20/020885 Accident involving SGY6676X and SHC1341Z on 05.09.18
Attachments: 21092018092752.pdf

Dear Shu Pei,

Attached copy of insured's GIA report for your attention

Kindly assess liability before proceeding with direct settlement as our insured is claiming against the third party.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 20 September, 2018 7:08 PM
To: ONG LI LI
Cc: MT_Claim_SG; Joy Irene (LKKAuto)
Subject: RE: Our Ref: 18/18/18/VC20/020885 Accident involving SGY6676X and SHC1341Z on 05.09.18

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 6 September 2018 4:22 PM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Our Ref: 18/18/18/VC20/020885 Accident involving SGY6676X and SHC1341Z on 05.09.18

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 07/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Thursday, 6 September 2018 4:06 PM
To: assignments@lkkauto.com; Nivitha (LKK Auto) <admin-d@lkkauto.com>; chunnimotor@gmail.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Our Ref: 18/18/18/VC20/020885 Accident involving SGY6676X and SHC1341Z on 05.09.18

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 06.09.18.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	

8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Dear Catherine/Nivitha

Please follow up.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 6 September 2018 4:06 PM
To: assignments@lkkauto.com; Nivitha (LKK Auto); chunnimotor@gmail.com
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VC20/020885 Accident involving SGY6676X and SHC1341Z on 05.09.18
Attachments: 06092018154255.pdf

4:20pm @ 6/9/2018
vehicle in
person @ Lynn
average on 7/9/18

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 06.09.18.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Dear Catherine/Nivitha

Please follow up.

Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

CHUNNI MOTOR WORK
PTE LTD



Date : 06.09.18

To : Lonpac Insurance Bhd

No of Pages : 9

Re : Accident involving veh no: SHC 1341Z & SGY 6676X Along
Tannery Lane towards Soon Wing Road on 05.09.18

We refer to the above mention matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey at AMK Autopoint, Soon Hock Motor, #01-05/06,

Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162. Email : chunnimotor@gmail.com

Thank you for your kind assistance.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18016364/Djb3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGY 6676X	Veh. Inspected	SHC 1341Z
Policy No.	Z/18/VC20/101680-001	Coverage (\$)	0.00
Claim No.	18/18/18/VC20/020885	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	06/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU503560593	Colour	BLUE
Odometer	216862	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION, N/S BODY AND N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/09/2018	Inspection Date	10/09/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1341Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER SUB-ASSY, FRONT LH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD, LH	DEFORMED	196.60	196.60
1	FRONT FENDER SHIELD CLIP	NECESSARY	3.80	3.80
1	FRONT FENDER HYBRID EMBLEM, LH	NECESSARY	53.50	53.50
1	PANEL SUB-ASSY, FRONT DOOR, LH	DENTED	1,238.50	1,238.50
1	FRONT DOOR TRIMBOARD, LH	CRACKED	725.00	725.00
1	FRONT DOOR WEATHER STRIP, LH	NECESSARY	226.80	226.80
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT, LH	NOT NECESSARY	768.90	-
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	BENT	228.40	228.40
1	MIRROR ASSY, OUTER REAR VIEW, LH	CRACKED	1,374.00	1,374.00
1	COVER, OUTER MIRROR, LH	TO REPAIR SEE LABOUR	141.90	-
1	MIRROR OUTER, LH	TO REPAIR SEE LABOUR	212.80	-
1	ROCKER PANEL OUTER, LH	CUT	559.20	559.20
1	FRONT PILLAR UPPER COVER, LH	NOT NECESSARY	96.00	-
1	FRONT WHEEL RIM (LH)	CUT	1,555.10	1,555.10
1	FRONT WHEEL HUB BEARING (LH)	DAMAGED	560.10	560.10
1	FRONT SHOCK ABSORBER (LH)	DISTORTED	401.80	401.80
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	637.50	637.50
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,186.20	1,186.20
1	RACK & PINION ASSY	DAMAGED	1,621.30	1,621.30
1	LINK ASSY, FRONT STABILIZER, LH	DISTORTED	199.00	199.00
1	KNUCKLE, STEERING LH	DISTORTED	562.30	562.30
1	END SUB-ASSY, TIE ROD, LH	DISTORTED	158.10	158.10
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER, LH	DENTED	817.50	817.50
1	REAR FENDER SHIELD (LH)	NOT NECESSARY	134.20	-
1	PANEL SUB-ASSY, REAR DOOR, LH	DENTED	1,227.00	1,227.00
1	REAR DOOR RUBBER SEAL, LH	SERVICEABLE	257.90	-

Report Ref No. CC4/LPC18016364/Djb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TYRE RIM, LH	SCRATCHED	1,555.00	1,555.00
1	REAR WHEEL BEARING ING & HUB, LH	DAMAGED	560.10	560.10
1	REAR CROSS MEMBER	DISTORTED	2,179.40	2,179.40
1	REAR SHOCK ABSORBER, LH	DISTORTED	118.30	118.30
1	REAR SHOCK ABSORBER MOUNTING, L	NOT NECESSARY	125.30	-
1	REAR LOWER ARM, LH	DISTORTED	345.70	345.70
1	REAR UPPER ARM, LH	DISTORTED	348.80	348.80
1	REAR KNUCKLE ARM, LH	DISTORTED	810.60	810.60
1	REAR STABILIZER BAR	DISTORTED	311.50	311.50
1	REAR STABILIZER LINK, LH	DISTORTED	151.60	151.60
1	REAR TRAILING ARM, LH	DISTORTED	314.20	314.20
1	REAR ASSIST ARM, LH	DISTORTED	342.20	342.20
	LESS 20% DISCOUNT		-4,746.40	-
	LESS 25% DISCOUNT		-	-5,384.11
			18,985.60	16,152.29
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
1	REAR DOOR COMFORT & APPS STICKER (SN)	NECESSARY	80.00	80.00
1	REAR TYRE, LH (SN)	NOT NECESSARY	216.00	-
			587.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF COVER, OUTER MIRROR, LH; MIRROR OUTER, LH AND REAR BUMPER.		1,500.00	800.00
	SPRAY PAINTING CHARGE.		1,700.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE / REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	REMOVE / REFIX UNDERCARRIAGE (RR).		200.00	150.00

Report Ref No. CC4/LPC18016364/Djb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR.		240.00	120.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
			4,580.00	2,400.00
GRAND TOTAL			24,152.60	18,707.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,950.00

Report Ref No. CC4/LPC18016364/Djb3s2

ANG BRYAN TANI

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.