

REF: CS1/SPF18016368/ Bsd3⁵²

Special Instruction:

P/p: \$ 11498.16

ASSIGNMENT (Office)

From (Person): Frankie Thay of SPF Date/Time: 6/9/18

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: L.B.S Auto Consultant

Workshop: World Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLG 7475M

Insured: GBC 7544 L

at Workshop m/s World Auto

Tel: 63621776

of _____ No. 1 Krunji Group

Policy No:

Claim No: AEMD/105/009/2017/173

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/12/2017


(Client's Record)

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 6 days)

Date/Time: 13/09/18 Submit Final Fig \$ 7,193.04, 5 days (Red \$ 4,295.12/37%; Original 6 days)

Date/Time	Action/Instruction
	SLG7475M-X
	GBC7544L - CS/SPF18000586/1/rbe2
	Frankie said. Unable to provide the GIA Report.
	DOA: -
	
	12/9/2018

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 13 SEP 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

Nivitha (LKK Auto)

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Sent: Thursday, 6 September 2018 3:19 PM
To: Frankie THAY (SPF); assignments
Cc: Abdul Rahman MOHAMAD SALIM (SPF); SUR
Subject: [SPF]: Post survey for SLG7475M (AEMD/105/009/2017/173
Attachments: 2017-173 SLG7475M survey report.pdf; 2017-173 SLG7475M.jpeg

Hi Frankie,

Thank you for your email.

Assignments Team – Kindly handle.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Make
good
use of
Today*

From: Frankie THAY (SPF) [mailto:Frankie_THAY@spf.gov.sg]
Sent: Wednesday, 5 September, 2018 5:08 PM
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Cc: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Re: Post survey for SLG7475M (AEMD/105/009/2017/173

Olivia,

Please conduct a post survey for SLG7475M which was already repaired.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Friday, 7 September 2018 4:00 PM
To: Nivitha (LKK Auto); 'assignments'
Cc: Abdul Rahman MOHAMAD SALIM (SPF)
Subject: RE: [SPF]: Post survey for SLG7475M (AEMD/105/009/2017/173)

Your reference : SLG7475M (Post Survey)
Our reference: AEMD/105/009/2017/173

Nivitha,
We spoke, unable to provide the GIA for SLG7475M.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DiD: (65) 6478 4841 | FAX: (65) 6478 4848



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Friday, 7 September 2018 3:06 PM
To: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; 'assignments' <assignments@lkkauto.com>
Cc: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: RE: [SPF]: Post survey for SLG7475M (AEMD/105/009/2017/173)

Dear Frankie,

Kindly assist to provide GIA Report for both parties.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto) [<mailto:olivialau@lkkauto.com>]
Sent: Thursday, 6 September 2018 3:19 PM
To: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>; SUR



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLG7475M

Our Ref : AEMD/105/009/2017/173

Tel: 64784841
Fax: 64784848

Date : 5 Sep 2018

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 # 01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT INVOLVING GOVT VEHICLE GBC 7544L AND OTHER VEHICLE SLG7475M

We refer to the above matter.

- 2 Kindly arrange for a paper survey for SLG 7475M
- 3 Third party survey will be provided.
- 4 Thank you.

Yours faithfully,

Frankie Thay
Safe Driving Manager
for ASST DIRECTOR

A FORCE FOR THE NATION

L.B.S. AUTO CONSULTANTS PTE LTD

Co. Reg. No.: 200311321D

Serangoon Garden Post Office PO Box 398

Singapore 915530

Telephone: 65-62832866 Facsimile: 65-62832166

AUTOMOBILE INSPECTION REPORT

WORLD AUTO PTE LTD

NO 1 KRANJI LOOP

SINGAPORE 739535

OUR REFERENCE: LBS/MISC/17/12/H082/WA

REFERENCE: THIRD PARTY CLAIM

VEHICLE NUMBER : SLG 7475M

ACCIDENT DATE : 13.12.2017

PARTICULARS OF DAMAGED VEHICLE:

MAKE	: HONDA VEZEL 1.5X CVT	MODEL	: 2016
COLOUR	: SILVER	MILEAGE KM	: -
ENGINE NUMBER	: 1496 CC	V.I.N.	: RU11202326

STATIC CHECKS: GENERAL CONDITION: GOOD

STEERING: DAMAGED

BRAKES: DAMAGED

TYRE CONDITIONS: SIZE: 215/65R15

FRONT N/S : 4 MM

FRONT O/S : 4 MM

REAR N/S : 5 MM

REAR O/S : 5 MM

Percentages denote the remaining estimated life of the tyre threads

INSPECTION DETAILS AND ADJUSTMENTS: KINDLY SEE SCHEDULE/S OVERLEAF

ORIGINAL QUOTATION: \$ 13,975.44

REVISED QUOTATION: \$ 11,488.16

ESTIMATED NORMAL PERIOD FOR REPAIR: 06 WORKING DAYS

POINT OF IMPACT/S

The impacts were confined to the off side front fender broadside and off side front wheel portion of the vehicle.

REMARKS

Nil

L.B.S. AUTO CONSULTANTS PTE LTD

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

WORKSHOP:

WORLD AUTO PTE LTD
NO 1 KRANJI LOOP
SINGAPORE 739535

OUR REFERENCE: LBS/MISC/17/12/H082/WA

QTY DESCRIPTIONS

CONDITION

ORIGINAL QUOTATION REVISED QUOTATION

VEHICLE NUMBER: SLG 7475M

1	Front bonnet	Distorted	\$ 819.00	\$ 819.00 DD ✓
1	Front bonnet insulator	Torn	\$ 288.00	\$ -288.00 NHX
1	Front rh fender	Distorted	\$ 580.00	\$ 580.00 DD ✓
1	Front rh fender "Hybrid" emblem	Necessary	\$ 86.80	\$ 86.80 NEC ✓
1	Front rh fender wheel arc moulding	Dislodged	\$ 172.30	\$ 172.30 CUT ✓
1	Front rh headlamp assembly	Cracked	\$ 1,850.00	\$ 1,850.00 CR ✓
1	Front rh headlamp lower bracket	Cracked	\$ 78.80	\$ 78.80 CR ✓
1	Radiator grille	Scratched	\$ 1,386.40	\$ ^{500.00} 1,386.40 SCR ✓
1	Radiator grille bracket	Cracked	\$ 78.60	\$ 78.60 CR ✓
1	Front bumper	Deformed/Torn	\$ 955.00	\$ ^{800.00} 955.00 DD ✓
1	Front bumper lower cover	Torn	\$ 233.60	\$ 233.60 TN ✓
1	Front bumper lower grille	Serviceable	\$ 280.00	\$ -
1	Front rh bumper fog lamp cover	Serviceable	\$ 68.00	\$ -
1	Front rh bumper fog lamp garnish	Serviceable	\$ 68.00	\$ -
1	Front rh fog lamp	Serviceable	\$ 324.60	\$ -
1	Front support panel top garnish	Serviceable	\$ 250.00	\$ -
1	Front support panel	Distorted	\$ 723.20	\$ ^{576.20} 723.20 DD ✓
1	Front rh lower arm	Distorted	\$ 555.00	\$ -555.00 SVC X
1	Front rh steering knuckle	Distorted	\$ 550.00	\$ 550.00 SVC X
1	Front rh steering knuckle bearing	Distorted	\$ 120.00	\$ 120.00 JM ✓
1	Front rh strut assembly	Distorted	\$ 700.00	\$ 700.00 SVC X
1	Steering rh tie rod end	Serviceable	\$ 280.00	\$ -
1	Wheel rim	Repair	\$ 250.00	\$ -
1	Front bumper tow cover	Dislodged	\$ 20.00	\$ 20.00 MIS ✓
1	Front bumper reinforcement	Distorted	\$ 380.00	\$ 380.00 DD ✓
1	Front rh headlamp top bracket	Cracked	\$ 30.00	\$ 30.00 CR ✓
1	Front rh fender inner liner	Torn	\$ 110.00	\$ 110.00 TN ✓
1	Front rh wheelhouse ext inner panel	Distorted	\$ 300.00	\$ 300.00 SVC X
1	Front rh wheelhouse ext outer panel	Distorted	\$ 300.00	\$ 300.00 SVC X
1	Front rh bumper side retainer	Dislodged	\$ 30.00	\$ 30.00 CUT ✓
1	Front lh bumper side retainer	Serviceable	\$ 30.00	\$ -
1	Front rh wheelhouse inner panel	Distorted	\$ 390.00	\$ -390.00 SVC X
1	Front rh wheelhouse outer panel	Distorted	\$ 390.00	\$ 390.00 SVC X
1	Wiper washer tank	Deformed	\$ 150.00	\$ ^{80.00} 150.00 DD ✓
1	Front rh stabilizer link	Distorted	\$ 96.00	\$ 96.00
			\$ 12,923.30	\$ 11,372.70
Less 20%			\$ 2,584.66	\$ 2,274.54
			\$ 10,338.64	\$ 9,098.16
<u>Special Nett</u>				
1	Front bumper clips (set)	Necessary	\$ 78.40	\$ 30.00 NEC ✓
1	Front fender wheel arc moulding clips (set)	Necessary	\$ 78.40	\$ 30.00 NEC ✓

L.B.S. AUTO CONSULTANTS PTE LTD

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS:

Towing.	\$ 60.00	\$ 60.00
To respray front bonnet, front bumper, support panel, front rh fender .	\$ 1,200.00	\$ 900.00 <i>800.00</i>
To labour charge for removing front bonnet, front bumper, support panel, front lh fender out to facilitate repair & replacement of damaged parts.	\$ 1,000.00	\$ 750.00 <i>600.00</i>
To conduct wheel alignment.	\$ 180.00	\$ 80.00
To labour charge for removing front rh suspension system out to facilitate repair & replacement damaged parts.	\$ 280.00	\$ 150.00 <i>100.00</i>
To conduct a standard of operating procedure post repair diagnostic scan test as a requirement for hybrid cars upon completion of collision repair.	\$ 380.00	\$ 150.00 <i>80.00</i>
To deactivate & activate high voltage hybrid battery as a requirement for safety precaution.	\$ 380.00	\$ 240.00 <i>100.00</i>
	<u>\$ 13,975.44</u>	<u>\$ 11,488.16</u>

This inspection is conducted on a "Without Prejudice" basis.

INSTRUCTION RECEIVED:

FROM: Messrs World Auto Pte Ltd

ON: 18.12.2017

DATE OF INSPECTION: 18.12.2017

DATE OF REPORT: 13.07.2018

L.B.S. AUTO CONSULTANTS PTE LTD



Gary Chuah Poh Siong
Automotive Appraiser

Repair days 5



Your Ref: AEMD/105/009/2017/173

Date: 28th September 2018

Our Ref: CS1/SPF18016368/Bsd3s2

M/s Automotive Engineering & MGT Division

Contract Management Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLG 7475M INSURED VEHICLE: GBC 7544L ACCIDENT DATE: 13/12/2017**

We thank you for your instruction on 06/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLG 7475M from M/s L.B.S Auto Consultants Pte Ltd.
- b) Colour damaged vehicle photographs of SLG 7475M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLG 7475M
Make & Model	: Honda Vezel 1.5X CVT
Year of Registration	: 2016
Chassis Number	: RU11202326
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7475M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	DENTED	819.00	819.00
1	FRONT BONNET INSULATOR	NOT NECESSARY	288.00	-
1	FRONT RH FENDER	DENTED	580.00	580.00
1	FRONT RH FENDER "HYBRID" EMBLEM	NECESSARY	86.80	86.80
1	FRONT RH FENDER WHEEL ARC MOULDING	CUT	172.30	172.30
1	FRONT RH HEADLAMP ASSEMBLY	CRACKED	1,850.00	1,850.00
1	FRONT RH HEADLAMP LOWER BRACKET	CRACKED	78.80	78.80
1	RADIATOR GRILLE	SCRATCHED	1,386.40	500.00
1	RADIATOR GRILLE BRACKET	CRACKED	78.60	78.60
1	FRONT BUMPER	DENTED	955.00	800.00
1	FRONT BUMPER LOWER COVER	TORN	233.60	233.60
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	280.00	-
1	FRONT RH BUMPER FOG LAMP COVER	SERVICEABLE	68.00	-
1	FRONT RH BUMPER FOG LAMP GARNISH	SERVICEABLE	68.00	-
1	FRONT RH FOG LAMP	SERVICEABLE	324.60	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	250.00	-
1	FRONT SUPPORT PANEL	DENTED	723.20	576.20
1	FRONT RH LOWER ARM	SERVICEABLE	555.00	-
1	FRONT RH STEERING KNUCKLE	SERVICEABLE	550.00	-
1	FRONT RH STEERING KNUCKLE BEARING	JAMMED	120.00	120.00
1	FRONT RH STRUT ASSEMBLY	SERVICEABLE	700.00	-
1	STEERING RH TIE ROD END	SERVICEABLE	280.00	-
1	WHEEL RIM	TO REPAIR SEE LABOUR	250.00	-
1	FRONT BUMPER TOW COVER	MISSING	20.00	20.00
1	FRONT BUMPER REINFORCEMENT	DENTED	380.00	380.00
1	FRONT RH HEADLAMP TOP BRACKET	CRACKED	30.00	30.00
1	FRONT RH FENDER INNER LINER	TORN	110.00	110.00
1	FRONT RH WHEELHOUSE EXT INNER PANEL	SERVICEABLE	300.00	-
1	FRONT RH WHEELHOUSE EXT OUTER PANEL	SERVICEABLE	300.00	-
1	FRONT RH BUMPER SIDE RETAINER	CUT	30.00	30.00

Report Ref No. CS1/SPF18016368/Bsd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH BUMPER SIDE RETAINER	SERVICEABLE	30.00	-
1	FRONT RH WHEELHOUSE INNER PANEL	SERVICEABLE	390.00	-
1	FRONT RH WHEELHOUSE OUTER PANEL	SERVICEABLE	390.00	-
1	WIPER WASHER TANK	DENTED	150.00	80.00
1	FRONT RH STABILIZER LINK	DISTORTED	96.00	96.00
	LESS 20% DISCOUNT		-2,584.66	-1,328.26
			10,338.64	5,313.04
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	78.40	30.00
1	SE FRONT FENDER WHEEL ARC MOULDING CLIPS (SN)	NECESSARY	78.40	30.00
			156.80	60.00
	<u>LABOUR</u>			
	TOWING.		60.00	60.00
	TO RESPRAY FRONT BONNET, SUPPORT PANEL, FRONT RH FENDER.		1,200.00	800.00
	TO LABOUR CHARGE FOR REMOVING FRONT BONNET, FRONT BUMPER, SUPPORT PANEL, FRONT LH FENDER OUT TO FACILITATE REPAIR & REPLACEMENT OF DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF WHEEL RIM.		1,000.00	600.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	80.00
	TO LABOUR CHARGE FOR REMOVING FRONT RH SUSPENSION SYSTEM OUT TO FACILITATE REPAIR & REPLACEMENT DAMAGED PARTS.		280.00	100.00
	TO CONDUCT A STANDARD OF OPERATING PROCEDURE POST REPAIR DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIR.		380.00	80.00
	TO DEACTIVATE & ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTION.		380.00	100.00
			-	-
			-	-
			-	-
			3,480.00	1,820.00
	GRAND TOTAL		13,975.44	7,193.04

Report Ref No. CS1/SPF18016368/Bsd3s2



RECOMMENDED COST OF REPAIRS			7,193.04
-----------------------------	--	--	----------

Report Ref No. CS1/SPF18016368/Bsd3s2

LIM TEOW GUAN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.