

ASS. REC. BY:

REF: CS/AIG18016381/Acd3n2

Special Instruction:

Surveyor: Adrian
Memmen

ASSIGNMENT (Office)

From (Person): Chan Yoke Shi of AIG

Date/Time: 7/9/18 @ 3:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 2377U

Insured: SLK 3562A

at Workshop m/s Hiang Hee Motor

Tel: 9752 7252

of 1 Kaki Bkt Ave 6 # 01-62

Policy No: 0999994759

Claim No: F12976442856

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 3:20pm @ 7/9/18

Person Contacted: David

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBF 2377U - x</u>
	<u>SLK 3562A - x</u>

REF: AIG

ASSIGNMENT

From: Date: 7/19/18

Veh No: GBF2377U Yr Regn: 2016 / August.
Type: M.Car / M.Cycle / Bus / Van (Lorry) / Taxi / Prime Mover /

Estimated Cost:
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or
Make: Toyota Dyna. C.C. 2982
Colour: Silver. A/C: Insured / Std / NI / NA
Sp. Reading: 34755 T/Radio: Insured / Std / NI / NA

To inspect Vehicle No: GBF 2377U
at Workshop n/s: Liang Hee
of 1 Kaki Skt Ave 6 # 01-62

Eng/No:
C/No: ~~JEAT~~ JTFAT-35Y 301c 206761
Gen. Cond: (Good) / Fair / Poor / Burnt

Insured
Policy No.
Claims No.

Steering: (In order) / Jammed / Leaked / Burnt or
Brake: (In order) / Jammed / Leaked / Burnt or
Modi: (Nil) / S/Rim / STD A/Rim or

Sum Insured: Excess:
(Client's Record)

Tyre Size: F: 195 R15 Rucingmax
R: 155 R12C BSU

Make of Veh:

N/S	O/S

(Policy Condition)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Remark: The veh had commenced its repair at the time of inspection.

Front		Rear
R/Bal.	06 mm	R/Bal. 06 mm
L/Bal.	06 mm	L/Bal. 06 mm
D.O.A.		D.O.I. 07/09/18.

Bal. or Market Value:

Survey held at: Liang Hee.

IDAC Accident Rpt: Consistent? : Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front o/s.

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. 1-24 HRS (up)

The U/C / Chassis frame / Body Structure affected due to collision.

Date: Person Contacted: Vehicle: IN / OUT

Date / Time	Action / Instruction
	TP AIG.
6/12	Adrian confirmed LS \$8,050 with repairer. (Red. 10,525.12, 56%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$) 8050

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: \$ + RS. \$

Transportation: 250
20

Photos
Others

TOTAL: 270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18016381/Ard3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-09-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 3562A	Veh. Inspected	GBF 2377U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHAN YOKE SHI	Assign Date	07/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/09/2018	Inspection Date	07/09/2018
Survey held at	LIANG HEE MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-62 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Pre repair inspection request - GBF2377U VS SLK3562A (OI) DOA 05/09/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, Admin A
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azian, Syazairdina
Sent: 7/9/2018 3:05:37 PM
Attachments:  SLK3562A(2).tif

Hi,

Please refer to the enclosed request from JusEquity Law Corporation.

Claim no : 71297644285G003
Case Owner : KHOO KAY ENG

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

From: juseq@singnet.com.sg [mailto:juseq@singnet.com.sg]
Sent: Friday, September 07, 2018 1:03 PM
To: Chan, Yoke Shi
Cc: juseq@singnet.com.sg
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK3562A AND GBF2377U ON 05/09/2018

Your ref: SLK3562A
Our ref: JEQ/GBF2377U/LHEE

Dear Yoke Shi,

We refer to your email today.

Our client is agreeable to appoint the following surveyor as our single joint expert.

[Adrian Ling- LKK Auto Consultants Pte Ltd](#)

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

Liang Hee Motor Workshop

1 Kaki Bukit Ave 6 #01-62,
Singapore 417883
Tel:9752 7252 Fax: 6747 2935
Person in charge : David

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:
This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

From: Chan, Yoke Shi
Sent: Fri, 7 Sep 2018 03:18:03 +0000

To: juseq@singnet.com.sg

Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Azlan, Syazairdina

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK3562A AND GBF2377U ON 05/09/2018

Without Prejudice

Your Reference : JEQ/GBF2377U/L.HEE(zl)
Our Reference : SLK3562A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Jusequity Law Corporation

ADVOCATES & SOLICITORS - COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877
Telephone (65) 6536 9339. (65) 6253 1812. (65) 6397 2008. (65) 6533 2327
Fax : (65) 6263 0120 (Conveyancing) . (65) 6536 5368 (Litigation)
Email : juseq@juseqnet.com.sg

Our Ref: JEQ/GBF2377U/ L.HEE (zi)

Your Ref:

6 September 2018

LCRF PTE LTD
60 Anson Road #11 - 01
Mapletree Anson
Singapore 079914
(Owner **SLK3562A**)

NI WEIYI
527 Bedok Reservoir Road #01 - 95
Singapore 479280
(Owner **SLL7314T**)

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore
(Insurers for **SLK3562A**)

TOKIO MARINE INSURANCE SINGAPORE LTD
Singapore
(Insurers for **SLL7314T**)

Dear Sir

ACCIDENT INVOLVING GBF2377U, SLK3562A & SLL7314T ON 05.09.2018

We act for the owner of vehicle no. GBF2377U.

We hereby notify you of a road traffic accident on 5 September 2018 at about 1835 hrs, at Bartley Road - Braddell Road involving our client's vehicle and vehicle registration no. **SLK3562A & SLL7314T** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Enc:

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

Liang Hee Motor Workshop
 1 Kaki Bukit Ave 6 Autobay
 Singapore 417883

TPALG.

Janice

Vehicle Registration Number: GBF2377U
 Make and Model : Toyota Dyna
 Chassis Number: JTFAT35Y30K206761
 Registration Date: 2016 August
 Date Of Accident: 5th September 2018

No	Quantity	Part Description (List Price)	Unit Price	Amount
1	1	Front Bumper <i>Distorted.</i>	481.60	481.60 ✓
2	1	Front Bumper Bracket RH <i>Bent</i>	165.30	165.30 ✓
3	1	Front Grille <i>Crushed</i>	488.30	488.30 ✓
4	1	Front Grille Logo <i>new</i>	68.10	68.10 ✓
5	1 Set	Front grille Clips <i>new</i>	20.00	20.00 ✓
6	1	Headlamp RH <i>crushed.</i>	593.20	593.20 ✓
7	1	Headlamp Lower Rubber <i>wt</i>	35.90	35.90 ✓
8	1 Set	Headlamp Lower Rubber Clips <i>new</i>	10.00	10.00 ✓
9	1	Front Panel <i>Distorted</i>	1245.10	1245.10 ✓
10	1	Front Panel Dyna Wording <i>new</i>	68.30	68.30 ✓
11	1	Front Corner Panel RH <i>Distorted.</i>	288.00	288.00 ✓
12	1	Front Panel Top Centre Moulding <i>wt</i>	288.30	288.30 ✓
13	1	Front Panel Top Moulding RH <i>wt</i>	107.40	107.40 ✓
14	1	Front Step Garnish RH <i>Distorted</i>	282.00	282.00 ✓
15	1	Front Door RH <i>Distorted</i>	1450.50	1450.50 ✓
16	1	Front Door Lock RH <i>new</i>	245.60	245.60 ✗
17	1	Front Door Weatherstrip RH <i>wt</i>	195.60	195.60 ✓
18	2	Front Door Hinge RH <i>Bent.</i>	79.50	159.00 ✓
19	1	Front Door Check RH <i>new</i>	98.70	98.70 ✗
20	1	Front Door Inner Trim RH <i>crushed</i>	581.80	581.80 ✓
21	1 Set	Front Door Inner Trim Clips RH <i>new</i>	30.00	30.00 ✓
22	1	Front Door Glass Regulator Gear RH <i>new</i>	295.60	295.60 ✗
23	1	Front Door Glass Regulator Motor RH <i>new</i>	489.60	489.60 ✗
24	1	Front Wheel Arc Panel RH <i>Repairs</i>	516.20	516.20 ✗
25	1	Front Wheel Arc Panel Garnish RH <i>Defunct</i>	139.80	139.80 ✓
26	1	Front Windscreen Moulding <i>new</i>	268.70	268.70 ✓
27	1	Front Lower Arm RH	688.20	688.20 ✗
28	1	Front Upper Arm RH	489.00	489.00 ✗
29	1	Front Shock Absorber RH <i>new</i>	210.90	210.90 ✗
30	1	Front Knuckle Arm RH	581.90	581.90 ✗
31	1	Front Wheel Hub C/W Bearing RH <i>new</i>	563.00	563.00 ✗
32	1	Steering Rack & Pinion	3255.80	3255.80 ✗
33	1	Accelerator Bracket <i>new</i>	248.00	248.00 ✗

34	1 Air Tank <i>deduct.</i>	193.80	193.80 ✓
35	1 Brake Booster Pump } <i>repair</i>	806.20	806.20 +
36	1 Brake Master Pump } <i>repair</i>	504.10	504.10 +
	Front RH Door Pillar Distortd <i>711.50 ✓</i>		
		Total	16153.50
		Less 25%	4038.38
		Sub Total	12115.12

*7872.20
less 25% : 5904.15*

Part Description (Special Nett)

37	1 Front Number Plate <i>new</i>	30.00	30.00 +
38	1 Front Door Adress Sticker RH <i>new</i>	30.00	30.00 ✓
39	1 Front Door Advertisement Sticker RH <i>new</i>	300.00	300.00 <i>200</i>
40	1 Front Windscreen Sealant <i>new</i>	60.00	60.00 ✓
41	1 Front Wheel Rim RH <i>wt</i>	250.00	250.00 <i>-180</i>
42	1 Front Tyre RH <i>wt</i>	220.00	220.00 <i>-180</i>
		Sub Total	890.00

650

Labour Description

43	Panel Beating		2000.00 <i>1400</i>
44	Spray Painting		1600.00 <i>1100</i>
45	Wiring		50.00 <i>30</i>
46	To Spray Underseal		150.00 <i>60</i>
47	To Remove Upholstery	<i>3500</i>	150.00 <i>60</i>
48	To Remove Front Windscreen		180.00 <i>120</i>
49	To Remove Dashboard		350.00 <i>220</i>
50	To Transfer Front Door Fittings		150.00 <i>80</i>
51	To Removing Braking System		250.00 <i>150</i>
52	To Remove Front Undercarriage		480.00 <i>220</i>
53	To Perform Wheel Alignment		150.00 <i>X.</i>
54	Towing Fees		60.00 ✓
		Sub Total	5570.00

Grand Total 18575.12
19108.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*total: 10084.15
L/S: 8050.
12 Days.*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18016381/ACD3N2

Date: 12/12/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994759
Claimant Vehicle No :	GBF2377U	Insured Vehicle No :	SLK3562A
Date of Loss:	05/09/2018	Nature of Claim:	TP
			Claim No: 7129764428SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2377U	Engine No:	1KD2635482
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y30K206761
Reg. Date:	08/08/2016 (Man. Year: 2016)	Odometer:	54755 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	155R12C
Front Left Side:	RACINGMAX 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	RACINGMAX 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,538.75	6,554.15	6,984.60	51.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	3,500.00	2,070.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,108.75	10,054.15	9,054.60	47.38
Approved Total (Overridden) (S\$)		8,050.00		
Nett Amount (S\$)	19,108.75	8,050.00	11,058.75	57.87

INSPECTION

Date of Assignment:	07/09/2018	
Date Inspected:	07/09/2018	Inspected At:
		Liang Hee Motor Workshop (HQ) 1 KAKI BUKIT AVE 6 #01-62, AUTOBAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	481.60 FL	*481.60 FL
2	1		*FRONT BUMPER BRACKET RH	Bent	165.30 FL	*165.30 FL
3	1		*FRONT GRILLE	Cracked	488.30 FL	*488.30 FL
4	1		*FRONT GRILLE LOGO	Necessary	68.10 FL	*68.10 FL
5	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FL	*20.00 FL
6	1		*HEADLAMP RH	Cracked	593.20 FL	*593.20 FL
7	1		*HEADLAMP LOWER RUBBER	Cut	35.90 FL	*35.90 FL
8	1		*SET HEADLAMP LOWER RUBBER CLIPS	Necessary	10.00 FL	*10.00 FL
9	1		*FRONT PANEL	Distorted	1,245.10 FL	*1,245.10 FL
10	1		*FRONT PANEL DYNA WORDING	Necessary	68.30 FL	*68.30 FL
11	1		*FRONT CORNER PANEL RH	Distorted	288.00 FL	*288.00 FL
12	1		*FRONT PANEL TOP CENTRE MOULDING	Cut	288.30 FL	*288.30 FL
13	1		*FRONT PANEL TOP MOULDING RH	Cut	107.40 FL	*107.40 FL
14	1		*FRONT STEP GARNISH RH	Distorted	282.00 FL	*282.00 FL
15	1		*FRONT DOOR RH	Distorted	1,450.50 FL	*1,450.50 FL
16	1		*FRONT DOOR LOCK RH	Not Necessary	245.60 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIP RH	Cut	195.60 FL	*195.60 FL
18	2		*FRONT DOOR HINGE RH	Bent	159.00 FL	*159.00 FL
19	1		*FRONT DOOR CHECK RH	Not Necessary	98.70 FL	*- FL
20	1		*FRONT DOOR INNER TRIM RH	Cracked	581.80 FL	*581.80 FL
21	1		*SET FRONT DOOR INNER TRIM CLIPS RH	Necessary	30.00 FL	*30.00 FL
22	1		*FRONT DOOR GLASS REGULATOR GEAR RH	Not Necessary	295.60 FL	*- FL
23	1		*FRONT DOOR GLASS REGULATOR MOTOR RH	Not Necessary	489.60 FL	*- FL
24	1		*FRONT WHEEL ARC PANEL RH	Repair	516.20 FL	*- FL
25	1		*FRONT WHEEL ARC PANEL GARNISH RH	Deformed	139.80 FL	*139.80 FL
26	1		*FRONT WINDSCREEN MOULDING	Necessary	268.70 FL	*268.70 FL
27	1		*FRONT LOWER ARM RH	Not Necessary	688.20 FL	*- FL
28	1		*FRONT UPPER ARM RH	Not Necessary	489.00 FL	*- FL
29	1		*FRONT SHOCK ABSORBER RH	Not Necessary	210.90 FL	*- FL
30	1		*FRONT KNUCKLE ARM RH	Not Necessary	581.90 FL	*- FL
31	1		*FRONT WHEEL HUB C/W BEARING RH	Not Necessary	563.00 FL	*- FL
32	1		*STEERING RACK & PINION	Not Necessary	3,255.80 FL	*- FL
33	1		*ACCELERATOR BRACKET	Not Necessary	248.00 FL	*- FL
34	1		*AIR TANK	Dented	193.80 FL	*193.80 FL
35	1		*BRAKE BOOSTER PUMP	Not Necessary	806.20 FL	*- FL
36	1		*BRAKE MASTER PUMP	Not Necessary	504.10 FL	*- FL
37	1		*FRONT RH DOOR PILLAR	Distorted	711.50 FL	*711.50 FL
38	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
39	1		*FRONT DOOR ADDRESS STICKER RH	Necessary	30.00 FS	*30.00 FS
40	1		*FRONT DOOR ADVERTISEMENT STICKER RH	Necessary	300.00 FS	*200.00 FS
41	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
42	1		*FRONT WHEEL RIM RH	Cut	250.00 FS	*180.00 FS
43	1		*FRONT TYRE RH	Cut	220.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,755.00	8,522.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,216.25	1,968.05
Total Parts (\$\$)	13,538.75	6,554.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING	New	1,600.00	1,100.00
3	WIRING	New	50.00	30.00
4	TO SPRAY UNDERSEAL	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE FRONT WINDSCREEN	New	180.00	120.00
7	TO REMOVE DASHBOARD	New	350.00	220.00
8	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
9	TO REMOVING BRAKING SYSTEM	New	250.00	150.00
10	TO REMOVE FRONT UNDERCARRIAGE	New	480.00	220.00
11	TO PERFORM WHEEL ALIGNMENT	New	150.00	-
12	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			5,570.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >