

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG18012597/BQD3S2-1**Date:** 03/10/2018REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28861316QMX
Claimant Vehicle No :	PC3006J	Insured Vehicle No :	SGC7771M
Date of Loss:	07/07/2018	Nature of Claim:	TP
		Claim No:	563835

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3006J	Engine No:	6HK1662872
Make & Model:	ISUZU LT434P 7.8 SMT, 7.8 D (M)	Chassis No:	JALLT434PE7000075
Reg. Date:	17/02/2015 (Man. Year: 2014)	Odometer:	178035 km
Colour:	White		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6/6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,630.00	1,290.00	2,340.00	64.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	860.00	1,640.00	65.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,130.00	2,150.00	3,980.00	64.93
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	6,130.00	1,700.00	4,430.00	72.27
+ GST 7.00/7.00% (S\$)	429.10	119.00	310.10	72.27
Nett Amount (S\$)	6,559.10	1,819.00	4,740.10	72.27

INSPECTION

Date of Assignment:	10/07/2018	
Date Inspected:	11/07/2018	Inspected At: Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Oct 2018)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3006J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH LOWER BODY PANEL	Repair	2,200.00 F	*- FL
2	1		*LH LOWER ROCKER PANEL ASSY	Dented	1,400.00 F	*1,400.00 FL
3	1		*LH LOWER BODY PANEL EXCURSION BUS STICKER	Necessary	30.00 FS	*30.00 FS
					Sub Total (S\$)	3,630.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00
					Total Parts (S\$)	3,630.00
						1,290.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS.	New	1,200.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.	New	1,200.00	400.00
3	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.	New	100.00	60.00
Gross Labour Cost (\$)			2,500.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >