

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		USJ Reg No : MR-8500111-		
Mr Rajagobal Navin Prabu	Cust No/Name	KCV05938/Mr Rajagobal Navin Prabu		
400 linner Control	Reg No/Reg Date	SLL4769J*1F / 28/02/201		
488 Upper East Coast Road #01-09 Venezio	Date In/Mileage	/ 0		
Singapore 466520	Chassis No	JMYXTGF3WHZ001362		
		4B12SH8912 MIT/OUTLANDER 2.4 CVT AWD (E44)		
Contact No	Make/Mode1			
	Colour/Trim	POZ RED METALLIC / BK BLACK		

Account No		Date/Time Printe	Annual Company of the Company of the Company	Operator		WIP No	
KCV05938	CRDVCH	06/09/2018/ 15:		442 / CocoLu		30623	
E PNT88000		Description of C	oods / Services		Qty	Unit Price Disc%	Amount
		R, TAILGATE, REAF	END DANK			the state of the s	3300.00
E PNT88000	OUT DUTIELL	A TATEGATE, REAL	END PANEL				3,300.00
	AR TAILGA	NTE GLASS					300.00
M SUNDRY							
_ APPLY SE	ALANT FOR	TAILGATE GLASS					80.00
E PNT88000							
REMOVE &	INSTALL	TAILGATE TRIMS &	REAR COMPARTM	ENT TRIMS			400.00
- IN130000							1600
SUNDRY	TINÍ ÞOK K	EAR BUMPER, TAIL	GATE , REAR EN	D PANEL			1680.00
APPLY SE	ALANT FOR	ACCIDENT PORTIO			m		40.00
54900099	reşiiri ron	VCCTDENI BOKTTO	1999	IMAG	147/5	*	40,100
CHECK WI	RING & ELI	ECTRICAL SYSTEM-	11165				20.00
1 54900099						7	-5.00
CONDUCT	DIAGNOSTI	C CHECK FOR THE (CAR SYSTEM				200.00
LINTOOOOO			• po (E)				
REMOVE &	INSTALL F	PARKING SENSOR				1	100.00
SUNDRY C&C LOGO:							100 20
SUNDRY							40.00
Sundry						ľ	20.00
FACE,RR B	UMPER					1	20.00
BRKT,R/BM	PR FACE S	IDE, RH			1.00	873.00 00.00	873.00
BRKT,R/BM	PR FACE S	IDE.LH			1.00	12.00 00.00	12.00
REINFORCE	MENT, RR B	UMPER 1 H			1.00	12.00 00.00	12.00
REINFORCE	MENT,RR B	UMPER,RH			1.00	78.00 00.00	78.00
EXTENSION	, RR. BUMPE!	R			1.00 1,00	78.00 00.00	78.00
MOULDING,	KR BUMPER	,RH			1.00	230.00 00.00	230.00
MOULDING,	KK ROWNER	,LH			1.00	105.00 00.00 105.00 00.00	105.00
PANEL ASS	INU Z Tatleati				1.00	243.00 00.00	105.00
GARNISH, TA	I, IALLUALI Miloate	-			1.00	924.00 00.00	243.00
Country 17	TEGATE				1.00	489 00 00 00	924.00
onfirm & acc	cepted by				· · · · · · · · · · · · · · · · · · ·	.52.00 00.00	489.00
•							
uthorized si	gnatory ar	nd company stamp	······································				

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

Co Reg No : 1977014696	ESTIMATE	GST Reg No : MR-8500111-X		
Invoice Name & Addres	ss Ov	vner Name & Vehicle Info		
Mr Rajagobal Navin Prabu	Cust No/Name KCVC	5938/Mr Rajagobal Navin Prabu		
The stranger of the stranger o	Reg No/Reg Date SLL4	769J*1F / 28/02/201		
488 Upper East Coast Road	Date In/Mileage	/ 0		
#01-09 Venezio	Chassis No JMYX	JMYXTGF3WHZ001362 4B12SH8912		
Singapore 466520 Contact No	Engine No 4B12			
	Make/Model MIT/	OUTLANDER 2.4 CVT AWD (E44)		
	Colour/Trim PO2	RED METALLIC / BK BLACK		

ccount No	Terms	Date/Time Pi		CSE	Operator		WIP No	
CV05938	CRDVCH	06/09/2018/		BLC	442 / CocoLu		30623	
		Description	of Goo	ds / Service	S	Qtý l	Init Price Disc%	Amount
W/STRIP,		OPENING				1.00	211.00 00.00	211.0
1 LATCH, TA						1.00	470.00 00.00	470.0
DAM, TAIL		·				1.00	12.00 00.00	12.0
DAM, TAIL						2.00	27.00 00.00	54.0
FASTENER						4.00	6.00 00.00	24.0
GLASS,TAI STOPPER,						1.00	743.00 00.00	743.0
TRIM, TAIL		D GERSS				2.00	3.00 00.00	.60
TRIM, TAIL		ı li li				1.00	286.00 00.00	286.0
TRIM, TAIL						1.00	72.00 00.00	72.0
TRIM, TAIL	· -		HILOTOCIECUM SCORE	75,000	energie energi	1.00 []1.00	93.00 00.00	93.0
MARK, OUTL		1311				1.00	72.00 00.00 94.00 00.00	72.0
TRIM, RR		of management of the state of t	***************************************		IIInnig	1.00	122.00 00.00	94.0
LAMP: ASSY		1 H	<u> </u>				594.00 00.00	122.0
LAMP ASSY		RH	E	Samuel Marie	id the fall the Name	1.00	594.00 00.00	594.0
LAMP ASSY						2.00	34.00 00.00	594.0
REFLECTOR						1.00	94.00 00.00	68.0
REFLECTOR						1.00	99.00 00.00	94.0 99.0
LAMP ASSY						1.00	501.00 00.00	501.0
LAMP ASS						1.00	501.00 00.00	501.00
MOTOR, RR	WINDOW W	IPER				1.00	500.00 00.00	500.0
ARM ASSY,	RR WINDO	W WIPER				1.00	64.00 00.00	64.0
		DOW WIPER				1.00	32.00 00.00	32.0
		·				2.00	52.00 00.00	72.0
							i	
							1	
onfirm & ac	cepted by	<u> </u>		••••		···		····
							Nett	14,635.0
						7% GST on	14635.00	1024.4
						Tota	ıl Payable	15,659.4
uthowing is		and company s						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.