

CHUNNI MOTOR WORK PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHC 8996M
MAKE :
MODEL : HYUNDAI i40

the Repairer of the following:

- To resurvey and display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surplus is on a "Whichever is highest" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

90 Power Bus LKK

TEL : 6542 5119
FAX : 6542 6039
Loprac
Signature:
Date:

Qty	Parts Description/ Labour	Unit Price	Amount	
	Rear Bumper <i>cut</i>	\$	553.00	✓
	Rear Bumper Clip 10 pcs <i>new</i>	\$	22.00	✓
	Rear Bumper Bracket <i>broken</i>	\$	49.00	✓
	Tail Lamp (RH) <i>crack</i>	\$	565.60	✓
	Rear Fender With Housing (RH) <i>new</i>	\$	4,736.80	✓
	Rear Fender Inner Lining (RH) <i>damaged</i>	\$	164.40	✓
	Rear Fender Air-Duct <i>new</i>	\$	51.60	X
	Rear Windscreen Moulding <i>new</i>	\$	28.30	✓
	Rear Door (RH) <i>dent</i>	\$	2,201.10	✓
	Rocker Panel Outer Garnish (RH) <i>cut</i>	\$	483.60	✓ photo
	Rear Tyre Rim (RH) <i>2 1/2"</i>	\$	325.30	✓
	Rear Wheel Hub-Cap (RH) <i>broken</i>	\$	107.10	✓
	Rear Wheelbearing ING & Hub <i>2 new</i>	\$	362.00	✓
	Rear Trailing Arm (RH) <i>2 1/2"</i>	\$	192.00	✓
	Rear Assist (RH) <i>2 chassis</i>	\$	145.70	✓
	Rear Shock Absorber (RH) <i>2 disturbed</i>	\$	276.30	✓
	Rear Shock Absorber Mounting (RH) <i>new</i>	\$	81.30	X
	Rear Crossmember <i>2 disturbed</i>	\$	1,190.00	✓
	Stabilizer Bar <i>2 disturbed</i>	\$	199.60	✓
	Stabilizer Link <i>2 disturbed</i>	\$	85.90	✓
	Rear Upper Arm (RH) <i>2 disturbed</i>	\$	335.75	✓
	Rear Lower Arm (RH) <i>2 disturbed</i>	\$	353.80	✓
	Rear Knuckle Arm (RH) <i>2 disturbed</i>	\$	545.60	✓
	SUB TOTAL	\$	13,055.75	
	LESS 20%	\$	2,611.15	
	DISCOUNTED TOTAL	\$	10,444.60	
	Rear Windscreen Sealant <i>new</i>	\$	46.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>new</i>	\$	80.00	Nett ✓
	Rear Tyre (RH) <i>new</i>	\$	216.00	Nett X
		\$	342.00	
	Labour Charge			
	Panel Beating	\$	1,500.00	700/-
	Spray Painting Charge	\$	1,250.00	600/-
	Wiring Charge	\$	50.00	new
	Tuff Kote	\$	100.00	40/-
	Remove/Refix Cushion & Upholstery Rear	\$	150.00	80/-
	Remove/Refix Rear Windscreen Glass	\$	120.00	80/-
	Remove/Refix Reverse Sensor	\$	120.00	40/-
	Remove/Refix Undercarriage (RR)	\$	200.00	150/-
	Transfer of Door	\$	120.00	60/-
	Rear Wheel Alignment	\$	120.00	60/-
	Diagnostic & Resetting To Erase Fault Code	\$	480.00	new
	TOTAL LABOUR	\$	4,210.00	
	ESTIMATE TOTAL	\$	14,996.60	

03/09/2018
Not Author

15mm 6 days

LKK Auto

Signature

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHC 8996 M
Technician:
Mileage: 545033
Time Printed 3.9.18 12:28 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
0°12'		-3°00' 3°00'
3°10'		-0°19' 5°41'
-1°18'		-1°30' 1°30'
20°20'		
20°32'		

Front : Right

Actual	BEFORE	Specified Range
-0°01'		-3°00' 3°00'
5°03'		-0°19' 5°41'
0°07'		-1°30' 1°30'
14°47'		
14°45'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

	Actual	BEFORE	Specified Range
Cross Camber	0°13'		-3°00' 3°00'
Cross Caster	-1°53'		-3°00' 3°00'
Cross SAI	5°33'		-3°00' 3°00'
Total Toe	-1°11'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
0°29'		-3°30' 2°30'
0°54'		-1°30' 1°30'

Rear : Right

Actual	BEFORE	Specified Range
13°34'		-3°30' 2°30'
26°06'		-1°30' 1°30'

Camber
Toe

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-13°04'		-3°00' 3°00'
Total Toe	27°00'		-3°00' 3°00'
Thrust Angle	-12°36'		-3°00' 3°00'