

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18016438/KPA3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SLN664T

Insured Vehicle No :

SHF743M

Date of Loss: 23/08/2018

Nature of Claim:

TP

Claim No: C0474291

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN664T**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS039546

Reg. Date: 21/04/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU403556230

Colour: Metallic Silver

Odometer: 202828 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Davanti 9 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Davanti 9 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,165.19	6,138.78	9,026.41	59.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,320.00	1,630.00	55.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,115.19	7,458.78	10,656.41	58.83
+ GST 7.00/7.00% (S\$)	1,268.06	522.11	745.95	58.83
Nett Amount (S\$)	19,383.25	7,980.89	11,402.36	58.83
+ Car Rental (5.0 x S\$80.95/day) (S\$)		404.75		
(S\$)		8,385.64		
Liab Amount (50.00%) (S\$)		4,192.82		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,200.27		

INSPECTION

Date of Assignment: 07/09/2018

Date Inspected: 17/09/2018 Inspected At:

385 SIN MING DRIVE

Repairer: Esteem Performance Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN664T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE (CONSISTENT)	Bent	45.00 FS	*45.00 FS
2	1		*FRONT NUMBER PLATE GARNISH (CONSISTENT)	Cracked	129.00 FL	*129.00 FL
3	1		*BONNET (CONSISTENT)	Bent	812.40 FL	*812.40 FL
4	1		*BONNET LOCK (CONSISTENT)	Repair	130.00 FL	*- FL
5	1		*BONNET HINGE LH (CONSISTENT)	Distorted	57.80 FL	*57.80 FL
6	1		*BONNET HINGE RH (CONSISTENT)	Repair	57.80 FL	*- FL
7	1		*FRONT SUPPORT PANEL CENTRE (CONSISTENT)	Repair	338.50 FL	*- FL
8	1		*FRONT SUPPORT PANEL LH (CONSISTENT)	Repair	213.50 FL	*- FL
9	1		*FRONT SUPPORT PANEL RH (CONSISTENT)	Repair	213.50 FL	*- FL
10	1		*HEADLAMP PANEL LH (CONSISTENT)	Repair	89.20 FL	*- FL
11	1		*HEADLAMP PANEL RH (CONSISTENT)	Repair	89.20 FL	*- FL
12	1		*SUPPORT PANEL LOWER (CONSISTENT)	Repair	387.95 FL	*- FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	Serviceable	285.40 FL	*- FL
14	10		*FRONT SUPPORT PANEL TOP GARNISH CLIP (CONSISTENT)	Not Necessary	35.00 FL	*- FL
15	1		*AIR DUCT (CONSISTENT)	Serviceable	195.40 FL	*- FL
16	1		*AIR DUCT -INLET (CONSISTENT)	Serviceable	109.75 FL	*- FL
17	1		*BRACE PANEL (CONSISTENT)	Repair	105.20 FL	*- FL
18	1		*CONSENSER (CONSISTENT)	Serviceable	1,544.70 FL	*- FL
19	1		*RADIATOR (CONSISTENT)	Serviceable	1,841.80 FL	*- FL
20	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Serviceable	455.70 FL	*- FL
21	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Serviceable	491.79 FL	*- FL
22	1		*RADIATOR FAN BLADE LH (CONSISTENT)	Serviceable	197.80 FL	*- FL
23	1		*RADIATOR FAN BLADE RH (CONSISTENT)	Serviceable	219.80 FL	*- FL
24	1		*RADIATOR FAN COWLING (CONSISTENT)	Serviceable	287.67 FL	*- FL
25	1		*HEADLAMP LH (CONSISTENT)	Mtg Cracked	2,531.60 FL	*2,531.60 FL
26	1		*HEADLAMP RH (CONSISTENT)	Mtg Cracked	2,531.60 FL	*2,531.60 FL
27	1		*FRONT BUMPER (CONSISTENT)	Buckled	450.80 FL	*450.80 FL
28	10		*FRONT BUMPER CLIP (CONSISTENT)	Necessary	40.00 FL	*40.00 FL
29	1		*FRONT BUMPER REINFORCEMENT -UPPER (CONSISTENT)	Bent	711.50 FL	*711.50 FL
30	1		*FRONT BUMPER REINFORCEMENT -LOWER (CONSISTENT)	Repair	245.30 FL	*- FL
31	1		*FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	Distorted	107.20 FL	*107.20 FL
32	1		*FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	Distorted	107.20 FL	*107.20 FL
33	1		*FRONT BUMPER UPPER GRILLE (CONSISTENT)	Distorted	321.90 FL	*321.90 FL
34	1		*FRONT BUMPER LOWER GRILLE (CONSISTENT)	Cracked	148.60 FL	*148.60 FL
35	1		*FRONT BUMPER EMBLEM (CONSISTENT)	Dented	87.10 FL	*87.10 FL
36	1		*FRONT BUMPER TOW COVER RH (CONSISTENT)	Serviceable	25.70 FL	*- FL
37	1		*FRONT BUMPER TOW COVER LH (CONSISTENT)	Serviceable	25.70 FL	*- FL
38	1		*FRONT BUMPER SPONGE -UPPER (CONSISTENT)	Serviceable	89.81 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT BUMPER SPONGE -LOWER (CONSISTENT)	Serviceable	135.70 FL	*- FL
40	1		*FOG LAMP LH (CONSISTENT)	Serviceable	910.70 FL	*- FL
41	1		*FOG LAMP RH (CONSISTENT)	Serviceable	910.70 FL	*- FL
42	1		*ENGINE UNDER COVER (CONSISTENT)	Serviceable	198.30 FL	*- FL
43	10		*ENGINE UNDER COVER CLIP (CONSISTENT)	Not Necessary	35.00 FL	*- FL
44	1		*RH FRONT FENDER (CONSISTENT)	Repair	868.70 FL	*- FL
45	1		*RH FRONT FENDER UNDERSHIELD (CONSISTENT)	Serviceable	185.64 FL	*- FL
46	10		*RH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	Not Necessary	25.00 FL	*- FL
47	1		*RHF FENDER WORDING HYBRID (CONSISTENT)	Necessary	44.17 FL	*44.17 FL
48	1		*LH FRONT FENDER (CONSISTENT)	Repair	868.70 FL	*- FL
49	1		*LH FRONT FENDER UNDERSHIELD (CONSISTENT)	Serviceable	195.60 FL	*- FL
50	10		*LH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	Not Necessary	25.00 FL	*- FL
51	1		*LHF FENDER WORDING HYBRID (CONSISTENT)	Necessary	44.17 FL	*44.17 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,205.25 8,170.04
- List Item Discount on L Items 25.00/25.00% (\$\$) 5,040.06 2,031.26

Total Parts (\$\$) 15,165.19 6,138.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,BONNET ,SUPPORT PANEL, LHF FENDER,RHF FENDER)	New	1,400.00	500.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,BONNET ,SUPPORT PANEL,LHF FENDER ,RHF FENDER)	New	1,200.00	800.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	20.00
4	TO REMOVE & REFIT RADIATOR ,CONDENSER TO ASSIST WORK LOAD,TO TOP UP A/C GAS	New	150.00	0.00
5	TO TUFF COAT	New	150.00	0.00
Gross Labour Cost (\$\$)			2,950.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >