Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18016493/UPA3Q2

111808 km

Date: 28/04/2020

Odometer:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015 Claimant SJT6218B

Insured Vehicle No: SHA2334Z Vehicle No:

Date of Loss: 19/08/2018 Nature of Claim: TP Claim No: MCT18080956

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SJT6218B** Reg No:

Make & Model: BMW Z4, 2.5 sDrive23i (A) Engine No: 04527184N52B25AF Reg. Date: 22/10/2009 (Man. Year: 2009) Chassis No: WBALM32040E355236

Colour: Black

**Engine Capacity:** 2497 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 235/35Z R19 Rear Tyre Size: 235/35Z R19 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,322.80	2,037.65	10,285.15	83.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	750.00	1,280.00	63.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,352.80	2,787.65	11,565.15	80.58
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	14,352.80	2,250.00	12,102.80	84.32
+ GST 7.00/7.00% (S\$)	1,004.70	157.50	847.20	84.32
Nett Amount (S\$)	15,357.50	2,407.50	12,950.00	84.32
Global Sum Settlement (S\$)		0.00		

**INSPECTION** 

10/09/2018 Date of Assignment:

10/09/2018 Inspected At: RICO 60 AUTO SERVICES PTE LTD Date Inspected:

(HQ)

8, KAKI BUKIT AVENUE 4, #02-24,

PREMIER @ KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Apr 2020)

Parts: M1-COUPE BMW Z4 2.5 sDrive23i (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJT6218B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

**Total Parts (S\$)** 12,322.80

**Amount** 

2,037.65

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qtv Part No. Particulars

NO.	щı	i ait ito.	railiculais	Condition	Kehairer 2	Amount
1	1		*FRONT BONNET	Not Necessary	2,598.85 F	*- FL
2	1		*FRONT HEADLAMP LH	Not Necessary	2,437.65 F	*- FL
3	1		*FRONT BUMPER	Deep Cut	1,408.05 F	*1,408.05 FL
4	2		*FRONT BUMPER RETAINER L+R	Not Necessary	72.50 F	*- FL
5	2		*FRONT BUMPER BRACKET L+R	Not Necessary	72.50 F	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	658.05 F	*- FL
7	2		*FRONT BUMPER GRILLE L+R	Not Necessary	227.30 F	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	55.15 F	*- FL
9	1		*FRONT BUMPER FOG LAMP GRILLE LH	Not Necessary	55.50 F	*- FL
10	2		*FRONT BUMPER SENSOR LH	Not Necessary	473.70 F	*- FL
11	1		*FRONT BUMPER HEADLAMP NOZZLE LH	Not Necessary	159.85 F	*- FL
12	1		*FRONT KNUCKLE LH	Not Necessary	424.25 F	*- FL
13	1		*FRONT KNUCKLE BEARING LH	Not Necessary	476.25 F	*- FL
14	1		*FRONT BEARING HUB LH	Not Necessary	373.10 F	*- FL
15	1		*FRONT ABSORBER LH	Not Necessary	541.35 F	*- FL
16	1		*FRONT LOWER ARM LH	Not Necessary	268.75 F	*- FL
17	1		*FRONT NUMBER PLATE	Not Necessary	120.00 FS	*- FS
18	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
19	1		*FRONT RIM LH	Cut	1,000.00 FS	*650.00 FS
20	1		*FRONT TYRE LH	Serviceable	800.00 FS	*- FS
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	12,322.80	2,108.05
	- List Item Discount on L Items 0.00/5.00% (S\$)					70.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RNR ACCIDENT DAMAGED PARTS ,CUT/WELD ,KNOCK ,& REALIGN	New	600.00	250.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	600.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	0.00
4	TO RNR UNDERCARRIAGE SYSTEM	New	350.00	0.00
5	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	120.00	20.00
7	TO RNR TYRE AND WHEEL BALANCING	New	120.00	0.00
	Gross Labour Cost (S\$)		2,030.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >