

REF:

LPC

ASSIGNMENT

From:

Date:

11/09/18

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJX 7717A

at Workshop n/s:

Vision Autowork

of

8 kaki Blk Ave 4 # 08-09

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP: 1-24 HRS

Lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJX 7717A

Yr Regn:

2016 / Jan.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan X-Trail

C.C. 1997

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading:

63571

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1JANT3220001360

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R18

R:

225/60R18

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

11/09/18

Survey held at

Vision

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Lon Pac.

45.1 + 17,000 (RED: + 23,249.62 58%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$

Survey Fee:

Transportation

) \$ + R5. St

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18016590/Aeb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 11-09-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 644H	Veh. Inspected	SJX 7717A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/09/2018	Inspection Date	11/09/2018	
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 10.09.18

TO : LONPAC MOTOR CLAIMS DEPTS

VEHICLE NO : SJX7717A

MODEL : NISSAN X-TRAIL

DATE OF ACCIDENT : 08.09.18

TIME OF ACCIDENT : 12:20HRS

Achar - INIJANT32Z0001360

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delud</i>	1	\$ 534.70	\$ 534.70
2	FRONT BUMPER FOG LAMP <i>Not New</i>	2	\$ 321.60	\$ 643.20
3	FRONT BUMPER FOG LAMP COVER C/W RING <i>New</i>	2	\$ 87.90	\$ 175.80
4	FRONT BUMPER LOWER MOULDING <i>lt</i>	1	\$ 153.10	\$ 153.10
5	FRONT BUMPER LOWER GRILLE <i>Not New</i>	1	\$ 227.50	\$ 227.50
6	FRONT BUMPER BOTTOM GARNISH <i>Not New</i>	1	\$ 584.00	\$ 584.00
7	FRONT BUMPER TOWING HOOD COVER <i>New</i>	1	\$ 20.30	\$ 20.30
8	FRONT BUMPER SIDE RETAINER <i>Not New</i>	2	\$ 29.80	\$ 59.60
9	FRONT BUMPER REINFORCEMENT <i>Painted</i>	1	\$ 473.10	\$ 473.10
10	FRONT BUMPER REINFORCEMENT SPONGE <i>Cracked</i>	1	\$ 291.60	\$ 291.60
11	FRONT BUMPER REINFORCEMENT BRACKET <i>Not New</i>	2	\$ 110.80	\$ 221.60
12	HEADLAMP HID <i>Cracked</i>	2	\$ 2,352.10	\$ 4,704.20
13	HEADLAMP LOWER BRACKET <i>Not New</i>	2	\$ 146.40	\$ 292.80
14	FRONT FENDER ARCED GARNISH <i>3 Not New</i>	2	\$ 178.40	\$ 356.80
15	FRONT FENDER COWLING <i>Not New</i>	2	\$ 123.60	\$ 247.20
16	RADIATOR GRILLE C/W CHROME <i>lt</i>	1	\$ 398.30	\$ 398.30
17	RADIATOR GRILLE LOGO <i>New</i>	1	\$ 73.60	\$ 73.60
18	BONNET <i>Cracked</i>	1	\$ 961.90	\$ 961.90
19	BONNET INSULATOR <i>2</i>	1	\$ 154.70	\$ 154.70
20	BONNET STOPPER <i>Not New</i>	4	\$ 17.10	\$ 68.40
21	BONNET LOCK <i>Not New</i>	1	\$ 134.20	\$ 134.20
22	BONNET INNER RUBBER	5	\$ 48.60	\$ 243.00
23	FRONT SUPPORT PANEL <i>Not New</i>	1	\$ 842.80	\$ 842.80
24	FRONT BRACE PANEL <i>Not New</i>	1	\$ 93.70	\$ 93.70
25	HORN <i>Not New</i>	2	\$ 95.50	\$ 191.00
26	OIL COOLER <i>Not New</i>	1	\$ 240.00	\$ 240.00
27	OIL COOLER BRACKET <i>Not New</i>	1	\$ 337.50	\$ 337.50
28	RADIATOR SUPPORT GARNISH (TOP) <i>Cracked</i>	1	\$ 261.80	\$ 261.80
29	RADIATOR <i>Not New</i>	1	\$ 894.40	\$ 894.40

30	RADIATOR MOUNTING <i>3 new</i>	4	\$ 12.70	\$ 50.80	+
31	AIRCON CONDENSOR <i>3 new</i>	1	\$ 774.20	\$ 774.20	+
32	AIRCON CONDENSOR SIDE GARNISH <i>3 new</i>	2	\$ 41.70	\$ 83.40	+
33	AIRCON CONDENSOR LOWER GARNISH <i>3 new</i>	1	\$ 127.30	\$ 127.30	+
34	TAILGATE <i>cracked.</i>	1	\$ 4,200.00	\$ 4,200.00	✓
35	TAILGATE HINGE <i>not new</i>	2	\$ 39.60	\$ 79.20	+
36	TAIL GATE LAMP <i>not new</i>	2	\$ 179.10	\$ 358.20	+
37	TAILGATE LOGO <i>3 new</i>	1	\$ 59.70	\$ 59.70	✓
38	TAILGATE EMBLEM 'X-TRAIL'	1	\$ 101.30	\$ 101.30	✓
39	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 181.60	\$ 181.60	✓
40	TAILGATE LOCK BUTTON SWITCH (OUTER) <i>not new</i>	1	\$ 137.70	\$ 137.70	+
41	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 164.90	\$ 164.90	✓
42	TAILGATE STOPPER <i>Not new</i>	4	\$ 15.00	\$ 60.00	+
43	TAILGATE INNER TRIM (LOWER) <i>cracked.</i>	1	\$ 457.60	\$ 457.60	✓
44	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 165.70	\$ 165.70	✓
45	TAIL GATE DAMPER (ELECTRIC) <i>not new</i>	2	\$ 1,055.60	\$ 2,111.20	+
46	TAILGATE SIDE SENSOR <i>not new</i>	2	\$ 330.10	\$ 660.20	+
47	TAILGATE DETECTOR <i>cracked</i>	1	\$ 469.30	\$ 469.30	95
48	REAR BUMPER <i>Distorted.</i>	1	\$ 673.80	\$ 673.80	✓
49	REAR BUMPER REFLECTOR <i>not new</i>	2	\$ 65.40	\$ 130.80	+
50	REAR BUMPER CENTER AIR VENT <i>cracked</i>	1	\$ 105.30	\$ 105.30	✓
51	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.80	\$ 79.60	✓
52	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 587.10	\$ 587.10	✓
53	REAR BUMPER REINFORCEMENT BRACKET <i>Best</i>	2	\$ 196.20	\$ 392.40	266.80
54	REAR BUMPER SIDE GARNISH <i>Deformed</i>	2	\$ 159.40	\$ 318.80	✓
55	TAIL LAMP <i>not new</i>	1	\$ 287.20	\$ 287.20	+
56	REAR FENDER ARCED GARNISH <i>not new</i>	2	\$ 164.70	\$ 329.40	+
57	REAR FENDER INNER COWLING <i>not new</i>	2	\$ 97.30	\$ 194.60	+
58	REAR FENDER INNER TRIM <i>cracked</i>	2	\$ 479.40	\$ 958.80	✓
59	REAR END PANEL <i>Dented</i>	1	\$ 496.30	\$ 496.30	✓
60	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 127.10	\$ 127.10	✓
61	REAR END EXTEND LOWER PANEL <i>Dented</i>	1	\$ 175.40	\$ 175.40	✓
62	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,040.80	\$ 1,040.80	+
63	REAR STORAGE COVER BOARD <i>Deformed</i>	1	\$ 915.80	\$ 915.80	✓
64	REAR STORAGE COVER BOARD (SIDE) <i>not new</i>	2	\$ 71.40	\$ 142.80	+
65	SPARE TYRE TOP COVER GARNISH <i>Deformed</i>	1	\$ 164.30	\$ 164.30	✓
66	REAR EXHAUST BOX <i>Dented.</i>	1	\$ 1,082.60	\$ 1,082.60	✓
67	REAR EXHAUST INSULATOR <i>Damaged.</i>	1	\$ 178.20	\$ 178.20	+
68	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 29.40	\$ 117.60	+

TOTAL PRICE \$ 32,621.80
 LESS 10% \$ 3,262.18
 SUB TOTAL PRICE \$ 29,359.62

19467.60
 17520.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Beated</i>	1	\$ 50.00	\$ 50.00	-
2	FRONT BUMPER CLIP (SET) <i>ne</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT FENDER COWLING CLIP (SET) <i>ne n</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT GRILLE CAMERA <i>ne n</i>	1	\$ 450.00	\$ 450.00	+
5	BONNET SEALANT <i>ne n</i>	1	\$ 150.00	\$ 150.00	+
6	BONNET INSULATOR CLIP (SET) <i>ne n</i>	1	\$ 60.00	\$ 60.00	+
7	RADIATOR GRILLE CLIP (SET) <i>ne</i>	1	\$ 40.00	\$ 40.00	20
8	AIRCON CONDENSOR SIDE GARNISH CLIP (SET) <i>ne</i>	1	\$ 40.00	\$ 40.00	+
9	COOLANT <i>ne n</i>	1	\$ 60.00	\$ 60.00	+
10	REAR NUMBER PLATE <i>ne n</i>	1	\$ 50.00	\$ 50.00	+
11	REAR BUMPER CLIP (SET) <i>ne n</i>	1	\$ 80.00	\$ 80.00	30
12	TAILGATE SEALANT <i>ne n</i>	1	\$ 150.00	\$ 150.00	+
13	TAILGATE INNER TRIM CLIP (SET) <i>ne</i>	1	\$ 60.00	\$ 60.00	30
14	TAILGATE WINDSCREEN SEALANT <i>ne n</i>	1	\$ 80.00	\$ 80.00	30
15	TAILGATE WINDSCREEN INNER SHIELD <i>ne</i>	1	\$ 60.00	\$ 60.00	30
16	TAILLAMP CLIP (SET) <i>ne n</i>	1	\$ 40.00	\$ 40.00	+
17	REAR FENDER INNER TRIM CLIP (SET) <i>ne</i>	1	\$ 60.00	\$ 60.00	30
18	REAR FENDER INNER COWLING CLIP (SET) <i>ne n</i>	1	\$ 60.00	\$ 60.00	+
19	REAR END PANEL INSULATION SEAL <i>ne</i>	1	\$ 150.00	\$ 150.00	60
20	REAR END PANEL TOP GARNISH CLIP (SET) <i>ne</i>	1	\$ 40.00	\$ 40.00	10
21	REAR FLOOR PANEL INSULATION SEAL <i>ne n</i>	1	\$ 350.00	\$ 350.00	+
22	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
23	REVERSE CAMERA <i>ne n</i>	1	\$ 550.00	\$ 550.00	+

520.

TOTAL \$ 2,940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	400
3	REFOCUS HEADLAMP BEAM	\$ 80.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	+
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	+

830

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	40
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
12	RESET BOOTLID SYSTEM	\$ 350.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	100

TOTAL \$ 7,950.00

2380

ESTIMATE REPORT

TOTAL PARTS COST : \$ 32,299.62

TOTAL LABOUR COST : \$ 7,950.00

TOTAL REPAIR COST : \$ 40,249.62

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

SERVICE ADVISOR

ABBY

HP : 9856 4815

LKK Auto Consultants hence notify the Repaire of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is to be carried out on a "Without Prejudice" basis
 • No illegal modifications are allowed
 • Supplementary item(s) must be resurveyed and approved
 • is subject to final approval from Insurance Company
 Acknowledged by Repaire
 Signature:
 Date:

Adrian heng
 2/s 11/10/18.
 12 Days.

total: 21050.84
 2/s 11/10/18.

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 10 September 2018 5:47 PM
To: Vision Autowork; MT_Claim_SG; assignments@lkkauto.com; catherine
Subject: RE: SJX7717A (Pre-inspection) / Your vehicle : SLH644H Our Ref: 18/18/18/VP05/020894
Attachments: 10092018150742.pdf

9:07am @ 11/09/18
person @ Michelle
vehicle In
sur @ Adrian

Without Prejudice
Save as to Costs

Dear Michelle

Please liaise with LKK AutoConsultants Pte Ltd for survey. You may choose one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input checked="" type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Dear Catherine/Nivitha

Please liaise with workshop for TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Vision Autowork [mailto:visionautowork@gmail.com]
Sent: Monday, 10 September, 2018 3:09 PM

To: MT_Claim_SG; GERALD POH WEE BIN; ericwoo

Subject: SJX7717A (Pre-inspection) / Your vehicle : SLH644H

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE THE ABOVE CASE LIABILITY ****

--

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09,Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201500371E

Date: 10/09/18

By Fax & Email

To: Lonpac

Attn : Motor Claims Department

Re: Accident involving motor vehicle Nos. SJX 7717A and SLH 644H
along PIE towards Changi (Before Lornie Road Exit) on 08/09/2018

We refer to the above matter.

We are instructed by Rehmat Bin Taib to notify you of a road traffic accident
on 08/09/2018 at about 12:30 at PIE towards Changi (Before Lornie Road Exit)
involving our client's/customer's vehicle registration number SJX 7717A and vehicle
registration number SLH 644H driven by you at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our
client/we proceed to repair the damaged vehicle, please let us know within 2 working days of
your receipt of this notice whether you or your insurer would like to conduct a pre-repair
survey of the vehicle. If we do not receive any reply from you within the stipulated timeline,
our client/we shall proceed to repair the vehicle without further reference to you.

Thank You

Yours faithfully



Abby

Hp : 9856 4815

Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 12 September 2018 9:00 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: SJX7717A (Pre-inspection) / Your vehicle : SLH644H Our Ref: 18/18/18/VP05/020894
Attachments: SLH644H 080918.PDF

Dear Shu Pei

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 11 September, 2018 7:33 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAUTO)
Subject: RE: SJX7717A (Pre-inspection) / Your vehicle : SLH644H Our Ref: 18/18/18/VP05/020894

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJX 7717A at M/s Vision Autowork Pte Ltd.

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 11 September 2018 9:14 AM
To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SJX7717A (Pre-inspection) / Your vehicle : SLH644H Our Ref: 18/18/18/VP05/020894

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Monday, 10 September 2018 5:47 PM
To: Vision Autowork <visionautowork@gmail.com>; MT_Claim_SG <mt_claim@lonpac.com>;
assignments@lkkauto.com; catherine <admin-d@lkkauto.com>
Subject: RE: SJX7717A (Pre-inspection) / Your vehicle : SLH644H Our Ref: 18/18/18/VP05/020894

Without Prejudice
Save as to Costs

Dear Michelle

Please liaise with LKK AutoConsultants Pte Ltd for survey. You may choose one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	

10	Sathya Sai Kathirrasen	
----	------------------------	--

Dear Catherine/Nivitha

Please liaise with workshop for TP survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Vision Autowork [<mailto:visionautowork@gmail.com>]

Sent: Monday, 10 September, 2018 3:09 PM

To: MT_Claim_SG; GERALD POH WEE BIN; ericwoo

Subject: SJX7717A (Pre-inspection) / Your vehicle : SLH644H

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE THE ABOVE CASE LIABILITY ****

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778



This email has been checked for viruses by AVG antivirus software.
www.avg.com

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201500371E

Letter of Authorisation & Indemnity

Accident Involving Vehicle no. SJX7717A and SLH644H On 08/09/2018

At PIE towards Changi (Before Lornie Road Exit)

1. I/We, the owner of vehicle no. SJX7717A hereby instruct and authorize Vision Autowork Pte. Ltd. ("the workshop") to commence repairs to the said vehicle. Pending the outcome of my/our claim against the third party, I/we forthwith pay you the sum of \$ _____ being refundable deposit of the repair to my/our said vehicle.
2. You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in court in my/our name against the third party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit.
4. Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional costs and disbursement for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account. In the event that my/our claim or legal costs of the third party as well as the professional costs and disbursements of my/our solicitors notwithstanding that my/our solicitors were appointed by you on our behalf.
5. I/we also hereby instruct and authorise you deduct directly from the claim monies received from the third party all outstanding balances that are still owing to you, namely the balance of repair costs and rental of substitute vehicles.
6. In the event that I/we am/are required to attend at my/our solicitors office or to attend court in connection with my/our claim, I/we shall render full co-operation.
7. In the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with and/or if any Judgement or settlement is not honoured or satisfied by the third party, I/we authorise you to revert the claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respect, I/we understand and accept that the excess amount applicable under policy of insurance shall be borne by me/us.
8. If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I/we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
9. I/we shall keep you informed of any correspondences and/or summons that I may receive due to this action agreeing to pay or receive any monies due to this claim.

Dated this 10 day of 09 2018

Signature of vehicle owner Rahmat



Rahmat

Name - Rahmat Bin Taib

Witnessed by :

IC No : S1521528C

Abby

(Company stamp, if applicable)

Address : Blk 159 Yung Ping Road

#05-05 Singapore 610151

Tel : 9667 4452




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18016590/Aeb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 09-05-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 644H	Veh. Inspected	SJX 7717A	
Policy No.	Z18VP05019921	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020894	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	11/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0001360	Colour	RED	
Odometer	63571	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60R18	DUNLOP	6 mm	
L/H Front Tyre	225/60R18	DUNLOP	6 mm	
R/H Rear Tyre	225/60R18	DUNLOP	6 mm	
L/H Rear Tyre	225/60R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/09/2018	Inspection Date	11/09/2018	
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 7717A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	534.70	534.70
2	FRONT BUMPER FOG LAMP @ \$321.60	NOT NECESSARY	643.20	-
2	FRONT BUMPER FOG LAMP COVER C/W RING @ \$87.90	NOT NECESSARY	175.80	-
1	FRONT BUMPER LOWER MOULDING	CUT	153.10	153.10
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	227.50	-
1	FRONT BUMPER BOTTOM GARNISH	NOT NECESSARY	584.00	-
1	FRONT BUMPER TOWING HOOD COVER	NOT NECESSARY	20.30	-
2	FRONT BUMPER SIDE RETAINER @ \$29.80	NECESSARY	59.60	59.60
1	FRONT BUMPER REINFORCEMENT	DENTED	473.10	473.10
1	FRONT BUMPER REINFORCEMENT SPONGE	CRACKED	291.60	291.60
2	FRONT BUMPER REINFORCEMENT BRACKET @ \$110.80	NOT NECESSARY	221.60	-
2	HEADLAMP HID @ \$2352.10	CRACKED	4,704.20	4,704.20
2	HEADLAMP LOWER BRACKET @ \$146.40	NOT NECESSARY	292.80	-
2	FRONT FENDER ARCED GARNISH @ \$178.40	NOT NECESSARY	356.80	-
2	FRONT FENDER COWLING @ \$123.60	NOT NECESSARY	247.20	-
1	RADIATOR GRILLE C/W CHROME	CUT	398.30	398.30
1	RADIATOR GRILLE LOGO	NECESSARY	73.60	73.60
1	BONNET	BUCKLED	961.90	961.90
1	BONNET INSULATOR	NOT NECESSARY	154.70	-
4	BONNET STOPPER @ \$17.10	NOT NECESSARY	68.40	-
1	BONNET LOCK	NOT NECESSARY	134.20	-
5	BONNET INNER RUBBER @ \$48.60	NOT NECESSARY	243.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	842.80	-
1	FRONT BRACE PANEL	NOT NECESSARY	93.70	-
2	HORN @ \$95.50	NOT NECESSARY	191.00	-
1	OIL COOLER	NOT NECESSARY	240.00	-
1	OIL COOLER BRACKET	NOT NECESSARY	337.50	-
1	RADIATOR SUPPORT GARNISH (TOP)	CRACKED	261.80	261.80
1	RADIATOR	NOT NECESSARY	894.40	-
4	RADIATOR MOUNTING @ \$12.70	NOT NECESSARY	50.80	-
1	AIRCON CONDENSOR	NOT NECESSARY	774.20	-

Report Ref No. CC4/LPC18016590/Aeb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	AIRCON CONDENSOR SIDE GARNISH @ \$41.70	NOT NECESSARY	83.40	-
1	AIRCON CONDENSOR LOWER GARNISH	NOT NECESSARY	127.30	-
1	TAILGATE	CRACKED	4,200.00	4,200.00
2	TAILGATE HINGE @ \$39.60	NOT NECESSARY	79.20	-
2	TAIL GATE LAMP @ \$179.10	NOT NECESSARY	358.20	-
1	TAILGATE LOGO	NECESSARY	59.70	59.70
1	TAILGATE EMBLEM 'X-TRAIL'	NECESSARY	101.30	101.30
1	TAILGATE INNER LOCK	DAMAGED	181.60	181.60
1	TAILGATE LOCK BUTTON SWITCH (OUTER)	NOT NECESSARY	137.70	-
1	TAILGATE WEATHER STRIP	CUT	164.90	164.90
4	TAILGATE STOPPER @ \$15.00	NOT NECESSARY	60.00	-
1	TAILGATE INNER TRIM (LOWER)	CRACKED	457.60	457.60
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	165.70	165.70
2	TAIL GATE DAMPER (ELECTRIC) @ \$1055.60	NOT NECESSARY	2,111.20	-
2	TAILGATE SIDE SENSOR @ \$330.10	NOT NECESSARY	660.20	-
1	TAILGATE DETECTOR	CRACKED	469.30	95.00
1	REAR BUMPER	DISTORTED	673.80	673.80
2	REAR BUMPER REFLECTOR @ \$65.40	NOT NECESSARY	130.80	-
1	REAR BUMPER CENTER AIR VENT	CRACKED	105.30	105.30
2	REAR BUMPER SIDE RETAINER @ \$39.80	NECESSARY	79.60	79.60
1	REAR BUMPER REINFORCEMENT	BENT	587.10	587.10
2	REAR BUMPER REINFORCEMENT BRACKET @ \$196.20	BENT	392.40	266.80
2	REAR BUMPER SIDE GARNISH @ \$159.40	DEFORMED	318.80	318.80
1	TAIL LAMP	NOT NECESSARY	287.20	-
2	REAR FENDER ARCED GARNISH @ \$164.70	NOT NECESSARY	329.40	-
2	REAR FENDER INNER COWLING @ \$97.30	NOT NECESSARY	194.60	-
2	REAR FENDER INNER TRIM @ \$479.40	CRACKED	958.80	958.80
1	REAR END PANEL	DENTED	496.30	496.30
1	REAR END PANEL TOP GARNISH	DEFORMED	127.10	127.10
1	REAR END EXTEND LOWER PANEL	DENTED	175.40	175.40
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,040.80	-
1	REAR STORAGE COVER BOARD	DEFORMED	915.80	915.80

Report Ref No. CC4/LPC18016590/Aeb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR STORAGE COVER BOARD (SIDE) @ \$71.40	NOT NECESSARY	142.80	-
1	SPARE TYRE TOP COVER GARNISH	DEFORMED	164.30	164.30
1	REAR EXHAUST BOX	DENTED	1,082.60	1,082.60
1	REAR EXHAUST INSULATOR	CRUMPLED	178.20	178.20
4	REAR EXHAUST MOUNTING @ \$29.40	NOT NECESSARY	117.60	-
	LESS 10% DISCOUNT		-3,262.18	-1,946.76
			29,359.62	17,520.84
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	50.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT FENDER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	FRONT GRILLE CAMERA (SN)	NOT NECESSARY	450.00	-
1	BONNET SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	60.00	-
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	40.00	20.00
1	SET AIRCON CONDENSOR SIDE GARNISH CLIP (SN)	NOT NECESSARY	40.00	-
1	COOLANT (SN)	NOT NECESSARY	60.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	60.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	TAILGATE WINDSCREEN INNER SHIELD (SN)	NECESSARY	60.00	30.00
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	40.00	10.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	350.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
			2,940.00	520.00

Report Ref No. CC4/LPC18016590/Aeb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		3,000.00	1,400.00
	TO SPRAY PAINT AFFECTED AREA.		2,800.00	1,200.00
	REFOCUS HEADLAMP BEAM.		80.00	30.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS.	NOT NECESSARY	120.00	-
	REMOVE AND REFILL RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
	TUFF COAT.		250.00	40.00
	WIRING AND BULB CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		350.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX VIDEO RECORDER.		80.00	50.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	120.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	RESET BOOTLID SYSTEM.	NOT NECESSARY	350.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.		180.00	100.00
			7,950.00	3,210.00
	GRAND TOTAL		40,249.62	21,250.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,000.00

Report Ref No. CC4/LPC18016590/Aeb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.