ASS. REC. BY: REF: TMI	60. 10
,	CC3/TMIL 8016606/KHbn2
Kenneth	SSIGNMENT
From: Date:	1 N 1 N 1 N 1 N 1 N 1 N 1 N 1 N 1 N 1 N
Estimated Cost:	Veh No: S/10 58702 Yr Regn: 12, 19
OD TP WS I TP RES I OD RES I EVA / INV I MV	- Prime Mover
To Inspect Vehicle No:	Truck / Traller or
at Workshop min	Make: Renault Letitude cc 1895
of mans lab	- COLOUR PARTIE / PRES AC: Insured / Std / NI / NA
Insured: PZ 1338T	Sp.Reading 4/56/5 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: VIFIABLISAUC. 280837
Sure leaves 4	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder/ Jammed / Leaked / Burnt or
	Modi: Mil) S/Rim / STD A/Rim or
(Dellas Condutos)	Tyre Size: F: 215/60R16
(Policy Condition)	R:
Remark: The veh had commenced its repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO OF GITT
Bal. or Market Value:	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No	R/Bal. 9 mm R/Bal S
	L/Bal. S mm L/Bal. S
Est. Repairs: 02 days Res.: Yes or No Lum Sum: 2 C % 3 Val: Yes or No	D.O.A. 9/9/18 D.O.I. 11/9/19
Lum Sum: 20% 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	_013 /77
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
12/9 File pass to Carpenne	
61 En & 32501 (Red: 423)	11.68: 92%)
	11001 1210
- SHC 58701 - CC4/LPC 16071445/KUB3S	DUF: 3106206
PZ 13307 - 063/IMI/ID19971/m16bn2	DUA: 171017
PEOPLYED	
RECEIVED	1 3 SEF 2010
Oate/Time, File Pass to?	
: Prell. Report Da	ys Of Repair: 2
Oste/Time, File Return to?	survey No. of Trip; Survey Fee:
_	Transportation: 250
Add Fee:	: Site Insp (\$)_s-Rs_si 10
Ronard Formation (P)	: Interview (\$), Fixos
Report Format :	Tech Invs (\$). Others
Lump Sum / I.B.I: (\$ 3250\	Weekend (\$
	10TAL 260
	200

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5870L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002303
Chassis No.:	VF1ABL15AUC280937
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	11 Dec 2014
First Registration Date:	11 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	904997000Wa 5 40
COE Expiry Date:	10 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$27,448.00
Total Rebate Amount:	\$36,821.00
Message	

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	to tieredy consent to the distinishing of time report of the extent of the distinishing of time report of the distinishing of the distinishing of time report of the distinishing of the distin
	ACCIDENT STATEMENT
Date Of Report	10/09/2018 15:37
Date Of Accident	09/09/2018 17:40
Exact Location Of Accident	PAN PACIFIC HOTEL EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5870L
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG

Mobile Phone No

OFFICE-62866666 Alternative Phone No

Vehicle Particulars

RENAULT Manufacturer

Model LATITUDE-2.0 L (A)

Exact Purpose for which vehicle was being used at

time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY

Fleet Policy

YES

Policy Number

VPX/P1680520

Cover Note Number

Driver

LIANG CHEN QUEN Name of Driver

S1635090G NRIC No 25/05/1964 Date Of Birth Occupation OUTDOOR 28/10/1982 Date Of Driving Pass

35 YEARS AND 10 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-98210208 Mobile Number

Fax Number

Contact Number

NOFMAIL **EMail Address**

BLK 545 SERANGOON NORTH AVENUE 3

Address #10-212

550545 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

SIDE SWIPE Type Of Accident CLEAR Weather Conditions

DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

NO

NO

NO

YES

NO

Circumstances of Accident

On 09.09.2018 at about 1740hours, I was heading towards Pan Pacific Hotel exit after alighting my passenger when I made a stop to check for oncoming vehicle. Suddenly I felt an impact. Vehicle B (PZ1338T) which drive out from my right and hit onto my taxi's right side front portion.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera?

Was there any audio recorded?

NO NO

DETAILS OF OTHER VEHICLE PROPERTY 1

PZ1338T Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

TAN LYE YONG

S1513587E NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

GIARMC SketchPlanForm_V5

Sketch Plan #2 Pg. 1



GIARMC SketchPlanForm_V3

Page 4 of 10

AAD1809-081

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

Vehicle No.:

SHC 5870L

Not Northanker 21 Say & 3250/

SHC 5870L

Chassis No.: VF1ABL15AUC280937

Vehicle Make: RENAULT Vehicle Model: LATITUDE

Date of Accident: 9.9.2018

Third Party Insurer : TOKIO MARINE

	PART	LIST
1	BUMPER COVER FRT	\$ Bn/N 1,259.42
1	BUMPER SPOILER FRT	\$ 5 181.75 X
1	BUMPER ABSORBER FRT	\$ 5 394.68 X
1	BUMPER RETAINER FRT RH	\$ 150.77 X
1	BUMPER SUPPORT FRT	\$ 5- 123.88 X
1	BUMPER UNDERTRAY FRT	\$ √~ 472.83 <
1	BUMPER GRILLE LOWER FRT	\$ ∫∽ 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$ DV 207.21 V
1	BUMPER BEAM FRT	\$ 914.08 💉
1	HEADLAMP RH	\$ Mgcm 1,184.43
1	HEADLAMP PANEL FRT RH	\$ 7 152.15 X
1	HEADLAMP LH	\$ 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$ 152.15 X
1	FENDER PANEL FRT RH	\$ Bu 783.83 -
1	WHEELARCH FRT RH	\$ 278.84
1	FENDER BRACKET LOWER RH	\$ 5m 15.79
1	FENDER INSULATOR RH	\$ ∫ _{130.84}
1	DOOR PANEL FRT RH	\$ N 2,844.66
1	RADIATOR GRILLE	\$ ∫ _{1,707.78}
1	RADIATOR GRILLE BADGE 'RENAULT'	\$ رم 225.36
1	RADIATOR GRILLE FRAME	\$ ر 1,353.75
1	RADIATOR FAN COWLING	\$ S→ 820.54 X
1	RADIATOR FAN MOTOR LH	\$ 967.36
1	RADIATOR FAN MOTOR RH	\$ √ 1,479.46
1	FRAME FULL SUPPORT PANEL	\$ ا 615.90
1	FRAME FULL SUPPORT BRACKET	\$ A 89.79
1	DOOR MIRROR ASSY RH	\$ Sm 1,483.40
1	DOOR PANEL FRT RH	\$ N 2,844.66
1	BONNET	\$ N 1,941.63
1	BONNET INSULATOR	\$ √ 405.73 C
		24633-9

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

Tel No. : 6287 6666 Fax No. CO./GST Reg. No. 201019626G

SHC 5870L

		10%	\$	3,696.31 33,266.80
		TOTAL		36,963.11
1	WIPER RESERVOIR MOTOR	Λ,	\$	270.06)
1	WIPER RESERVOIR NECK	27	\$	€ 270.06
1	WIPER RESERVOIR	5	. \$	5 348.25 5 136.11
1	DRIVESHAFT RH	2	\$	1,747.45
1	STABILIZER BAR FRT		\$	
1	ABSORBER FRT RH		\$	Sn 360.54 sn 604.65
1	KUNCKLE ARM RH		\$	
1	LOWER ARM RH		\$	
1	A/C CONDENSER GARNISH RH		\$	59.60 Sh 685.76
1	A/C CONDENSER GARNISH LH		\$	√n 58.81
1	A/C CONDENSER GARNISH RH UPPER		\$	39.67
	A/C CONDENSER GARNISH LH UPPER		\$	رم 39.67 در 39.67
	A/C CONDENSER		\$	2,020.37
	ENGINE UNDERTRAY		\$	564.98
	SUBFRAME BRACKET OUTER RH		\$	Ju 92.36
	SUBFRAME BRACKET OUTER LH		\$	رار 92.36 الم
	SUBFRAME OUTER FRT		\$	J- 2,652.45
	BONNET SEAL INNER		\$	5 157.28
	BONNET SEAL OUTER		\$	92.36
	BONNET CABLE COVER		\$	161.03
	BONNET CABLE		\$	ر ا 119.19
	BONNET LOCK		\$	N 305.48
	BONNET HINGE RH		\$	A 348.31
	BONNET HINGE LH		\$	7 348.31
	BONNET STRUT RH		\$	Sh 88.61
	BONNET STRUT LH		\$	Sh 88.61)

Specical Nett

1SET	BUMPER CLIP FRT	\$ Ne 66.00
1	BUMPER BRACKET CLIP FRT RH	\$ ~~ 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$ 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$ 69.00 X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$ 70.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-081

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5870L

2		Ψ.	Nr 20.00
2	FRAME FULL SUPPORT PANEL NUT FRAME FULL SUPPORT PANEL STUD	\$	~~ 30.00
1SET	WHEELARCH CLIP FRT RH	\$	Na 30.50
6	BONNET INSULATOR CLIP L70Y	\$	ル へ 7.30
2	BONNET STRUT L70Y	\$	Sm 88.61
2	BONNET CABLE CLIP L70Y	\$	۸۸ 6.31 \
2	BONNET CABLE COVER SCREW L70Y	\$	5 10.85 } X
00000	WINDSCREEN SEALANT	\$	مر 253.80
1	FRONT WINDSCREEN MOULDING	\$	120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	ひん 100.00
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	80.00
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	50.00
1	FRONT RIGHT TYRE	\$	Sh 330.00
1	FRONT RIGHT TYRE RIM	\$	380.00

TOTAL	\$ 1,734.88	
TOTAL PARTS	\$ 35,001.68	
LABOUR Panel beating, knocking and straightening the		
necessary portion, remove and renewal of parts, adjust and realign the same	\$ 4,500.00	400
Putty and spray painting of the affected portion.	\$ 4,000.00	4401
To rust-proofing of the affected areas.	\$ 170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ Mr 380.00	×
To check steering geometry and computer wheel alignment	\$ ルル 220.00	×
To transfer of tire, rim and on wheel balancing.	\$ イル 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1809-081

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330 CO./GST Reg. No. 201019626G

SHC 5870L

LUMP SUM (REPAIR DAY)	,	2 days	
Over All Total		46,091.68 46261-3	10
TOTAL		11,090.00	
To transfer of front windscreen fittings and conduct water seepage test	\$	7 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	5 170.00 >	<
To replace, refix and top up coolant for radiator	\$	4 170.00 3	×
To vacuum, replace, refix and recharge air condenser	\$	4 380.00 2	×
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	G 380.00)	×
To transfer of front fender fittings, attachment and perform water seepage test.	\$	12 380.00 j	×
To Check Electrical Lighting Concerned.	\$	170.00 2	201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI18016606/KTBN2

Date:

19/09/2018

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MB010047

Claimant Vehicle No :

Claimant

SHC5870L

Insured Vehicle No:

PZ1338T

Date of Loss:

09/09/2018

Nature of Claim:

TP

Claim No: M1804492

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC5870L

Make & Model:

RENAULT LATITUDE, 2.0 L (A) 11/12/2014 (Man. Year: 2014)

Engine No: Chassis No: M9R8839C002303 VF1ABL15AUC280937

Reg. Date: Colour:

Metallic White/Red

Odometer:

415615 km

Engine Capacity:

Market Value/New Car

1995 cc N/A

Price:

1316.35

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

e: 215/60R16 e: Giti 9 mm Rear Tyre Size:

215/60R16 Giti 9 mm

Front Left Side: Front Right Side: Giti 9 mm Giti 9 mm Rear Left Side: Rear Right Side:

Giti 9 mm Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,001.70	3,157.40	31,844.30	90.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,260.00	890.00	10,370.00	92.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,261.70	4,047.40	42,214.30	91.25
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	46,261.70	3,250.00	43,011.70	92.97
+ GST 7.00/7.00% (S\$)	3,238.32	227.50	3,010.82	92.97
Nett Amount (SS)	49.500.02	3,477.50	46,022.52	92.97

INSPECTION

Date of Assignment:

13/09/2018

Date Inspected:

11/09/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Amount

Repairer's

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 19 Sep 2018) Part Source: MRM-SG

RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SHC5870L)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

Condition

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	com	mended Parts
No.	Qty	Part No. Particulars
1	1	*BUMPER CO
2	1	*BUMPER SP

1	1	*BUMPER COVER FRT	Buckled/Dented		*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Serviceable	181.75 FL	
3	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	
4	1	*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	
5	1	*BUMPER SUPPORT FRT	Serviceable	123.88 FL	
5	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	
7	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	
3	1	*BUMPER FOG LAMP GRILLE RH	Dented	207.21 FL	
9	1	*BUMPER BEAM FRT	Repair	914.08 FL	
10	1	*HEADLAMP RH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
11	1	*HEADLAMP PANEL FRT RH	Repair	152.15 FL	
12	1	*HEADLAMP LH	Serviceable	1,184.43 FL	
13	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	
14	1	*FENDER PANEL FRT RH	Buckled	783.83 FL	
15	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	
16	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
17	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	
18	1	*DOOR PANEL FRT RH	Repair	2,844.66 FL	
19	1	*RADIATOR GRILLE	Serviceable	1,707.78 FL	
20	1	*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	
21	1	*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
22	1	*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
23	1	*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*-FL
24	1	*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*-FL
25	1	*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*-FL
26	1	*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*-FL
27	1	*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*-FL
28	1	*DOOR PANEL FRT RH	Repair	2,844.66 FL	*-FL
29	1	*BONNET	Repair	1,941.63 FL	. *- FL
30	1	*BONNET INSULATOR	Serviceable	405.73 FL	*-FL
31	1	*BONNET STRUT LH	Serviceable	88.61 FL	. *-FL
32	1	*BONNET STRUT RH	Serviceable	88.61 FL	. *-FL
33	1	*BONNET HINGE LH	Repair	348.31 FL	. *- FL
34	1	*BONNET HINGE RH	Repair	348.31 FL	. *-FL
35	1	*BONNET LOCK	Repair	305.48 FL	*- Fl
36	1	*BONNET CABLE	Serviceable	119.19 FL	. *-Fl
37	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*-Fl
		*BONNET SEAL OUTER	Serviceable	92.36 FL	. *- Fl
38	1	*BONNET SEAL INNER	Serviceable	157.28 FI	
39	1	*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	
40	1	*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	
41	1	*SUBFRAME BRACKET OUTER RH	Serviceable	92.36 FI	
42	4	*ENGINE UNDERTRAY	Serviceable	564.98 FL	
43	1	*A/C CONDENSER	Serviceable	2,020.37 FI	TO 100 MG 200

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*-FL
46	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*-FL
47	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*-FL
48	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*-FL
49	1		*LOWER ARM RH	Serviceable	685.76 FL	*-FL
50	1		*KNUCKLE ARM RH	Serviceable	846.98 FL	*-FL
51	1		*ABSORBER FRT RH	Serviceable	360.54 FL	*-FL
52	1		*STABILIZER BAR FRT	Serviceable	604.65 FL	*-FL
53	1		*DRIVESHAFT RH	Repair 1,747.45 FL		*- FL
54	1		*WIPER RESERVOIR	Serviceable	348.25 FL	*-FL
55	1		*WIPER RESERVOIR NECK	Serviceable	eable 136.11 FL	
56	1		*WIPER RESERVOIR MOTOR	Serviceable		
57	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
58	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
59	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*-FS
60	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*-FS
61	1		*SET FRAME FULL SUPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
62	2		*FRAME FULL SUPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
63	2		*FRAME FULL SUPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
64	1		*SET WHEELARCH CLIP FRT RH	Not Necessary 30.50		S *-FS
65	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*-FS
66	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*-FS
67	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
68	2		*BONNET CABLE COVER SCREW L70Y	Serviceable	10.85 FS	*- FS
69	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
70	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*-FS
71	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
72	1		*FRONT RIGHT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
73	1		*FRONT RIGHT DOOR STICKER 6555-3333	Not Necessary	50.00 FS	*- FS
74	1		*FRONT RIGHT TYRE	Serviceable	330.00 FS	*- FS
75 F=Fra	1 anchise	nart S=Snct	*FRONT RIGHT TYRE RIM Nett. L=ListItemDisc.	Serviceable	380.00 FS	*-FS
				Sub Total (S\$)	38,698.02 3,696.32	3,500.89
		- List Item Discount on L Items 10.00/10.00% (S\$)				343.49
				Total Parts (S\$)	35,001.70	3,157.40

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

D	امما	I abau	
Recommend	lea	Labou	Г

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	*
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	-
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	<u> </u>
10	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER	New	380.00	2
11	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	
12	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	
13	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	8
	Gross Labou	r Cost (S\$)	11,260.00	890.00
	Report was unsubmitted during	na this print-out.		

< END OF ESTIMATES >